

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2018 00:58
Date Of Accident	23/12/2018 22:00
Exact Location Of Accident	WITHIN SPC PETROL KIOSK, 100 JURONG WEST AVE 1, SI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR7504S
Insured/Policyholder	
Name Of Registered Owner	KOH GUAN SEIW
NRIC No	S0227934G
Email Address	GSKOH@UOBKAYHIAN.COM
Mobile Phone No	(LOCAL) +65-98173050
Alternative Phone No	Office-81838613

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BENZ E200 2.0 CGI SEDAN
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100404304-03
Cover Note Number	

Driver

Name of Driver	KOH GUAN SEIW
NRIC No	S0227934G
Date Of Birth	04/06/1952
Occupation	INDOOR
Date Of Driving Pass	03/01/2004
Driving Experience	14 YEARS AND 11 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-98173050
Fax Number	
Contact Number	OFFICE-81838613
E-Mail Address	GSKOH@UOBKAYHIAN.COM
Address	122 JURONG EAST STREET 13 #09-27 SINGAPORE
Postcode	600122
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Collision - Head to Rear (I hit a third party vehicle), #carpark, Moving & Parked, Blue Car SKR7504S, White Car SHC8508P, The accident occurred on 23 December 2018 9.54pm at the lane between Pump 10 and "Manual Wash" Car wash at SPC 100 Jurong West Ave 1 Singapore 649519. Mr. Lee Han Seng driver for the Comfort Delgro Taxi (SHC 8505P) had parked his taxi beside the narrow exit for Pump 10. This taxi was parking directly on a double yellow line. When I was stopping my car to use Pump 10 my car collided with SHC 8505P. For Mr. Lee the collision occurred when he had sat into his vehicle after leaving it parked right next to the pump exit and on the double yellow line. The collision was between the front left bumper of my car and the rear right bumper of the taxi. There were no injuries and both drivers did not complain of other physical conditions resulting from the incident. As for damages both cars suffered paint transfers and cosmetic scratches. There were no dents for both bumpers. Both parties did not make any form of third party settlement. A video of the accident is available for your reference but cannot be attached to this online submission due to file format. Please advise on how to send you the file.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NO VIDEO FILE ATTACHED
Was there any audio recorded?	NO

Sketch Plan



Insd's Nric (Front)




Insd's Nric (Back)



Insd's Driving License (Front)



Insd's Driving License (Back)



Accident Photo



Accident Photo



Accident Photo



Accident Photo

