

REF: ASM(AXA)

Surveyor

ASSIGNMENT

From:

Date: 31/12/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 2469M

at Workshop m/s

Esteem performance

of

385 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am
owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$42k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-6 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SME 2469M Yr Regn: 09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda A Free C.C. 1486

Colour:

M. Blue Grey A/C: Insured / Std / NI / NA

Sp. Reading

22256 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GBF 1070757

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

2 mm

L/Bal.

7 mm

L/Bal.

8 mm

D.O.A.

13/12/18

D.O.I.

31/12/18

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/1 15h 45 to 16h 15

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL