

ASS. REC. BY:

REF:

es/1pc18023090/Uqd3et

Special Instruction:

Surveyor:
Meunier

Marcus

ASSIGNMENT (Office)

From (Person):

Gerald poh

of

JPC

Date/Time

26/12/18 @ 12:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 9372U

Insured:

at Workshop m/s:

VAC Auto

Tel:

96312535

of

1 Kaki Bukit Ave 6 # 02-11

Policy No:

Z18VP05017830

Claim No:

18/18/18/VP05/021253

Sum Insured:

Excess:

TBA of 28/12/18

Make of Veh:

(Client's Record)

D.O.A. 23/12/2018

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:48pm @ 26/12/18

Person Contacted:

Mr. Victor

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 9372U-X
26/12/18 @ 5:27pm	Report to Gerald Poh via Meunier.
28/12/18 @ 10am	Gerald Poh informed C/A by email.
28/12/18 @ 10:18am	Victor informed C/A by email.

(08/11/13) wel

ASS. REC. BY: Marcus

REF:

LPC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLA 93724

at Workshop m/s JAC

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: ?

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 58k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: 8 Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LIA 42720

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLA93724 Yr Regn: 3, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mif Lancer EX c.c. 1590

Colour: S-hu A/C: Insured / Std / NI / NA

Sp. Reading: 48946 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSRCY1AG4004404

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/12/18 D.O.I. 26/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7 yrs. 3 m.

4/1/19 confirmed fire by \$8400.40 with victor

note parts have to include GST 7%

(Red B5553.60, 40%)

RECEIVED 15 JAN 2019

Date/Time, File Pass to? ☐ : Preli. Report1) 1/1/19 ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$) TOTAL

Report Format: MER - OF

Lump Sum / I.B.I. (\$ 8400.40)

$$3 \times 16 = 48$$

$$170 + 48 = 218$$

$$218 \times 20\% = 43$$

$$218 + 43 = 258$$

258
50
50 + 50
151
559 + 10
569

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018 Sendback Est	26 Dec 2018 11:14 S\$13,954.00	26 Dec 2018 12:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TAY SEOW TUCK (ZHENG SHAODA), ID: S6903785B, Tel: +6594759977, Email: NOEMAIL		
Vehicle Reg. No.:	SLA9372U	Date of Loss:	23/12/2018 17:00 - :59 [33 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 18/18/18/VP05/021253	Policy/Cover Note No.:	Z18VP05017830 (Comprehensive) Coverage: 23/03/2018 - 22/03/2019
		Excess:	S\$0.00
Repairer:	VAC Auto Centre Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #02-11, 417883 Kaki Bukit - Tel: 96312535/86188008		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/01/2019]		
Driver/Custodian:	TAY SEOW TUCK (ZHENG SHAODA) (49 / Male), NRIC: S6903785B, Tel: +6594759977		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 28 December 2018 10:18 AM
To: vphlim@singnet.com.sg
Cc: SUR
Subject: VEHICLE SLA 9372U (DOA: 23/12/2018)

Dear Victor,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SLA 9372U (Excess \$0.00)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Friday, 28 December 2018 10:00 AM
To: 'GERALD POH WEE BIN'; SUR
Cc: 'MT_Claim_SG'; assignments
Subject: RE: OD CLAIM - SLA9723U

Dear Gerald,

Thank you for the email.

Dear Shiau Chan,

FYNA Our Ref : CS/LPC18023090/Uqd3

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Friday, 28 December 2018 7:15 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Victor Lim <vphlim@singnet.com.sg>
Subject: RE: OD CLAIM - SLA9723U

Dear Nivitha,

Your Immediate Advice dated 23 December 2018 refers.

You may proceed to authorize repair as adjusted.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 26 Dec 2018

Preliminary Advice

Vehicle No	: SLA9372U	Accident Date	: 23/12/2018
Make	: MITSUBISHI LANCER EX	Policy No.	: Z18VP05017830
Assignment Date	: 26/12/2018	Excess	: S\$0.00
Date of Inspection	: 26/12/2018	Est. Duration of Repair	: 5.00
Inspection At	: VAC AUTO CENTRE PTE LTD (HQ) 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,954.00
Revised Amount	:S\$	5,613.00
Check Items (Estimated)	:S\$	3,496.00
Total	:S\$	9,109.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	42,720.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,280.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3785B
Vehicle Details	
Vehicle No.:	SLA9372U
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	4A92CH3610
Chassis No.:	JMYSRCY1AGU004404
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$13,571.00
Original Registration Date:	23 Mar 2016
First Registration Date:	23 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$13,571.00 <i>6785</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2026
PARF Rebate Amount:	\$10,178.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$32,542.00
Total Rebate Amount:	\$42,720.00

The information contained herein is correct as at 26 Dec 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.68%P.A Lowest Interest@GV
Cars Financing \$1500
Downpayment Monthly From \$468
GV Credit Pte Ltd StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES



Browse by Category

▼

Sort by Date Posted

▼

20 results/page

▼

4 vehicles

lancer

Advanced Search

Submit

Search Selection

lancer

Any

Any

2016

Any

Any

Any

Available

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	Mitsubishi	Lancer EX 1.6A	\$58,800	\$7,490 /yr	13-Jan-2016	1,590 cc	75,000 km	Sedan	Available
One Owner Only, Fully Maintained By Cycle And Carriage! 10 Years Engine Warranty And 5 Years Unlimited Mileage Warranty By Agent. Nicely Maintained By Owner. Please Call Or Visit Us Now For Further De...									
Pure Motors Pte Ltd									
Posted: 24-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									
	Mitsubishi	Lancer EX 1.6A	\$81,800	\$10,140 /yr	19-May-2016	1,590 cc	30,000 km	Sedan	Available
(Facelited Model With LED Tail Lamps And 5 Years Unlimited Mileage C&C Warranty) \$0 Down Payment Available! Buy With Confidence! No Hidden Cost! Low Mileage! 100% Accident Free! In House Loan Or Bank ...									
Posted: 23-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									
	Mitsubishi	Lancer EX 1.6A	\$61,800	\$7,030 /yr	05-Oct-2016	1,590 cc	-	Sedan	Available
\$0 Down Payment Available! No Gimmiks! 100% Approval! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Ban...									
88 Motor Trading									
Posted: 19-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									
	Mitsubishi	Lancer EX 1.6A	\$64,888	\$7,270 /yr	20-Dec-2016	1,590 cc	35,000 km	Sedan	Available
Newly Fitted Upholstery, Stylish Designer Colour, Regularly Serviced At Cycle And Carriage, Well Maintained By Lady Owner, Selling As Relocating.									
Posted: 16-Dec-2018 Tags: 2016 Mitsubishi Lancer, 2016 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Home

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article

Forum

Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used lancer, lancer Singapore, used lancer Singapore, used lancer, used vehicles Singapore or even buy used lancer Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Compare

Follow sgCarMart.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2018 11:33
Date Of Accident	23/12/2018 17:55
Exact Location Of Accident	PUNGGOL WAY TOWARDS SUMANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA9372U
Insured/Policyholder	
Name Of Registered Owner	TAY SEOW TUCK (ZHENG SHAODA)
NRIC No	S6903785B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94759977
Alternative Phone No	OFFICE-94759977

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05017830
Cover Note Number	

Driver

Name of Driver	TAY SEOW TUCK (ZHENG SHAODA)
NRIC No	S6903785B
Date Of Birth	06/02/1969
Occupation	INDOOR
Date Of Driving Pass	14/04/1998
Driving Experience	20 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94759977
Fax Number	
Contact Number	OFFICE-94759977
EMail Address	NOEMAIL

Address	BLK 736 TAMPINES STREET 72 #12-26
Postcode	520736
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 23/12/2018 AT ABOUT 1755 HOURS, I WAS TRAVELLING ALONG PUNGGOL WAY TOWARDS SUMANG DIRECTION. WHEN THE TRAFFIC LIGHTS IN FRONT TURNED GREEN THE FRONT VEHICLES MOVED AND I ALSO FOLLOWED. SUDDENLY I NOTICED THAT THE VEHICLE IN FRONT OF ME, A WHITE MAZDA 3 (REGN NO: SLN5470C) JAMMED BRAKES. ON SEEING THAT I IMMEDIATELY APPLIED MY EMERGENCY BRAKES BUT TO NO AVAIL. AS A RESULT, THE FRONT PORTION OF MY VEHICLE (REGN NO: SLA9372U) COLLIDED INTO THE REAR PORTION OF SLN5470C. NEXT I ALIGHTED FROM MY VEHICLE TO TAKE PHOTOS/VIDEOS AND EXCHANGED PARTICULARS. I ALSO NOTICED THAT THE FRONT PORTION OF SLN5470C HAD ALSO COME INTO CONTACT WITH THE REAR PORTION OF ANOTHER VEHICLE, A RED HONDA VEZEL (REGN NO: SLL4481M). THE DRIVER OF SLL4481M, MR TEE HERNG CHERNG SAID THAT HE ALSO APPLIED HIS BRAKES AS THE VEHICLE IN FRONT OF HIM (REGN NO: UNKNOWN) HAD APPLIED BRAKES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG. CANNOT UPLOAD
Was there any audio recorded?	NO

SKETCH PLAN

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.


(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Page 3 of 9

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PLEASE REFER TO REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 24/12/18
1215 Hrs

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:



VAC Auto Centre Pte Ltd (Co.Reg.No:200210945Z)

1 Kaki Bukit Ave 6 #02-11
Singapore 417883

Tel: 96312535/86188008 Fax: 66365355 Email: vphlm@singnet.com.sg; vacauto@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	Z18VP05017830	Date of Loss:	23/12/2018
Vehicle Reg. No.:	SLA9372U	Driveable?	
Driver Age/Info:	49 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	TAY SEOW TUCK (ZHENG SHAODA)	Contact No:	+6594759977
Driver:	TAY SEOW TUCK (ZHENG SHAODA)		
Make/Model:	MITSUBISHI LANCER EX, 1.6 (A)	Vehicle Reg. Date:	23/03/2016
Vehicle Colour:	Silver	Chassis No:	JMYSRCY1AGU004404
Engine No:	4A92CH3610		
Odometer:	48946 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		

*not Authorized
Sdy. 26/12/18
5:15 PM*

Description of Accident/Loss ON 23/12/2018 AT ABOUT 1755 HOURS, I WAS TRAVELLING ALONG PUNGGOL WAY TOWARDS SUMANG DIRECTION. WHEN THE TRAFFIC LIGHTS IN FRONT TURNED GREEN THE FRONT VEHICLES MOVED AND I ALSO FOLLOWED. SUDDENLY I NOTICED THAT THE VEHICLE IN FRONT OF ME, A WHITE MAZDA 3 (REGN NO: SLN5470C) JAMMED BRAKES. ON SEEING THAT I IMMEDIATELY APPLIED MY EMERGENCY BRAKES BUT TO NO AVAIL. AS A RESULT, THE FRONT PORTION OF MY VEHICLE (REGN NO: SLA9372U) COLLIDED INTO THE REAR PORTION OF SLN5470C. NEXT I ALIGHTED FROM MY VEHICLE TO TAKE PHOTOS/VIDEOS AND EXCHANGED PARTICULARS. I ALSO NOTICED THAT THE FRONT PORTION OF SLN5470C HAD ALSO COME INTO CONTACT WITH THE REAR PORTION OF ANOTHER VEHICLE, A RED HONDA VEZEL (REGN NO: SLL4481M). THE DRIVER OF SLL4481M, MR TEE HERNG CHERNG SAID THAT HE ALSO APPLIED HIS BRAKES AS THE VEHICLE IN FRONT OF HIM (REGN NO: UNKNOWN) HAD APPLIED BRAKES.

Present Location: VAC AUTO CENTRE PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	10,580.00
Miscellaneous Items	644.00
Labour	2,730.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (\$\$)	13,954.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Resurvey results are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed:

This claim is handled by: VICTOR LIM PUAY HONG

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2018)

Parts: 143 MITSUBISHI LANCER EX 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: VAC Auto Centre Pte Ltd/SLA9372U/26/12/2018 11:14

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>Dis</i>	0.00	0.00	*520.00 F
2	1		*FRONT BUMPER TOW HOOK COVER <i>For 1</i>	0.00	0.00	*30.00 F
3	1		*FRONT BUMPER GRILLE <i>300</i>	0.00	0.00	*95.00 F
4	1		*FRONT BUMPER GRILLE MOULDING <i>Bent/Scr</i>	0.00	0.00	*185.00 F
5	2		*FRONT BUMPER FOG LAMPS <i>17</i>	0.00	0.00	*560.00 F
6	2		*FRONT BUMPER DAY LIGHTING <i>17</i>	0.00	0.00	*840.00 F
7	1		*FRONT BUMPER TOP SEAL <i>scr</i>	0.00	0.00	*45.00 F
8	1		*FRONT BUMPER TOP BEAM <i>scr</i>	0.00	0.00	*155.00 F
9	1		*FRONT BUMPER REINFORCEMENT <i>scr</i>	0.00	0.00	*280.00 F
10	2		*FRONT BUMPER SIDE RETAINERS <i>scr</i>	0.00	0.00	*40.00 F
11	10		*FRONT BUMPER CLIPS <i>scr</i>	0.00	0.00	*25.00 F
12	2		*FRONT BUMPER HOLDER <i>scr</i>	0.00	0.00	*70.00 F
13	1		*FRONT BONNET <i>scr</i>	0.00	0.00	*480.00 F
14	2		*FRONT FENDERS <i>scr</i>	0.00	0.00	*640.00 F
15	1		*FRONT BONNET LOCK <i>scr</i>	0.00	0.00	*80.00 F
16	1		*FRONT GRILLE ASSEMBLY <i>scr</i>	0.00	0.00	*250.00 F
17	2		*FRONT HEADLAMPS <i>holder one</i>	0.00	0.00	*1,100.00 F
18	2		*FRONT HEADLAMP PANELS <i>scr</i>	0.00	0.00	*190.00 F
19	2		*FRONT HEADLAMP SIDE CLIPS <i>scr</i>	0.00	0.00	*30.00 F
20	1		*FRONT TOP PANEL <i>Dis/scr</i>	0.00	0.00	*220.00 F
21	1		*FRONT TOP GARNISH <i>scr/scr</i>	0.00	0.00	*95.00 F
22	1		*AIR CLEANER INTAKE <i>wagon</i>	0.00	0.00	*120.00 F
23	1		*AIRCON CONDENSER <i>scr/scr</i>	0.00	0.00	*580.00 F
24	1		*AIRCON DISCHARGE PIPE <i>scr</i>	0.00	0.00	*310.00 F
25	1		*AIRCON SUCTION PIPE <i>scr</i>	0.00	0.00	*310.00 F
26	1		*AIRCON LIQUID PIPE <i>scr</i>	0.00	0.00	*195.00 F
27	1		*RADIATOR ASSEMBLY <i>Bent/scr</i>	0.00	0.00	*680.00 F
28	1		*RADIATOR FAN COLWING <i>one</i>	0.00	0.00	*195.00 F
29	1		*RADIATOR FAN BLADE <i>scr</i>	0.00	0.00	*85.00 F
30	1		*RADIATOR FAN MOTOR <i>scr/should</i>	0.00	0.00	*280.00 F
31	1		*RADIATOR LOWER MEMBER <i>scr</i>	0.00	0.00	*190.00 F
32	2		*HORN <i>scr/scr</i>	0.00	0.00	*160.00 F
33	1		*NUMBER PLATE WITH HOLDER <i>scr</i>	0.00	0.00	*45.00 F
34	1		*AIRCON OIL <i>scr</i>	0.00	0.00	*60.00 F
35	1		*RADIATOR COOLANT <i>scr</i>	0.00	0.00	*60.00 F

F=Franchise part.

Sub Total (\$\$)	9,200.00
+ Margin on L,N Items 15.00% (\$\$)	1,380.00
Total Parts (\$\$)	10,580.00

VAC Auto Centre Pte Ltd/SLA9372U/26/12/2018 11:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

P-5320
Add GST 372.40
Add 15% 798.00
Add s.n 140.00
Add 16% 1770.00
8400.40

P-5320
+ 7% GST = 372.40
P + 15% = 798.00

S.N-140

P-5320

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	GST	372.40 644.00
Sub Total (\$\$)			644.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00 20
2	TO REMOVE, REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	New	120.00 100
3	TO RESPRAY PAINTING AND ETC	New	1,200.00 800
4	TO DIAGNOSE, ERASE FAULT MEMORY AFTER REPAIR	New	280.00 11 2
5	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	1,080.00 750
Gross Labour Cost (\$\$)			2,730.00

VAC Auto Centre Pte Ltd/SLA9372U/26/12/2018 11:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1770

日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

VAC AUTO CENTRE PTE LTD
NO 1 KAKI BUKIT AVE 6
#02-11

SINGAPORE
TEL : 66365355 FAX : 66365355
ATTN : VICTOR 96312535

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201812-1312
DATE : 27/12/2018
CUSTOMER ID : VAC00
VEH REG. NO. : SLA9372U
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR. : SGI

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	JJ6400G805XA/BA CY1A	FR BUMPER TOW COVER	MO SUPPLIER	1	30.00	30.0
2.	JJ5902A078 CY2 CY4	BONNET RUBBER FR	MO 2E6	1	45.00	45.0
3.	JJ6400F549 CY2 CY4	FR BUMPER SIDE BRACKET LH	MO 2E11L	1	20.00	20.0
4.	JJ6400F550 CY2 CY4	FR BUMPER SIDE BRACKET RH	MO 2E11L	1	20.00	20.0
5.	JJ6400A851 CY2 CY4	FR BUMPER INR BRACKET LH	MO 2E10A	1	35.00	35.0
6.	JJ6400A852 CY2 CY4	FR BUMPER INR BRACKET RH	MO 2E10A	1	35.00	35.0
7.	JJMR200300 CK1 Z23 CS2 CS3 CY2	CLIP,BUMPER (NC)	MO 2G2SD	10	2.50	25.0

CONTINUE NEXT PAGE

[P] 27/12/2018 12:53:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 27/12/2018 11:45:15AM

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

=====**GST REG. NO: M2-0119201-3 CO. REG. NO: 199307741M**=====

VAC AUTO CENTRE PTE LTD
NO 1 KAKI BUKIT AVE 6
#02-11

SINGAPORE
TEL : 66365355 FAX : 66365355
ATTN : VICTOR 96312535


WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon-Denso, NGK (Made in Japan)

TAX INVOICE : AR201812-1312
DATE : 27/12/2018
CUSTOMER ID : VAC00
VEH REG. NO. : SLA9372U
TERMS : 30 day
PO NO. :
PAGE NO. : Page 2 of
CURR. : SGI

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
8.	JJ5908A056/080 CY2	BONNET LOCK	MO 1S3C	1	80.00	80.0
9.	JJMN167828 NA4W CY2 CY4	HEADLAMP LWR CLIP	MO II8	2	15.00	30.0
10.	JJ1505A955/130 CY2,CY4,CY1	DUCT,AIR CLEANER INTAKE	MO 2G7	1	120.00	120.0
11.	JJ7812A030 R CY2 CY4	A/C CONDENSER ASSY	MO 2MI0T	1	580.00	580.0
12.	JJ1350A298 (J) CY1 CY2	RADIATOR ASSY (JAPAN)	MO 2MS	1	680.00	680.0
13.	JJ1355A141(J) CY2	MOTOR,COOLING FAN	MO 1LS5	1	280.00	280.0
14.	JJ8211A212 CY2 CY4	HORN (HIGH-TONE)	MO SUPPLIER	2	80.00	160.0

CONTINUE NEXT PAGE

[P] 27/12/2018 12:53:52PM

[E] 27/12/2018 11:45:15A

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

VAC AUTO CENTRE PTE LTD

NO 1 KAKI BUKIT AVE 6

#02-11

SINGAPORE

TEL : 66365355 FAX : 66365355

ATTN : VICTOR 96312535

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201812-1312

DATE : 27/12/201

CUSTOMER ID : VAC00

VEH REG. NO. : SLA93721

TERMS : 30 day

PO NO. :

PAGE NO. : Page 3 of

CURR. : SG

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
1	JJ5900A209R CY2A,CY4A	BONNET(MB20046A)	MO NEW	1	480.00	480.0
16	JJ6400H438 CY1A	FACE,FR BUMPER	MO NEW	1	520.00	520.0
17	JJ6402A399 CY1A	FR BUMPER LWR GRILLE	MO NEW	1	95.00	95.0
18	JJ6402A402 CY1A	FR BUMPER GRILLE GARNISH	MO NEW	1	185.00	185.0
19	JJ6400A832 CY2,CY4	FR BUMPER TOP BEAM	MO NEW	1	155.00	155.0
20	JJ6400C639 CY1A,CY4A GT 09"	FR BUMPER REINFORCEMENT	MO NEW	1	280.00	280.0
21	JJ7450B019 CY1A	FR RADIATOR GRILLE	MO NEW	1	250.00	250.0

CONTINUE NEXT PAGE

[P] 27/12/2018 12:53:52PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 27/12/2018 11:45:15AM

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO. M2-0118201-3 CO. REG. NO. 199307741M

VAC AUTO CENTRE PTE LTD
NO 1 KAKI BUKIT AVE 6
#02-11

SINGAPORE

TEL : 66365355 FAX : 66365355

ATTN : VICTOR 96312535

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9938



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon-Denso, NGK (Made in Japan)

TAX INVOICE : AR201812-13125
DATE : 27/12/2018
CUSTOMER ID : VAC001
VEH REG. NO. : SLA9372U
TERMS : 30 days
PO NO. :
PAGE NO. : Page 4 of 4
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
22	JJ8301C341/8301A911 CY2A,CY1A NEW	HEADLAMP ASSY LH	MO NEW	1	550.00	550.00
23	JJ8301C342/8301A912 CY2A,CY1A NEW	HEADLAMP ASSY RH	MO NEW	1	550.00	550.00
24	JJ5256A607 CY2 CY4	SUPPORT TOP PANEL	MO NEW	1	220.00	220.00
25	JJ6400A831 CY2,CY4A	SUPPORT TOP COVER	MO NEW	1	95.00	95.00
26	JJ1355A146 CY2	SHROUD,COOLING FAN	MO NEW	1	195.00	195.00
27	JJ1355A132 CY2,CZ4,CV5	FAN,COOLING	MO NEW	1	85.00	85.00

SUB-TOTAL : 5,800.00
ADD GST 7.00 % 406.00

E. & O.E

TOTAL AMOUNT SGD : 6,206.00

[P] 27/12/2018 12:53:52PM

[E] 27/12/2018 11:45:15AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : NIN

This is computer generated document.

No signature is required.



* A R 2 0 1 8 1 2 - 1 3 1 2 5 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

SLA 9372 U MITSUBISHI LANCER EX

1	Front Bumper	16		\$	520
1	Bumper tow cover	1			30
1	Bumper grille	17			95
1	Bumper grille moulding	18			185
1	Bumper top seal	2			45
1	Bumper top beam	19			155
1	Bumper reinforcement	20			280
2	Bumper side retainers	3/4	@ 20		40
10	Bumper clips	7	@ 2.50		25
2	Bumper holder	5/6	@ 35		70
1	Bonnet	15		Repair	X 480
1	Bonnet lock	8			80
1	Grille assy	21			250
2	Headlamps	22/23	@ 550		1100
2	Headlamp side clips	9	@ 15		30
1	Top panel	24			220
1	Top garnish	25			95
1	Air cleaner intake	10			120
1	Air con condenser	11			580
1	Radiator assy	12			680
1	Radiator fan cowling	26			195
1	Radiator fan blade	27			85
1	Radiator fan motor	13			280
2	Horn	14	@ 80		160
TOTAL \$5320				TOTAL \$	5800
GST 7% 372.40				Add GST 7%	406
cost 15% 798.00				Add Cost 15%	870
S.N 140.00				Add SN items	140
labour 1770.00				Add Labour	1770
\$8400.40				SUB TOTAL \$	8986

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2018 Sendback Est	26 Dec 2018 11:14 \$13,954.00	26 Dec 2018 12:40 Edit Adj Rpt	\$8,400.40 Edit Estimates	\$8,400.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TAY SEOW TUCK (ZHENG SHAODA) , ID: S6903785B, Tel: +6594759977, Email: NOEMAIL									
Vehicle Reg. No.: SLA9372U		Date of Loss: 23/12/2018 17:00 - :59 [33 Months From LTA Reg Date (Man Yr)]							
Claim Type: OD / 18/18/18/VP05/021253		Policy/Cover Note No.: Z18VP05017830 (Comprehensive) Coverage: 23/03/2018 - 22/03/2019							
		Excess: \$0.00							
Repairer: VAC Auto Centre Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #02-11, 417883 Kaki Bukit - Tel: 96312535/86188008									
Handling Insurer: Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/01/2019]									
Driver/Custodian: TAY SEOW TUCK (ZHENG SHAODA) (49 / Male), NRIC: S6903785B, Tel: +6594759977									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> LONPAC_HQ (31/12/2018): Alert - Adj Mandate Approved (\$9109.00) - SLA9372U - Claim Handler: Gerald Poh 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





































SLA9372U (18/18/18/VP05/021253)



















































OD



















































Dec 23 2018 5:00PM

[TAY SEOW TUCK (ZHENG SHAODA)]

VAC Auto Centre Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	26/12/18 11:14	VAC Auto Centre Pte Ltd (HQ) Repairer Estimates	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/18 17:21	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/12/18 17:42	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	26/12/18 17:42	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC Auto Centre Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
60	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
61	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
62	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
64	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
65	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
66	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
67	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
68	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
69	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
70	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
71	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
72	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
73	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
74	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
75	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
76	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
77	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
78	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
79	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
80	26/12/18 17:43	General View	 Load JPG	<input checked="" type="checkbox"/>
81	15/01/19 11:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/01/19 11:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/01/19 11:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC Auto Centre Pte Ltd (HQ)	Thumbnail	Print
84	15/01/19 11:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/01/19 11:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	15/01/19 11:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC Auto Centre Pte Ltd (HQ)	Thumbnail	Print
134	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
135	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
136	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
137	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
138	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
139	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
140	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
141	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
142	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
143	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
144	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
145	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
146	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
147	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
148	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
149	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
150	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
151	15/01/19 11:52	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/18 09:19	ESTIMATE		<input type="checkbox"/>
2	17/01/19 09:53	Parts Invoice		<input type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	24/12/18 12:37	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	24/12/18 12:31	Identification Card		<input checked="" type="checkbox"/>
2	24/12/18 12:31	Identification Card		<input checked="" type="checkbox"/>
3	24/12/18 12:31	Accident Photo		<input checked="" type="checkbox"/>
4	24/12/18 12:31	Accident Photo		<input checked="" type="checkbox"/>
5	24/12/18 12:31	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	24/12/18 12:31	Sketch Plan		<input checked="" type="checkbox"/>
2	24/12/18 12:31	Sketch Plan #2		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18023090/UQD3E2

Date: 17/01/2019

REFERENCE

Insured/Claimant: TAY SEOW TUCK (ZHENG SHAODA) Policy No: Z18VP05017830

Date of Loss: 23/12/2018

Nature of Claim: OD

Claim No: 18/18/18/VP05/021253

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA9372U	Engine No:	4A92CH3610
Make & Model:	MITSUBISHI LANCER EX, 1.6 (A)	Chassis No:	JMYSRCY1AGU004404
Reg. Date:	23/03/2016 (Man. Year: 2016)	Odometer:	48946 km
Colour:	Silver		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	S\$58,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,580.00	6,258.00	4,322.00	40.85
Miscellaneous Items	644.00	372.40	271.60	42.17
Labour	2,730.00	1,770.00	960.00	35.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	13,954.00	8,400.40	5,553.60	39.80

INSPECTION

Date of Assignment:	26/12/2018	Present Location:	VAC Auto Centre Pte Ltd (HQ)
Date Inspected:	26/12/2018	Inspected At:	VAC Auto Centre Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #02-11 Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2019)
Parts: 143	MITSUBISHI LANCER EX 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA9372U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Distorted	520.00 F	*520.00 F
2	1		*FRONT BUMPER TOW HOOK COVER (WCP)	Torn	30.00 F	*30.00 F
3	1		*FRONT BUMPER GRILLE (WCP)	Broken	95.00 F	*95.00 F
4	1		*FRONT BUMPER GRILLE MOULDING (WCP)	Bent / Scratched	185.00 F	*185.00 F
5	2		*FRONT BUMPER FOG LAMPS (WCP)	Not Necessary	560.00 F	*- F
6	2		*FRONT BUMPER DAY LIGHTING (WCP)	Not Necessary	840.00 F	*- F
7	1		*FRONT BUMPER TOP SEAL (WCP)	Necessary	45.00 F	*45.00 F
8	1		*FRONT BUMPER TOP BEAM (WCP)	Bent	155.00 F	*155.00 F
9	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	280.00 F	*280.00 F
10	2		*FRONT BUMPER SIDE RETAINERS (WCP)	Bent	40.00 F	*40.00 F
11	10		*FRONT BUMPER CLIPS (WCP)	Necessary	25.00 F	*25.00 F
12	2		*FRONT BUMPER HOLDER (WCP)	Bent	70.00 F	*70.00 F
13	1		*FRONT BONNET (WCP)	Repair	480.00 F	*- F
14	2		*FRONT FENDERS (WCP)	Repair	640.00 F	*- F
15	1		*FRONT BONNET LOCK (WCP)	Bent	80.00 F	*80.00 F
16	1		*FRONT GRILLE ASSEMBLY (WCP)	Cracked	250.00 F	*250.00 F
17	2		*FRONT HEADLAMPS (WCP)	Holder Cracked	1,100.00 F	*1,100.00 F
18	2		*FRONT HEADLAMP PANELS (WCP)	Repair	190.00 F	*- F
19	2		*FRONT HEADLAMP SIDE CLIPS (WCP)	Necessary	30.00 F	*30.00 F
20	1		*FRONT TOP PANEL (WCP)	Dented / Bent	220.00 F	*220.00 F
21	1		*FRONT TOP GARNISH (WCP)	Deformed / Torn	95.00 F	*95.00 F
22	1		*AIR CLEANER INTAKE (WCP)	Warped	120.00 F	*120.00 F
23	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	580.00 F	*580.00 F
24	1			Not Necessary	310.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*AIRCON DISCHARGE PIPE (WCP)			
25	1		*AIRCON SUCTION PIPE (WCP)	Not Necessary	310.00 F	*- F
26	1		*AIRCON LIQUID PIPE (WCP)	Not Necessary	195.00 F	*- F
27	1		*RADIATOR ASSEMBLY (WCP)	Bent / Punctured	680.00 F	*680.00 F
28	1		*RADIATOR FAN COLWING (WCP)	Cracked	195.00 F	*195.00 F
29	1		*RADIATOR FAN BLADE (WCP)	Cut	85.00 F	*85.00 F
30	1		*RADIATOR FAN MOTOR (WCP)	Jammed / Shorted	280.00 F	*280.00 F
31	1		*RADIATOR LOWER MEMBER (WCP)	Repair	190.00 F	*- F
32	2		*HORN (WCP)	Dented / Damaged	160.00 F	*160.00 F
33	1		*NUMBER PLATE WITH HOLDER	Bent	45.00 F	*40.00 FS
34	1		*AIRCON OIL	Necessary	60.00 F	*50.00 FS
35	1		*RADIATOR COOLANT	Necessary	60.00 F	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	9,200.00	5,460.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,380.00	798.00
Total Parts (S\$)	10,580.00	6,258.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	GST	644.00	372.40
Sub Total (S\$)			644.00	372.40

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	New	120.00	100.00
3	TO RESPRAY PAINTING AND ETC	New	1,200.00	900.00
4	TO DIAGNOSE, ERASE FAULT MEMORY AFTER REPAIR	New	280.00	0.00
5	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	1,080.00	750.00
Gross Labour Cost (S\$)			2,730.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >