

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI18023097/Jcd302

Special Instruction:

Surveyor
Mennen

fwee Jee

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

21/12/18 @ 5:20pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBG 6308M

Insured:

PC 4687L

at Workshop m/s

E-Motoring

Tel:

6910 0369 / 9183 5669

of

2 Yishun Ind. St. 1 # 01-23 Northpoint Bizhub

(Javier)

Policy No:

DMB1SN3026681800

Claim No:

JNM18D05884C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/12/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

5:22pm @ 21/12/18

Person Contacted:

Robert

Vehicle

IN / OUT

Date/Time	Action/Instruction (X) Estimate
-	call was answered on 26/12/18 @ 2:06pm by Robert.
	FBG 6308M - X
	PC 4687L - X

PRS

Bryan Hare Jia


REF: CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s **E-motoring 2 Yishun Ind St 1**
 of **#01-23**
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.




Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. **FB66308M** Yr Regn: **20 Sep 2012**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Honda CBR1000RR** C.C. **998**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp. Reading: **44366** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C7No: **JH2SCS9A4CK401284**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **Order** / Jammed / Leaked / Burnt or
 Brake: **Order** / Jammed / Leaked / Burnt or
 Modi: Nil / **8/Rim** / STD A/Rim or
 Tyre Size: F: **120/70 R17**
 R: **190/15 R17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Diablo**
 Front Rear
 R/Bal. **7** mm R/Bal. **7** mm
 L/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **18/12/18** D.O.I. **26/12/18**
 Survey held at **E-motoring**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Knock N/S, fall O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$2,800 - \$3,500 3 days
	 28/12/2018

Date/Time File Pass to?

☐ : Preli. ReportDays Of Repair: **3**

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

) \$ + PS \$

Report Format: **PRS -**

Lump Sum / I.B.I: (\$)

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

TOTAL

190

190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2018		21 Dec 2018 17:20 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	ONG XING LE		
Vehicle Reg. No.:	FBG6308M	Date of Loss:	18/12/2018 00:00 - :59
Claim Type:	TP / SNM18D05884C02	Policy/Cover Note No.:	DMB1SN3026681800
Vehicle Reg. No. (Insured):	PC4687L	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	E Motoring (HQ) 2 Yishun Industrial Street 1, Northpoint Bizhub #01-23, 768159 Yishun - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/01/2019]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

2018 10:36AM FAX

0001/0009

DmB1SN 3026681800

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
梁 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
林
師 CATHERINE C.L.LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律師
M.B.A. (BUSINESS LAW) - 商業系 - 碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: PC 4687L
Our Ref: CI/181240/T/EM.sg

20 December 2018

To: M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

via fax: 6224 7175 & by hand

SSJJ Transport Pte Ltd
2 Yishun Industrial Street 1
#01-21 North Point Bizhub
Singapore 768159

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBG 6308M / PC 4687L ON 18.12.2018 AT 2 YISHUN INDUSTRIAL STREET 1
#01-21 NORTH POINT BIZHUB**

We are instructed by **ONG XING LE** to notify you of a road traffic accident involving our client's vehicle No. **FBG 6308M** and vehicle No. **PC 4687L** driven by you at the material time. A copy of the Singapore Accident Statement and or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: E Motoring
2 Yishun Industrial Street 1
Northpoint Bizhub #01-21
Singapore 768159

Contact: Sam @ 8363 3050

Yours faithfully

Enc
cc: clients

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2894E
Vehicle Details	
Vehicle No.:	FBG6308M
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	CBR1000RR
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	SC59E2405372
Chassis No.:	JH2SC59A4CK401284
Maximum Power Output:	-
Open Market Value:	\$16,572.00
Original Registration Date:	20 Sep 2012
First Registration Date:	20 Sep 2012
Transfer Count:	4
Actual ARF Paid:	\$2,486.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,852.00
COE Rebate Amount:	\$690.00
Total Rebate Amount:	\$690.00

The information contained herein is correct as at 27 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2018 12:45
Date Of Accident	18/12/2018 18:00
Exact Location Of Accident	2 YISHUN IND ST.1 #01-23 NORHTPOINT BIZHUB
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG6308M
Insured/Policyholder	
Name Of Registered Owner	ONG XING LE
NRIC No	S9622894E
Email Address	EMOTORINGSINGAPORE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98342153
Alternative Phone No	OTHERS-98342153

Vehicle Particulars

Manufacturer	HONDA
Model	CBR1000RR
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5104032407
Cover Note Number	20/09/18 - 19/09/19

Driver

Name of Driver	ONG XING LE
NRIC No	S9622894E
Date Of Birth	29/06/1996
Occupation	INDOOR
Date Of Driving Pass	16/01/2018
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98342153
Fax Number	
Contact Number	OTHERS-98342153
EMail Address	EMOTORINGSINGAPORE@GMAIL.COM

Address	BLK 416 WOODLANDS ST.41 #09-153
Postcode	730416
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4687L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: FRG 6308 M
INSURER : NTUC
DATE & TIME: 18/12/18 @ 12:00


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

 19/12/18
Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No - T/20181219/2003

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Center: Personnel's Signature
Name: (VS)
NRIC/FIN No.

() Claim Own Policy () Claim Third Party () Reporting Only
(√) Claim ~~ODTP~~ at other workshop (by E-Metering)



**SINGAPORE
POLICE FORCE**



T/20181219/2003

Police Station Of Origin
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No T/20181219/2003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/12/2018 00:38	Vide Report No: L/20181218/0104	Station Diary No: 15
--	------------------------------------	-------------------------

Informant's Particulars

Name of Informant: ONG XING LE	Address APT BLK 416 WOODLANDS STREET 41 #09-153 SINGAPORE 730416		
ID Type / ID No. NRIC NO / S9622894E	Contact No: Home/Office Mobile: 98342153		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 22	Date of Birth: 29/06/1996	Type of Informant: Rider
Race: Chinese	Language: English		Institution / School Name:
Occupation: NSF	Driving Licence Information: Class: 2B,2A Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 18/12/2018 18.00	Type of Location: Car Park
Location: YISHUN INDUSTRIAL STREET 1 2 YISHUN IND ST 1 #01-23 NORTH POINT BIZHUB S(768159)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Parked vehicles			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG6308M	Motorcycle	HONDA	CBR1000RR	White	Slightly Damaged	0
PC4687L	Van	TOYOTA		White	No Damage	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20181219/2003

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No. 1800-8529999

2 of 3

Report No. T/20181219/2003

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBG6308M	NTUC Income Insurance Co-Operative Limited	5104032407	20/09/2018	19/09/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	ONG XING LE	ID No.	S9622894E
Related Vehicle	PC4687L (Van)	Contact No	98342153
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/12/2018, at about 1800hrs, at the above mentioned location, I was inside a mechanic shop "E-motoring". I overheard one of the mechanics instructing his manager to move one of his vehicles away. Hence, I left the shop to observe the situation. As soon as I left the shop to observe, I noticed that my motorcycle (vehicle number: FBG6308M) was already lying down on the floor. I noticed that there was a van (vehicle number: PC4687L) in front of my motorcycle, and a lorry (unknown license plate) behind my motorcycle.

I did not notice any CCTVs around.

I believe that it was the van that reversed and knocked down my motorcycle due to his misjudgement.



**SINGAPORE
POLICE FORCE**



T/20181219/2003

Police Station Of Origin
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3




Report No T/20181219/2003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 2 LOW WEI DE 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/12/2018 00:38
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No: 65476151 	Classification Of Case:

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2018		21 Dec 2018 17:20 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ONG XING LE								
Vehicle Reg. No.:	FBG6308M	Date of Loss:	18/12/2018 00:00 - :59 [74 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05884C02	Policy/Cover Note No.:	DMB1SN3026681800						
Vehicle Reg. No. (Insured):	PC4687L	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	E Motoring (HQ) 2 Yishun Industrial Street 1, Northpoint Bizhub #01-23, 768159 Yishun - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 03/01/2019]								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBG6308M (SNM18D05884C02)**
[PC4687L]
TP
ONG XING LE
Dec 18 2018 12:00AM
[-]
E Motoring

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
2	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
3	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
4	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
5	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
6	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
7	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
8	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
9	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
10	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
11	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
12	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
13	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
14	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
15	27/12/18 09:36	General View		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	21/12/18 17:19	PRS		Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18023097/JCD3E2

Date: 02/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN3026681800

Claimant Vehicle No: FBG6308M Insured Vehicle No: PC4687L

Date of Loss: 18/12/2018 Nature of Claim: TP Claim No: SNM18D05884C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG6308M**

Make & Model: HONDA CBR1000RR, 998cc Engine No: SC59E2405372

Reg. Date: 20/09/2012 (Man. Year: 2012) Chassis No: JH2SC59A4CK401284

Colour: Black Odometer: 44366 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 190/15 R17

Front Left Side: DIABLO 7 mm Rear Left Side: DIABLO 7 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/12/2018

Date Inspected: 26/12/2018 Inspected At: E Motoring (HQ)
2 Yishun Industrial Street 1, Northpoint
Bizhub #01-23
Singapore 768159

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 -\$3,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Jan 2019)

Parts: N/A HONDA CBR1000RR 998cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBG6308M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >