

ASS. REC. BY:

REF: CS/SMO/8023098/Ng d3e2

Special Instruction:

Surveyor
Menmon

ASSIGNMENT (Office)

From (Person): Irene Juma of SMO Date/Time: 26/12/18 @ 11:12am

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 8156J Insured: SLM 4258L

at Workshop m/s Keith Mutor Tel: 6514 5218 / 8288 6302

of GA Mandii Estate

Policy No: D18MTPV01005886 Claim No: CMTD1805616

Sum Insured: Excess:

Make of Veh: D.O.A. 20/12/2018
(Client's Record)CA / REV / REF. / REV 24 HRS ^{lup}

H.O.D. Endorsement:

Date/Time: 11:47am @ 26/12/18 Person Contacted: Anikka

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 8156J - X
	SLM 4258L - CS/SMO/8022920/d3
04/1/19 @ 1:40pm	Revised to Irene via Mwinshi.

REF: SMD

ASSIGNMENT

From: Date: 02012018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLT 8156 J Yr Regn: 13/11/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA HRV cc 1496

Colour: BLUE

A/C: Insured / Std / NI / NA

Sp. Reading: 89, 778

T/Radio: Insured / Std / NI / NA

Eng/No:

C/N:

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

215/60 R16

Front

Rear

R/Bal: 6 mm

R/Bal: 5 mm

L/Bal: 6 mm

L/Bal: 5 mm

D.O.A. 20/12/18

D.O.I. 2/1/19

Survey held at: KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

213/19 FINALIZED PART BY PART REPAIR \$8093.50 / 4 DAYS
(Red \$5177.92, 39%)

RECEIVED 12 MAR 2019

Date/Time, File Pass to?

☐ : Prel. Report

11/13/18

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) 8093.50

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

350

10

360

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2018		26 Dec 2018 11:12 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	HO YIN CHOY, ID: S1479968J, Tel: +6596788704, Email: mike.ho95@yahoo.com.sg		
Main Claimant:	TOH SER GEE, ID: S1322386F		
Vehicle Reg. No.:	SLT8156J	Date of Loss:	20/12/2018 06:00 - :59
Claim Type:	TP / CMTD1805616	Policy/Cover Note No.:	D18MTPV01005886 (Comprehensive)
Vehicle Reg. No. (Insured):	SLM4258L	Policy No. (Claimant):	
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by IRENE JAMES HENRY - 6322 4618]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/01/2019]		
Driver/Custodian (Insured):	HO YIN CHOY (57 / Male), NRIC: S1479968J, Tel: +6596788704		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Henry, Irene James

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Monday, 24 December, 2018 1:16 PM
To: Claims - Motor Survey
Cc: Henry, Irene James
Subject: SLT8156J - TP CLAIMS AGAINST SLM4258L DOA: 20/12/2018
Attachments: 3788_001.pdf; SAS2524302.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Sir / Madam,

Attached pls find the claims document for your necessary action. Kindly advise the liability of direct settlement.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Monday, 24 December, 2018 1:03 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: IRENE JAMES HENRY

Date: 04 Jan 2019

Preliminary Advice

Insured Vehicle No	: SLM4258L	Accident Date	: 20/12/2018
TP Vehicle No	: SLT8156J	Assignment Date	: 26/12/2018
Make	:	Est. Duration of Repair	: 4.00
Date of Inspection	: 02/01/2019		
Inspection At	: KAH MOTOR CO SDN BHD (HQ) 6A MANDAI ESTATE, SINGAPORE 729903 SINGAPORE 729903		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,235.20
Revised Amount	:S\$	6,609.88
Check Items (Estimated)	:S\$	796.54
Total	:S\$	7,406.42

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ASSIST TO FILL IN THE MAKE & MODEL OF HONDA HRV 1.5 LX CVT.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6795W
Vehicle Details	
Vehicle No.:	SLT8156J
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	L15B4533238
Chassis No.:	JHMRU1830GX203238
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,451.00
Original Registration Date:	13 Nov 2017
First Registration Date:	13 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$17,032.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2027
PARF Rebate Amount:	\$12,774.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$31,880.00
Total Rebate Amount:	\$44,654.00

The information contained herein is correct as at 04 Jan 2019

OK

Enquire Transfer Fee

Enquire Transfer Fee			
Vehicle Details			
Vehicle No.:	SLT8156J		
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	HONDA		
Vehicle Model:	HRV 1.5 LX CVT		
Chassis No.:	JHMRU1830GX203238		
Propellant:	Petrol		
Engine No.:	L15B4533238		
Engine Capacity:	1496 cc		
Maximum Power Output:	96.0 kW (128 bhp)		
Maximum Laden Weight:	1760 kg		
Unladen Weight:	1190 kg		
Year Of Manufacture:	2017		
Original Registration Date:	13 Nov 2017		
Lifespan Expiry Date:	-		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium:	\$36,001.00		
COE Expiry Date:	12 Nov 2027		
Road Tax Expiry Date:	12 Nov 2019		
PARF Eligibility Expiry Date:	12 Nov 2027		
Inspection Due Date:	12 Nov 2020		
Intended Transfer Date:	04 Jan 2019		
CO2 Emission:	129.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$5,000.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/12/2018 20:18
Date Of Accident	20/12/2018 06:05
Exact Location Of Accident	SLIP RD FM TPE (CHANGI) TO LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLT8156J
Insured/Policyholder	
Name Of Registered Owner	SER GEE SERVICES
Co Reg No	53366765W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96617953
Vehicle Particulars	
Manufacturer	HONDA
Model	HR-V-1.5 LX (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	TOH SER GEE
NRIC No	S1322386F
Date Of Birth	08/06/1958
Occupation	INDOOR
Date Of Driving Pass	22/12/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96617351
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address -
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS ANNEX D&E

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLM4258L
 Vehicle Make/Model/Colour NISSAN SILPHY
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver HO YIN CHOY
 NRIC/Passport Number S1479968J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Vehicle No _____

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Vehicle No _____

Annex E


Describe Circumstances of the Accident

On 20/12/2018 @ about 06:00 hr, my vehicle (A) was travelling from TPE towards Loyang Ave, stopped at the slip road to give way to the oncoming traffic from right. Suddenly Vbl B hit onto my vehicle rear portion.

No par and no injury involved

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SLT8156J

Chassis No : JHMRU1830GX203238

Model : HRV LX-SIN CVT YM 2016

Owner's Name : SER GEE SERVICES

Ins Policy No. :

Date of Accident : 20/12/2018

Document No. : SQT18005470 Page 1

Date : 24. Dec 2018

Customer No. : WZH023

Svc Advisor :

Engine No : L15B4533238

Date | Time : 24. Dec 2018 12:11:12 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SER GEE SERVICES OWNER INSURER: LIBERTY ACC DATE: 20/12/2018 SURVEYED BY: DATE: REF NO: TP INSURER: SOMPO TP VEH: SLM4258L						
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30	35.22
84400-T7A-J01ZA	COVER COMPTONNEAU	1	123.00	25	92.25	6.46	98.71
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	189.80	25	142.35	9.96	152.31
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	136.00	25	102.00	7.14	109.14
75725-T8N-T00	EMBLEM.RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
04715-T7A-900ZZ	FACE.RR.BUMPER	1	483.70	25	347.77	24.34	372.11
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	94.10	25	70.57	4.94	75.51
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	156.30	25	117.22	8.21	125.43
34150-T7A-J01	LIGHT ASSY,R.LID	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID	1	269.90	25	202.42	14.17	216.59
33502-T7A-J01	LAMP UNITR.	1	441.50	25	331.12	23.18	354.30
33552-T7A-J01	LAMP UNITL.	1	441.50	25	331.12	23.18	354.30
66100-T7A-300ZZ	PANEL COMPRR.	1	373.10	25	279.82	19.59	299.41
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
74800-T7A-J02	LOCK ASSYTAILGATE	1	78.90	25	59.17	4.14	63.31
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.18	79.20
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SLT8156J

Chassis No : JHMRU1830GX203238

Model : HRV LX-SIN CVT YM 2016

Owner's Name : SER GEE SERVICES

Ins Policy No. :

Date of Accident : 20/12/2018

Acknowledged by Repairer : **Document No.** : SQT18005470 **Page** 2

Signature: **Date** : 24. Dec 2018

Date: **Customer No.** : WZH023

Svc Advisor :

Engine No : L15B4533238

Date | Time : 24. Dec 2018 12:11:12 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
73226-SZW-000	DAMPERSTD 5X5 / N/A	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL WINDSHIELD DAMPER / N/A	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT / N/A	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD / N/A	4	5.30	25	15.70	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD / N/A	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / N/A	2	60.00		120.00	8.40	128.40
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ? X300	1	320.00		320.00	22.40	342.40
74940-TZ5-A01	BUZZER ASSYSMART ? X300	1	60.40	25	45.30	3.17	48.47
Sum Item					4415.20	309.06	4,724.26
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. (TAILGATE)	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT. (FRONT-RL)	1	100.00	80	100.00	7.00	107.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	80	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	120	140.00	9.80	149.80
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	220.00	N/A	220.00	15.40	235.40
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	200.00	N/A	200.00	14.00	214.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	600.00	50	600.00	42.00	642.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	80	100.00	7.00	107.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	600.00	280	600.00	42.00	642.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3000.00	2240	3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00	2250	3000.00	210.00	3210.00
Sum Labor					8820.00	617.40	9,437.40

Survey By _____

Date & Time _____

Excess _____

[Signature]
4/1/19

Total Amount 13,235.20 926.46 14,161.66

Total (Inclusive of GST) 14,161.66

Printed on 24/12/2018 1:01:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

N/AZ LEX 1500
2/1/19
PIP
4-5 Days
CHECKED ITEMS PHOTO / BEFORE PAINT PHOTO



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SLT8156J
Chassis No : JHMRU1830GX203238
Model : HRV LX-SIN CVT YM 2016
Owner's Name : SER GEE SERVICES
Ins Policy No. :
Date of Accident : 20/12/2018

Document No. : SQT18005470 **Page** 3
Date : 24. Dec 2018
Customer No. : WZH023
Svc Advisor :
Engine No : L15B4533238
Date | Time : 24. Dec 2018 12:11:12 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Status							
Signature							

Printed on 24/12/2018 1:01:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRU1830GX203238
License No: SLT8156J
Mileage: 89778
Engine No: L15B4533238

Document No: SVO19000270
Printed By: ANIKKALAI
Order Date: 2. January 2019
Order Time: 1:58:27 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SER GEE SERVICES OWNER INSURER: LIBERTY ACC DATE: 20/12/2018 SURVEYED BY: NAZ / LKK DATE: 02/01/2019 REF NO: TP INSURER: SOMPO TP VEH: SLM4258L						
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.90	25	32.92	2.30	35.22
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
74440-T7A-003	WEATHERSTRIPTAILGATE	1	98.70	25	74.02	5.18	79.20
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CLWINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
91513-T6A-003	CLIPTAILGATE SPOILER	9	2.50	25	16.87	1.18	18.05
	SUM PARTS:				1,313.50	91.93	1,405.43
BOSUN		1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT.						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT.						
BODAMKIT		1	80.00		80.00	5.60	85.60
	WINDSCREEN DAM KIT.						
BA02R	0669	1	120.00		120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOMISC1	0669	1	220.00		220.00	15.40	235.40
	REMOVE & INSTALL REAR VIEW CAMERA (N)						
BOMISC1	0669	1	200.00		200.00	14.00	214.00
	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)						
BMI03D	1757	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BML02I		1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: JHMRU1830GX203238
License No: SLT8156J
Mileage: 89778
Engine No: L15B4533238

Document No: SVO19000270
Printed By: ANIKKALAI
Order Date: 2 January 2019
Order Time: 1:58:27 PM
Service Advisor: ANIKKA LAI SWEE KAM

BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00	560.00	39.20	599.20
BKTG02R	0669 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	280.00	280.00	19.60	299.60
BKRP02M	0669 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,240.00	2,240.00	156.80	2,396.80
BP05R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,250.00	2,250.00	157.50	2,407.50
			SUM LABOUR:	6,780.00	474.60	7,254.60
			TOTAL SGD	8,093.50	566.53	8,660.03

Total Payable (SGD)

8,660.03

GST Amount is calculated from individual line(s)

PARTS \$1313.50

LABOUR \$6780.00

TOTAL \$8093.50

/ 4 DAYS

FINALIZED PART BY PART REPAIR \$8093.50 / 4 DAYS

make
7/1



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: 53366795W / SER GEE
Chassis No: JHMRU1830GX203238
License No: SLT8156J
Mileage: 89778
Engine No: L15B4533238

Document No: SVO19000270
Printed By: ANIKKALAI
Order Date: 2. January 2019
Order Time: 1:58:27 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	ADDITIONAL PART						
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
91513-T6A-003	CLIPTAILGATE SPOILER	9	2.50	25	16.87	1.18	18.05
	SUM PARTS:				28.27	1.98	30.25
	TOTAL SGD				28.27	1.98	30.25

Total Payable (SGD) 30.25

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2018		26 Dec 2018 11:12 Edit Adj Rpt	S\$8,093.50 Edit Estimates	S\$8,093.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HO YIN CHOY , ID: S14799683, Tel: +6596788704, Email: mike.ho95@yahoo.com.sg									
Main Claimant: TOH SER GEE , ID: S1322386F									
Vehicle Reg. No.: SLT8156J		Date of Loss: 20/12/2018 06:00 - :59 [13 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1805616		Policy/Cover Note No.: D18MTPV01005886 (Comprehensive)							
Vehicle Reg. No. (Insured): SLM4258L		Policy No. (Claimant):							
		Excess:							
Repairer: Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by IRENE JAMES HENRY - 6322 4618]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 07/01/2019]									
Driver/Custodian (Insured): HO YIN CHOY (57 / Male) , NRIC: S14799683, Tel: +6596788704 Email: mike.ho95@yahoo.com.sg									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT8156J (CMTD1805616)**
[SLM4258L]
TP
TOH SER GEE
Dec 20 2018 6:00AM
[HO YIN CHOY]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/01/19 13:40	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 12:06	General View	Load JPG	☒
2	03/01/19 12:06	General View	Load JPG	☒
3	03/01/19 12:06	General View	Load JPG	☒
4	03/01/19 12:06	General View	Load JPG	☒
5	03/01/19 12:06	General View	Load JPG	☒
6	03/01/19 12:06	General View	Load JPG	☒
7	03/01/19 12:06	General View	Load JPG	☒
8	03/01/19 12:06	General View	Load JPG	☒
9	03/01/19 12:06	General View	Load JPG	☒
10	03/01/19 12:06	General View	Load JPG	☒
11	03/01/19 12:06	General View	Load JPG	☒
12	03/01/19 12:06	General View	Load JPG	☒
13	03/01/19 12:06	General View	Load JPG	☒
14	03/01/19 12:06	General View	Load JPG	☒
15	03/01/19 12:06	General View	Load JPG	☒
16	03/01/19 12:06	General View	Load JPG	☒
17	03/01/19 12:06	General View	Load JPG	☒
18	03/01/19 12:06	General View	Load JPG	☒
19	03/01/19 12:06	General View	Load JPG	☒
20	07/03/19 18:16	Replacement Part Photo	Load JPG	☒
21	07/03/19 18:16	Replacement Part Photo	Load JPG	☒
22	07/03/19 18:16	Replacement Part Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/18 10:40	Repair Estimates	Load PDF	
2	26/12/18 10:41	E-filed GIA report	Load PDF	
3	26/12/18 11:13	Pre-Repair Survey	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/19 17:20	Supplementary	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18023098/NQD3E2

Date: 12/03/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01005886

Claimant Vehicle No: SLT8156J

Insured Vehicle No: SLM4258L

Date of Loss: 20/12/2018

Nature of Claim: TP

Claim No: CMTD1805616

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT8156J

Make & Model: HONDA HR-V, 1.5 LX CVT (A)

Engine No: L15B4533238

Reg. Date: 13/11/2017 (Man. Year: 2017)

Chassis No: JHMRU1830GX203238

Colour: Blue

Odometer: 89778 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,551.42	1,343.50	3,207.92	70.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,720.00	6,750.00	1,970.00	22.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,271.42	8,093.50	5,177.92	39.02
+ GST 7.00/7.00% (S\$)	929.00	566.55	362.45	39.02
Nett Amount (S\$)	14,200.42	8,660.05	5,540.37	39.02

INSPECTION

Date of Assignment: 26/12/2018

Date Inspected: 02/01/2019 Inspected At:

Kah Motor Co Sdn Bhd (HQ)
6A MANDAI ESTATE, SINGAPORE
729903
Singapore 729903

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Mar 2019)	
Parts:	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8156J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE COMP	Dented	641.77 FS	*629.17 FS
2	1		*LINING ASSYRR.PANEL	Deformed	32.92 FS	*32.92 FS
3	1		*COVER COMPTONNEAU	Serviceable	92.25 FS	*- FS
4	1		*BOARD ASSYTRUNK FLOOR	Serviceable	142.35 FS	*- FS
5	1		*LINING ASSYTAILGATE	Serviceable	102.00 FS	*- FS
6	1		*EMBLEM,RR.I-VTEC	Necessary	10.87 FS	*10.87 FS
7	1		*EMBLEMRR.	Necessary	9.97 FS	*9.97 FS
8	1		*FACE,RR.BUMPER	Deformed	347.77 FS	*347.77 FS
9	1		*FACER.RR.BUMPER CORNER	Serviceable	70.57 FS	*- FS
10	1		*FACEL.RR.BUMPER CORNER	Serviceable	70.57 FS	*- FS
11	1		*REFLECTOR ASSYR.RR	Serviceable	117.22 FS	*- FS
12	1		*REFLECTOR ASSYL.RR	Serviceable	117.22 FS	*- FS
13	1		*LIGHT ASSY,R.LID	Serviceable	202.42 FS	*- FS
14	1		*LIGHT ASSYL.LID	Serviceable	202.42 FS	*- FS
15	1		*LAMP UNITR	Serviceable	331.12 FS	*- FS
16	1		*LAMP UNITL	Serviceable	331.12 FS	*- FS
17	1		*PANEL COMPRR	Serviceable	279.82 FS	*- FS
18	1		*TAIL GATE COMP	Serviceable	641.77 FS	*- FS
19	1		*LOCK ASSYTAILGATE	Serviceable	59.17 FS	*- FS
20	1		*WEATHERSTRIPTAILGATE	Deformed	74.02 FS	*74.02 FS
21	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
22	1		*DAMPERSTD 5X5	Necessary	6.37 FS	*6.37 FS
23	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
24	1		*CAPIVVOT	Necessary	3.60 FS	*3.60 FS
25	1		*FASTENER BW/SHIELD (4PCS)	Necessary	15.90 FS	*15.90 FS
26	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
27	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
28	1		*ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
29	1		*BUZZER ASSYSMART	Serviceable	45.30 FS	*- FS
30	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
31	1		*FASTENER B (2PCS)	Necessary	7.95 FS	*7.95 FS
32	1		*GROMMET SCREW (2PCS)	Necessary	3.45 FS	*3.45 FS
33	1		*CLIPTAILGATE SPOILER (9PCS)	Necessary	16.87 FS	*16.87 FS
Total Parts (\$\$)					4,551.42	1,343.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT (TAILGATE)	New	100.00	80.00
2	BODY JOINT SEALANT (END PANEL)	New	100.00	80.00
3	WINDSCREEN DAM KIT	New	100.00	80.00
4	REMOVE & RENEW REVERSE SENSOR - 4 PCS	New	140.00	120.00
5	REMOVE & INSTALL REAR VIEW CAMERA	New	220.00	220.00
6	RESET & CALIBRATE SMART ENTRY SYSTEM	New	200.00	200.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	600.00	560.00
8	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	100.00	80.00
9	REMOVE & INSTALL RR WINDSCREEN	New	560.00	560.00
10	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	600.00	280.00
11	CUT OFF & RENEW RR PANEL. STRAIGHTEN	New	3,000.00	2,240.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	3,000.00	2,250.00
Gross Labour Cost (S\$)			8,720.00	6,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >