MOMMON		ENT (Office)	C362 Special Instru		•
From (Person		RMO	Date/Tir	ne: 26/12/180	12.4P
Estimated Co	st:/	Bill to:	•		- 1
OD (TP) W	STTP RES / OD RES / EVA / INV / MV 7	CS			0.
To Inspect V	0111 01000		_ Insured:	SKP 2555M	(Wazo
at Workshop			Tel: 6=	144 1995	
of	Blk 3006 ubi Rd	1#01-33			
Policy No:)18M7pv01012972	Claim No:	CM7D180	5642	
Sum Insured:		Excess:			
Make of Veh: Client's Record			D.O.A.	21/12/2018	
CA / REV	REP. / REV 24 HRS		02/0	enlige after Hor	n
Date/Time:	2.55pm 20/12/18 Person Contacted:	Mr. Na	Vehicle II		
Date/Time	Action/Instruction () Estimate	,		<u> </u>	
	8KK34655-NA/III180229	10		DA: 21/12/201	8
	8102555M- NA/11/8023	931/13	A	21 = 1112 AU	•
	Dismantle: 3/1/2019				

PRS	
Enrague.	emo.
Merimen	ASSIGNMENT
rom: Date: 0	03.01.2019 Veh No. SKIC346SJ. Yr Regn: 2013, J.
stimated Cost	Type M.Car M.Cycle / Bus. / Van / Lorry / Taxi / Prime Mover /
OD THE WS / TP RES / OD RES / EVA / INV / MV	V Truck / Trailer or
o Inspect Vehicle No: SKK 3465	11 1 2 (10)
it Workshop m/s UE Mila	Colour Brue A/C: Insured / Std / NI /
3006 Ubi Rd	1 4 01-334 Sp.Reading 111460 . T/Radio: Insured / Std / NI /
nsured	Eng/No:
Policy No.	CTNO: WP 72040312A831917
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
οΛ - J.	Tyre Size: F: 275/45 R17 .
(Policy Condition)	R: 225/45R17.
Remark: The veh had commenced its	N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal, or Market Value:	<u>Front</u> <u>Rear</u>
DAC Accident Rport: Consistent? : Ye	es or No R/Bal. of mm R/Bal.
GIA / PR Seen: Consistent? : Ye	es or No L/Bal. 06 mm L/Bal. 06 •
Est. Repairs: S days Res.: Ye	es or No D.O.A. D.O.I. 02 01 19.
Lum Sum: % 3 Val.: Ye	es or No Survey held at UE.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA I KEY I KEP. I 241ING	Vehicle: IN / OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to col
Estimated repa	air range \$5,000 -\$6,000
MV: 95E PV: 49.6K Nett: 25.4K	4/1/2019
8V 149.6K	
PV 149.6K Nett; 25.4K Date/Time, File Pass to? : Preli. Report : Final Report	Resurvey No. of Trip: Survey Fee: 100
PV 149.6K Nett; 25.4K Date/Time, File Pass to? : Preli. Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 100
PV 149.6K Nett; 25.4K Date/Time, File Pass to? : Preli. Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 100 Transportation: 60 Add Fee: Site Insp (\$)s+Rs,si
PV 1 49.6K Nett : 35.4K Date/Time, File Pass to? : Preli. Report Date/Time, File Return to? : Final Report	Resurvey No. of Trip: Survey Fee: 100 Transportation: 60 Add Fee: : Site Insp (\$)s+Rssi Interview (\$) Photos
PV 149.6K Nett; 25.4K Date/Time, File Pass to? : Preli. Report : Final Report	Resurvey No. of Trip: Survey Fee: 100 Transportation: 60 Add Fee: Site Insp (\$)s+Rs,si

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	22 Dec 2018		26 Dec 2018 12:41 Assign					New As	ssignment Case
1	1ain	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SUI	BFOLDER DE	TAILS	CONTRACTOR OF THE PARTY OF THE	and the state of t		Creat	ed by insurer1	STATE OF STREET	
Insured:	HOW HEE	PENG, ID: S743	86655D			Levear	ca by mourer]		
Main Claimant:	SEOW LE	NA, ID: S68136	12A						
Vehicle Reg. No.:	SKK346	5)			Date of Loss:	21/12/2	2018 11:00 - :59		
Claim Type:	TP / CMT	D1805642			Policy/Cover Note No.:	D18MTF	V01012972 (Com	prehensive)	
Vehicle Reg. No. (Insured):	SKP25551	4			Policy No. (Claimant):				
					Excess:				
Repairer:	U Е МОТО	R (HQ) 3006, Ubi	Road 1, #01-33	34, 408700	Ubi - Tel:				
Handling Insurer:	Sompo In	surance Singapo	re Pte. Ltd. (H	Q) - Tel: 64	61 6555 [Han	dled by C	HAN SHU HUI A	GNES - 632	9 5327]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 07/	01/20191		
Driver/Custo dian (Insured):		SIANG GRACE(ZHA							
ASSOCIAT	ED MAIL RE	CEIVED						View All	Compose Case Ma
There are no	mail for this	case.							
ALL ASSO	CIATED TAS	KS⊟				View A	II Search Tasks	Create Ne	ew Task Complete
Due Date	Priority	Type Task	Group Subj	ect Han	dler Assign		Completed O		ited On Done
							marriage was a	WICO	The Will Dulle

A J TAHIR LAW PRACTICE

ADVOCATES & SOLICITORS COMMISSIONER FOR OATHS NOTARY PUBLIC (UEN No. 53289380L)

CM1D1 805642/AGC

Your Ref: to be advised

Our Ref : J 3707.18.Gn.kk

41 14 10,10.70

: 21 December 2018

Motor Claims

Via fax 6221 3147 only M/s Sompo Insurance Singapore Pte. Ltd.

Singapore.

Dear Sir/Madam

ACCIDENT ON 21.12.2018 INVOLVING SKK3465J AND SKP2555M

We are instructed by Ms Seow Lena to notify you of a road traffic accident on 21.12.2018 along Lorong 1 Toa Payoh slip road into PIE (Changi) involving our client's vehicle registration number SKK3465J and vehicle registration number SKP2555M driven by your insured at the material time. A copy of the Singapore Accident Statement filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

You may proceed to carry out the pre-repair survey of our client's motorvehicle at:-

U E Motor Blk. 3006 Ubi Road 1 #01-334 Singapore 408700. Tel: 6744 1995

Kindly contact the repairer directly.

Yours faithfully

Sompo	 Cia	ernie	100	
	 	45		
	240	20 1	313	
	 	+-		

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars		Air
Owner ID Type:	Singapore NRIC	
Owner ID:	3612A	
Vehicle Details		
Vehicle No.:	SKK3465J	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	02 Jan 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	C 180 BLUEEFFICIENCY	
Primary Colour:	Blue	
Manufacturing Year:	2013	
Engine No.:	27491030038182	
Chassis No.:	WDD2040312A831917	
Maximum Power Output:	115.0 kW (154 bhp)	
Open Market Value:	\$31,746.00	
Original Registration Date:	04 Jun 2013	
First Registration Date:	04 Jun 2013	
Transfer Count:	1	
Actual ARF Paid:	\$31,445.00	
Intended PARF Rebate Details	A SAME TO MAKE THE PROPERTY OF	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	03 Jun 2023	
PARF Rebate Amount:	\$22,011.00	
Intended COE Repate Details	学生的一种,但是一种,但是一种的一种,是一种的一种,是一种的一种。	70
COE Expiry Date:	03 Jun 2023	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$62,497.00	
COE Rebate Amount:	\$27,620.00	
Total Rebate Amount:	\$49,631.00	

The information contained herein is correct as at 02 Jan 2019




Become a Lalamove Driver

Be Your Own Boss. Calling all Bike / Car / Van / Lorry drivers.









\$76,000

Mercedes-Benz C-Class C180

Coupe

Posted: 25-Der-2018 Tags: 2013 Mercedes-Benz C180, 2013 mercedes-benz C180, mercedes-b

\$14,660 /vr

Excellent Condition, 1 Lady Owner, Seriously Low Mileage, 2nd Car For Sale, Maintained By C&C. 100% Accident-Free, Reliable And Fuel Efficient Coupe For Daily Commute. Reluctant Sale Due To Relocation...

27-Mar-2013

1,595 cc

44,000 km

Sports

Available

DIRECT OWNER



Compare 🙆

Posted: 31-Dec-2018 Tags: 2013 Mercedes-Benz C180, 2013 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz C180, c180, Used Mercedes-Benz C180, mercedes-benz c180,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	21/12/2018 15:02
Date Of Accident	21/12/2018 11:40
Exact Location Of Accident	LOR 1 TOA PAYOH SLIP RD INTO PIE(CHANGI)
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE

	DETAILS OF OW	VN VEHICLE		
Vehicle Registration Number	SKK3465J			
Insured/Policyholder			A 4	

 Name Of Registered Owner
 SEOW LENA

 NRIC No
 \$6813612A

 Email Address
 LSEOW95@HOTI

 Email Address
 LSEOW95@HOTMAIL.COM

 Mobile Phone No
 (LOCAL) +65-97526922

 Alternative Phone No
 OTHERS-97526922

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO
Policy Number M497227

Cover Note Number

Driver

 Name of Driver
 SEOW LENA

 NRIC No
 S6813612A

 Date Of Birth
 14/04/1968

 Occupation
 INDOOR

 Date Of Driving Pass
 30/03/1987

Driving Experience 31 YEARS AND 8 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-97526922

Fax Number

Contact Number OTHERS-97526922

EMail Address LSEOW95@HOTMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms; the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ollorholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

A-SKR34655 Sero Fon Paylong

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls 12pv to the stadement.

I/We declare the foregoing particulars are true in every respect.

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

Address

700 LOR 1 TOA PAYOH #12-02

Postcode

319773

NO

Was driver an employee of the Insured's Company If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own Vehicle.

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NO 2

Passenger 1

NAME:

: ISAAC HAY

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

MY VEH WAS STATIONARY AT THE GIVEWAY LINE AT LOR 1 TOA PAYOH SLIP RD INTO PIE(CHANGI) TO GIVE WAY FOR ONCOMING VEH.SUDDENLY VEH(B)BEARING REG NO SKP2555M CAME FROM BEHIND AND HIT ONTO MY REAR

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FRONT ONLY

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKP2555M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TEO HAW SIANG, GRACE

NRIC/Passport Number

S8129500Z

Contact Number

97656241

Address

Postcode

Page 2 of 18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case N	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ac	j Submitted	Ins Auth'ed	Status	
Main	22 Dec 2018		26 Dec 2018 12:41 Edit Adj Rpt	S\$0.00 Edit Est	- (\$0.00 View Rpt		Pending f Report Cancel Ca	or Survey
м	lain	R	eference	CI	aim Details		Documents	5	Show All
CLAIM SUB		TAILS PENG, ID: S74	36655D		-21	[Created	by insurer]		
Main Claimant:	SEOW LE	NA, ID: S68136	12A						
Vehicle Reg. No.:	SKK3465J Date of Loss: 21/12/2018 11:00 - :59 [66 Months and 17 Days From					om LTA Reg Dat	n LTA Reg Date (Man Yr)]		
Claim Type:	: TP / CMTD1805642 Policy/Cover Note No.: D18MTPV01012972 (Comprehensive)								
Vehicle Reg. No. (Insured):	SKP2555	м			Policy No. (Claimant):				
					Excess:				
Repairer: Handling Insurer:			Road 1, #01-334, ore Pte. Ltd. (HQ)			ndled by CHAI	N SHU HUI AGN	ES - 6329 5327	']
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled by	ADRIAN LIN	G] [Final Rp	t due 07/01,	/2019]
Driver/Custo dian (Insured):		SIANG GRACE(ZH	ANG HAOCHANG,GR	RACE) (),	NRIC: S8129	500Z, Tel: +	-6597656241		
ASSOCIATI	ED MAIL RE	CEIVED					Vie	w All Comp	ose Case Mai
There are no	mail for this	case.						_	
ALL ASSO	CIATED TAS	sks⊟				View All	Search Tasks C	Create New Task	Complet
Due Date No results.	Priority	Type Task	Group Subjec	t Handl	er Assi	gned By	Completed On	Created	On Done

Claim Documents

Pho	tos/Images		3 per page ✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	-
1	03/01/19 14:56	General View	1 Load JPG	✓
2	03/01/19 14:56	General View	Load JPG	~
3	03/01/19 14:56	General View	1 Load JPG	✓
4	03/01/19 14:56	General View	Load JPG	✓
5	03/01/19 14:56	General View	1 Load JPG	✓
6	03/01/19 14:56	General View	1 Load JPG	✓
7	03/01/19 14:56	General View	1 Load JPG	✓
8	03/01/19 14:56	General View	1 Load JPG	V
9	03/01/19 14:56	General View	1 Load JPG	✓
10	03/01/19 14:56	General View	1 Load JPG	V
11	03/01/19 14:56	General View	1 Load JPG	✓
12	03/01/19 14:56	General View	1 Load JPG	✓
13	03/01/19 14:56	General View	1 Load JPG	V
14	03/01/19 14:56	General View	1 Load JPG	✓
15	03/01/19 14:56	General View	Load JPG	V
16	03/01/19 14:56	General View	1 Load JPG	~
17	03/01/19 14:56	General View	1 Load JPG	V
18	03/01/19 14:56	General View	1 Load JPG	V
19	03/01/19 14:56	General View	Load JPG	~
20	03/01/19 14:56	General View	1 Load JPG	4
21	03/01/19 14:56	General View	1 Load JPG	✓
22	03/01/19 14:56	General View	1 Load JPG	V
23	03/01/19 14:56	General View	1 Load JPG	✓
24	03/01/19 14:56	General View	1 Load JPG	~
25	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	V
26	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	✓
27	03/01/19 14:57	Photographs of Damaged Parts	Load JPG	✓
28	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	V
29	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	✓
30	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	V
31	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	✓
32	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	✓
33	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	~
34	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	✓
35	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	V
36	03/01/19 14:57	Photographs of Damaged Parts	■ Load JPG	~
37	03/01/19 14:57	Photographs of Damaged Parts	1 Load JPG	V

Pho	tos/Images		3 per p	oage 🔻	Y
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
39	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	Y
40	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
41	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
42	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	\checkmark
43	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
44	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	V
45	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
46	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	V
47	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
48	03/01/19 14:57	Photographs of Damaged Parts	6	Load JPG	✓
49	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
50	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
51	03/01/19 14:57	Photographs of Damaged Parts	0	Load JPG	✓
Doc	cumentation		1 per	page 🔻	V
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	24/12/18 10:50	Pre-Repair Survey - FAX FR A J TAHIR LAW - SKK3465J	0	Load PDF	
2	26/12/18 12:40	Pre-Repair Survey	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO18023108/ACD3E2

Date:

08/01/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No:

D18MTPV01012972

Claimant Vehicle

SKK3465J

Insured Vehicle No: SKP2555M

No:

21/12/2018 Date of Loss:

Nature of Claim:

TP

Claim No: CMTD1805642

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKK3465J

Make & Model:

MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6

Engine No:

27491030038182

Reg. Date:

04/06/2013 (Man. Year: 2013)

Chassis No:

WDD2040312A831917

Colour:

Blue

Odometer:

111460 km

Engine Capacity:

1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

225/45 R17

Rear Tyre Size:

No

225/45 R17

Pre-accident Condition:

Front Tyre Size: Front Left Side: Front Right Side:

Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

26/12/2018

Date Inspected:

02/01/2019

Inspected At:

U E MOTOR (HQ)

3006, Ubi Road 1, #01-334

Singapore 408700

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen p... 8/1/2019

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 08 Jan 2019)

Parts:

143

MERCEDES-BENZ C180 BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKK3465J)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >