

ASS. REC. BY:

REF: CS/ALG18023113/ A-1d3ⁿ² Special Instruction:

Surveyor

Marmen

Adren

ASSIGNMENT (Office)

From (Person):

ehin lee ying

of

ALG

Date/Time:

26/12/18 @ 3:36pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 3717G

Insured:

SJF 4385P

at Workshop m/s

Ace Automobile

Tel:

6844 1154

of

Bkaki Bukit Rd 1 # 03-29

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3:51pm @ 26/12/18

Person Contacted:

Anna

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJW 3717G-X
	SJF 4385P-X
	lump sum \$7500 (Red: 10/182-30:52%)

REF: AIG

ASSIGNMENT

From:

Date:

27/12/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJW 3717G

at Workshop n/s:

Ace Autolution

of

13 Kaki Bk Rd 4 # 03-29

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{wp}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJW 3717G

Yr Bogn:

2010 March

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

C.G. 1598

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

242103

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053ZEE106168092

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

27/12/18

Survey held at

Ace Autolution

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AIG.

MV: 19.5K

PV: 11.7K

Nett: 7.8K.

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

1) 10/1 Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 12

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS 31

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

7500/-

250
20

270

- Pre repair inspection request - SJW3717G VS SLF4385P (OI) DOA 22/12/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit
Sent: 25/12/2018 3:36:06 PM
Attachments: 20181226115014667.pdf

Hi,

Please refer to the enclosed request from **Chia S Arul LLC**.

Claim no : 7381696319SG003
Case Owner : BERNARD JI QIAN LER

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOI, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Jerone [mailto:jerone@chiaarul.com]
Sent: Wednesday, December 26, 2018 3:34 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit; 'Weng Kit'; 'Maia'
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF4385P AND SJW3717G ON 22/12/2018

O/Ref: SJW 3717G (Jr)
Y/Ref: SLF 4385P

Dear Sirs,

We refer to the above matter.

Kindly be informed that we have our client's instructions to appoint **Mr. Marcus Chua of LKK Auto Consultants Pte Ltd** as the Single Joint Expert for the matter herein.

As such, do follow up with our client's workshops and carry out the PRS.

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

Mr. Jerone Lee (Paralegal)
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]
Sent: Wednesday, 26 December, 2018 2:34 PM
To: jerone@chiaarul.com
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF4385P AND SJW3717G ON 22/12/2018

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์แนบ

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-01-02 14:34 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina Azlan@aig.com

To: jerone@chiaanul.com

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, NoorMariasa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Yinnul.Hor@aig.com, yokeshi.chan@aig.com, Bal

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF4385P AND SJW3717G ON 22/12/2018

Date: Wed, 26 Dec 2018 08:33:49 +0000

Without Prejudice

Your Reference : SJW 3717G (Jr)
Our Reference : SLF4385P

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teek (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: AIG SGP, Claims-Survey

Sent: Wednesday, December 26, 2018 12:00 PM

To: Azlan, Syazairdina

Subject: FW: PRS Notice for SJW 3717G

From: Jerone [mailto:jerone@chiaanul.com]

Sent: Wednesday, December 26, 2018 11:52 AM

To: AIG SGP, Claims-Survey

Cc: 'Weng Kit'; 'Maia'

Subject: PRS Notice for SJW 3717G

O/Ref: SJW 3717G (Jr)

Y/Ref: TBA

Dear Sirs,

We refer to the above matter.

Kindly find enclosed herewith the PRS Notice for your attention.

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

Mr. Jerone Lee (Paralegal)

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

**CHEAPEST CAR
INSURANCE RENEWAL**

Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!
SEARCH

Vios

Price Range

Depreciation

2010

Vehicle Type



Search

View All

Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Vios 1.5A E



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Toyota Vios 1.5A G



Add to Shortlist

Toyota Vios 1.5A E



Add to Shortlist



NO IMAGE AV

Use search bar above to
to compare

CAR DETAILS

Price	\$16,888	\$15,800	\$20,800	-
Instalment	\$1,343	\$1,133	\$946	-
Registration Date	13-Oct-2009	02-Nov-2009	28-Apr-2010	-
Manufactured	2009	2009	2010	-
Mileage	-	156,000 km	83,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,497 cc	1,497 cc	1,497 cc	-
Road Tax	\$684 /yr	\$684 /yr	\$684 /yr	-
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	-
Curb Weight	1,095 kg	1,110 kg	1,095 kg	-
Features	1.5 Litre VVT-I 16 Valves Inline DOHC Engine, Auto Transmission, ABS, EBD, Dual SRS Airbags, Fuel Efficiency Of 15Km Per Litre.	Sport Rims, Original Seat, Factory Fitted Audio Player, Retractable Side Mirrors With Indicators, Reverse Sensors, Solar Film.	Reliable And Fuel Efficient 1.5L VVT-I 4 Cylinders Inline DOHC 16 Valves Engine, Auto Transmission, Dual SRS Airbags, ABS, Retractable Side Mirrors.	-
Accessories	Reverse Sensors, CD Player, Auto Retractable Side Mirror And More Call Now!	Responsive And Fuel Efficient 1.5L VVTI Engine, Consumption Up To 16KM/L, Airbags, Original Bodykits, Rear Knockdown Seats ABS Etc.	Leather Interior, Original Sound System, Retractable Side Mirrors With Indicators, Reverse Sensors, Remote.	-
Description	Most Value Toyota Vios In The Market! Very Well Maintained By Owner 100% Accident Free, 8 Week Engine And Gearbox Warranty! Still In Original Paintwork Since Day One! Available For Viewing! Call For More Info!	Great Car To Starts With. Sporty Look And Very Well Maintained By Previous Owner. Drive First And Decide Later Whether To Renew COE For This Beauty. Call For An Non Obligation Chat Now.	1 Owner Throughout, Excellent Condition Inside Out With Original Paintwork, Great Fuel Efficiency And Responsiveness, Easy Maintenance, Call Now To Find Out More. New Facelift. Bank Loan And In-house Loan Available.	-
COE	\$16,201	\$18,020	\$30,000	-
OMV	\$12,717	\$14,155	\$12,331	-
ARF	\$12,717	\$14,155	\$12,331	-
Depreciation	\$13,340 /yr	\$10,340 /yr	\$10,990 /yr	-
No. of Owners	3	2	1	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car	PARF Car	PARF Car, Low Mileage Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

Seller	Net Link Partners Pte Ltd	Wise Auto Pte Ltd	Motor Universe Credit Pte Ltd	-
Address		1 Tampines North Drive 1 #06-03	210 Turf Club Road Lot A32	-

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJW 3717G (Jr)

Your Ref : To be advised

26 December 2018

AIG ASIA PACIFIC INSURANCE PTE LTD

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : OHK LIMO
ACCIDENT INVOLVING SJW 3717G & SLF 4385P ALONG CLAYMORE HILL
TOWARDS DRAYCOTT DRIVE ON 22 DECEMBER 2018
PRE-REPAIR SURVEY NOTICE

1. We act for OHK Limo, the owner of motor vehicle no. SJW 3717G which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SLF 4385P for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

M/s Chia S Arul LLC

Page 2

Our Ref : SJW 3717G (Jr)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)

WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)

WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY

WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

Enquire Vehicle & Owner Information (Vehicle No. SLF4385P As At 22 Dec 2018 / 15:15:00)**Law Firm Search Details****Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** SJW3717G**Current Owner Details****Owner ID Type:** Singapore NRIC**Owner ID:** S2207016I**Owner Name:** VIKAS MADHAV GORE**Registered Address Type:** Private Residential (Condo Apt or House) / Shopping / Office Complexes**Registered Block/House No.:** 5**Registered Street Name:** PANDAN VALLEY**Registered Unit No.:** # 03 - 702**Registered Building Name:** -**Registered Postal Code:** 597629**Current Vehicle Details****Vehicle No.:** SLF4385P**Make Description/Model:** JAGUAR / XJ 3.0S/C TSS LWB SR**Insurance Company Name:** AIG ASIA PACIFIC INSURANCE PTE. LTD.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5438X
Vehicle Details	
Vehicle No.:	SJW3717G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	3ZZ4976870
Chassis No.:	MR053ZEE106168092
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	19 Mar 2010
First Registration Date:	19 Mar 2010
Transfer Count:	1
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Mar 2020
PARF Rebate Amount:	\$9,193.00
Intended COE Rebate Details	
COE Expiry Date:	18 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$2,533.00
Total Rebate Amount:	\$11,726.00

The information contained herein is correct as at 28 Dec 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 5438X

Vehicle Details

Vehicle No.: SJW3717G

Vehicle to be Exported: Yes

Intended Deregistration Date: 26 Dec 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Blue

Manufacturing Year: 2010

Engine No.: 3ZZ4976870

Chassis No.: MR053ZEE106168092

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,716.00

Original Registration Date: 19 Mar 2010

First Registration Date: 19 Mar 2010

Transfer Count: 1

Actual ARF Paid: \$16,716.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Mar 2020

PARF Rebate Amount: \$9,193.00

Intended COE Rebate Details

COE Expiry Date: 18 Mar 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$20,802.00

COE Rebate Amount: \$2,545.00

Total Rebate Amount: \$11,738.00

The information contained herein is correct as at 26 Dec 2018

OK



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

MRO532EE106168092
TPA16 Denise

Page No. 1

Vehicle No. SJW3717G TOYOTA ALTIS

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
2	HEADLAMP LH & RH @ \$612.70 <i>crushed</i>		1225.40	/
1	FRONT BONNET <i>Reps</i>		862.90	X.
2	FRONT BONNET HINGE LH & RH @56.60 <i>new</i>		113.20	X.
1	FRONT BONNET LOCK <i>band</i>		137.10	/
1	FRONT BONNET LOCK CABLE <i>new</i>		52.90	X.
1	FRONT BUMPER <i>distorted</i>		486.50	/
1	FRONT BUMPER REINFORCEMENT <i>set</i>		362.20	/
1	FRONT BUMPER SIDE RETAINER RH <i>and.</i>		110.00	/
1	FRONT GRILLE <i>crushed</i>		220.00	/
1	FRONT CENTRE LOWER GRILLE <i>behind</i>		105.00	/
1	FRONT LOGO <i>new</i>		80.00	/
2	FRONT FOGLAMP LH & RH @300.00 <i>Replaced</i>		600.00	300.
2	FRONT FOGLAMP COVER LH & RH @130.00 <i>new</i>		260.00	X.
2	FRONT FENDER LH & RH @622.10 <i>RH Buckled</i>		1244.20	622.10.
1	FRONT FENDER INNER SHIELD RH <i>torn</i>		173.40	/
1	FRONT FENDER "WT-I" EMBLEM <i>new</i>		85.00	40.
1	SUPPORT PANEL <i>Buckled.</i>		780.00	/
1	FRONT AIRCON CONDENSER ASSY <i>Bent</i>		580.00	/
1	FRONT RADIATOR <i>crushed</i>		674.00	/
1	FRONT RADIATOR HOSE <i>new</i>		630.00	X.
1	RADIATOR SPARE TANK <i>behind</i>	8278.50	143.10	/
1	FRONT COOLING FAN MOTOR <i>crushed</i>	6209.17	543.70	223.40.
1	FRONT WIPER WASHER TANK <i>new</i>		121.10	X.
1	FRONT WIPER COVER <i>crushed</i>		180.00	/
1	FRONT CROSS MEMBER <i>Not new</i>		2050.00	X.
1	FRONT ENGINE LOWER SHIELD COVER <i>torn</i>		90.70	/
1	DASHBOARD <i>torn</i>		752.00	/
1	ABS PUMP <i>new</i>		1500.00	X.
1	ABS SENSOR		580.00	X.
1	FRONT DOOR <i>new</i>		0.00	X.
2	Sent Belts. <i>Activated.</i> $497 \times 2 = 994$	REPAIR 15736.40	14742.40	
		less 25%	3685.60	25%
			11056.80	
SPECIAL NETT ITEMS				
1	CAR PLATE <i>new</i>		50.00	X.
1	CAR PLATE COVER		30.00	X.
1	STEERING AIRBAG <i>Activated</i>	1470	710.00	/
1	DASHBOARD AIRBAG		680.00	/
1 SET	FRONT BUMPER CLIPS <i>new</i>		35.00	/
1 SET	FRONT GRILLE CLIPS		35.00	15
1 SET	FRONT FENDER SHIELD CLIPS <i>new</i>		60.00	30.
Total Parts			12656.80	



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #08-29
 Singapore 417807
 Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SJW3717G TOYOTA ALTIS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	800
3	To remove and refix wiring at damaged areas	200.00	30
4	To perform anti rust treatment on affected areas	180.00	50
5	To remove & replace dashboard	150.00	✓
6	To carry out chassis alignment	350.00	x.
Labour Total :		4280.00	
TOTAL (PARTS & LABOUR):		16936.80	

17662.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim

L/S 27/12/18.

L/S: \$7.51K.

12 Days

Total: 9709.17

L/S: 7.51K (Nett)
 Value

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18023113/ATD3N2

Date: 11/01/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480541
Claimant Vehicle No :	SJW3717G	Insured Vehicle No :	SLF4385P
Date of Loss:	22/12/2018	Nature of Claim:	TP
		Claim No:	7381696319SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW3717G	Engine No:	3ZZ4976870
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106168092
Reg. Date:	19/03/2010 (Man. Year: 2010)	Odometer:	242103 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,402.30	7,679.17	5,723.13	42.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	2,030.00	2,250.00	52.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,682.30	9,709.17	7,973.13	45.09
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	17,682.30	7,500.00	10,182.30	57.58

INSPECTION

Date of Assignment:	26/12/2018	
Date Inspected:	27/12/2018	Inspected At:
		Ace Autolution (HQ)
		13 KAKI BUKIT ROAD 4, #03-29
		Bartley Biz Centre
		Singapore 417807
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEADLAMP LH & RH	Cracked	1,225.40 FL	*1,225.40 FL
2	1		*FRONT BONNET	Repair	862.90 FL	*- FL
3	2		*FRONT BONNET HINGE LH & RH	Not Necessary	113.20 FL	*- FL
4	1		*FRONT BONNET LOCK	Damaged	137.10 FL	*137.10 FL
5	1		*FRONT BONNET LOCK CABLE	Not Necessary	52.90 FL	*- FL
6	1		*FRONT BUMPER	Distorted	486.50 FL	*486.50 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	362.20 FL	*362.20 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Damaged	110.00 FL	*110.00 FL
9	1		*FRONT GRILLE	Cracked	220.00 FL	*220.00 FL
10	1		*FRONT CENTRE LOWER GRILLE	Deformed	105.00 FL	*105.00 FL
11	1		*FRONT LOGO	Necessary	80.00 FL	*80.00 FL
12	1		*FRONT FOGLAMP LH & RH	O/s Cracked	600.00 FL	*300.00 FL
13	2		*FRONT FOGLAMP COVER LH & RH	Not Necessary	260.00 FL	*- FL
14	1		*FRONT FENDER LH & RH	O/s Buckled	1,244.20 FL	*622.10 FL
15	1		*FRONT FENDER INNER SHIELD RH	Torn	173.40 FL	*173.40 FL
16	1		*FRONT FENDER VVT-I EMBLEM	Necessary	85.00 FL	*40.00 FL
17	1		*SUPPORT PANEL	Buckled	780.00 FL	*780.00 FL
18	1		*FRONT AIRCON CONDENSER ASSY	Bent	580.00 FL	*580.00 FL
19	1		*FRONT RADIATOR	Cracked	674.00 FL	*674.00 FL
20	1		*FRONT RADIATOR HOSE	Not Necessary	630.00 FL	*- FL
21	1		*RADIATOR SPARE TANK	Deformed	143.10 FL	*143.10 FL
22	1		*FRONT COOLING FAN	Cracked	543.70 FL	*223.40 FL
23	1		*FRONT WIPER WASHER TANK	Not Necessary	121.10 FL	*- FL
24	1		*FRONT WIPER COVER	Cracked	180.00 FL	*180.00 FL
25	1		*FRONT CROSS MEMBER	Not Necessary	2,050.00 FL	*- FL
26	1		*FRONT ENGINE LOWER SHIELD COVER	Torn	90.70 FL	*90.70 FL
27	1		*DASHBOARD	Torn	752.00 FL	*752.00 FL
28	1		*ABS PUMP	Not Necessary	1,500.00 FL	*- FL
29	1		*ABS SENSOR	Not Necessary	580.00 FL	*- FL
30	1		*FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
31	2		*SEAT BELTS	Activated	994.00 FL	*994.00 FL
32	1		*CAR PLATE	Not Necessary	50.00 FS	*- FS
33	1		*CAR PLATE COVER	Not Necessary	30.00 FS	*- FS
34	1		*STEERING AIRBAG	Activated	710.00 FS	*710.00 FS
35	1		*DASHBOARD AIRBAG	Activated	680.00 FS	*680.00 FS
36	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
37	1		*SET FRONT GRILLE CLIPS	Necessary	35.00 FS	*15.00 FS
38	1		*SET FRONT FENDER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,336.40	9,748.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,934.10	2,069.73
Total Parts (\$\$)	13,402.30	7,679.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	1,000.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	800.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	200.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	180.00	50.00
5	TO REMOVE & REPLACE DASHBOARD	New	150.00	150.00
6	TO CARRY OUT CHASSIS ALIGNMENT	New	350.00	-
Gross Labour Cost (S\$)			4,280.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >