

INSURANCE

INS. CASE OWNER:

Stacy Ng

CC 4, ASM 2023129, Uea3 9

LKK: 89955  
IDAC: 89955

Assignor:

WAPMS

DOI:

ASSIGNMENT

26/12/18

Date / Time:

26/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

X08621 A

Claim No. :

88M01707

Name of Insured :

TBC Transportation & Trading P/L

Policy No. :

Insured Tel No. :

HP:

D.O.A: 16/11/18

Make / Model :

Excess Sec II :SS

Nature of Accident :

Place of Accident :

Is driver the owner? ( YES / NO )

( YES / NO )

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO )

Insured Liability : % Final ? Yes / No

GISE 718U



INSRS:

WSP:

Tel:

Liability:

RMKS:

WAPMS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

10/1  
APW

GISE 718U - X  
X08621 A - CS/ANALIST/567/MI/EA3:008/11/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

20-2-19

After call ltr to OI:

to request clearer DL & get LOA.

20.2.19 2:30

Called own company, considered ALL-OWN. DID REVEALED INFO TO TP. INSURED TP CLAIM WOULD TO BEILE AND FURGE FROM NED PSAL.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: (25 FORM)

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: 100%

Repair Cost:

9% SS 6,150

( 5 days) Reduction:

5% %

Email  Call

FINAL SETTLEMENT

Date/Time: 03.05.19

Confirm with: SUGAM

Email  Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : NIL

If NO or B 28, Ass. Lia :

Repair Cost:

SS 6,150.00

DID REVEALED INFO TO

Loss of Rental (LOR):

SS -

( days)

Loss of Use (LOU):

SS 90.00

(\$ 90 x 1 days)

Loss of Income (LOI):

SS -

(3 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/ Independent )

2) Report Format: TP

Legal Cost

SS -

3) Survey fee: 9500

Total:

SS 7,302.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 03-05-19

Confirm with: SUGAM

Email  Call

Payee 1:

SS 7,302.00

Name 1:

WAS REUTHEE A/D, ENGINEERING, WOODBROOK.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

16/5/19

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 93E7128U

at Workshop n/s: 1. u/s.

of \_\_\_\_\_

insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 486

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen:   Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 50 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

4A 3272  
Vehicle: IN / OUT

Veh No: 93E7128U Yr Ragn: 3, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer: CAJ

Make: mit center cc: 2998

Colour: white/Blud A/C: Insured / Std / NI / NA

Sp. Reading: 80845 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

Chassis: FEA01BA 2005-1

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 195-02 15

BS / DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal: 6 mm R/Bal: 6/6 mm

L/Bal: 6 mm L/Bal: 6/6 mm

D.O.A: 16/11/18 D.O.I: 26/12/18

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop, or

frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7.15. 3.45.

40 + 6,190 (REQ. + 8,985.30 56%)

Date/Time, File Pass to?  : Prelim. Report

: Final Report

Date/Time, File Return to?

0)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
\$ + RS: \$	_____
Photos	_____
Others	_____
TOTAL	_____

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 478873

ROB No: 53207931, Tel: 6741-1230 / 731, Fax: 6744-5745, Email: liusbrogymail.com

Invoice/Ref No: GBE7128U18116

**Estimate****Customer**

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower Singapore 068881

Date: 24-12-18

Vehicle No: GBE7128U

Model/Make: Mitsubishi

Center FE: BR: SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 882.70	
2	Bumper Bracket 02 pcs (@ S\$108.40)	\$ 216.80	X
3	Bumper Side 02 pcs (@ S\$441.70)	\$ 883.40	
4	Head Lamp 02 pcs (@ S\$672.70)	\$ 1,345.40	
5	Signal Lamp 02 pcs (@ S\$313.60)	\$ 627.20	17
6	Grille	\$ 426.80	
7	Grille Clips 08 pcs (@ S\$9.50)	\$ 76.00	SN X
8	"Mitsubishi" Logo Motif 115	\$ 186.80	
9	"Center" Emblem	\$ 75.40	
10	Panel	\$ 864.30	
11	Corner Panel 02 pcs (@ S\$486.90)	\$ 973.80	
12	Corner Panel clips 06 pcs (@ S\$8.00)	\$ 48.00	SN X
13	Wiper Panel Garnish	\$ 480.20	
14	Side Mirror Arm 02 pcs (@ S\$410.80)	\$ 821.60	X
15	"Round" Side Mirror	\$ 67.80	X
16	Windscreen Glass Weather Strip 3125	\$ 473.90	
17	Aircon Blower 055	\$ 2,277.20	
18	Number Plate "Metal"	\$ 28.00	SN 145.00
19	"Corporate" Advertisement & Artwork	\$ 180.00	805.00
	To check all wiring & electrical component for proper function	\$ 300.00	30
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	800
	To putty & spray painting & including touch up paint on accident affected	\$ 1,600.00	900
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 300.00	100
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc	\$ 400.00	200
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	100
	To apply Rust Proofing, rescal tuff-coating treatment on accident area	\$ 80.00	50

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 15,235.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

... notice

... following:

- ... painting
- ... repair
- ... confirmation
- ... without Prejudice" basis
- ... is allowed
- ... must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Actual

L/Br

26/12/18

5 day

L/S \$: 6750.

P-895280

less 50%

P-447640

S.N-94.00

labor-2180.00

6750.40

> Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle**

**Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Company

1196N

**Vehicle Details**

Vehicle No.:

GBE7128U

Vehicle to be Exported:

No

Intended Deregistration Date:

24 Dec 2018

Vehicle Make:

MITSUBISHI

Vehicle Model:

CANTER FEA01BR1SDEB (CBU)

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

4P10B94230

Chassis No.:

FEA01BA20051

Maximum Power Output:

-

Open Market Value:

\$26,229.00

Original Registration Date:

09 Mar 2016

First Registration Date:

09 Mar 2016

Transfer Count:

1

Actual ARF Paid:

\$1,312.00

**Intended PARF Rebate Details**

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

**Intended COE Rebate Details**

COE Expiry Date:

08 Mar 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$4,545.00

COE Rebate Amount:

\$3,272.00

**Total Rebate Amount:**

**\$3,272.00**

The information contained herein is correct as at 24 Dec 2018

OK



## ◀ MANDATE IA (S8M017V7)

Type

🔔 Question

Message

Liability: Insured reversed and hit third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$6,750.00 Loss of Use: \$560.00 (7days x \$80) LTA Search: \$2.00 Total: \$7,312.00 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (21/03/2019)

Reply

◀ Re:RE: MANDATE IA (S8M017V7)

Type

🗉 Question

Message

Please proceed

Reply

## Service Request Details

### Claim

S8M017V7

### Reference

None 

### Loss Date

16 November 2018

### Request Date

26 December 2018

### Due Date

2 January 2019

### Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

### Type of Loss

Third Party Vehicle Damage

### Services

Pending verification - Direct Settlement

### Actions

#### Next Step

Agree to perform service

### Vehicle Information

#### Incident Vehicle Registration #

GBE7128U

#### Make

TPVD MITSUBISHI

*Mem3**Murus*

### Service Address

---

...

### Primary Contact/Insured

---

T B C TRANSPORTATION & TRADING PTE LTD

102E PASIR PANJANG ROAD, #04-02 CITILINK WAREHOUSE, COMPLEX, 118529, Singapore

65674755

joannetan@tbc.com.sg

### Claim Handler

---

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

## Catherine Chong (LKK Auto)

---

**From:** Jasmine Low <liusbrojasmie@yahoo.com>  
**Sent:** Monday, 24 December, 2018 4:28 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** Susan Low  
**Subject:** Request for 3rd party survey GBE7128U Claims against XD8621A  
**Attachments:** XD8621A.docx; STV3-MARS00000351-GBE7128U-GIA.pdf; Image.jpg

**Categories:** SHEKHAR

Accident on 16/11/2018 Along PIONEER SECTOR 2

Involving GBE7128U and XD8621A

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regards!

Jasmine Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit

Singapore 417883 ☎: [6741 1730](tel:67411730) 📠: [6744 5746](tel:67445746)

Date of Survey:- \_\_\_\_\_

Name of Authorise Surveyor:- \_\_\_\_\_

Surveyor Email: \_\_\_\_\_

Remark :- \_\_\_\_\_

Our Ref: GBE7128U181116

Date: 05/01/2019

Your Ref:

AXA Insurance Singapore Pte Ltd  
8 Shenton Way #27-01  
AXA Tower  
Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG PIONEER SECTOR 2  
INVOLVING GBE7128U AND XD8621A ON 16/11/2018**

We/I, Messers Goldbell Leasing Pte Ltd (Nric / ROC No: 199001196N, the registered owners of m/vehicle – **GBE7128U** at all material times of the above accident. Our/my vehicle was surveyed by "AXA" authorized appraiser and we/I based our/my claims on his recommendation for **S\$6,750-00** being the repair for **05** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **XD8621A** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBE7128U**.

We/I whereby you are the insurers of m/vehicle **XD8621A** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBE7128U** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	6,750-00
(b) LOU for pre-repair notice 02 days @ S\$80-00		160-00
(c) LOU Fee for 05 days @S\$80-00		400-00
(d) GIA / LTA search fee		2-00

**Total Amount** **S\$ 7,312-00**

We/I enclose herewith copies of the supporting documents for vehicle no. **GBE7128U** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,

  
The owner of m/vehicle **GBE7128U**  
Messers Goldbell Leasing Pte Ltd  
cc. Liu's Bro Auto Engrg Ws

**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Wednesday, 20 February 2019 2:46 PM  
**To:** 'LHLEE@TBC.COM.SG'  
**Subject:** ACCIDENT INVOLVING XD 8621A AND GBE 7128U ALONG PIONEER SECTOR 2 ON 16/11/2018

20 FEB 2019

**TBC TRANSPORTATION & TRADING PTE LTD**

Dear Sir/ Mdm

**OUR REF : CC4/ASM18023129/Uea3**

**YOUR REF : XD 8621A**

**ACCIDENT INVOLVING XD 8621A AND GBE 7128U ALONG PIONEER SECTOR 2 ON 16/11/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s LIU'S BROTHER AUTO ENGINEERING WORKSHOP acting on behalf of the owner of GBE 7128U against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had reversed and hit Third Party vehicle GBE 7128U. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- **Letter Of Authorisation from the company**
- **Driver's driving license Of Mr Yang Chai Mea**

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher

*Case Handler*

DID: 6841 6051

FAX: 6741 4108

Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. *AXA Insurance Pte Ltd (AXA)*  
*(Motor Claims Dept)*

## Authorization To Act

**Attn: Motor Claims Department**  
AXA Insurance Singapore Pte Ltd  
8 Shenton Way #27-01  
AXA Tower  
Singapore 068811

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBE7128U (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. GBE7128U that was damaged pursuant to the accident which occurred on 16/11/2018 (date) along Pioneer Sector 2 (location) involving XD8621A ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 13th day of May (month) 2019 (year)

3<sup>rd</sup> Party Claimant:

Workshop:

Signature: 

Name: Goldbell Leasing Pte Ltd

Address: No. 18 Tuas Avenue 10

Singapore 639142

Nric/ROC No: 199001196N

Signature: 

Name: Liu's Brother Auto Engrg Workshop

Address: 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

ROB No: 53291793J



### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	XD 0021A	(Insd veh)	Model: MITSUBISHI CANTER FEA01
	QBE 7120U	(TP veh)	
Date of Accident/ Time:	16/11/2018		

Repair Estimate	S	15,235.00	
Final Repair Cost	S	6,750.00	
Loss of Use	S	560.00	7 days at S 80.00 per day
Rental (if any)	S	-	days at S- per day
LTA / GIA Search Fee	S	2.00	
Others	S	-	
	S		
<b>Final Settlement Sum</b>	<b>S</b>	<b>7,312.00</b>	

**Payee Name :** LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Is Third Party Workshop GIA Registered?     YES     NO    (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/No    BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (%) _____ (%)
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>		
Remarks:		

**NOTE:**

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

<p style="text-align: center;"></p> <p style="text-align: center;">Signature of workshop representative / Workshop stamp</p> <p style="text-align: center;">Name of Representative: <b>Liu's Brother Auto Engineering Workshop</b></p> <p style="text-align: center;">Date: <b>13 MAY 2019</b></p> <p style="text-align: center;"></p>	<p style="text-align: center;"></p> <p style="text-align: center;">Signature of Witness / Workshop stamp (if applicable)</p> <p style="text-align: center;">Name of Witness: <b>Low Siew Yian - S1543134B</b></p> <p style="text-align: center;">Date: <b>13 MAY 2019</b></p> <p style="text-align: center;"></p>
<p style="text-align: center;"></p> <p style="text-align: center;">Signature of AXA's surveyor representative</p> <p style="text-align: center;">Name of AXA's surveyor representative: <b>LKK</b></p> <p style="text-align: center;">Date: <b>16/05/19</b></p> <p style="text-align: center;">CKS</p>	

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417881

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5246, Email: liushro@gmail.com

Invoice/Ref No: GBE7128U18116

**Final Bill**

<b>Customer</b>		<b>Date:</b>	05-01-19
<b>Name:</b>	AXA Insurance Singapore Pte Ltd	<b>Vehicle No:</b>	GBE7128U
<b>Address</b>	Motor Claims Department 8 Shenton Way #27-01 AXA Tower Singapore 068801	<b>Model/Make:</b>	Mitsubishi ✓ Canter FEAA1BRISDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 882.70	\$ -
2	Bumper Bracket 02 pcs (@ \$5108.40)	\$ 216.80	\$ -
3	Bumper Side 02 pcs (@ \$5441.70)	\$ 883.40	\$ -
4	Head Lamp 02 pcs (@ \$5672.70)	\$ 1,345.40	\$ -
5	Signal Lamp 02 pcs (@ \$5313.60)	\$ 627.20	\$ -
6	Grille	\$ 426.80	\$ -
7	Grille Clips 08 pcs (@ \$59.50)	\$ 76.00	SN \$ -
8	"Mitsubishi" Logo Motif	\$ 186.80	\$ -
9	"Canter" Emblem	\$ 75.40	\$ -
10	Panel	\$ 864.30	\$ -
11	Corner Panel 02 pcs (@ \$5486.90)	\$ 973.80	\$ -
12	Corner Panel clips 06 pcs (@ \$58.00)	\$ 48.00	SN \$ -
13	Wiper Panel Garnish	\$ 480.20	\$ -
14	Side Mirror Arm 02 pcs (@ \$5410.80)	\$ 821.60	\$ -
15	"Round" Side Mirror	\$ 67.80	\$ -
16	Windscreen Glass Weather Strip	\$ 473.90	\$ -
17	Aircon Blower	\$ 2,277.20	\$ -
18	Number Plate "Metal"	\$ 28.00	SN \$ -
19	"Corporate" Advertisement & Artwork	\$ 180.00	\$ -
	To check all wiring & electrical component for proper function	\$ 300.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 1,600.00	\$ -
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 300.00	\$ -
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc	\$ 400.00	\$ -
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	\$ -
	To apply Rust Proofing, re-seal tuff-coating treatment on accident area	\$ 80.00	\$ -

<b>Total Parts &amp; Labour of estimate for damaged vehicle</b>	\$ 15,235.30
---	--------------

<b>Total amount in Lump Sum Basis for repaired vehicle</b>	\$ 6,750.00
--	-------------

SDLS: Six Thousand Seven Hundred Fifty Only



M/s Liu's Brother Auto Engrg Wks



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-197524

Date of Request: 24/12/2018

Your Ref No: Online Purchase

 LIU'S BROTHER AUTO WORKSHOP  
 1 Kaki Bukit Ave 6 #01-01  
 Auto Bay@Kaki Bukit  
 Singapore 417883

Dear Sir/Madam,

 Enquiry Date 24/12/2018  
 Enquiry By Jasmine Low Lay Hong  
 TP Vehicle No. XD8621A  
 Accident Date 16/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [ ] Cash [ ] Cheque

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	XD 8621A (Insd veh)	Model:	MITSUBISHI CANTER (A)
	GBE 7128U (TP veh)		
Date of Accident:	16/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	15,235.30	
Final Repair Cost	:	\$	6,750.00	
Loss of Use	:	\$	560.00	7days at \$80.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$	2.00	

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	7,312.00

Is Third Party Workshop GIA Registered?  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_100\_\_\_(%)  
 B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_  
 BOLA Liability: \_\_\_(%) Assessed Liability (\*): \_\_\_(%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks  
 \_\_\_\_\_  
 \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	LIU'S BROTHER AUTO ENGINEERING WORKSHOP	:	\$ 7,312.00

\_\_\_\_\_  
 JOANNE LEE KHANG MIN  
 LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
 24/05/2019  
 Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18023129/Uea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 24-05-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 8621A	Veh. Inspected	GBE 7128U
Policy No.		Coverage (\$)	0.00
Claim No.	S8M017V7	Excess (\$)	0.00
Assign From		Assign Date	26/12/2018
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi canter (A)	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	FEA01BA20051	Colour	WHITE / BLUE
Odometer	80845	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	DUNLOP	6 mm
L/H Front Tyre	195 R15	DUNLOP	6 mm
R/H Rear Tyre	195 R15 (D)	DUNLOP	6/6 mm
L/H Rear Tyre	195 R15 (D)	DUNLOP	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/11/2018	Inspection Date	26/12/2018
Survey held at	LIU'S BROTHER, AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7128U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	DENTED	882.70	882.70
2	FRONT BUMPER BRACKET @\$108.40 (CONSISTENT)	TO REPAIR SEE LABOUR	216.80	-
2	FRONT BUMPER SIDE @\$441.70 (CONSISTENT)	DENTED /DEFORMED	883.40	883.40
2	FRONT HEAD LAMP @\$672.70 (CONSISTENT)	HOLDER CRACKED	1,345.40	1,345.40
2	FRONT SIGNAL LAMP @\$313.60 (CONSISTENT)	O/S BROKEN	627.20	313.60
1	FRONT GRILLE (CONSISTENT)	CRACKED	426.80	426.80
1	FRONT 'MITSUBISHI' LOGO MOTIF (CONSISTENT)	NECESSARY	186.80	115.00
1	FRONT 'CANTER' EMBLEM (CONSISTENT)	NECESSARY	75.40	75.40
1	FRONT PANEL (CONSISTENT)	BADLY DENTED	864.30	864.30
2	FRONT CORNER PANEL @\$486.90 (CONSISTENT)	CRACKED	973.80	973.80
1	FRONT WIPER PANEL GARNISH (CONSISTENT)	CRACKED	480.20	480.20
2	FRONT SIDE MIRROR ASSY @\$410.80 (CONSISTENT)	NOT NECESSARY	821.60	-
1	FRONT 'ROUND' SIDE MIRROR (CONSISTENT)	NOT NECESSARY	67.80	-
1	FRONT WINDSCREEN GLASS WEATHER STRIP (CONSISTENT)	NECESSARY	473.90	315.00
1	FRONT AIRCON BLOWER ASSY (CONSISTENT)	CRACKED	2,277.20	2,277.20
	LESS 50% DISCOUNT		-	-4,476.40
			10,603.30	4,476.40
<b>SPECIAL NETT ITEMS</b>				
8	FRONT GRILLE CLIPS @\$9.50 (CONSISTENT)(SN)	NOT NECESSARY	76.00	-
6	FRONT CORNER PANEL CLIPS @\$8.00 (CONSISTENT)(SN)	NOT NECESSARY	48.00	-
1	FRONT NUMBER PLATE 'METAL' (CONSISTENT)(SN)	BENT	28.00	14.00
1	FRONT 'CORPORATE' ADVERTISEMENT & ARTWORK (CONSISTENT)(SN)	NECESSARY	180.00	80.00
			332.00	94.00
<b>LABOUR</b>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		300.00	30.00

Report Ref No. CC4/ASM18023129/Uea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET .		1,500.00	800.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		1,600.00	900.00
	TO REMOVE & REFIX AIRCON ,RE-FILL AIR CON GAS & TEST FOR LEAKAGES.		300.00	100.00
	REMOVE & REINSTALL DASHBOARD ,METER INSTRUMENTS,DISCONNECT WIRING & ETCS.		400.00	200.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS.		120.00	100.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		80.00	50.00
			4,300.00	2,180.00
	<b>GRAND TOTAL</b>		<b>15,235.30</b>	<b>6,750.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,750.00</b>

Report Ref No. CC4/ASM18023129/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

### Service Request Details

Claim: SSM017V7

Reference: CCA/ASM18023129/Usa3qZ

Loss Date: 16 November 2018

Report Date: 26 Dec 2018 8:56:35 AM

Request Date: 26 December 2018

Due Date:

**Actions**

Next Step: Wait for Approve invoice

Next Step: [Next Step](#)

**Vehicle Information**

Incident Vehicle Registration #: GBE712BU

Make: TPVO MITSUBISHI

Model: CANTER

Service Address:

Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss: Third Party Vehicle Damage

Services: Pending verification - Direct Settlement

Primary Contact/Insured:

T B C TRANSPORTATION & TRADING PTE LTD  
 102E PASIR PANJANG ROAD, #04-02 CITILINK WAREHOUSE, COMPLEX, 118529, Singapore  
 65674755  
 psannetanj@tbc.com.sg

Claim Handler:

NG Stacy  
 6568804351  
 stacy.n@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type:

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice3 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Payment Breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
LKK Adjustment 1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
US FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
WORKSHOP INVOICE.pdf	Invoice	Receipt	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
LETTER TO OUP.pdf	Letters and Correspondence	Policy Holders / Issued	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2019
OLD DRIVING LICENCE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
LETTER OF AUTHORIZATION.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
TP ESTIMATE - MARKED (REVISED).pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
LKK Reurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	L&K AUTO CONSULTANTS PTE LTD (TP)	10 January 2019
LIST OF SURVEY.MIG	Letters and Correspondence	Surveyor / Assessor	VISHNU BATHAM Shekhar	26 December 2018
GIA XDR421A INSD PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	26 December 2018
EMAIL TP PRJ.MIG	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	26 December 2018
P2118209_NB_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	MG Stacy	26 December 2018
P2118209_CI_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	MG Stacy	26 December 2018