

ASS. REC. BY:

REF:

CS3/AIG18023145/Ecd301

Special Instruction:

Surveyor:

Steve

Meinen

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

27/12/18 @ 9:20am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLM 9798L

Insured:

GY 8303J

at Workshop m/s

Autobest Motor

Tel:

67456932

of

Blk 3006 Ubi Rd 1 #01-362

Policy No.:

2100495295

Claim No.:

340150104786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/12/2018

CA / REV / REP. / REV 24 HRS

/up

H.O.D. Endorsement:

Date/Time:

9:22am @ 27/12/18

Person Contacted:

Mr. Lee

Vehicle:

IN OUT

Date/Time

Action/Instruction ( X ) Estimate

SLM 9798L - NA/AIG18022028/h4

JIA: 5/12/18

GY 8303J - NA/AIG18022028/h4

JIA: 5/12/18

Surveyor

REF: AIG

### ASSIGNMENT

From: Date: 27/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLM 9798L  
at Workshop m/s: Autobest  
of: 811c 3006, ubi Rd 1 # 01-362

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>wp</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLM 9798L Yr Regn: 19/04/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz B180 C.C: 1595

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 59269 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W0024624-22J414881

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16  
R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 5/12/2018 D.O.I. 27/12/2018

Survey held at: Auto best motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format :


Lump Sum / I.B.I. (\$)

180

20

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 27/12/2018 9:20:08 AM  
Attachments:  NEW PRI - GY8303J.PDF

---

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** gslimlaw@singnet.com.sg [mailto:gslimlaw@singnet.com.sg]  
**Sent:** Tuesday, December 11, 2018 3:43 PM  
**To:** Azlan, Syazairdina  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; gslimlaw@singnet.com.sg  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GY8303J AND SLM9798L ON 05/12/2018

Your Ref : 3401501047SG003

Our Ref : HL/ABM/11960/18/ck

Dear Sirs

We refer to your email of even date.

Pursuant to State Courts Practice Directions Amendment No. 1 of 2016, our client is not agreeable to your list of surveyors. Our client's appointed surveyor is Mr Kent Ong (KTO Automobile Assessors).

Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them.

Workshop	Auto Best Motor Services
Address	Blk 3006 Ubi Road 1 #01-362 Singapore 408700
Contact Person	Mr Lee
Tel No.	67456932

Thank you

Regards,

**G S Lim & Partners** | 150 South Bridge Road #02-30 Fook Hai Building Singapore 058727  
Tel : 65324518 | Fax : 65325410 | [gslimlaw@singnet.com.sg](mailto:gslimlaw@singnet.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**林 錦 秀 律 師 館** **G S LIM & PARTNERS**

Advocates & Solicitors  
Notary Public  
Commissioner for Oaths

**HENRY G S LIM**  
LLB (Hons) (London)  
Barrister-at-Law (Lincoln's Inn)

**DAVID YONG KHUNG LIN**  
LLB (Hons) (University of Bristol)

150 South Bridge Road  
#02-30 Fook Hai Building  
Singapore 058727  
Tel 65324518 Fax 65325410  
email : gslimlaw@singnet.com.sg  
UEN 53131358A  
GST Reg No. M90361086A

Our Reference : HL/ABM/11960/18/ck

Your Reference :

10 December 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#08-16  
SINGAPORE 079120

**BY FAX 64153727 ONLY**

Attn : Motor Claims Department

Dear Sirs

**PRE-REPAIR SURVEY – NOTIFICATION OF INSPECTION  
ACCIDENT AT LOR 27A GEYLANG (GEYLANG ROAD) INVOLVING SLM 9798L & GY 8303J ON  
05.12.18**

We are instructed by M/s Auto Best Motor Services to notify you of a road traffic accident on 05.12.18 at Lorong 27A Geylang (Geylang Road) involving our client's vehicle registration number SLM 9798L and GY 8303J driven by your insured at the material time. A copy of our client(s) Singapore Accident Statement is attached.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



**HENRY G S LIM**

Encl

cc : M/s Auto Best Motor Services

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7564D
<b>Vehicle Details</b>	
Vehicle No.:	SLM9798L
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 STYLE (R16 LED)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	27091031045247
Chassis No.:	WDD2462422J414881
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,956.00
Original Registration Date:	19 Apr 2017
First Registration Date:	19 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$23,339.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2027
PARF Rebate Amount:	\$17,504.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$41,637.00
<b>Total Rebate Amount:</b>	<b>\$59,141.00</b>

The information contained herein is correct as at 27 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/12/2018 11:51
Date Of Accident	05/12/2018 15:30
Exact Location Of Accident	LOR 27A GEYLANG (GEYLANG RD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM9798L
-----------------------------	----------

### Insured/Policyholder

Name Of Registered Owner	NG YANG SIANG @ SECK FA SUE
NRIC No	S0207564D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96184888
Alternative Phone No	OFFICE-96184888

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	B180
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100506633-01
Cover Note Number	-

### Driver

Name of Driver	CHEW HOON LONG
NRIC No	S7563991J
Date Of Birth	01/06/1975
Occupation	OUTDOOR
Date Of Driving Pass	06/08/2004
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91785601
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	10 LOR 26 GEYLANG #06-04
Postcode	398485
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - PARTNERSHIP
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	LEE KAY KIAT
Phone Number	86018720
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY8303J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LOW THIAM SENG
NRIC/Passport Number	S0978869G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law (in administering, processing, handling and/or dealing with my claims, collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Accident Sketch Plan

### SKETCH PLAN

Geplang Rd

Revised

B

A

Lot 27 A Geplang

A = SLM 97982

B = GY 93033

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to statement

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

MY VEH WAS PARKED INFRONT THE COFFEE SHOP AT LOR 27A GEYLANG,  
BEFORE I LEAVE MY VEH, EVERYTHING WAS INTACT, WHEN I WENT BACK  
TO MY VEH, AN EYEWITNESS INFORM ME THE LORRY (BEARING NO  
GY8303J) WHICH WAS PARKED INFRONT OF ME REVERSING HIT ONTO MY  
VEH FRONT PORTION.

Accident Sketch Plan

# MOTOR CAR (Frt)

Aug 2005

## Front Position

Vehicle No.

SLM-9798L

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	✓	✓	
1002	991887	Frt Number Plate Base	DD	✓	
1003	991889	Frt Number Plate Garnish	DD	✓	
1004	991300	Frt Bumper	DD	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991463	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	RR	✓	
1022	991328	Frt Grille Emblem	RR	✓	
1023	991799	Frt Grille Chrome Moulding	?		
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	998339	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990214	Battery Cover			

31/12/18

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Moulding			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Dec 2018 <a href="#">Edit Reg</a>		27 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	<b>JIAN YUAN CHENG RELIGIOUS GOODS &amp; CEREMONIAL PROD</b> , Co. Reg. No.: 50919100B		
Main Claimant:	<b>NG YANG SIANG @ SECK FA SUE</b> , ID: S0207564D		
Vehicle Reg. No.:	<b>SLM9798L</b>	Date of Loss:	05/12/2018 15:00 - :59 [19 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 3401501047SG</b>	Policy/Cover Note No.:	2100495295 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	<b>GY8303J</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Auto Best Motor Services (HQ)</b> BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 08/01/2019]		
Insurer's Solicitor:	<b>G S LIM &amp; PARTNERS (HQ)</b> - Tel: 65324518 ... Incoming Assignment		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (28/12/2018): TP GIA REPORT

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLM9798L (3401501047SG)**  
**[GY8303J]**

**TP**










**NG YANG SIANG @ SECK FA SUE**

**Dec 5 2018 3:00PM**

**[JIAN YUAN CHENG RELIGIOUS GOODS & CEREMONIAL PROD]**

**Auto Best Motor Services**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		▼			
Assessment Reports																	1 per page		▼		☑	
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print				
1	28/12/18 11:43		Accident Statement From:SC - Reg. No: GY8303J, Claimant: JIAN YUAN CHENG RELIGIOUS GOODS & CEREMONIAL PROD													1 Load HTM						
Photos/Images																	3 per page		▼		☑	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print				
1	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
2	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
3	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
4	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
5	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
6	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
7	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
8	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
9	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
10	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
11	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
12	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
13	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
14	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
15	27/12/18 10:53		Accident Photo													1 Load JPG		☑				
16	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
17	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
18	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
19	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
20	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
21	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
22	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
23	27/12/18 10:54		Accident Photo													1 Load JPG		☑				
24	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
25	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
26	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
27	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
28	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
29	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
30	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
31	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
32	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				
33	28/12/18 17:38		Dismantled Parts													1 Load JPG		☑				

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	28/12/18 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To:

☐ Handling Insurer☐ Insurer's Solicitor

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18023145/ECD3E2

Date: 02/01/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100495295  
**Claimant Vehicle No :** SLM9798L **Insured Vehicle No :** GY8303J  
 Date of Loss: 05/12/2018 Nature of Claim: TP Claim No: 3401501047SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLM9798L**  
 Make & Model: MERCEDES-BENZ B180, 2.0 (A) Engine No: 27091031045247  
 Reg. Date: 19/04/2017 (Man. Year: 2016) Chassis No: WDD2462422J414881  
 Colour: White Odometer: 59269 km  
 Engine Capacity: 1595 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 27/12/2018  
 Date Inspected: 27/12/2018 Inspected At: Auto Best Motor Services (HQ)  
 BLK 3006 UBI ROAD 1, #01-362  
 Singapore 408700  
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Dented	0.00 F	*- F
3	1		*FRT BUMPER	Dented	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT GRILLE	Broken	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*- F
7	1		*FRT GRILLE CHROME MOULDING	* Check	0.00 F	*- F
					<b>Total Parts (\$\$)</b>	<b>0.00 0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >