

ASS. REC. BY:

REF:

CS/SMO18023154/USD302

Special Instruction:

Surveyor  
Minimen

Marcus

ASSIGNMENT (Office)

From (Person): Ngo Sai Wei shawn

of

SMO

Date/Time:

26/12/18 @ 19:13pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YM 9145S

Insured:

XD 2658J

at Workshop m/s

Hu's Brother

Tel:

67411730

of

1 kaki Bukit Ave 6 # 01-01

Policy No:

D18MT4 CVE001622

Claim No:

CMTD1805658

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/11/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

27/12/18 @ 9:16am

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YM 9145S - X
	XD 2658J - CS/SMO18013120/TLVD352
28/12/18	@ 14:53 p.m. revert pending estimate from repairer to shawn ngo via minimen.

JWA: 10/07/2018

(08/11/13) Wel

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Y491455

at Workshop m/s: 100's 420

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 406.

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: Y491455 Yr Regn: 11 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM

Make: HINO C.C. 7684

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 343848 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GH8JRK 10511

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 10.00-20

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front 6 Rear 6/6

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. 27/11/18 D.O.I. 27/12/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/1/19 L7A14784  
1/5 \$5200 confirmed with Susan.  
4/1/19 Confirmed HS \$5,200/- @ 4 days with Marcus.  
( \$ 4,187.90 RL - 45% )

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

☐ : Prel. Report

☒ : Final Report

1) 4/1/19  
Typing

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ -- RS -- SI

Photos

Others

TOTAL

250

10

260

Report Format :

Lump Sum / I.B.I: (\$ 5,200/- HS)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2018		26 Dec 2018 19:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HOE HENG TRANSPORT, Co. Reg. No.: 24336700K		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	YM9145S	Date of Loss:	27/11/2018 11:00 - :59
Claim Type:	TP / CMTD1805658	Policy/Cover Note No.:	D18MTHCVE001622 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	XD2658J	Policy No. (Claimant):	
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/01/2019]		

#### ASSOCIATED MAIL RECEIVED

[View All](#)   [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#)   [Search Tasks](#)   [Create New Task](#)   [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Company

1196N

**Vehicle Details**

Vehicle No.:

YM9145S

Vehicle to be Exported:

No

Intended Deregistration Date:

24 Dec 2018

Vehicle Make:

HINO

Vehicle Model:

GH8JRKA

Primary Colour:

White

Manufacturing Year:

2008

Engine No.:

J08EUB11194

Chassis No.:

GH8JRK10511

Maximum Power Output:

-

Open Market Value:

\$54,791.00

Original Registration Date:

28 Jul 2008

First Registration Date:

28 Jul 2008

Transfer Count:

2

Actual ARF Paid:

\$2,740.00

**Intended PARF Rebate Details**

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

**Intended COE Rebate Details**

COE Expiry Date:

27 Jul 2023

COE Category:

C - Goods Vehicle &amp; Bus

COE Period(Years):

5

PQP Paid:

\$16,100.00

COE Rebate Amount:

\$14,784.00

**Total Rebate Amount:****\$14,784.00****Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 24 Dec 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1196N

**Vehicle Details**

Vehicle No.:	YM9145S
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2018
Vehicle Make:	HINO
Vehicle Model:	GH8JRKA
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	J08EUB11194
Chassis No.:	GH8JRK10511
Maximum Power Output:	-
Open Market Value:	\$54,791.00
Original Registration Date:	28 Jul 2008
First Registration Date:	28 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$2,740.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	27 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,100.00
COE Rebate Amount:	\$14,784.00
<b>Total Rebate Amount:</b>	<b>\$14,784.00</b>

**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 24 Dec 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



hino

Price Range ▾

Depreciation ▾

&gt; 10 year(! ▾

Vehicle Type ▾



Home » Used Cars » Chuan Choon Motor Trading Co. » Hino FD8JPKA (COE till 03/2023)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres



## Hino FD8JPKA (COE till 03/2023)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price	\$44,800	
Depreciation	\$10,720 /yr	?
Reg Date	04-Mar-2008 (4yrs 2mths 3days COE left)	
Lifespan	03-Mar-2028	
Manufactured	2008	?
Mileage	-	
Transmission	Manual	
Engine Cap	7,684 cc	
Curb Weight	5,080 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	6 Ton, 24 Feet Wooden Body Lorry Attached With Hood. Suitable For Carrying Goods And Workers. New Paintwork. Very Good Condition.	
COE	\$20,115	?
OMV	\$45,435	?
ARF	\$2,272	?
Dereg Value	\$16,819 as of today (change)	?
No. of Owners	1	?
Type of Veh	Truck	
Category	COE Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 21-Dec-2018 | Last Updated on: 28-Dec-2018

Tags: Hino FD8JPKA, hino fd8jpka, 2008 Hino FD8JPKA, 2008 hino fd8jpka, Hino, FD8JPKA, fd8jpka, Used Hino

Compare



Location Map

## Seller Information

Company	Chuar Co.
	» deale
	» 7 veh
Address	5 Pione
	Search
Office No	62683:
Contact Person(s)	Mr Onq

## Useful Services

Afraid of lemm  
this car eval

Vehicle E

## View Sent Message

This mail is associated with :

**\*YM9145S (CMTD1805658)  
[XD2658J]**

TP

GOLDBELL LEASING PTE LTD

Nov 27 2018 11:00AM

[HOE HENG TRANSPORT]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 28/12/2018 14:53 PM.

**To** shawn.ngo@sompo.com.sg

**CC** sur@lkkauto.com

**Subject** YM9145S (CMTD1805658) [XD2658J] TP

Dear Shawn,

Please be informed that we have inspected the vehicle YM 9145S on 27/12/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/11/2018 10:26
Date Of Accident	27/11/2018 11:30
Exact Location Of Accident	9 CHANGI SOUTH ST 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM9145S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833

### Vehicle Particulars

Manufacturer	HINO
Model	GH8JRKA-7.7 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090757MFCV
Cover Note Number	

### Driver

Name of Driver	NITHAIYAN AYYAPPAN
Passport No/FIN	G6424701N
Date Of Birth	27/07/1982
Occupation	OUTDOOR
Date Of Driving Pass	12/03/2014
Driving Experience	4 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81806141
Fax Number	
Contact Number	
E Mail Address	JEAMSTPT@SINGNET.COM.SG



Address	18 TUAS AVE 10 LEVEL 6
Postcode	639142
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 27/11/18 AT ABOUT 1130HRS, I HAD JUST REACHED 9 CHANGI SOUTH ST 3 FOR DELIVERY. I SAW VEHICLE B MOVING FORWARD. VEHICLE B SUDDENLY REVERSED WITHOUT WARNING. I PRESSED MY HORN TO ALERT THE DRIVER; HOWEVER HE CONTINUED REVERSING UNTIL HE COLLIDED INTO MY VEHICLE'S FRONT RIGHT PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD2658J
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM MUI YONG STEPHEN
NRIC/Passport Number	S1398433F
Contact Number	98152450 (STEVEN)
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	NO DAMAGE
No. Of Passenger (Including Driver)	1

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*Handwritten signature*


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Handwritten signature*  
14/11/15



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



Van A: YH 9145S  
P: XD 2058J

9 Changi South St 3.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/11/18 at about 1130hrs, I had just reached 9 Changi South St 3 for delivery. I saw van B moving forward. Vehicle B suddenly reversed without warning. I pressed my horn to alert the driver, however he continued reversing until he collided into my vehicle's front right portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-197549

Date of Request: 24/12/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 24/12/2018  
Enquiry By Jasmine Low Lay Hong  
TP Vehicle No. XD2658J  
Accident Date 27/11/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
XD2658J	Sompo Insurance Singapore Pte. Ltd.	30/06/2018-29/06/2019	6461 6555

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-197549  
Date of Request: 24/12/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 24/12/2018  
Enquiry By Jasmine Low Lay Hong  
TP Vehicle No. XD2658J  
Accident Date 27/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [ ] Cash ☐ [ ] Cheque

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YM9145S181127

9145

**Estimate****Customer**

Name: Sompo Insurance Singapore Private Limited  
Address: Motor Claims Department  
50 Raffles Place #05-01 / 06  
Singapore Land Tower Singapore 048623

Date: 26-12-18

Vehicle No: YM9145S

Model/Make: Hino GH8JRKA

GH8

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
----------	-----------------------	---------------------------------	------------------------------------

1	Front Panel	\$ 1,325.50	
2	Panel Lock 02 pcs (@ S\$148.00) 11	\$ 296.00	X
3	"HINO" Emblem	\$ 195.00	
4	"500" Emblem	\$ 158.60	
5	Grille	\$ 974.00	
6	Corner Panel	\$ 945.00	
7	Signal Lamp	\$ 230.00	
8	Wiper Panel	\$ 619.00	
9	Wiper Arm	\$ 295.30	
10	Wiper Nozzle	\$ 177.60	
11	Head Lamp	\$ 1,450.00	
12	Radiator Spare Tank	\$ 381.90	
To check all wiring & electrical component for proper function		\$ 60.00	20
To apply Rust Proofing , reseal tuff-coating treatment on accident area		\$ 80.00	30
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 1,200.00	500
To putty & spray painting & including touch up paint on accident affected area		\$ 1,000.00	600

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 9,387.90

Total amount in Lump Sum Basis for repaired vehicle

SDLS: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks

Liu's Brother Auto Engineering Workshop hereby notify the Insurer of the following:

- Total survey before spray painting
- Total survey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The above survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

not attached  
work  
2/5 @ 5-200/  
21/12/18  
4 day  
the job. After up

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2018		26 Dec 2018 19:13 <a href="#">Edit Adj Rpt</a>	<b>S\$5,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	<b>HOE HENG TRANSPORT</b> , Co. Reg. No.: 24336700K		
Main Claimant:	<b>GOLDBELL LEASING PTE LTD</b> , Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	<b>YM9145S</b>	Date of Loss:	27/11/2018 11:00 - :59 [123 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / CMTD1805658</b>	Policy/Cover Note No.:	D18MTHCVE001622 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	<b>XD2658J</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)</b> Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>NGO SAU WEI SHAWN</b> - 6329 5202]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 07/01/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*YM9145S (CMTD1805658)**  
**[XD2658J]**






































**TP**

**GOLDBELL LEASING PTE LTD**
























**Nov 27 2018 11:00AM**

**[HOE HENG TRANSPORT]**

**Liu's Brother Auto Engineering Workshop (kaki Bukit)**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	04/01/19 09:37	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
2	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
3	04/01/19 09:37	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
4	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
5	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
6	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
7	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
8	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
9	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
10	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
11	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
12	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
13	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
14	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
15	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
16	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
17	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
18	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
19	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
20	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
21	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
22	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
23	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
24	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
25	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
26	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
27	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
28	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
29	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
30	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
31	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
32	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
33	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
34	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
35	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
36	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					
37	04/01/19 09:37	General View		Load JPG	<input checked="" type="checkbox"/>					



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/01/19 09:37	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	04/01/19 09:37	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/18 19:12	E-filed GIA Report	 Load PDF	
2	26/12/18 19:12	Pre-Repair Survey	 Load PDF	
3	27/12/18 09:30	LTR FROM HOE HENG TRANSPORT DT 26.12.18	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18023154/USD3E2

Date: 09/01/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE001622
Claimant Vehicle No :	YM9145S	Insured Vehicle No :	XD2658J
Date of Loss:	27/11/2018	Nature of Claim:	TP
		Claim No:	CMTD1805658

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	YM9145S	Engine No:	J08EUB11194
Make & Model:	HINO GH8JRKA, 7.7 D (M)	Chassis No:	GH8JRK10511
Reg. Date:	28/07/2008 (Man. Year: 2008)	Odometer:	343848 km
Colour:	White		
Engine Capacity:	7684 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	10.00-20	Rear Tyre Size:	10.00-20 (D)
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6/6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,047.90	5,388.84	1,659.06	23.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,150.00	1,190.00	50.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,387.90</b>	<b>6,538.84</b>	<b>2,849.06</b>	<b>30.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,387.90</b>	<b>5,200.00</b>	<b>4,187.90</b>	<b>44.61</b>

## INSPECTION

Date of Assignment:	26/12/2018	
Date Inspected:	27/12/2018 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** MARCUS CHUA**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 09 Jan 2019)	
<b>Parts:</b>	N/A	HINO GH8JRKA 7.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YM9145S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	1,325.50 F	*1,325.50 FL
2	2		*FRONT PANEL LOCK	Not Necessary	296.00 F	*- FL
3	1		*FRONT HINO EMBLEM	Necessary	195.00 F	*156.00 FL
4	1		*FRONT 500 EMBLEM	Necessary	158.60 F	*145.00 FL
5	1		*FRONT GRILLE	Cracked	974.00 F	*974.00 FL
6	1		*FRONT CORNER PANEL	Cracked	945.00 F	*945.00 FL
7	1		*FRONT SIGNAL LAMP	Broken	230.00 F	*185.00 FL
8	1		*FRONT WIPER PANEL	Cracked	619.00 F	*619.00 FL
9	1		*FRONT WIPER ARM	Repair	295.30 F	*- FL
10	1		*FRONT WIPER NOZZLE	Not Necessary	177.60 F	*- FL
11	1		*FRONT HEAD LAMP	Cracked	1,450.00 F	*1,350.00 FL
12	1		*FRONT RADIATOR SPARE TANK	Deformed	381.90 F	*288.10 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,047.90</b>	<b>5,987.60</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>598.76</b>
<b>Total Parts (\$\$)</b>	<b>7,047.90</b>	<b>5,388.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
3	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	500.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTECD AREA	New	1,000.00	600.00
Gross Labour Cost (\$\$)			<b>2,340.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >