

ASS. REC. BY:

REF:

CS/AIG18023157/Kt d3⁵²

Special Instruction:

Survivor
MAMMEN

From (Person):

Azlen syqairina

ASSIGNMENT (Office)

AG

Date/Time: 27/12/18 @ 11:33am

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 1051B

Insured:

YN 4076K

at Workshop m/s

Massive Trading

Tel:

9108 2728

of

Blk 5038, AMK Ind. park 2 #01-405

Policy No:

A00 038546

Claim No:

83405 25482 SG

Sum Insured:

Excess:

D.O.A.

24/12/18

Make of Veh:
(Client's Record)

CA / REV / REF. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:52am @ 27/12/18

Person Contacted:

Anthony

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 1051B-NA/EQI18023144/13

DOA: 24/12/18

YN 4076K-NA/EQI18023144/13

DOA: 24/12/18

61 Lyr @ 465d email

Revised 61 Lyr @ 660d

ASS. REC. BY:

REF:

AIG /

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / AWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claim No:

Sum Insured:


Excess:

(CP/CR Record)

Make of Vch:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Alter. Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / R/S / S/N:

Consistent? : Yes or No

Est. Repair:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REP / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time:

Action / Instruction

The UIC / Chassis frame / Body Structure affected due to collision.

Veh No:

GBD 10513

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MS Cabrio

c.c.

2.953

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading:

115168

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

JN1PC 21-2480855934

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F: BS

195 R15 X8

R: Yoko

165 R13 X8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

8

8

mm

L/Bal.

9

mm

L/Bal.

8

8

mm

D.O.A.

24/12/18

D.O.I.

27/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date/Time:



Prell. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Form:

Lump Sum / REP / IS

TP

7000+

RECEIVED 21 JAN 2019

Pre repair inspection request - GBD1051B VS YN4076K (OI) DOA: 24/12/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit
Sent: 27/12/2018 11:33:04 AM
Attachments:  2018122710204442.pdf

16,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan

IG

Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto
IG Claims Operations | AIG Shared Services

syazairdina.Azlan@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteoprtr.com]

Sent: Thursday, December 27, 2018 11:10 AM

To: Azlan, Syazairdina

Cc: Anthony Cheong; Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN4076K AND GBD1051B ON 24/12/2018

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,

Janice Kee

c/o Teo Keng Siang LLC

111 North Bridge Road,

29-07-08 Peninsula Plaza,

Singapore 179098

Tel: 6333 4222 Fax: 6333 5676

On Thu, Dec 27, 2018 at 10:19 AM Azlan, Syazairdina <Syazairdina.Azlan@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-01-03 10:19 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazaidina Azlan@aig.com
To: janice.kee@ksteopttr.com, cheonganthony@yahoo.com.sg
Cc: Andy-SY Fong@aig.com, Lee-Ying Chin@aig.com, NoorMarissa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Yinnul Hor@aig.com, yokeshi.chan@aig.com, Bal Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN4076K AND GBD1051B ON 24/12/2018
Date: Thu, 27 Dec 2018 02:19:38 +0000

Without Prejudice

Your Reference : TKSF/M492-ACC-41335.18/sf
Our Reference : YN4076K

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
IG Claims Operations | AIG Shared Services
Syazaidina.Azlan@aig.com | www.aig.sg

From: Janice Kee [mailto:janice.kee@ksteopttr.com]
Sent: Thursday, December 27, 2018 10:16 AM
To: Azlan, Syazaidina; Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Marissa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinnul; Chan, Yoke Shi; Kaur, Baljit
Cc: Anthony Cheong
Subject: Pre Repair Survey for GBD 1051 B (Your Ref: YN 4076 K Our Ref: TKSF/M492-ACC-41335.18/sf)

Dear Sir

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
29-07-08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTEOCO@singnet.com.sg
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/M492-ACC-41335.18/sf (mc)
Your Ref : YN 4076 K
Date : 27 December 2018

Secretary in charge: Janice

Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteoptr.com

To: AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16 Singapore 079120
Attn: Motor Claims Dept

WITHOUT PREJUDICE
BY PDX# 8181 & FAX 6835 7416 ONLY

Cc: Dominie Press Pte Ltd (Owner)
Tay Soon Huat (Driver)
C/o 26 Kallang Avenue
#01-00
Singapore 339417

BY POST ONLY

PDX Intercompany Exchange Pte Ltd



010808622089

FROM: TEO KENG SIANG LLC
PDX Box No. 8902

Dear Sirs

RE: ACCIDENT INVOLVING GBD 1051 B / YN 4076 K ON 24/12/18 ALONG CTE TOWARDS AYE BEFORE PIE (CHANGI EXIT)

We are instructed by Jae Plastic Pte Ltd to notify you of a road traffic accident on 24/12/18 at about 14:30 hours at **ALONG CTE TOWARDS AYE BEFORE PIE (CHANGI EXIT)** involving our client's vehicle registration number **GBD 1051 B** and vehicle registration number **YN 4076 K** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **GBD 1051 B** is now at the following workshop:-

Massive Trading & Auto
Blk 5038 Ang Mo Kio Industrial Park 2
#01-405
Singapore 569541
Contact: 9108 2728 Anthony

Yours faithfully,

M/s Teo Keng Siang LLC
Encs

****Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2018 09:21
Date Of Accident	24/12/2018 14:30
Exact Location Of Accident	CTE TWDS AYE B4 PIE(CHANGI EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD1051B
Insured/Policyholder	
Name Of Registered Owner	JAE PLASTIC PTE LTD
Co Reg No	201313350H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-87556360

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-003237
Cover Note Number	

Driver

Name of Driver	PREM KUMAR S/O SARKUNA RAJAH
NRIC No	S7326744G
Date Of Birth	27/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	13/08/2004
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87556360
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 223 ANG MO KIO AVE 1 #02-505
Postcode	560223
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN4076K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAY SOON HUAT
NRIC/Passport Number	S1147722D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders




Insured's Signature

Insurer's Signature

Records Centre Representative's Signature

Individual Statement

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 24/12/2018 @ ord 1430hrs, I was travelling along CTE towards A/E. Just before PIE (Change exit) due to heavy traffic, I slowed down my lorry and eventually came to a stop. Suddenly I felt an strong impact from the rear of my vehicle. I got out and realised that veh B (YN4076K) had collided into my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Report to Centre Personnel's Signature
Name:
NRU/PTL No:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3350H

Vehicle Details

Vehicle No: CBD1051B

Vehicle to be Exported: Yes

Intended Deregistration Date: 31 Dec 2018

Vehicle Make: NISSAN

Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Primary Colour: White

Manufacturing Year: 2014

Engine No: 2D30339568K

Chassis No: JN15C2F2420855934

Maximum Power Output: -

Open Market Value: \$75,061.00

Original Registration Date: 26 Jun 2014

First Registration Date: 26 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$1,255.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2024

COE Category: C - Goods Vehicle & Bus

COE Period (Years): 10

MCP Paid: \$28,514.00

COE Rebate Amount: \$15,643.00

Total Rebate Amount: \$15,643.00

The information contained herein is correct as at 29 Dec 2018

OK

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Fax : 64816131

JAE Plastic Pte Ltd
Blk 516 Hougang Ave 10
#07-211
Singapore 530516

Vehicle No: GBD 1051 B
Make : Nissan Cabstar
Year : 2014

Not Notified
6/2/14 8:00 AM Food
Resurvey After Paint
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Qty	Acknowledged by Repairer Signature: Date:	Unit Price	Amount
-----	---	------------	--------

Nett Item

- 2 pcs Rear tail-lamp assy
2 pcs Rear tail-lamp housing

\$255.10	CM	\$510.20	✓
\$187.60	A	\$375.20	X
		\$885.40	
Less 10 %		\$88.54	
		\$796.86	

S Nett Item

- 1 pc Rear o/s aluminium tail-gate pillar
1 pc Rear o/s aluminium tail-gate hinge
1 pc Rear o/s aluminium tail-gate *P-?*
1 pc Rear o/s aluminium tail-gate air vent
1 pc Rear o/s aluminium tail-gate lock handle *P-?*
1 pc Rear n/s aluminium tail-gate *P-?*
1 pc Rear n/s aluminium tail-gate hinge
1 pc Rear n/s aluminium tail-gate air vent
1 pc Rear n/s aluminium tail-gate lock handle *P-?*
1 pc Rear tail-gate sticker " 70 kmph "
1 pc Rear reverse sensor
1 pc Rear no plate

<i>Pd A</i>	\$2,050.00	<i>2900sn</i>
<i>A</i>	\$250.00	X
<i>A2</i>	\$4,000.00	<i>2900sn</i>
<i>Sn</i>	\$400.00	X
<i>A2</i>	\$1,050.00	<i>300sn</i>
<i>A2</i>	\$4,000.00	<i>2900sn</i>
<i>A</i>	\$250.00	X
<i>A</i>	\$400.00	X
<i>A2</i>	\$1,050.00	<i>300sn</i>
<i>Sn</i>	\$15.00	✓
<i>Sn</i>	\$200.00	✓
<i>Sn</i>	\$40.00	X
	\$13,705.00	

Labour Charges

To remove/renew the above accident parts including knocking, welding & cutting.

\$1,500.00 *600*

To spray paint on rear end panel

\$300.00 *150*

To check and reconnect wiring.

\$40.00 *20*

Total \$16,341.86

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2018 Edit Reg		27 Dec 2018 00:00 Edit Adj Rpt	S\$7,000.00 Edit Estimates	S\$7,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Dominie Press Pte Ltd, Co. Reg. No.: -		
Main Claimant:	JAE PLASTIC PTE LTD, Co. Reg. No.: 201313350H		
Vehicle Reg. No.:	GBD1051B	Date of Loss:	24/12/2018 14:00 - :59 [53 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8340525482SG	Policy/Cover Note No.:	1700038546 (Comprehensive)
Vehicle Reg. No. (Insured):	YN4076K	Policy No. (Claimant):	
		Excess:	
Repairer:	Massive Trading & Auto () Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/01/2019]		
Insurer's Solicitor:	TEO KENG SIANG LLC (HQ) - Tel: 63334222 ... Incoming Assignment		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (28/12/2018): NO TP GIA REPORT
- AIG_SG (28/12/2018): NO OI GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBD1051B (8340525482SG)**
[YN4076K]

TP

JAE PLASTIC PTE LTD
Dec 24 2018 2:20PM
[Dominie Press Pte Ltd]
Massive Trading & Auto

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/01/19 12:18	General View		Load JPG	
2	21/01/19 12:18	General View		Load JPG	
3	21/01/19 12:18	General View		Load JPG	
4	21/01/19 12:18	General View		Load JPG	
5	21/01/19 12:18	General View		Load JPG	
6	21/01/19 12:18	General View		Load JPG	
7	21/01/19 12:18	General View		Load JPG	
8	21/01/19 12:18	General View		Load JPG	
9	21/01/19 12:18	General View		Load JPG	
10	21/01/19 12:18	General View		Load JPG	
11	21/01/19 12:18	General View		Load JPG	
12	21/01/19 12:18	General View		Load JPG	
13	21/01/19 12:18	General View		Load JPG	
14	21/01/19 12:18	General View		Load JPG	
15	21/01/19 12:18	General View		Load JPG	
16	21/01/19 12:18	General View		Load JPG	
17	21/01/19 12:18	General View		Load JPG	
18	21/01/19 12:18	General View		Load JPG	
19	21/01/19 12:25	Reinspection Photo		Load JPG	
20	21/01/19 12:25	Reinspection Photo		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☒ Handling Insurer ☐ Insurer's Solicitor

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18023157/KTD3S2

Date: 22/01/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700038546
Claimant Vehicle No :	GBD1051B	Insured Vehicle No :	YN4076K
Date of Loss:	24/12/2018	Nature of Claim:	TP
		Claim No:	8340525482SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD1051B	Engine No:	ZD30339568K
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Chassis No:	JN1SC2F24Z0855934
Reg. Date:	26/06/2014 (Man. Year: 2014)	Odometer:	115168 km
Colour:	White		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	165 R13X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Yokohama 8/8 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,501.86	7,974.18	6,527.68	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	770.00	1,070.00	58.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,341.86	8,744.18	7,597.68	46.49
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	16,341.86	7,000.00	9,341.86	57.17

INSPECTION

Date of Assignment:	27/12/2018	
Date Inspected:	27/12/2018	Inspected At: Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541 Repairer: Massive Trading & Auto
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAIL-LAMP ASSY	Cracked	510.20 FN	*510.20 FN
2	2		*REAR TAIL-LAMP HOUSING	Repair	375.20 FN	*- FN
3	1		*REAR O/S ALUMINIUM TAIL-GATE PILLAR	Dented	2,050.00 FS	*900.00 FS
4	1		*REAR O/S ALUMINIUM TAIL-GATE HINGE	Repair	250.00 FS	*- FS
5	1		*REAR O/S ALUMINIUM TAIL-GATE	Bent	4,000.00 FS	*2,900.00 FS
6	1		*REAR O/S ALUMINIUM TAIL-GATE AIR VENT	Serviceable	400.00 FS	*- FS
7	1		*REAR O/S ALUMINIUM TAIL-GATE LOCK HANDLE	Bent	1,050.00 FS	*300.00 FS
8	1		*REAR N/S ALUMINIUM TAIL-GATE	Bent	4,000.00 FS	*2,900.00 FS
9	1		*REAR N/S ALUMINIUM TAIL-GATE HINGE	Repair	250.00 FS	*- FS
10	1		*REAR N/S ALUMINIUM TAIL-GATE AIR VENT	Repair	400.00 FS	*- FS
11	1		*REAR N/S ALUMINIUM TAIL-GATE LOCK HANDLE	Bent	1,050.00 FS	*300.00 FS
12	1		*REAR TAIL-GATE STICKER 70KMPH	Necessary	15.00 FS	*15.00 FS
13	1		*REAR REVERSE SENSOR	Scratched	200.00 FS	*200.00 FS
14	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part, S=SpcNett, N=NettItemDisc.

Sub Total (\$\$)	14,590.40	8,025.20
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	88.54	51.02
Total Parts (\$\$)	14,501.86	7,974.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE / RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING, WELDING & CUTTING.	New	1,500.00	600.00
2	TO SPRAY PAINT ON REAR END PANEL.	New	300.00	150.00
3	TO CHECK AND RECONNECT WIRING.	New	40.00	20.00
Gross Labour Cost (S\$)			1,840.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >