

ASS. REC. BY:

REF:

CS3/ATG18023160/Gdber

Special Instruction:

Surveyor:  
Maimun

GA

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ATG

Date/Time:

27/12/2018 12:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SG12 9858K

Insured:

98J 882U

at Workshop m/s

Jemantuh Motor

Tel:

9299 6636

of

14 Defu Lane 10 #01-406

Policy No:

Claim No:

920867440186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/12/2018

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

27/12/2018 12:35pm

Person Contacted:

Ah Chuan

Vehicle: IN/OUT

Date/Time	Action/Instruction ( X )	Estimate
	SG12 9858K - CS3/MSH15000714/Umb2-1	DIA: 12/01/2015
	98J 882U - X	
	Dismantle: 28/12/2018	



PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBJ882U AND SGQ9858K ON 24/12/2018

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: Thursday, 27 December, 2018 12:13:05 PM  
Attachments:  CY.SGQ9858K.18.JM(HW).wp(Lh).pdf

---

Hi YK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

Age

Claims | AIG Asia Pacific Insurance Pte. Ltd.

700 Raffles Place #08-16 Singapore 079120

Tel: (65) 6419 1947

[Email: lying.Chin@aig.com](mailto:lying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allianz International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref : CY.SGQ9858K.18.JM(HW).wp(Lh)

Your Ref : Your insured vehicle **SBJ 882U**

27 December 2018

**TONG PING HENG**  
c/o The Motor Claims Department  
**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way #07-16  
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS  
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES  
(NIMA) ROAD TRAFFIC ACCIDENT INVOLVING SGQ 9858K & SBJ 882U ON 24.12.2018 @  
13:10HRS ALONG 257 UPPER THOMSON ROAD**

We are instructed by YEOW CHOON HONG to notify you of a road traffic accident on 24.12.2018 @ 13:10hrs along 257 Upper Thomson Road involving our client's vehicle registration number SGQ 9858K and vehicle registration number SBJ 882U driven by you at the material time. A copy of the Singapore accident statement is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

  
C. Yogarajah LLC  
Enc

Cc: M/s. Jementah Motor Works  
Block 14 Defu Lane 10 #01-406, Singapore 539195  
Mr. Ah Chuan (9299 6636)  
Fax no.6285 7054

Vehicle & Owner Information ( Vehicle No. SBJ882U As At 24 Dec 2018 / 13:10:00 )

Insurance Claim Description: Insurance claim in relation to traffic accident  
Insurance Policy No: CY.SGQ9858K.18.HW.WP

Driver's License No: Singapore NRIC  
Driver's License No: S1610984C  
Driver's Name: TONG PING HENG

Address Type: HDB / HUDC  
House No: 308  
Street Name: WOODLANDS AVENUE 1  
Block No: # 11 - 337  
Flat No: -  
Postcode: 730308

Vehicle No: SBJ882U  
Vehicle Model: SUBARU / FORESTER 2.0XT CVT AWD SR  
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



Phee Lay San has successfully logged out.  
Your last login date and time was 27 Dec 2018, 10:05:34.  
To return to ONE MOTORING, please [click here](#)  
For security reasons, please **CLEAR YOUR CACHE** after each session.

Transaction History

Asset ID	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction
	Vehicle	SB1882U	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0670B

### Vehicle Details

Vehicle No.:	SGQ9858K
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	HR15076687A
Chassis No.:	JN1BAAC11Z0004015
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,752.00
Original Registration Date:	29 Jan 2007
First Registration Date:	29 Jan 2007
Transfer Count:	0
Actual ARF Paid:	\$15,128.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	31 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,636.00
COE Rebate Amount:	\$15,422.00
<b>Total Rebate Amount:</b>	<b>\$15,422.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/12/2018 10:24
Date Of Accident	24/12/2018 13:10
Exact Location Of Accident	257 UPPER THOMSON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ9858K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEOW CHOON HONG (YAO JUNHONG)
NRIC No	S7630670B
Email Address	YEOW100200@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93853081
Alternative Phone No	OTHERS-93853081

### Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5052735113-06
Cover Note Number	

### Driver

Name of Driver	YEOW CHOON HONG (YAO JUNHONG)
NRIC No	S7630670B
Date Of Birth	01/10/1976
Occupation	INDOOR
Date Of Driving Pass	04/08/1997
Driving Experience	21 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93853081
Fax Number	
Contact Number	OTHERS-93853081
Email Address	YEOW100200@GMAIL.COM

Address	BLK 238 #08-212 BISHAN STREET 22
Postcode	570238
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

**General Information of the Accident**

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 20 BISHAN STREET 23 , <b>POSTCODE:</b> 579757 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-5529999 - <b>FAX NO:</b> 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

AS PER POLICE REPORT No.T/20181224/2107

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SBJ832U
Vehicle Make/Model/Colour	SUBARU
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

# Accident Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
24/12/2018  
4:50

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Date & Time:


DAC SIN MING (VAC)  
385 Sin Ming Drive  
Singapore 575718  
Tel: 64555358(ARC), 66975243  
Fax: 6-52862

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

25 DEC 2018

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

HIT AND RUN. (KNOCK TO MY CAR BACK  
 While he is parking. My CAR is stationary  
 Passerby view and wrote a slip for me.

Refer  
 To Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

*[Signature]*  
 24/12/2018  
 4:50pm.

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC SIN MING (VAC)  
 305 Sin Ming Drive  
 Reporting Officer's Signature  
 Name: 4555358(ARC), 669754 r-  
 NRIC/FIN No: 6-526621

25 DEC 2018



**SINGAPORE  
POLICE FORCE**



T/20181224/2107

1 of 3

Report No: T/20181224/2107

Police Station Of Origin  
Bishan N.P.C.  
23 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800 5529999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made 24/12/2018 17:29	Vide Report No.:	Station Diary No 120
<b>Informant's Particulars</b>		
Name of Informant YEW CHOON HONG	Address: APT BLK 209 BISHAN STREET 23 #11-367 SINGAPORE 570209	
ID Type / ID No NRIC NO / S76308708	Contact No.:	Mobile: 93853087
Nationality SINGAPORE CITIZEN	Email:	
Age 42	Date of Birth: 01/10/1976	Type of Informant: Driver
Language:	Institution / School Name:	
Occupation DIRECTOR	Driving Licence Information: Class: 3 Date of Expiry:	

<b>Information of the Accident</b>				
Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 24/12/2018 13:10	Type of Location:	
THOMSON ROAD				
Thomson Rd S(574390) outside the Chicken Rice stall				
Road Surface:		Road Speed Limit:		
Traffic Control:		Traffic Volume:		
Anyone conveyed by ambulance: No				

<b>Vehicle Involved</b>					
Type	Make	Model	Color	Condition	No of Passenger
Car	NISSAN	LATIO 1.5L A	Silver		0

<b>Insurance</b>			
Insurance Company	Insurance No	Effective	Expiry Date
Income Insurance Co-Operative	5052735113-06	29/01/2018	28/01/2019

SINGAPORE  
POLICE FORCE



1/2018122402197

Report No. 1/2018122402197

Origin:

Sheet 23 SINGAPORE 579757  
529999

CONTINUATION OF REPORT

Person Involved		Use of Pedestrian Crossing: NA	
Person Involved: No			
Persons Injured: NIL			
YEOW CHOON HONG		ID No.	S7630670B
SGQ9858K (Car)		Contact No.	93853087
NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
NIL		Date Discharge	NIL
Medical Leave		Degree of Injury	NIL

I had parked my vehicle at about 1230hrs at the 263 Upp Thomson Rd S(574390) outside  
to retrieve my vehicle at about 1400hrs on the same day, I then drove off to the petrol  
kiosk, I then discovered a piece of paper on my windscreen. There was a  
below text:

check while parking

car came off and there was a dent due to the incident. Nobody was injured. I wish to  
was all the way in the stationary position from 1230hrs-1400hrs. I have an in-car  
however it was not on a recording mode when I turned off the engine. I wish to state that  
incident and I do not know the vehicle owner mentioned. I also do not know the  
and the note on my windscreen.





SINGAPORE  
POLICE FORCE



Police Station: 17 Angkor  
170079  
170079  
170079

Report No: 24/12/2018/170079

CONTACT INFORMATION: 65474888

Police Station: 17 Angkor  
170079

*[Large handwritten signature]*

WISLAN SPC  
19 BINSAN STREET 13  
SINGAPORE 439137  
TEL: 65474888



Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have one with you now, please fax a copy to 65474888 stating the report number as reference.

Officer Recording The Report:


MORHIDAHYAH BINTE AHMAD

Interpreter:

Name Of Case:

EM BIN ABDUL HAQUE

170079



Signature Of Informant

Date/Time:  
24/12/2018 17:29

Classification Of Case

SN 061

*[Handwritten signature]*

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

### MOTORCAR (Rear)

ACTION (AC)  
 (1) Replace (✓) (2) Repair (X) (3) Check (Ø)  
 (4) Not Consistent (NC)

Aug 2005

#### Rear Portion

Vehicle No: *SGA-9858K*

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	RT	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RR	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRU	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	RR	✓	2
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish	CRA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem	NEC	✓	2
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	RT	✓	
1178	990377	Bootlid Rubber	DD	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe		DDR	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Reserve Camera ?



## Claim Documents

\*SGQ9858K (9208674401SG)  
[SBJ882U]  
TP  
YEOW CHOON HONG (YAO JUNHONG)  
Dec 24 2018 1:00PM  
[-]  
Jementah Motor Works - Defu Lane

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
<b>Photos/Images</b>											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	31/12/18 09:31	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
2	31/12/18 09:31	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
3	31/12/18 09:31	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
4	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
5	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
6	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
7	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
8	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
9	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
10	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
11	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
12	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
13	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
14	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
15	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
16	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
17	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
18	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
19	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
20	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
21	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
22	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
23	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
24	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
25	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
26	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
27	31/12/18 09:32	<b>Accident Photo</b>							Load JPG	<input checked="" type="checkbox"/>		
28	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
29	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
30	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
31	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
32	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
33	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
34	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
35	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
36	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		
37	31/12/18 09:34	<b>Dismantled Parts</b>							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	31/12/18 09:34	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18023160/GCBE2

**Date:** 02/01/2019

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SGQ9858K

**Insured Vehicle No :** SBJ882U

Date of Loss: 24/12/2018

Nature of Claim: TP

Claim No: 9208674401SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGQ9858K**

Make & Model: NISSAN LATIO, 1.5 (A)

Reg. Date: 29/01/2007 (Man. Year: 2006)

Colour: Gold

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HR15076687A

Chassis No: JN1BAAC11Z0004015

Odometer: 245709 km

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 27/12/2018

Date Inspected: 27/12/2018 Inspected At:

Jementah Motor Works - Defu Lane (HQ)  
BLK 14 DEFU LANE 10 #01-406  
Singapore 539195

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Crumpled	0.00 F	*- F
6	2		*REVERSE SENSOR	Broken	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Repair	0.00 F	*- F
12	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LOCK	Bent	0.00 F	*- F
14	1		*BOOTLID RUBBER	Dented	0.00 F	*- F
15	1		*REVERSE CAMERA	* Check	0.00 F	*- F
16	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >