

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cedge.com.sg

Company Registration No: 199508048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Defu
6 Defu Avenue 1
Singapore 539537

Marymount
600 Sin Ming Avenue
Singapore 575733

Our Ref : 305254131

Date : 27.12.18

Time of Fax : _____

AIG

Via Fax : Email

Your Insured : SLR 7916A

Date of Acc : 25.12.18

Attn : Motor Claims Dept:

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHB 29964

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng	Tel no. 62148316 or Hp no. 98240811
Jumari Masudin	Tel no. 62148315 or Hp no. 96355305
Chiang Liat Choon	Tel no. 62148314
Lim Tien Siong	Tel no. 62148398 or Hp no. 96358546
- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an Initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully


for Vice President
Crash Repairs & Claims Recovery

REPAIR ESTIMATE*

DATE 12/27/2018 10:17

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 544.50
	Front Bumper Grille (RH)			\$ 41.60
	Front Bumper Bracket (RH)			\$ 24.60
	Headlamp (RH)			\$ 1,388.00
	Front Fender (RH)			\$ 566.30
	Front Fender Shield (RH)			\$ 174.90
	Front Wheel Hub Cap (RH)			\$ 107.10
	SUB TOTAL			\$ 2,847.00
	LESS 20%			\$ 569.40
	DISCOUNTED TOTAL			\$ 2,277.60
	Front Fender Advertisement Logo (RH)			\$ 100.00
	Front Door Advertisement Logo (RH)			\$ 100.00
	TOTAL			\$ 200.00
	Labour Charge			
	Panel Beating (Repair)			\$ 500.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,430.00
	ESTIMATE TOTAL			\$ 3,907.60
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2018 11:43
Date Of Accident	25/12/2018 17:45
Exact Location Of Accident	T JUNCTION OF SCOTTS RD AND CAIRNHILL RD
Country/State Of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB2996H
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	YEO SANG KAM
NRIC No	S1570227C
Date Of Birth	15/10/1962
Occupation	OUTDOOR
Date Of Driving Pass	02/09/1983
Driving Experience	35 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97826182
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	308A 11-419 ANG MO KIO AVENUE 1
Postcode	561308
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR7916A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEO KONG
NRIC/Passport Number	S0211136E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT LEFT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/2018 @ 12:45hrs. My taxi (A) was travelling along Rouse Rd towards Cavenhill Rd. with no passengers on board. I was on the extreme left lane. while travelling straight. Suddenly, veh (B) 8LR 7916A. on my right side cut into my lane and collided onto my taxi (A) front right portion. My taxi (A) front right portion was damaged. Veh (B) was driven by Mr. Yeo Kong @ Roger Yeo Kong. NRIC no: S021136E. LP no: 8718 9523. NO injury in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

Loke Wei Yiang

24/12/18

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839C

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Lo Wei Yiong

20/12/18

