

INSURANCE

INS. CASE OWNER

WONG KAH

CC 4/AIG1802

3177, Hh3

LKK:

IDAC:

Surveyor:

FALVIN

DOI:

18/1/20

Date / Time:

27/1/19

Registered in Merit:

27/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJB 8662H

Name of Insured:

ONG SHENG HARY

Insured Tel No.:

HP:

Claim No.:

3491714256

Policy No.:

710507088-01

Excess Sec II :SS

D.O.A:

25/1/19

Make / Model:

W56R

Is driver the owner?

(YES / NO)

Nature of Accident:

Place of Accident:

68MG KAYU EAST KOW LANE 3

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: (YES / NO) : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SJC 70424



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

LOHE  
WY



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date / Time

27/1/19

SJC 70424

SJB 8662H

27/1/19

OI VIDEO UPLOADED IN WORKBOOK  
TP LOB IN

24/1/19

CALL TO TP REPAIR.  
TP REPAIR.  
TRANSFERRED TO VIDEO FOOTAGE  
TP VIDEO IN. U/VIC SJC 70424  
UPLOADED IN WORKBOOK

25-1-19

W/ OI DISPUTE TP HAS FAULTY  
BRAKES.

28/01/2020

AIG MAINTAIN RESTORATION  
CALL TO TP TO MAINTAIN RESTORATION.  
TO CLOSING CASE.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

VIC  
Yan

28/01/20

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

4,014.00

( 4

days) Reduction:

63

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Email

Call

Repair Cost:

SS

Loss of Rental (LOR):

SS

—

(

days)

Loss of Use (LOU):

SS

—

(5

x

days)

Loss of Income (LOI):

SS

—

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

—

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/ Independent)

Legal Cost

SS

—

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

—

Name 1:

—

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—

Email

Call

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3510.00

COPY SENT

30/11/2020

Surveyor: Kelvin

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/HS/TP RES/OD RES/EVA/INV/MV  
 To Inspected Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vch: \_\_\_\_\_

(Policy Condition)

Remark: The Vch had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repair: 4 days Rep: Yes or No  
 Lure Strip: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SH C 7042Y Yr Regn: 4 Nov 2016  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / T/G / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai cc 1.6L  
 Colour: Yellow A/C: Insu G / Std / HI / HA  
 Sp. Reading: 410047 T/Radio: Insu O / Std / HI / HA  
 Eng/No: \_\_\_\_\_  
 C/No: KMHCB414AG4085493  
 Gen. Cond: Good / G / Poor / Burnt  
 Steering: Inord / G / Jammed / Leaked / Burnt or  
 Brake: Inord / G / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD G / Rim or  
 Tyre Size: F: 205/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EX/NOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Triangle  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 2 mm R/Bal: 2 mm  
 L/Bal: 2 mm L/Bal: 2 mm  
 D.O.A: 25/12/8 D.O.I: 27/12/8  
 Survey held at: CDGE (Loyang)  
 Des. of Damages: Frl / Rear / O/S / N/S / U/C / Roottop or  
Pen n/s.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PIP + 4,014.00</u>
	<u>(REP: 47,024.42/63%)</u>

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L21: 15

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Insp (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photo

Other




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18023177/K1jb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 27-12-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 8662H	Veh. Inspected	SHC 7042Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/12/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	25/12/2018	Inspection Date	27/12/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## CITYCAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 7042Y

DATE 12/27/2018 10:43

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>X repz</i>			\$ 2,174.90	
	Boot Lid Rubber <i>X sue</i>			\$ 96.50	
	Boot Lid 'H' Emblem <i>- me</i>			\$ 28.70	
	Boot Lid CRDI Plate <i>- me</i>			\$ 27.90	
	Boot Lid Lamp (LH) <i>- oe</i>			\$ 565.60	
	Bootlid Moulding <i>- ct</i>			\$ 85.00	
	Bootlid i40 Emblem <i>- me</i>			\$ 27.90	
	Bootlid Lower Garnish <i>- me</i>			\$ 227.90	
	Rear Bumper <i>Refined</i>			\$ 553.00	
	Rear Bumper Reinforcement <i>X sue</i>			\$ 428.40	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X sue</i>		\$ 80.30	\$ 160.60	
	Rear Bumper Clip 10 pcs <i>- me</i>			\$ 22.00	
	Rear Bumper Bracket (LH) <i>- me</i>			\$ 35.60	
	Rear Bumper Sponge <i>X sue</i>			\$ 103.50	
	Rear Bumper Under Cover <i>- me</i>			\$ 228.00	
	Rear Bumper Reflector Lamp (LH) <i>- me</i>			\$ 30.60	
	Tail Lamp (LH) <i>- me</i>			\$ 697.80	
	Tail Lamp Quarter Panel (LH) <i>X repz</i>			\$ 226.50	
	Rear Panel <i>X repz</i>			\$ 526.70	
	Rear Panel Garnish <i>X sue</i>			\$ 57.70	
	Rear Panel Lower Panel <i>X repz</i>			\$ 495.50	
	Rear Fender (LH) <i>X repz</i>			\$ 2,171.40	
	Rear Fender Inner Lining (LH) <i>X sue</i>			\$ 169.30	
	Rear Fender Air-Duct (LH) <i>X sue</i>			\$ 51.60	
	Rear Windscreen Moulding <i>X me</i>			\$ 28.30	
	<b>SUB TOTAL</b>			<b>\$ 9,220.90</b>	
	<b>LESS 20%</b>			<b>\$ 1,844.18</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 7,376.72</b>	
	Boot Lid Comfort Logo & Tel No. Sticker <i>- me</i>			\$ 30.00	Nett
	Rear Bumper Reverse Sensor <i>X sue</i>			\$ 135.70	Nett
	Rear Bumper Advertisement Logo <i>X sue</i>			\$ 50.00	Nett
	Rear Bumper Rubber Mat <i>X sue</i>			\$ 50.00	Nett
	Rear Windscreen Sealant <i>X sue</i>			\$ 46.00	Nett
				<b>\$ 311.70</b>	
	<b>Labour Charge</b>			<b>800</b>	
	Panel Beating (Repair)			\$ 1,600.00	
	Spray Painting Charge			\$ 1,250.00	1000
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 100.00	30
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	X sue

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Remove/Refix Reverse Sensor			\$ 80.00
	<i>7.4m</i> <i>\$60</i>			
	TOTAL LABOUR			\$ 3,350.00
	ESTIMATE TOTAL			\$ 11,038.42
<p><i>Kalvi 11/16</i></p> <p><i>27/12/18 1250h</i></p> <p><i>4 by,</i></p> <p><i>PIP</i></p> <p><i>Before Post photo</i></p>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.


member of COMFORTDELGRO

Date/Time: 26.12.2018 14:10 Page : 1

Team:	ARC Repair TP(CFS0)1	JOB CARD	Sales Order:	JO NO: 305254132
TOMER		REGN NO:	SHC7042Y	MILEAGE
MS	CITYCAB PTE LTD	MAKE :	HYUNDAI	FUEL
TOMER NO.	7010070	MODEL	I-40	E 1/2 F
RESS	383 SIN MING DRIVE	YR OF MANU	04.03.2016	DATE/TIME IN
	Singapore SINGAPORE 575717	CHASSIS CODE	KMHLB41UMGU085493	25.12.2018 16:55
(R)	65551188			TARGET DATE
(P)				COMPLETION DATE/TIME
OUNT CARD NO.				

JOB DESCRIPTION

Accident Date: 25.12.2018  
NATURE: 3P 25.12.2018

S/NO	LABOR CODE	DESCRIPTION
		

CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

Acknowledgement Slip	Exit Pass
Vehicle No.: SHC7042Y CHIANG	Vehicle No.: SHC7042Y
Name of Service Advisor	Name of Service Advisor
Signature/Date	Signature/Date
returned to Service Reception upon collection	To be kept by Security Guard

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 3,350.00
	ESTIMATE TOTAL			\$ 11,038.42
<p>Kalvi 11/16</p> <p>✓ 27/12/18 1250h</p> <p>4 by,</p> <p>P/P</p> <p>Betre Post phb</p> <div style="border: 1px solid black; padding: 5px; transform: rotate(-10deg); margin-top: 20px;"> <p>URGENT - Compensation notice              The following information is being provided to you as it may be relevant to your claim.              It is important that you take action quickly to ensure that you are able to recover your costs.              Please contact us immediately if you have any queries or require further assistance.              We will be happy to help you.</p> </div>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305254132  
Date : 05/01/19

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK  
Attn : KALVIN  
Vehicle Reg No. : SHC7042Y  
Fax :  
25/12/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SJB8662H
  2. The finalized amount shall be:
    - (a) Spare Parts after List discount \$2,054.00
    - (b) Labour Charges \$1,960.00
    - Total for Part-By-Part Repair Cost \$4,014.00**
    - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \_\_\_\_\_
  3. Estimated normal period for repairs: 4 working days.
  4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
  5. Thank you for your assistance.  
  
Signature : \_\_\_\_\_  
Name : CHIANG  
Tel : 62148314  
Fax : 65468156
- We confirm the estimates and finalized amount  
  
Signature : \_\_\_\_\_  
Name : KALVIN  
Date : 20/1/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.48			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305254132  
 REGN NO : SHC7042Y  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 04.03.2016  
 DATE/TIME IN : 25.12.2018 16:55  
 ACCIDENT DATE : 25.12.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0103-0800-G	I40VC SYMBOL MARK-TRUNK L	1	28.70	20.00	22.96
0002	04-01-0103-0787-G	I40VC EMBLEM-I40	1	27.90	20.00	22.32
0003	04-01-0103-0786-G	I40VC EMBLEM-CRDI	1	27.90	20.00	22.32
0004	04-01-0103-0784-G	I40VC MLDG-BACK PANEL	1	227.90	20.00	182.32
0005	04-01-0103-0785-G	I40VC MLDG-CR PIECE	1	85.00	20.00	68.00
0006	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40
0007	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60
0008	04-01-0103-0907-G	I40VC BRKT ASSY-RR BUMPER	1	35.60	20.00	28.48
0009	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40
0010	04-01-0103-0851-G	I40VC REFLECTOR/REFLEX AS	1	30.60	20.00	24.48
0011	04-01-0103-0581-A	I40VC LAMP ASSY-RR COMB O	1	697.80	20.00	558.24
0012	04-01-0103-0584-G	I40V2 LAMP ASSY-RR COMB I	1	565.60	20.00	452.48
0013	28-01-0103-0009-A	(I40)REAR BOOT LOGO CCTPL	1	15.00	2.00-	15.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305254132  
REGN NO : SHC7042Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 04.03.2016  
DATE/TIME IN : 25.12.2018 16:55  
ACCIDENT DATE : 25.12.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 28-01-0103-0010-A (I40)REAR BOOT TEL NUMBER 1 15.00 0.20 15.00

SUB-TOTAL : 2,054.00

## JOB NATURE

0000 L PANEL BEATING 800.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA 1000.00

0002 17-01 CHECK ALL LIGHTING 20.00

0003 20-00 TUFF COAT ON AFFECTED PARTS. 30.00

0004 20-02 REMOVE/REFIX DOOR PARTS TO ASSIST REP 50.00

0005 23-01 TOWING FEE 60.00

SUB-TOTAL : 1,960.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305254132  
REGN NO : SHC7042Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 04.03.2016  
DATE/TIME IN : 25.12.2018 16:55  
ACCIDENT DATE : 25.12.2018

JOB / PARTS DESCRIPTION


QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,014.00

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

- SHC7042Y VS SJB8662H (AIG) THIRD PARTY CLAIM

From: Chin, Lee-Ying  
To: assignments, admin-a@kkauto.com  
Cc: Fong, Andy-SY  
Sent: 27/12/2018 11:35:54 AM  
Attachments:  [img-727112652-0001.pdf](#)

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel: 65 6419 1947

Lee Ying.Chin@aig.com | [www.aig.sg](http://www.aig.sg)

11:39am @ 27/12/18  
Person @ Chang  
vehicle in  
SURE @ Kelvin

---

From: Chiang Liat Choon [mailto:[chianglc@cdge.com.sg](mailto:chianglc@cdge.com.sg)]  
Sent: Thursday, December 27, 2018 11:32 AM  
To: AIG SGP, Claims-Survey  
Subject: Fw: SHC7042Y VS SJB8662H (AIG) THIRD PARTY CLAIM

Dear Sir,

Attached herewith repair estimate & via.

Best Regards

Chiang Liat Choon

Tax: Crash Repair ComfortDelGro Engineering Pte Ltd

Off: 62148314 Fax: 65468156

---

From: ApeosPort-IV C5570 <[sbs-singnalling@sbstransit.com.sg](mailto:sbs-singnalling@sbstransit.com.sg)>  
Sent: Thursday, 27 December 2018 11:26 AM  
To: Chiang Liat Choon  
Subject: Scan Data from CDG\_LO\_AW\_A5570

Number of Images: 10

Attachment File Type: PDF

Device Name: ApeosPort-IV C5570

Device Location:

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and promptly delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 28 January, 2020 10:07 AM  
**To:** Kazali Haji Selahudin  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** RE: SHC 7042Y and SJB 8662H on 25/12/2018 \_ LKK REF CC4/AIG18023177/K1hb3  
**Attachments:** SHC7042Y (251218).mp4

Without Prejudice

Dear Kazali,

We refer further to the below email.

Please be informed that our principal had further reviewed the matter and still maintained our position.

Our principal is still in the view that our Insured is not liable of this accident as your client stopped without any reason thus causing the collision.

As such, we will close off the matter.

Thank you.



*«Wishing you a Happy and Prosperous Lunar New Year»*

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK**

Public  
Company  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Joy Irene (LKKAUTO)

---

**From:** Kazali Haji Selahudin <kazali@cdge.com.sg>  
**Sent:** Wednesday, 24 April 2019 11:01 AM  
**To:** Joy Irene (LKKAUTO)  
**Cc:** Admin A; CS A Team  
**Subject:** Re: SHC 7042Y and SJB 8662H on 25/12/2018

**Importance:** High

Dear Joy,

We regret that we are **unable to agree with you to compare both cases**. It is clearly evident that your principal's insured for the cited case (ref : SH 6354Y/ SLQ4888Y/ 09/12/2017) had the intent to cause an accident (I have viewed the full footage). As per BOLA, your principal's insured is clearly liable towards our claims for this matter.

Alternatively, kindly let us have your principal insured's VF for us to review this matter. In the interim, we are still seeking 100% against your principal's insured. We had gathered from our driver that he **DID NOT lodge any police report** as no one was injured. His taxi was stalling prior to the collision thus he had no intentions to cause an accident. Please let us have your response urgently. Thank you.

Best Regards

*Kazali Hj Selahudin*

Claims Department / ComfortDelGro Engineering Pte Ltd

Off: 6214 8736 / Fax: 6214 1843

---

**From:** Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>  
**Sent:** Wednesday, 24 April 2019 10:31 AM  
**To:** Kazali Haji Selahudin  
**Cc:** Admin A; CS A Team  
**Subject:** SHC 7042Y and SJB 8662H on 25/12/2018

WITHOUT PREJUDICE

Dear Kazali,

We refer to the subject and to our telephone conversation earlier.

We have a similar case with your good-office M/s CDGE (ref : SH 6354Y/ SLQ4888Y/ 09/12/2017) In this particular case, our insured vehicle was in-front and our driver abruptly braked causing your taxi to hit our insured vehicle from the rear. We rejected your claim based on BOLA 27 head-to-rear and your good-office appealed citing a precedent high court case as follows:

"You may refer to a similar High Court case, *Tong Khing Kia & Anor v Yeo Kong Boon [1991] 2 MLJ 101*: High Court found the front car driver 100% liable for creating a dangerous situation which was the cause of the accident. Chao Hick Tin J (as he then was) added that "it does not follow that in the case of a front-to-rear collision, the vehicle that followed behind must necessarily be negligent to some extent".

In view of this, our principal gave due consideration and settled your claim.

Now, for the same scenario with SHC 7042Y, however, this time, your taxi was in-front which made a series of attempt to brake and made an abrupt braking causing the collision. We would like to apply the cited precedent by your good-office that "the front car driver 100% liable for creating a dangerous situation which was the cause of the accident. It does not follow that in the case of a front-to-rear collision, the vehicle that followed behind must necessarily be negligent to some extent".

As spoken, we are pending instruction from our principal and pending traffic police investigation result.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd (Registration No. 199506048W)

---



## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Tuesday, 28 January, 2020 9:50 AM  
**To:** Md Noor, Norsiah  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim - LKK REF CC4/AIG18023177/K1hb3

Dear Norsiah,

We refer to your below email and the contents were noted.

We will maintain position and rejection to TP and will close off and upload our report in merimen.

Thank you.



*“Wishing you a Happy and Prosperous Lunar New Year”*

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Md Noor, Norsiah [<mailto:Norsiah.MdNoor@aig.com>]  
**Sent:** Tuesday, 28 January, 2020 9:44 AM  
**To:** Vic (LKKAuto)  
**Cc:** Admin A  
**Subject:** RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim - LKK REF CC4/AIG18023177/K1hb3

Dear Vic,

Please maintained rejection.

Third party taxi brake abruptly without any reason.

Thank you

Kind regards  
Norsiah

Norsiah Md Noor

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419-1606

[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)



Follow us:



IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Vic (LKKAUTO) [<mailto:vicalpeh@lkkauto.com>]

**Sent:** Tuesday, November 5, 2019 12:13 PM

**To:** Md Noor, Norsiah <[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

**Subject:** [EXTERNAL] RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim - LKK REF CC4/AIG18023177/K1hb3

This message is from an external sender; be cautious with links and attachments.

Without Prejudice

Dear Norsiah,

We refer to your below email.

Please be informed that TP insisted to follow BOLA 27 on this matter and provided a copy of their client's video footage (see attached email).

Kindly advise further instruction.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Md Noor, Norsiah [<mailto:Norsiah.MdNoor@aig.com>]

**Sent:** Thursday, 25 April, 2019 4:59 PM

**To:** Joy Irene (LKKAuto)

**Cc:** Admin A; CS A Team

**Subject:** RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim

Dear Joy,

Please proceed to reject third party claim based on third party made an abrupt braking.

Please also request for taxi front video footage for our further assessment on this accident.

Thank you

Kind regards

Norsiah

**Norsiah Md Noor**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16 Singapore 079120

Tel: +(65) 6419-1606

[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)



**Celebrating 100 Years:**  
Visit [100.aig](http://100.aig) to learn more.

Follow us:



**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]  
**Sent:** Wednesday, April 24, 2019 10:20 AM  
**To:** Md Noor, Norsiah <Norsiah.MdNoor@aig.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>  
**Subject:** [EXTERNAL] RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim

This message is from an external sender; be cautious with links and attachments.

Dear Nor,

We refer to the subject. To date, our insured did not furnish us any PIR.

We have a similar case with CDGE (ref : TP/2066196142SG/ SLQ4888Y/ 09/12/2017) In this particular case, our insured vehicle was in-front and our driver abruptly braked causing the taxi to hit our insured vehicle from the rear. We rejected CDGE's claim based on BOLA 27 head-to-rear and TP appealed citing precedent high court case as follows:

"You may refer to a similar High Court case, *Tong Khing Kia & Anor v Yeo Kong Boon [1991] 2 MLJ 101*: High Court found the front car driver 100% liable for creating a dangerous situation which was the cause of the accident. Chao Hick Tin J (as he then was) added that "it does not follow that in the case of a front-to-rear collision, the vehicle that followed behind must necessarily be negligent to some extent".

In view of this, we have settled TP claim.

Now, for ref: 3491272485SG , it was the taxi (in-front) who made a series of attempt to brake and made an abrupt braking causing our insured to hit TP from behind. We would like to apply the cited precedent by CDGE that "the front car driver 100% liable for creating a dangerous situation which was the cause of the accident. It does not follow that in the case of a front-to-rear collision, the vehicle that followed behind must necessarily be negligent to some extent".

Videos uploaded in Merimen.

Kindly let us have your view and opinion whether we are to deny liability based on the above.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Monday, 28 January 2019 12:10 PM  
**To:** 'Md Noor, Norsiah' <[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com)>  
**Subject:** RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim

Hi Nor,

Spoken to insured Mr. Barry. He is disputing liability.

OI video uploaded in Merimen.

We are currently pending OI to respond if there is any PIR against taxi driver.

Thank you.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

---

**From:** Md Noor, Norsiah [<mailto:Norsiah.MdNoor@aig.com>]  
**Sent:** Thursday, 24 January 2019 6:05 PM  
**To:** Joy Irene (LKKAuto) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>  
**Subject:** RE: OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim

Dear Joy,

Have you contacted insured?

Thank you

Kind regards  
Norsiah

**Norsiah Md Noor**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)



**Celebrating 100 Years:**  
Visit [100.aig](http://100.aig) to learn more.

Follow us:



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Zawaye, Norsazani  
**Sent:** Thursday, December 27, 2018 5:16 PM  
**To:** Md Noor, Norsiah  
**Subject:** OD / 3491272485SG / SHC7042Y - OI Inquiry on TP claim

Hi Norsiah,

OI called in and ask regards the TP claim.

Kindly assist to called oi and advise accordingly.

OI have video footage in merimen.

Thanks & Regards,

Norsazani Zawaye  
AIG  
Claims Adjuster | Express Auto Claims  
Singapore Claims | AIG Shared Services

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref : CC18120708/ SHC7042Y /KS(st)

Date : 22-Jan-19

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**CHARTIS Buliding**  
**78 Shenton Way**  
**#07-16**  
**Singapore 079120**

**Attn : Motor Claims Department WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC7042Y YOUR INSURED**  
**SJB8662H AND OTHER ON 25.12.18**

We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor vehicle no: SHC7042Y which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SJB8662H we are submitting these claim for your consideration on behalf of the claimants.

**TAXI OWNER'S CLAIM**

1	Cost of Repair	\$ 4,294.98
2	5 days Loss of Rental @ \$ 115.00 per day	\$ 575.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ -
5	GIA / Police Report Fees	\$ 7.49
6	Towing / Medical / Transportation Fees	\$ -
<b>Sub Total :</b>		<b>\$ 4,877.47</b>

**HIRER'S CLAIM**

7	5 days Loss of Income @ \$ 80.00 per day	\$ 400.00
<b>Total Claims :</b>		<b>\$ 5,277.47</b>

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.  
b) LTA search slip/s of : SJB8662H  
c) GIA / Police report/s of : SHC7042Y  
d) Letter of authority from owner / hirer / operator  
( ) Witness statement/s ( ) Certificate of Insur ( x ) Rental Rate letter  
( x ) Photograph/s of Accident Scene ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully  
*Kazali Hj Selahudin*  
CDGE Taxi Claims Department  
Tel : 6214 8736 Fax : 6214 1843 Email : kazali@cdge.com.sg

This is a computer generated letter. No signature is required.

**COMFORTDELGRO**  
**ENGINEERING**

CDGE Taxi Claims Dept ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive 4th Floor 205 Braddell Road Singapore 579701  
Singapore 508969

Mainline +65 8383 8280  
Facsimile +65 8280 9755

www.cdge.com.sg

Company Registration No: 198800000P

Workshops

Braddell  
205 Braddell Road  
Singapore 579701

Loyang  
59 Loyang Drive  
Singapore 508969

Sin Ming  
383 Sin Ming Drive  
Singapore 575717

Pandan  
45 Pandan Road  
Singapore 609296

Ubi  
320 Ubi Road 3  
Singapore 408549

Senoko  
24 Senoko Loop  
Singapore 758156

Sungei Kadut  
7 Sungei Kadut Way  
Singapore 725751

Yishun  
501 Yishun Industrial Park A  
Singapore 768732

A member of

**COMFORTDELGRO**



## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING  
ALONG140 SHC7042Y , SJB8662H  
ALONG SENGKANG EAST RD

ON 25-Dec-18 13:15

I / We

KOH YONG LIT (XU YON... (Hirer) NRIC No.: S8115777D

and/or

WEE TIONG (Relief) NRIC No.: S1788489A

Taxi Number

SHC7042Y

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

26-Dec-2018

Name of Hirer  
Hirer NRICKOH YONG LIT (XU YONG LI)  
S8115777D

Signature :



Address

635A PUNGGOL DRIVE #16-613  
821635

Contact No.

81610704

Name of Relief  
Relief NRICWEE TIONG  
S1788489A

Signature :



Address

613D PUNGGOL DRIVE 03-821  
824613

Contact No.

82336662



GST REG. NO. M2-8921817-3

## TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, CHARLIS BUILDING #08  
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHC7042Y

MAKE  
HYUNDAI

MODEL  
I-40

DATE OF REG  
04.03.2016

CHASSIS CODE  
KMHCB411MCH085493

INV. NO/DATE  
91421706 21.01.2019

JOB NO.  
305254132

ODMETER READING

DATE/TIME IN  
25.12.2018 16:55

Description : 3P 25.12.2018

S/No Part No.

Qty Unit Price Disc Net

### PART REQUISITION

0001	04-01-0103-0800	I40VC SYMBOL MARK-TRUNK L	1	28.70	20.00	22.96
0002	04-01-0103-0787	I40VC HMBLHM-I40	1	27.90	20.00	22.32
0003	04-01-0103-0786	I40VC HMBLHM-CRDI	1	27.90	20.00	22.32
0004	04-01-0103-0784	I40VC MIXT-BACK PANEL	1	227.90	20.00	182.32
0005	04-01-0103-0785	I40VC MIXT-CR PICK	1	85.00	20.00	68.00
0006	04-01-0103-0579	I40VC COVER ASSY-RR BUMPER	1	553.00	20.00	442.40
0007	04-01-0101-0111	HYUNDAI BUMPER COVER CLIP	10	2.20	20.00	17.60
0008	04-01-0103-0907	I40VC BRCT ASSY-RR BUMPER	1	35.60	20.00	28.48
0009	04-01-0103-0738	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40
0010	04-01-0103-0851	I40VC REFLECTOR/REFLEX AS	1	30.60	20.00	24.48
0011	04-01-0103-0581	I40VC LAMP ASSY-RR COMB O	1	697.80	20.00	558.24

1. WHILE TAKING ALL REASONABLE PRECAUTIONS UNDER THE TERMS OF ACCEPTANCE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR DAMAGE OR OTHER PROPERTIES BELONGING TO CUSTOMER AND VEHICLES ARE DRIVEN AND TESTED ON OWNERS' RISK.

2. CUSTOMER SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SIGNAL WITHIN 7 DAYS FROM SUCH DELIVERY. NO NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS OTHERWISE, THE REPAIRS WILL BE TREATED TO HAVE BEEN ACCEPTED BY GOOD ORDER.

3. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN PREPAYMENT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DATE OF PAYMENT OR AFTER 10 DAYS FROM THE REPAIRS, PLUS THE PERIOD OF DEFECT.

4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY DISCREPANCY IMMEDIATELY WITHIN 10 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91421706	4,294.98	

GST REG. NO. M2-8921817-3

## TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, CHARTIS BUILDING #08  
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHC7042Y

INV. NO/DATE  
91421706 21.01.2019

MAKE  
HYUNDAI

JOB NO.  
305254132

MODEL  
I-40

ODOMETER READING

DATE OF REG  
04.03.2016

DATE/TIME IN  
25.12.2018 16:55

CHASSIS CODE  
KMHLB41JMGU085493

S/No	Part No.		Qty	Unit Price	%Disc	Net
0012	28-01-0103-0009	(140)REAR BOOT LOGO COTTEL	1	15.00	0.00	15.00
0013	28-01-0103-0010	(140)REAR BOOT TEL NUMBER	1	15.00	0.00	15.00
0014	04-01-0103-0584	I40V2 LAMP ASSY-RR COMB I	1	565.60	20.00	452.48
SUB-TOTAL:			:			2,054.00

### JOB NATURE

0001	L	PANEL HEATING	800.00		800.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	1,000.00		1,000.00
0003	17-01	CHECK ALL LIGHTING	20.00		20.00
0004	20-00	TUFF COAT ON AFFECTED PARTS	30.00		30.00
0005	20-02	REMOVE/REFIX DOOR PARTS TO ASSIST REP	50.00		50.00
0006	23-01	TOWING FEE	60.00		60.00
SUB-TOTAL:			:		1,960.00

WHILE TAKING ALL REASONABLE PRE CAUTIONS AGAINST FIRE THEFT OR ACCIDENTAL DAMAGE THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CAR OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN WITH THE DRIVER'S OWNERS RISK

CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND REPORT WITHIN 14 DAYS FROM SUCH DELIVERY ANY NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS OTHERWISE THE VEHICLE WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER

INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY PAYMENTS DUE AND OVERDUE TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT I.E. AFTER 14 DAYS FROM THE PRESENT DATE OF THE PERIOD OF DEFAULT

PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91421706	4,294.96	

## TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, CHARTIS BUILDING #08  
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHC7042Y

INV. NO/DATE  
91421706 21.01.2019

MAKE  
HYUNDAI

JOB NO.  
305254132

MODEL  
i-40

ODOMETER READING

DATE OF REG  
04.03.2016

DATE/TIME IN  
25.12.2018 16:55

CHASSIS CODE  
KMHLB41UMGU085493

Items total		4,014.00
Add GST @	7.000 %	280.98
Invoice amount		4,294.98

Issued by : KATHERINETAN 21.01.2019 15:12:36  
Repair type : CPSO/57/57  
Payment type/term: /Credit 30 days

WHILE TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENT DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR LOSS OR DAMAGE TO VEHICLES BELONGING TO CUSTOMERS AND WORKSHOPS ARE LOCATED AT OWNERS' RISK.  
CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS, OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.  
INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND DUE TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT, I.E. AFTER 15 DAYS FROM THE INVOICE FOR THE PERIOD OF DEFAULT.  
PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL THEREAFTER PROCEED AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91421706	4,294.98	

Our Ref: CC18120708



Date: 21 January 2019

## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON                    25/12/2018    @   13:15 hrs  
ALONG                            ALONG SENGKANG EAST RD  
INVOLVING                    SJB8662H

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC7042Y** (the "Taxi"). The Taxi was hired to **KOH YONG LIT (XU YONG LI) IC NO S8115777D** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$115.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SPC 70424  
MILEAGE READING

JING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
		FROM	TO
63	142	1615	2225
50	386	0300	1700
08	188	1415	2240
39	231	0300	1700
53	244	1230	2125
27	470	0300	1410
27	150	1415	2200
06	390	0740	2320
51	444	0830	2315
63	121	0400	0700
85	221	1040	2140

DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
				FROM	TO
23/12/18	Veh	410023	170	0300	0700
28/12/18	Nae	410046	23	1045	1410
29/12	Accident repair	WY	In Out	1655	1030

## Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SJB8662H	25 Dec 2018 / 13:15:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Previous](#)[OK](#)

SNC70424



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/12/2018 13:12
Date Of Accident	25/12/2018 13:15
Exact Location Of Accident	ALONG SENGKANG EAST RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC7042Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

### Driver

Name of Driver	WEE TIONG
NRIC No	S1788489A
Date Of Birth	14/10/1967
Occupation	OUTDOOR
Date Of Driving Pass	03/05/1990
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82336662
Fax Number	
Contact Number	
Email Address	GWEETWEE@GMAIL.COM



Address	613D 03-821 PUNGGOL DRIVE
Postcode	824613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJB8662H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG BAO SHENG
NRIC/Passport Number	S8420463C
Contact Number	97580028
Address	

Postcode


Insurance Company Name

Nature Of Damage

FRT RHT

No. Of Passenger (Including Driver)

### SKETCH PLAN



Along Sengkang East Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

**CITYCAB PTE LTD**  
**SG REG NO. 199502839G**  
 Policyholder's Signature

Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time 26.12.2018@1130HRS

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

Loo Wei Yiong

~~Steve Tan~~

26/12/18

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD  
CO. REG. NO. 199502839C

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Loke Wei Yang

26/12/18



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING





Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018 <a href="#">Edit Reg</a>		27 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$44,014.00</b> <a href="#">Edit Estimates</a>	<b>\$44,014.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Ong BaoSheng, Barry, ID: S8420463C								
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHC7042Y	Date of Loss:	25/12/2018 13:00 - :59 [33 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3491272485SG	Policy/Cover Note No.:	2100507688 (Comprehensive) Coverage: 20/04/2018 - 19/04/2019						
Vehicle Reg. No. (Insured):	SJB8662H	Policy No. (Claimant):	D-18088937MFSH						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 08/01/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHC7042Y (3491272485SG)  
 [SJB8662H]  
 TP  
 CITYCAB PTE LTD  
 Dec 25 2018 1:00PM  
 [Ong BaoSheng, Barry]  
 ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
<b>Video</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	28/01/19 12:07	FROM OI -							Load MP4		
2	05/11/19 11:56	Video - Accident TP VIDEO FOOTAGE (Front)							Load MP4		
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	28/12/18 16:13	Accident Statement From: OD - Reg. No: SJB8662H, Claimant: ONG BAO SHENG, BARRY							Load HTM		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
2	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
3	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
4	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
5	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
6	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
7	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
8	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
9	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
10	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
11	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
12	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
13	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
14	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
15	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
16	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
17	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
18	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
19	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
20	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
21	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
22	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
23	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
24	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
25	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
26	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
27	27/12/18 17:30	General View							Load JPG <input checked="" type="checkbox"/>		
28	28/12/18 18:04	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
29	28/12/18 18:04	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
30	28/12/18 18:04	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
31	28/12/18 18:04	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
32	28/12/18 18:04	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/12/18 15:44	EMAIL FROM AIG DD 27122018		Load PDF
2	27/12/18 15:44	TP EST & GIA REPORT		Load PDF
3	31/12/18 09:25	TP ESTIMATE- MARKED		Load PDF
4	05/11/19 11:02	EMAIL FROM AIG		Load PDF
5	05/11/19 11:28	EMAIL FROM TP		Load PDF
6	28/01/20 09:51	EMAIL FROM AIG		Load PDF
7	28/01/20 09:59	TP LOD		Load PDF
8	28/01/20 10:08	EMAIL TO TP		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18023177/K1HS3Q2

Date: 04/02/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507688  
 Claimant SHC7042Y Insured Vehicle No : SJB8662H  
 Vehicle No : SHC7042Y  
 Date of Loss: 25/12/2018 Nature of Claim: TP Claim No: 3491272485SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC7042Y  
 Make & Model: HYUNDAI I40, 1.7 D (A) Engine No: D4FDDU395096  
 Reg. Date: 04/03/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU085493  
 Colour: Yellow Odometer: 410047 km  
 Engine Capacity: 1685 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Triangle 7 mm Rear Left Side: Triangle 7 mm  
 Front Right Side: Triangle 7 mm Rear Right Side: Triangle 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,688.42	2,054.00	5,634.42	73.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,960.00	1,450.00	42.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,098.42</b>	<b>4,014.00</b>	<b>7,084.42</b>	<b>63.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>776.89</b>	<b>280.98</b>	<b>495.91</b>	<b>63.83</b>
<b>Nett Amount (S\$)</b>	<b>11,875.31</b>	<b>4,294.98</b>	<b>7,580.33</b>	<b>63.83</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 27/12/2018  
 Date Inspected: 27/12/2018 Inspected At: ComfortDelGro Engineering Pte Ltd  
 (Loyang)  
 59 Loyang Drive  
 Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	2,174.90 FL	*- FL
2	1		*BOOT LID RUBBER	Serviceable	96.50 FL	*- FL
3	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
4	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
5	1		*BOOT LID LAMP (LH)	Cracked	565.60 FL	*565.60 FL
6	1		*BOOTLID MOULDING	Cut	85.00 FL	*85.00 FL
7	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
8	1		*BOOTLID LOWER GARNISH	Cracked	227.90 FL	*227.90 FL
9	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	*- FL
11	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Serviceable	160.60 FL	*- FL
12	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
13	1		*REAR BUMPER BRACKET (LH)	Cracked	35.60 FL	*35.60 FL
14	1		*REAR BUMPER SPONGE	Serviceable	103.50 FL	*- FL
15	1		*REAR BUMPER UNDER COVER	Cracked	228.00 FL	*228.00 FL
16	1		*REAR BUMPER REFLECTOR LAMP (LH)	Cracked	30.60 FL	*30.60 FL
17	1		*TAIL LAMP (LH)	Cracked	697.80 FL	*697.80 FL
18	1		*TAIL LAMP QUARTER PANEL (LH)	Repair	226.50 FL	*- FL
19	1		*REAR PANEL	Repair	526.70 FL	*- FL
20	1		*REAR PANEL GARNISH	Serviceable	57.70 FL	*- FL
21	1		*REAR PANEL LOWER PANEL	Repair	495.50 FL	*- FL
22	1		*REAR FENDER (LH)	Repair	2,171.40 FL	*- FL
23	1		*REAR FENDER INNER LINING (LH)	Serviceable	169.30 FL	*- FL
24	1		*REAR FENDER AIR-DUCT (LH)	Serviceable	51.60 FL	*- FL
25	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.30 FL	*- FL
26	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
27	1		*REAR BUMPER REVERSE SENSOR	Serviceable	135.70 FS	*- FS
28	1		*REAR BUMPER ADVERTISEMENT LOGO	Not Necessary	50.00 FS	*- FS
29	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
30	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,532.60</b>	<b>2,560.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,844.18</b>	<b>506.00</b>
<b>Total Parts (\$\$)</b>	<b>7,688.42</b>	<b>2,054.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING (REPAIR)	New	1,600.00	800.00
2	SPRAY PAINTING CHARGE	New	1,250.00	1,000.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	100.00	30.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	50.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
7	REMOVE /REFIX REVERSE SENSOR	New	80.00	0.00
8	TOWING	New	60.00	60.00
Gross Labour Cost (S\$)			3,410.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >