

ASS. REC. BY:

REF:

CS/CTU8023181/Urbn2

Special Instruction:

S. J. V. J. O. Y.

M. J. B. J. O. Y.

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CIL

Date/Time:

27/12/2018 3:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLC 2194C

Insured:

SKX 2012X

at Workshop m/s

Slytech Auto

Tel:

9685 8843

of

2 Kaki Bukit Ave 2 #01-02

Policy No:

Claim No:

SKX 2012X

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

27/12/2018 4:02pm

Person Contacted:

Winston

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 2194C - X

SKX 2012X - X

9/1/19

@ 3:16pm Catherine Thia said claim no can indicate their OI vehicle

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLC2194C

at Workshop m/s stytech

of SKX2012X

Insured:

Policy No.:

Claims No.:

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 58

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC2194C Yr Regn: 5116

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Suzuki CIAK C.C. 1373

Colour: silver A/C: Insured / Std / Nil / NA

Sp. Reading: 51599 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/Nor: MMSCVC41500100038

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/55-216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 21/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Body.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 43584

7 yrs Veh. Rep 750

3/1/18 confirmed n/s 45350 with wiston. (Red 667, 539)

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 9/1 typist

Report Format : merimen

Lump Sum / I.B.I. (\$) 5350/-

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

220

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Thursday, 27 December 2018 3:52 PM
To: Admin A; 'assignments'
Cc: stytechent@singnet.com.sg
Subject: FW: SURVEY INVITATION for accident on 21/12/18 Along Middle Road, involving vehicle SLC2194C & SKX2012X.
Attachments: SLC2194C_21122018.pdf

Dear LKK oic

Please conduct PRI inspection on w/o prejudice basis

Thanks

Catherine Thia

Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI
Sent: Thursday, 27 December, 2018 11:11 AM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: SURVEY INVITATION for accident on 21/12/18 Along Middle Road, involving vehicle SLC2194C & SKX2012X.

From: Stytech Auto Pte Ltd [<mailto:stytechent@singnet.com.sg>]

Sent: Thursday, December 27, 2018 10:57 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Feedback of China Taiping Insurance <feedback@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>

Subject: SURVEY INVITATION for accident on 21/12/18 Along Middle Road, involving vehicle SLC2194C & SKX2012X.

Dear Sir/Madam,

Any arrangement for this case?

Already more than 2 working days.

Please revert

Best Regards

Winston Teo

Stytech Auto Pte Ltd

Email: stytechent@singnet.com.sg | Mobile: +65 9685 8843 | Fax: +65 6445 3310

Address: 2 Kaki Bukit Ave 2 #01-02/ #02-30, Kaki Bukit Autohub, Singapore 417921



STYTECH AUTO PTE LTD

From: Stytech Auto Pte Ltd <stytechent@singnet.com.sg>

Sent: Wednesday, December 26, 2018 10:13 AM

To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>

Cc: 'Lucas Lee' <lucas.lee@sg.cntaiping.com>; 'feedback@sg.cntaiping.com' <feedback@sg.cntaiping.com>

Subject: SURVEY INVITATION for accident on 21/12/18 Along Middle Road, involving vehicle SLC2194C & SKX2012X.

Dear Sir/Madam,

Any assignment for this case (SLC2194C)?

Please revert

Best Regards

Winston Teo

Stytech Auto Pte Ltd

Email: stytechent@singnet.com.sg | Mobile: +65 9685 8843 | Fax: +65 6445 3310

Address: 2 Kaki Bukit Ave 2 #01-02/ #02-30, Kaki Bukit Autohub, Singapore 417921



STYTECH AUTO PTE LTD

From: Stytech Auto Pte Ltd <stytechent@singnet.com.sg>

Sent: Saturday, December 22, 2018 12:38 PM

To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; 'Lucas Lee' <lucas.lee@sg.cntaiping.com>
Subject: SURVEY INVITATION for accident on 21/12/18 Along Middle Road, involving vehicle SLC2194C & SKX2012X.

Dear Claims Officer

We would like to invite your surveyor to our workshop to survey our vehicle SLC2194C whom involved an accident with your insured SKX2012X.

Note: Vehicle in workshop

Location : **2 Kaki Bukit Ave 2 #01-02**
Kaki Bukit Autohub S(417921)
(enter via Kaki Bukit Road 2) Heavy Vehicle Workshops
Contact Person : **Mr. Winston Teo**
Hp. No. 9685 8843

Kindly reply to this email or contact me at 96858843 to confirm.

Thank You

Best Regards

Winston Teo

Hp 96858843

Stytech Auto Pte Ltd

2 Kaki Bukit Ave 2 #01-03

Kaki Bukit Autohub Singapore 417921

TEL : 64448125

Fax : 64453310

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2077G
Vehicle Details	
Vehicle No.:	SLC2194C
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2018
Vehicle Make:	SUZUKI
Vehicle Model:	CIAZ 1.4 GLS AT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K14BS128528
Chassis No.:	MMSCVC41S00100038
Maximum Power Output:	68.0 kW (91 bhp)
Open Market Value:	\$16,745.00
Original Registration Date:	05 May 2016
First Registration Date:	05 May 2016
Transfer Count:	0
Actual ARF Paid:	\$11,745.00 5872
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 May 2026
PARF Rebate Amount:	\$8,808.00
Intended COE Rebate Details	
COE Expiry Date:	04 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$34,776.00
Total Rebate Amount:	\$43,584.00

The information contained herein is correct as at 27 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/12/2018 10:49
Date Of Accident	21/12/2018 15:55
Exact Location Of Accident	ALONG MIDDLE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC2194C
Insured/Policyholder	
Name Of Registered Owner	CAR CLUB PTE LTD
Co Reg No	200912077G
Email Address	NEWWIT@YAHOO.COM
Mobile Phone No	(LOCAL) +65-81571098
Alternative Phone No	OFFICE-81571098

Vehicle Particulars

Manufacturer	SUZUKI
Model	OTHERS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5069447486-03
Cover Note Number	

Driver

Name of Driver	SOH SEE KONG
NRIC No	S1826174Z
Date Of Birth	26/05/1967
Occupation	INDOOR
Date Of Driving Pass	19/12/2001
Driving Experience	17 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81571098
Fax Number	
Contact Number	
E Mail Address	NEWWIT@YAHOO.COM

Address	BLK 643 WOODLANDS RING ROAD #04-52
Postcode	730643
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX2012X
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEY PIAK KEE
NRIC/Passport Number	S7671628E
Contact Number	91706476
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

22 DEC 2018

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NG WING KIN JAMES
S7927881E

Vehicle:

SLC2194C

Make & Model:

Suzuki Ciaz

Chassis No:

MMSCVC41S00100038

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Front Right sport rim			8450.00	SN 11X
2	Right Wing Mirror			8418.00	2X
3	Right Front Door			8958.00	30/50/50 ✓
4	Right Front Door Sticker		*	822.00	SN 24 ✓
5	Right Front Door Chrome Moulding			858.00	24 ✓
6	Right Front Door Hinge (Top & Bottom)	2	838.00	876.00	11X
7	Right Front Door Lock			8178.00	700/500 ✓
8	Right Front Door Rubber (inner)			865.00	24 ✓
9	Right Front Door Inner trim board			8355.00	80X
10	Right Front Door Inner trim board clips		*	835.00	SN 24 ✓
11	Right Front Power Window Gear Assy			8253.00	50/50 ✓
12	Right ^{Rear} Door Center Pillar			8492.00	2X
13	Right Rear Door			8856.00	30/50 ✓
14	Right Rear Door Sticker		*	822.00	SN 24 ✓
15	Right Rear Door Chrome Moulding			892.00	24 ✓
16	Right Rear Door Hinge (Top & Bottom)	2	838.00	876.00	11X
17	Right Rear Door Lock			8195.00	800X
18	Right Rear Door Rubber			868.00	24 ✓
19	Right Rear Door Inner trim board			8480.00	24/24 ✓
20	Right Rear Door Inner trim board clips		*	835.00	SN 24 ✓
21	Right Rear Power Window Gear Assy			8185.00	50/50 ✓
22	Right Rocket Panel			8710.00	2.30 ✓
23	Right Side Skirt		*	8480.00	SN 24 ✓

102

6559

24	Right Rear Fender			\$ 852.00	2x
25	Rear Bumper			\$ 354.00	2x
26	Rear Bumper Retainer			\$ 22.00	5x /
27	Rear Bumper Clips		✓	\$ 30.00	SN 2x /
28	Right Rear Sport Rims			\$ 450.00	SN 1x 350 S.N

1 set Car club sticker

new 30 S.N /

1738

p-3925
 152
 p-3336.25
 S.N-1004.00
 1 down - 2350.00
 6690.25

Labour					
1	Labour to Transfer Front Door			\$ 150.00	60
2	Labour to Transfer Rear Door			\$ 150.00	60
3	Remove & Refix Rear Windscreen			\$ 120.00	17X
4	Check Wiring			\$ 100.00	30
5	Anti Rust Proofing			\$ 100.00	✓
6	Panel Beating			\$ 1,200.00	1000
7	Paint To putty & spray painting			\$ 1,400.00	1100

3320

11,517

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #02-30
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

I hereby acknowledge and agree to notify the Insurer of the following:

- I will not proceed after spray painting
- I will not proceed until I am satisfied with the resurvey
- I will not proceed until I am satisfied with the confirmation
- I will not proceed until I am satisfied with the "Without Prejudice" basis
- I will not proceed until I am satisfied with the approval
- I will not proceed until I am satisfied with the resurvey and approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Not Acknowledged
 2/5/12
 1/5/12 350/-
 6 days
 27/12/11
 the repairer

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118023181/UVBN2

Date: 11/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLC2194C	Insured Vehicle No :	SKX2012X
Date of Loss:	21/12/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2194C	Engine No:	K14BS128528
Make & Model:	SUZUKI CIAZ, 1.4 GLS (A)	Chassis No:	MMSCVC41S00100038
Reg. Date:	05/05/2016 (Man. Year: 2015)	Odometer:	51599 km
Colour:	Silver		
Engine Capacity:	1373 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R16	Rear Tyre Size:	195/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,297.00	4,340.25	3,956.75	47.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,350.00	870.00	27.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,517.00	6,690.25	4,826.75	41.91
Approved Total (Overridden) (S\$)		5,350.00		
(S\$)	11,517.00	5,350.00	6,167.00	53.55
+ GST 7.00/7.00% (S\$)	806.19	374.50	431.69	53.55
Nett Amount (S\$)	12,323.19	5,724.50	6,598.69	53.55

INSPECTION

Date of Assignment: 08/01/2019

Date Inspected: 27/12/2018 Inspected At:

STYTECH AUTO PTE LTD
2 KAKI BUKIT AVENUE 2 #02-30
KAKI BUKIT AUTOHUB
SINGAPORE 417921

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2019)	
Parts:	N/A	SUZUKI CIAZ 1.4 GLS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC2194C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RIGHT WING MIRROR	Repair	418.00 F	*- FL
2	1	*RIGHT FRONT DOOR	Badly Dented/Bent	958.00 F	*958.00 FL
3	1	*RIGHT FRONT DOOR CHROME MOULDING	Necessary	58.00 F	*58.00 FL
4	2	*RIGHT FRONT DOOR HINGE (TOP & BOTTOM)	Not Necessary	76.00 F	*- FL
5	1	*RIGHT FRONT DOOR LOCK	Twisted/Shorted	178.00 F	*178.00 FL
6	1	*RIGHT FRONT DOOR RUBBER (INNER)	Necessary	65.00 F	*65.00 FL
7	1	*RIGHT FRONT DOOR INNER TRIMBOARD	Serviceable	355.00 F	*- FL
8	1	*RIGHT FRONT POWER WINDOW GEAR ASSY	Bent/Jammed	253.00 F	*253.00 FL
9	1	*RIGHT REAR DOOR CENTER PILLAR	Repair	492.00 F	*- FL
10	1	*RIGHT REAR DOOR	Badly Dented	856.00 F	*856.00 FL
11	1	*RIGHT REAR DOOR CHROME MOULDING	Necessary	92.00 F	*92.00 FL
12	2	*RIGHT REAR DOOR HINGE (TOP & BOTTOM)	Not Necessary	76.00 F	*- FL
13	1	*RIGHT REAR DOOR LOCK	Serviceable	195.00 F	*- FL
14	1	*RIGHT REAR DOOR RUBBER	Necessary	68.00 F	*68.00 FL
15	1	*RIGHT REAR DOOR INNER TRIMBOARD	Deformed/Cracked	480.00 F	*480.00 FL
16	1	*RIGHT REAR POWER WINDOW GEAR ASSY	Bent/Jammed	185.00 F	*185.00 FL
17	1	*RIGHT ROCKET PANEL	Badly Dented	710.00 F	*710.00 FL
18	1	*RIGHT REAR FENDER	Repair	852.00 F	*- FL
19	1	*REAR BUMPER	Repair	354.00 F	*- FL
20	1	*REAR BUMPER RETAINER	Bent	22.00 F	*22.00 FL
21	1	*RIGHT FRONT DOOR STICKER	Necessary	22.00 FS	*22.00 FS
22	1	*RIGHT REAR DOOR STICKER	Necessary	22.00 FS	*22.00 FS
23	1	*RIGHT REAR DOOR INNER TRIMBOARD CLIPS	Necessary	35.00 FS	*35.00 FS
24	1	*RIGHT FRONT DOOR INNER TRIMBOARD CLIPS	Necessary	35.00 FS	*35.00 FS
25	1	*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1	*RIGHT REAR SPORT RIMS	Cut	450.00 FS	*350.00 FS
27	1	*SET CAR CLUB STICKER	Necessary	30.00 FS	*30.00 FS
28	1	*RIGHT SIDE SKIRT	Torn	480.00 FS	*480.00 FS
29	1	*FRONT RIGHT SPORT RIM	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 8,297.00 4,929.00
 - List Item Discount on L Items 0.00/15.00% (\$\$) 0.00 588.75

Total Parts (\$\$) 8,297.00 4,340.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO TRANSFER FRONT DOOR	New	150.00	60.00
2	LABOUR TO TRANSFER REAR DOOR	New	150.00	60.00
3	REMOVE & REFIX REAR WINDSCREEN	New	120.00	-
4	CHECK WIRING	New	100.00	30.00
5	ANTI RUST PROOFING	New	100.00	100.00
6	PANEL BEATING	New	1,200.00	1,000.00
7	TO PUTTY & SPRAY PAINTING	New	1,400.00	1,100.00
Gross Labour Cost (\$\$)			3,220.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >