

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.12.2018

Time: 12:18:59

Page: 1/2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

LKR-Kalvin

JOB NO : 305254062
REGN NO : SHD6816H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 23.04.2015
DATE/TIME IN : 26.12.2018 10:55
ACCIDENT DATE : 21.12.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G	FRONT BUMPER	1	544.50	25.00	408.37	/
0002 04-01-0103-0639-G	FRT BUMPER SIDE BRKT LH	1	24.60	25.00	18.45	?
0003 04-01-0103-0781-A	HEADLAMP LH	1	1,388.00	25.00	1,041.00	/
0004 04-01-0103-0574-A	FRT FENDER LH	1	566.30	25.00	424.72	X repair
0005 04-01-0103-0737-G	FRT BUMPER GRILLE LH	1	51.70	25.00	38.77	/

SUB-TOTAL : 1,931.31

JOB NATURE

0000 L	PANEL BEATING	480.00	400
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00	400
0002 17-01	CHECK ALL LIGHTING	40.00	20
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	X

SUB-TOTAL : 960.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.12.2018

Time: 12:18:59

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305254062
REGN NO : SHD6816H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 23.04.2015
DATE/TIME IN : 26.12.2018 10:55
ACCIDENT DATE : 21.12.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,891.31

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalvin 16/11/18
26/12/18 12356
3 bps.
4/5
After Repair photo

hence notify
by painting
resurvey
"no prejudice" basis
and
Insurance Company

Acknowledged by Repairer
Signature:
Date: