COMFORTDELGRO FNCINFFRINC

Our Ref: 305254790

Date: 27.12.2018

Time of Fax: 17456

ALG

Via Fax: ALCSP_clains

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Your Insured: SLG 75762

www.cdge.com.sg

Date of Acc: 26.12.2018 Company Registration No: 199506048W

Workshop

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHD 4992 U

Loyang 59 Loyang Drive Singapore 508969

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

Fax no. 6546 8156

- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Tel no. 62148355 or Hp no. 98240811 Lim Kwok Eng

Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305

Tel no. 62148398 or Hp no. 96358546 Lim Tien Siong Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006

Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176

Larry Ng

Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

1.00 Larry Ng

for Vice President Crash Repairs & Claims Recovery

A member of













COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

: SHD4992U

DATE:

27. Dec. 2018

MAKE

: HYUNDAI

MODEL: i40

DOA:

26. Dec. 2018

<u>AIG</u>

MODEL	: 140	DOA:	26. Dec. 2018	<u> </u>
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 Front Bumper Cover			\$544.50
21	Front Bumper Side Bracket – LH			\$24.60
	Front Bumper Top Bracket – LH			\$22.40
	Front Bunmper Clips		\$2.20	\$22.00
	1 Headlamp Panel		·	\$907.40
	1Headlamp – LH			\$1,388.00
1	1Front Fender – LH			\$566.30
ı				
3	1 Front Fender Shield – LH			\$174.90
				ē
				_
	SUB TOTAL			\$3,650.10
	LESS 20%	5		\$730.02
9	DISCOUNTED TOTAL			\$2,920.08
				. ,
			,	
				\$-
				,
	Labour Charge			
	1 Panel Beating			\$500.00
	1 Spray Painting Charge	1		\$500.00
	1Tuff Kote			\$50.00
	1 Wiring Charge			\$50.00
	Twitting charge			750.00
1				
			1	66 453 53
	TOTAL LABOUI	3		\$1,100.00
	ESTIMATE TOTA	니		\$4,020.08
	This is an initial estimate based on a visual inspection of	he above v	ehicle. The final repair of	quantum will
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			
	be prepared after the vernole is surveyed by a motor sur	cyci appo	The by the modified t	oparry.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Driving Experience

Mobile Number

Fax Number Contact Number **EMail Address**

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the indement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT		
Date Of Report	27/12/2018 15:26		
Date Of Accident	26/12/2018 16:30		
Exact Location Of Accident	ORCHARD TURN TWDS TAKASHIMAYA BLDG.		
Country/State of Loss	SINGAPORE		
	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SHD4992U		
Insured/Policyholder			
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD		
Co Reg No	199303821R		
Email Address	FLEETSAFETY@CDGTAXI.COM.SG		
Mobile Phone No			
Alternative Phone No	OFFICE-65508768		
Vehicle Particulars			
Manufacturer	HYUNDAI		
Model	140		
Exact Purpose for which vehicle was being used a time of accident	t .		
Are you claiming under your own insurance policy for repair to your vehicle?	NO		
If No, Please state action to be taken	THIRD PARTY		
Vehicle Category	TAXI		
Insurance Company			
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD		
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT		
Fleet Policy	YES		
Policy Number	MCOM0015		
Cover Note Number			
Driver			
Name of Driver	TEO BOCK CHOON		
NRIC No	S1479626F		
Date Of Birth	19/09/1961		
Occupation	OUTDOOR		
Date Of Driving Pass	06/11/1982		

36 YEARS AND 1 MONTH

(LOCAL) +65-98306808

RICKYTEO4352@GMAIL.COM

MALE

Address

180B #18-365 RIVERVALE CRESCENT

Postcode

542180

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO 2

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

GENDER:

Passenger 1

NAME:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLG7576E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIM HONG KIAT

NRIC/Passport Number

S1290766D

Contact Number

97909433

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT RHT

Page 2 of 9

No. Of Passenger (Including Driver)

SKETCH PLAN
FIFTH HELLER HEL
HILLIAN SIGHSIGE
TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
On 26/12/2018 est about 1630 hrs, I vehicle A was
driving my taxi along orchard turns toward takashim
building. Thore was heavy traffic tound toro wany "
There was two lane in the single lave, while of
was e in the outer lane going strong Lt. Vehicle &
on my left Snoldenly that I to my large and brush
against left front portion.
DECLARATION 27 /10/1 %
1/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTL JUNE CSO CSO CSO CSO
COMFORT TRANSPORT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

OMFORT TRANSPORTATION PIE LTD.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

27/12/18
Jackson Heng

C80

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Ya