ruminu)	thin		MENT (Office)		1. 1	-
Estimated Cost:) Say wei shawn	of		Date	Time: 28 2	88 12.20
	PRES / OD RES / EV		Bill to:			
To Inspect Vehicle	No:	SMF 2	527 1	Insured:	SCY 620	aD a
at Workshop m/s	Greek	1 Porest	tutumobile	2 Tel:	017112	214
of	& Iculà Bylo	+ Avo 4	# 0525	premier	1-11-	
Policy No: DI	8M7PV01004	342	Claim No:	CMTDI	806688	
Sum Insured:			Excess:	cr. (p)	803044	1110
Make of Veh:(Client's Record)				D.O.	A. 21/12/20	8
CA / REV / RI	P. / REV 24 HRS	(d)			The Processing	
	Pm@28/12/18 P		Chris	H.C	D.D. Endorsement:	
Date/Time: 1.41	1100011-116	erson Contacted	Ching	Vehicle	TILOUIF)	
Date/Time: 1'4(
	tion/lestruction (~	-) Estima	P			
Date/Time Ac	tion/Instruction (V		ke			
Date/Time Ac	8MF25201->		te			
Date/Time Ac				(no dii	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	•

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

NGO SAU WEI SHAWN

Date: 11 Apr 2019

Preliminary Advice

Insured Vehicle No : SCY6228D

TP Vehicle No

: SMF2522L

Accident Date

: 21/12/2018

Make

: MERCEDES-BENZ C200

Assignment Date

: 28/12/2018

Date of Inspection

Est. Duration of Repair

: 28/12/2018

: 9.00

Inspection At

: GREEN FOREST AUTOMOBILE PTE LTD (KAKI BUKIT)

8 KAKI BUKIT AVENUE 4, #05-25,, PREMIER@KAKI BUKIT

SINGAPORE 415875

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,435.30
Revised Amount	:S\$	9,712.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,712.65
30 Table 18		
Lump Sum Repair	:S\$	7,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ylb
		let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: KINDLY ASSIST TO AMEND THE MAKE & MODEL OF SMF 2522L TO MERCEDES BENZ (X) C200 KOMPRESSOR A (1796cc) INSTEAD OF MERCEDES BENZ C200 2.0.

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUL	FOLDER TRA	Est Submitted	Adi Assianed	Adi Rot	Adi Sub	enitted	Ins Auth'ed	Status		
Main	28 Dec 2018	Escaumater.	28 Dec 2018 12:29 Assign	AU, NA	(A0), SUD	interes.	ins Autoreu	New A	Assignmen	t
	Main	Re	ference		Claim Details		Documen	its] [show All
CLAIM SI	JBFOLDER DE	TAILS				[Creat	ed by insurer]	THE RESERVE OF THE PARTY.		
Insured:	LEE CHOY	YUON, ID: S25	52213C							
Main Claimant:	GREEN FO	REST LANDSCA	PE PTE LTD,	Co. Reg. No	o.: 200707841R					
Vehicle Re No.:	9. SMF252	2L			Date of Loss:	21/12/2	2018 15:00 - :59			
Claim Type	e: TP / CMTD1805688 Policy/Cover Note No.: D18MTPV01004342 (Comprehensive)							iensive)		
Vehicle Re No. (Insured):	SCY62281				Policy No. (Claimant):					
					Excess:					
Repairer:		rest Automobile 92712214	Pte Ltd (HQ) 8	Kaki Bukit	Avenue 4, #05-2	5, Premie	r@Kaki Bukit, Sing	apore 415	875, 4158	75 Kaki
Handling Insurer:	Sompo In	surance Singapo	ore Pte. Ltd. (H	IQ) - Tel: 6	461 6555 [Han	dled by N	IGO SAU WEI SH	AWN - 63	29 5202]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-356	1 [Final Rpt	due 09,	/01/2019]			
Adj Asg. Remarks:	-PLEASE B	E INFORMED THAT	OUR INSURED	HAS NOT R	REPORTED THE AC	CIDENT				
ASSOCIA	TED MAIL RE	CEIVED						View All	Compose	Case Ma
There are	no mail for this	case.								
ALL ASS	OCIATED TAS	KS⊟				View /	All Search Tasks	Create I	New Task	Complet
Due Da	te Priority	Type Task	Group Sub	foot Wa	ndler Assign	ned By	Completed O		eated On	Done

Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Monday, 31 December 2018 11:20 AM

To:

do-not-reply@merimen.com

Cc:

SUR

Subject:

VEHICLE SMF 2522L (YOUR REF: CMTD1805688)

This mail is associated with:

*SMF2522L (CMTD1805688) [SCY6228D]

TP

GREEN FOREST LANDSCAPE PTE LTD

Dec 21 2018 3:00PM

[LEE CHOY YUON]

Green Forest Automobile Pte Ltd

Dear Shawn,

Please be informed that we have inspected the vehicle SMF 2522L on 28/12/2018.

We are pending estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms) LKK Auto Consultants Pte Ltd

Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com

Toyota, Honda, Nissan, Mitsobishi & BMW. There are clienty of cars for sale, from yers, trucks, sedan cars, business invoques, SUV, HIPV, has tribuck, to COE cars & OPC cars. You can also buy from a car auction, look up car folias, financial services, low mileage cars, car brands, carpack rates & call mand. First law used c000, c200 Singapore, used c200 Singapore, used c200, used vehicles Singapore or even may used c200 Singapore. We have new cut dealers comprising parallel test, and used car dealers on our life. Find new car prior lists, new car launchies and new car promotions, visit our partner sites for job openings for Singapore jobs.

All prices and other information displayed on sqCarMarc.com are gathered from sources and based on algorithms that are believed by sqCarMarc.com to be reliable, but no assurance can be give

Follow sgCarMart.com











About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

-> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Sameulas	
Owner ID Type:	Company
Owner ID:	7841R
Vehicle Defalls	
Vehicle No.:	SMF2522L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 KOMPRESSOR A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	27195031179469
Chassis No.:	WDD2040412A255146
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,033.00
Original Registration Date:	05 Jun 2009
First Registration Date:	05 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$41,033.00
Intended PART Repare Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2019
PARF Rebate Amount:	\$20,516.00
Intenited COE Rebate Drazille	
COE Expiry Date:	04 Jun 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$7,552.00
COE Rebate Amount:	\$329.00
Total Rebate Amount:	\$20,845.00
e information contained herein is correct as at 28 Dec 2018	

ОК

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company			
Owner ID:	7841R			
Vehicle No.:	SMF2522L			
Vehicle to be Exported:	Yes			
Intended Deregistration Date:	31 Dec 2018			
Vehicle Make:	MERCEDES BENZ			
Vehicle Model:	C200 KOMPRESSOR A			
Primary Colour:	Black			
Manufacturing Year:	2009			
Engine No.:	27195031179469			
Chassis No.:	WDD2040412A255146			
Maximum Power Output:	135.0 kW (181 bhp)			
Open Market Value:	\$41,033.00			
Original Registration Date:	05 Jun 2009			
First Registration Date:	05 Jun 2009			
Transfer Count:	1			
Actual ARF Paid:	\$41,033.00			
PARF Eligibility:	Yes			
PARF Eligibility Expiry Date:	04 Jun 2019			
PARF Rebate Amount:	\$20,516.00	-		
COF Franks Date:	04 Jun 2019			
COE Category	B - Car (1601cc & above)			
COE Category: COE Period(Years):	10			
QP Paid:	\$7,552.00			
COE Rebate Amount:	\$323.00			
Total Rebate Amount:	\$20.839.00			

The information contained herein is correct as at 24 Dec 2018

ОК

xlett: 7.2K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

 By the lodgement of this report to the insurers, you aforesaid. 	u hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	27/12/2018 16:46
Date Of Accident	21/12/2018 15:15
Exact Location Of Accident	SLIP RD OF TAMPINES AVE 12
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMF2522L
Insured/Policyholder	
Name Of Registered Owner	GREEN FOREST LANDSCAPE PTE LTD
Co Reg No	200707841R
Email Address	CATHERINE@LANDSCAPE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64825191
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	C200-2.0 (A)
Exact Purpose for which vehicle was be	ing used at

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

GA353489

Cover Note Number

05/06/2018-04/06/2019

Driver

Name of Driver

KENNETH NEO GUO HAO

NRIC No Date Of Birth

Occupation

S9533476H 17/09/1995

INDOOR 09/12/2016

Date Of Driving Pass Driving Experience

2 YEARS AND 0 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-97302958

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

672 HOUGANG AVE 8

01-79

Postcode

5306722

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

4

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Was there any audio recorded?

SGT9750J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJN9967J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SCY6228D

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Subblished the Subblished State

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:/

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN		DESCRIPTION OF THE PROPERTY OF	ports warning
1-1	4		
	E-		VEHILLER + SGT 9780J
		THE TOWARDS CTE	VEHICLE C - SJN 9967.J
	1191		VEHICLE A - SMF 2522]
<u>ddii ba</u>	ITLI		VEHICLE D - ISCY 6228 D
14444			+ + + + + + + + + + + + + + + + + + + +
		ABKCKAKD	SLIP ECAD
			FROM TAMPINES AND U
			THE THE PARTY OF T
		<u></u>	1-11-1-1-1-1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

0	N :	21/0	e c	2018	<u>@</u>	15	15H	es,	1	WAS	DI	21/10	JG	CVEH	ICLE A)
ALONG	THE	SI	10	ROAC	> OF	TA	MPIN	£S	AV€	NUE	12	TO	EN	STER	INTO
TPE	TON	IAROS	, C	Te.	SU	OPE	VLY	, TH	E	CAR	(VE	HICL	E () B	RAKED
ANO	١	POH	-OW	SU	IT.	AT	THÉ_	Sam	ET	im€,	1	FELT	A t	IUGE	MPACT
CON	THE	REA	20	F M	4 0	R.	THE	IMP	ACT	CAU	SED	my	CAR	To	SURGE
FOR	WAR	٥.	A C	AR	(VEH	LLE	(O)	HAD	+	17 -	THE	REP	e of	- my	CAR.
NO	ONE	W	rs.	INJU	RED	12	TF	115 1	+(C)	DEN	Τ.	PLEF	SE	REFE	IL TO
SKET	TCH	ARO	٧£	V (V)	1		0/-0			- University			H8.00.		
ī	AM	1 01	PIN	1146	TH	RO	PART	14	AT	OUR	OV	N	NORK	(6/0/	9
		7419.Yo		Alchert -			7		- 1174						
		- 130			and the second				701					71/4	
														interior and the Control	
									CH .		70.00			11/12/2012	
						-			III.				VII-00-11		
ili a di sala			1.000000		West - F										-
71	Marie S	7.00		-				_	_			_		-	
			-						-						
		_													
	-														

DECLARATION

I/We declare the foregoing particular are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

Name: NRIC/FIN No.:

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

26th December 2018

8 KAKI BUKIT AVENUE 4 # 05-25 PREMIER @ KAKI BIKIT Singapore 415875

TPSompo. Viuo Chen.

Accident date:

Estimated repair cost for vehicle no: SMF2522L MERCEDES BENZ C200 '09

S/n	Qty	Items/Nett	U/price	Amount
1	1	Front Bonnet Wis		\$1,665.00
	1	Front Bonnet Emblem Logo New		\$95.00
2	2	Front head lamp could	\$ 1,250.00	\$2,240.00
3	1	Front Grille Could		\$663.00
4	1	Front Grille Star Could		\$80.00
5		Front Bumper Defend		\$1,220.00
6	1	Front Bumper Side Brackets	\$95.00	\$190.00
7	2	Front Bumper Side Brackets	•	\$408.00
8	1	Front Bumper Inner Sponge Could		\$153.00
9	1	Front Bumper Inner Sponge Side	\$88.00	\$176.00 ×
10	2	Front Bumper Reverse Sensor Xum	\$153.00	\$612.00 ×
11	4	Front Bumper Number Plate Garnish	and a	\$105.00
12	1	Front Bumper Number Plate Couled		\$50.00
13	1	Front Bumper Humber Flate	\$215.90	\$431.80
14	2	Front Bumper Fog Lamp Chrome	\$95.00	\$190.00 ×
15	2	1 Total Dumper - og	\$78.00	\$96.00
16	2	Front Bumper rog Lamp Cover	\$98.00	\$196.00
17	2	Front Bumper Side Chrome	\$5.00	\$50.00
18	10	From Dumper Supe	***************************************	\$755.00
19	1			\$1,050.00
20	1	Front air-con condenser		\$1,255.00 4
21	1	Front radiator		\$1,250.00
22	1	Front aircon fan motor assy		\$1,371.00
23	1	Rear boot lid		\$48.00
24	1	Rear boot lid Emble logo	\$6.50	\$19.50
25	3	Rear boot lid Emble logo clips	\$0.50	\$169.00
26	1	Rear boot lid center moulding Not New		\$98.00
27	1	Rear boot lid KOMPRESSOR logo 2 New	/	\$55.00
28	1	Rear boot lid CNC logo		\$55.00

Sheet1

		- 114 C200 large N/4		\$80.00
29	1	Rear boot lid C200 logo New		\$253.00 [×]
30	1	Rear boot lid inner rubber		\$248.00
31	1	Rear boot lid inner lock		\$385.00 [×]
32	1	Rear boot lid inner lock switch motor		\$98.00
33	1	Rear boot lid inner lock cover	\$8.50	\$34.00
34	4	Rear boot lid number plate clips		\$60.00
35	2	Rear Boot Lid number plate lamp	\$30.00	\$305.00
36	1	Rear boot lid inner trim board	20000	\$65.00×
37	10	Rear boot lid inner trim board clips	\$6.50	
38	2	Rear tail lamp	\$585.00	\$1,170.00
39	1	Rear bumper Deloud		\$1,192.00
40	2	Rear bumper side bracket	\$88.00	\$176.00
41	4	Rear Bumper reverse sensor-set		\$650.00 30
	- 4	Rear bumper center moulding 2		\$205.00 ×
42	1	Rear bumper center moduling	\$95.00	\$190.00
43	2	Rear bumper side moulding		\$52.00
44	1	Rear bumper towing cover	\$6.50	\$65.00-30
45	10	Real bulliper clips	\$0.00	\$606.00
46	1	Rear Bumper reinforcement But	\$75.00	\$150.00
47	2	Rear Bumper inner Side Bracket 140 W	\$15.00	\$485.00
48	1	Rear end panel		\$225.00
49	1	Rear End Panel Top Garnish		\$223.00

8 038.50 Subtotal:- \$21,385.30

Labour charges		\$120.00 60
To remove & refix cushion		1/1/2
To remove & refix front & rear reverse sensor		\$200.00 60
To check wiring		
To remove & refix rear exhaust		\$200.00
To remove & refix front air-con condenser, radiator		\$200.00 ×
Fan-motor and top up gas		
To reset computer	2460	\$150.00 80 \$120.00 X
Tuff kote		
Panel beating		\$1,408.00 1000
Spray painting		\$1,600.00 1200
Spray pariting	Subtotal :-	\$4,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K S E

total: 9694.65 1/s: 7.k (Nett Value)

Total:-

\$25,435.30

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO18023273/AQD3N2

Date:

13/05/2019

REFERENCE

Sompo Insurance Singapore Pte. Handling

Policy No:

D18MTPV01004342

Insurer:

Ltd.

Insured Vehicle

SCY6228D

Claimant Vehicle No:

SMF2522L

No:

Date of Loss:

21/12/2018

Nature of Claim:

TP

Claim No:

CMTD1805688

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMF2522L

Make & Model:

MERCEDES-BENZ C200 KOMPRESSOR, 1.8 (A) Engine No:

Chassis No:

27195031179469

Reg. Date:

05/06/2009 (Man. Year: 2009)

Odometer:

WDD2040412A255146 224382 km

Colour:

Black

Engine Capacity: Market Value/New Car 1796 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Front Right Side: Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's 21,385.30 0.00	Adjuster's 7,252.65 0.00	Difference 14,132.65 0.00	Diff % 66.09
Miscellaneous Items Labour	4,050.00 0.00	2,460.00	1,590.00 0.00	39.26
Paintwork Labour	0.00	0.00	0.00	
Towing Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	25,435.30	9,712.65 7,000.00	15,722.65	61.81
(S\$) + GST 7.00/7.00% (S\$)	25,435.30 1,780.47	7,000.00 490.00	18,435.30 1,290.47	72.48 72.48
Nett Amount (S\$)	27,215.77	7,490.00	19,725.77	72.48

INSPECTION

Date of Assignment:

28/12/2018

Date Inspected:

28/12/2018 Inspected At:

Green Forest Automobile Pte Ltd (Kaki

Bukit)

8 Kaki Bukit Avenue 4, #05-25,,

Premier@Kaki Bukit Singapore 415875

Estimated Period of Repair:

9.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 13 May 2019) Part Source: MRM-SG

MERCEDES-BENZ C200 KOMPRESSOR 1.8 (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SMF2522L)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Rec	commer	nded Parts No. Particulars	Condition I	Repairer's	Amount
10.	Qty Part	NO. 1 distribution	Popair	1,665.00 F	*-FL
	1	*FRONT BONNET	Repair	95.00 F	*95.00 FL
	1	*FRONT BONNET EMBLEM LOGO	Necessary Cracked	2,240.00 F	2.240.00 FL
3	2	*FRONT HEAD LAMP	Cracked	663.00 F	*663.00 FL
	1	*FRONT GRILLE		80.00 F	*80.00 FL
5	1	*FRONT GRILLE STAR	Cracked Deformed		*1,220.00 FL
3	1	*FRONT BUMPER		190.00 F	*190.00 FL
7	2	*FRONT BUMPER SIDE BRACKETS	Necessary	408.00 F	*408.00 FL
В	1	*FRONT BUMPER REINFORCEMENT	Bent	153.00 F	*153.00 FL
9	1	*FRONT BUMPER INNER SPONGE	Cracked	176.00 F	*-FL
	2	*FRONT BUMPER INNER SPONGE SIDE	Not Necessary	612.00 F	*-FL
10		*EPONT BUMPER REVERSE SENSOR	Not Necessary		*105.00 FL
11	4	*FRONT BUMPER NUMBER PLATE GARNISH	Deformed	105.00 F	*50.00 FL
12	1	*FRONT BUMPER NUMBER PLATE	Cracked	50.00 F	*-FL
13	1	*FRONT BUMPER FOG LAMP	Not Necessary	431.80 F	*-FL
14	2	*FRONT BUMPER FOG LAMP CHROME	Not Necessary	190.00 F	*- FL
15	2	*FRONT BUMPER FOG LAMP COVER	Not Necessary	96.00 F	*-FL
16	2	*FRONT BUMPER SIDE CHROME	Not Necessary	196.00 F	*50.00 FL
17	2	*FRONT BUMPER CLIPS	Necessary	50.00 F	*-FL
18	10	*FRONT SUPPORT PANEL	Not Necessary	755.00 F	*-FL
19	1	*FRONT AIR-CON CONDENSER	Not Necessary	1,050.00 F	
20	1	*FRONT RADIATOR	Not Necessary	1,255.00 F	*-FL
21	1	*FRONT AIRCON FAN MOTOR ASSY	Not Necessary	1,250.00 F	*-FL
22	1		Repair	1,371.00 F	*- FL
23	1	*REAR BOOT LID *REAR BOOT LID EMBLEM LOGO	Necessary	48.00 F	*48.00 FL
24	1	*REAR BOOT LID EMBLEM LOGO CLIPS	Necessary	19.50 F	*19.50 FL
25	3	*REAR BOOT LID CENTER MOULDING	Not Necessary	169.00 F	
26	1	*REAR BOOT LID COMPRESSOR LOGO	Necessary	98.00 F	
27	1	*REAR BOOT LID CNC LOGO	Necessary	55.00 F	
28	1	*REAR BOOT LID C200 LOGO	Necessary	80.00 F	
29	1	*REAR BOOT LID GLOVE COOL	Not Necessary	253.00 F	
30	1	*REAR BOOT LID INNER RUBBER	Not Necessary	248.00 F	
31	1	*REAR BOOT LID INNER LOCK SWITCH MOTOR	Not Necessary	385.00 F	*- FI
32	1	*REAR BOOT LID INNER LOCK SWITCH MOTOR	Not Necessary		
33	1	*REAR BOOT LID INNER LOCK COVER	Not Necessary	04.00 [
34	3 32	*REAR BOOT LID NUMBER PLATE CLIPS	Not Necessary		*-F
35		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary		*-F
36		*REAR BOOT LID INNER TRIM BOARD	Not Necessary		*-F
37		*REAR BOOT LID INNER TRIM BOARD CLIPS	Not Necessar	1,170.00	*-F
38		*REAR TAIL LAMP	Deformed	1,192.00	*1,192.00 F
39		*REAR BUMPER	Necessary	176.00	
40		*REAR BUMPER SIDE BRACKET	Damaged	650.00	F *500.00 F
4		*REAR BUMPER REVERSE SENSOR-SET	Not Necessar		
42		*REAR BUMPER CENTER MOULDING		400.00	
4:		*REAR BUMPER SIDE MOULDING	Not Necessar Not Necessar	,	
4		*REAR BUMPER TOWING COVER	Not Necessal) 02.00	**************************************

No.	Otv	Part No. Particulars	Condition	Repairer's	Amount
45	10	*REAR BUMPER CLIPS	Necessary Bent	65.00 F 606.00 F	*30.00 FL *606.00 FL
46 47	*REAR BUMPER REINFORCEMENT Bent *REAR BUMPER INNER SIDE BRACKET Not Necessary *REAR END PANEL *REAR END PANEL TOP GARNISH Not Necessary	150.00 F 485.00 F	*- FL *- FL		
48 49			225.00 F	*-FL	
F=Fr	anchise	part. L=ListItemDisc List Item Discount on L It	Sub Total (S\$) ems 0.00/10.00% (S\$)		8,058.50 805.85
			Total Parts (S\$)	21,385.30	7,252.65
_		Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Lahour
Recommended	Labour

Re	commended Labour	Lab.Type	Repairer's	Amount
No	Particulars	10 Section 21 For Un		
Lab	our Items	New	120.00	60.00
1 2	TO REMOVE & REFIX CUSHION TO REMOVE & REFIX FRONT & REAR REVERSE	New	200.00	60.00
(2)	SENSOR	New	60.00	60.00
3	TO CHECK WIRING	New	200.00	0.00
4	TO REMOVE & REFIX REAR EXHAUST	New	200.00	0.00
5	TO REMOVE & REFIX FRONT AIR-CON CONDENSER, RADIATOR FAN-MOTOR AND TOP UP		150.00	80.00
6	TO RESET COMPUTER	New	120.00	0.00
7	TUFF KOTE	New	1,400.00	1,000.00
8	PANEL BEATING	New	1,600.00	1,200.00
9	SPRAY PAINTING	-	23.07%43.07%	
	Gross L	abour Cost (S\$)	4,050.00	2,460.00
	Report was unsubmitted	during this print-out		

< END OF ESTIMATES >