

REF

CS3/MSA18023287/UCd302

Special instruction

Surveyor

Mehmen

From (Person): Fievel Foo

of

MSLG

Date/Time: 28/12/00 3.42pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF1548A

Insured:

XD 2509 G

at Workshop m/s

Precision Motorworks.

Tel:

8742 7247

of

68 kaki Bukit Ave 6 # 01-02

Policy No:

S28949814 MKC

Claim No:

580261

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/12/18

CA / REV / REP. / REV 24 HRS

hwp

3112180 Mumines

H.O.D. Endorsement:

Date/Time:

5:06pm 28/12/18

Person Contacted:

John


Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	GBF 1548A-X
	XD2509 G-CA/AIG11004103/WI
	Dismantle: 5/1/2019

REF: MSIG

ASSIGNMENT

From: Date: 3/12/18
 Estimated Cost:
 OD ☒ TP / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBF 1548A
 at Workshop m/s Precision Motorworks
 of 68 kaki Bukit Ave 6 # 01-02
 Insured:
 Policy No.
 Claims No.
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh: Morning



(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 53
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBF 1548A Yr Regn: 7116
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CM /
 Make: Toyota Dyna C.C. 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 128253 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: JTFAT35Y60K206625
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/75R15.
 R: 155R12
☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 6/6 mm

D.O.A. 20/12/18

D.O.I. 31/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No settlement; LIA 14919
 7 yrs 7 m. 10-11k.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

) :

TOTAL

Report Format : PRE.

Lump Sum / I.B.I. (\$) :

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2018		28 Dec 2018 15:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KIM SOON LEE PTE LTD, Co. Reg. No.: 200304459N, Email: PAULINEKIMSOONLEE@GMAIL.COM		
Main Claimant:	UNITED WOODEN CASE & PACKING ENTERPRISE (S), Co. Reg. No.: 200204250D		
Vehicle Reg. No.:	GBF1548A	Date of Loss:	26/12/2018 09:00 - :59 [29 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580261	Policy/Cover Note No.:	S28949814MKC (Comprehensive) Coverage: 08/05/2018 - 07/05/2019
Vehicle Reg. No. (Insured):	XD2509G	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Precision Motorworks Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB, 417896 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/12/2018]		
Driver/Custodian (Insured):	RAMALINGAM MUTHUMANI (34 / Male), NRIC: G6634837M, Tel: +6586150019		
Adj Asg. Remarks:	LIABILITY 100% Please contact MR JOHN @ 8742 7247 to arrange for survey		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2018 17:56
Date Of Accident	26/12/2018 08:55
Exact Location Of Accident	TUAS SOUTH AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF1548A
Insured/Policyholder	
Name Of Registered Owner	UNITED WOODEN CASE & PACKING ENTERPRISE (S)
Co Reg No	200204250D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800079452
Cover Note Number	

Driver

Name of Driver	LIM SWEE TECK
NRIC No	S0228427H
Date Of Birth	31/05/1953
Occupation	OUTDOOR
Date Of Driving Pass	12/12/1973
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82034090
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 193 BUKIT BATOK WEST AVE 6 #20-69
Postcode	650193
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20181226/2053.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD2509G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMALINGAM MUTHUMANI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM SWEE TECK

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBF1548A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20181226/2053

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

1 of 3

Report No. T/20181226/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/12/2018 13:33		Vide Report No.:		Station Diary No.: 14
Informant's Particulars				
Name of Informant: LIM SWEE TECK		Address: APT BLK 193 BUKIT BATOK WEST AVENUE 6 #20-69 SINGAPORE 650193		
ID Type / ID No.: NRIC NO / S0228427H		Contact No.: Home/Office: Mobile: 82034090		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 65	Date of Birth: 31/05/1953	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Lorry driver		Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/12/2018 09:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 TUAS SOUTH AVENUE 3 TUAS SOUTH AVENUE 5 At the junction between Tuas South Avenue 3 and Tuas South Avenue 5				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF1548A	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181226/2053

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

2 of 3

Report No. T/20181226/2053

CONTINUATION OF REPORT

Driver			
Name	LIM SWEE TECK	ID No.	S0228427H
Related Vehicle	GBF1548A (Lorry)	Contact No.	82034090
Hospital/Clinic	C & K FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/12/2018	Date Discharge	26/12/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On 26/12/2018 at about 0930hrs, I was driving my lorry bearing registration number - GBF1548A along Tuas South Avenue 3. As I was approaching the junction between Tuas South Avenue 3 and Tuas South Avenue 5, the traffic light had turned red and I stopped my vehicle. While I was waiting for the light to turn green, a trailer truck collided onto the rear of my lorry. The impact caused my lorry to be pushed forward and into the middle of the junction. The plastic cover for my lorry had fallen off and items that I had placed inside the lorry were thrown around as a result of the impact.

I felt a pain on my lower back and on the back of my neck and I was feeling disoriented. I exited the vehicle and saw that the rear of my lorry was damaged and heavily dented. I had as well noticed that the front of the trailer truck was dented and the bumper had fallen off and there were large dents. I immediately called my boss to inform him of what had happened. My boss told me he will be coming down to my scene and he will be calling for Traffic Police.

Traffic police had arrived at the scene and had attended to me and the trailer truck driver. My boss had come down to the scene and had taken pictures of the damages and exchanged particulars.

The driver of the trailer truck approached me and apologised to me for colliding into my lorry. As I was feeling pain on my lower back and on the back of my neck area, I decided to visit a clinic to see a doctor.

On 26/12/2018 at about 1200hrs, I had gone to C&K Family Clinic and was given 7 days MC from 26/12/2018 to 01/01/2018.

I wish to add that my lorry's in-car camera was damaged as a result of the collision, hence, I was unable to view the in-car camera footage. I was advised to lodge a Traffic Accident report by Traffic Police. I am now lodging this report under the instruction of Traffic Police and for insurance claiming purposes.



**SINGAPORE
POLICE FORCE**



T/20181226/2053

3 of 3

Report No. T/20181226/2053

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 JONATHAN LIM ZI XUAN
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt YUS MASTARI I KHAZALI Contact No: 65476214
Authentication Stamp

Signature Of Informant:
Date/Time: 26/12/2018 13:33
Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0228427H




Name
LIM SWEE TECK

Race
CHINESE

Date of birth
31-05-1953

Sex
M

Country of birth
SINGAPORE



12/12/1973

4653279




NRIC No S0228427H



Date of issue
06-11-2010

Address
APT BLK 193 BUKIT BATOK WEST AVENUE 6
#20-69
SINGAPORE 650193





POLICY SCHEDULE

COMMERCIAL AUTOPLUS COMMERCIAL VEHICLE

Policy No. : 1800079452

Period of Insurance : 18 Jul 2018 to 17 Jul 2019

Issued Date : 11 Jul 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : UNITED WOODEN CASE & PACKING ENTERPRISE (S)
 Address : 103 TUAS VIEW WALK 1
 WESTLINK TECHPARK
 SINGAPORE 637728

Occupation/Nature of Business : Manufacturing/ Engineering

ABOUT THE VEHICLE

Registration No. : GBF1548A Engine Capacity/Tonnage : 1.7 Tonnage
 Chassis No. : JTFAT35Y60K206625 Engine No. : 1KD2626546
 Seating Capacity : 2 First Year of Registration : 2016 Body Type : Lorry
 Make/Model : TOYOTA DYNA 150 1.7 ton [Lorry]
 Hire Purchase Company/Employer's Loan : MERCEDES BENZ FINANCE CO LTD

ABOUT THE COVER

Sum Insured : Market Value Off Peak Car : No
 Driver Restriction : NA Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive :

- a) Any person who is driving on the Policyholder's order or with their permission.
 b) This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

- 1) Use in connection with the Policyholder's business.
 2) Use for the carriage of passenger (other than for hire or reward) in connection with the Policyholder's business.
 3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing; and b) use whilst drawing a trailer except the towing of anyone disabled using a mechanically propelled vehicle. c) use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Key Replacement Cover- \$800, Strike, Riots and Civil Commotions, Dealer (First 3 years from original registration) + AIG Authorised Workshops, In-Car Camera Excess Waiver, Act of God

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

PREMIUM

Premium : \$ 1,205.10
 GST (7%) : \$ 84.36

Total : \$ 1,289.46

Your Premium includes the following discount(s):

No Claim Discount - 15%

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	4250D

Vehicle Details

Vehicle No.:	GBF1548A
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2626546
Chassis No.:	JTFAT35Y60K206625
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	18 Jul 2016
First Registration Date:	18 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,786.00
COE Rebate Amount:	\$14,919.00
Total Rebate Amount:	\$14,919.00

The information contained herein is correct as at 02 Jan 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SUPREME

CLICK HERE OR CALL US AT
6479 8221



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



2.88% P.A. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd StarAd

Lake View
Credit Pte Ltd

> Low p
> Specia
> Easy l
> All ter





Browse by Category

Sort by Date Posted

4 vehicles

toyota dyna

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	toyota dyna		Any	Any	2016	Any	Any	
	Toyota Dyna 150		\$53,800	\$6,850 /yr	08-Nov-2016	2,982 cc	57,000 km	
	Fuel Type: Diesel							
	Think One Automobile & Trading							
	Posted: 19-Dec-2018 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	Toyota Dyna 150		\$53,800	\$7,500 /yr	07-Mar-2016	2,982 cc	119,000 km	
	Fuel Type: Diesel							
	Comes With Canopy With Metal Truck Bed, Excellent Condition, Call To View Now Before It Is Too Late, In House Loan Available.							
	Hui Hua Credit Pte Ltd							
	Posted: 04-Dec-2018 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	Toyota Dyna 150		\$65,000	\$8,300 /yr	01-Nov-2016	2,982 cc	-	
	Fuel Type: Diesel							
	Toyota Dyna Clean And Well Maintained Interior And Exterior. Most Convenient And Reliable Truck For Day To Day Duties. Call Me Now.							
	Posted: 25-Nov-2018 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							
	Toyota Dyna 150		\$53,800	\$6,730 /yr	29-Dec-2016	2,982 cc	-	
	Fuel Type: Diesel							
	Please Call To Arrange For Viewing, Thanks.							
	Posted: 19-Nov-2018 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota							

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage V

For old advertisements, view **Expired ads**

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resource

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2018		28 Dec 2018 15:42 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KIM SOON LEE PTE LTD , Co. Reg. No.: 200304459N, Email: PAULINEKIMSOONLEE@GMAIL.COM								
Main Claimant:	UNITED WOODEN CASE & PACKING ENTERPRISE (S) , Co. Reg. No.: 200204250D								
Vehicle Reg. No.:	GBF1548A	Date of Loss:	26/12/2018 09:00 - :59 [29 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 580261	Policy/Cover Note No.:	S28949814MKC (Comprehensive) Coverage: 08/05/2018 - 07/05/2019						
Vehicle Reg. No. (Insured):	XD2509G	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Precision Motorworks Pte Ltd (HQ) 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB, 417896 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 29/12/2018]								
Driver/Custodian (Insured):	RAMALINGAM MUTHUMANI (34 / Male), NRIC: G6634837M, Tel: +6586150019								
Adj Asg. Remarks:	LIABILITY 100% Please contact MR JOHN @ 8742 7247 to arrange for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF1548A (580261)

[XD2509G]



































TP



















































UNITED WOODEN CASE & PACKING ENTERPRISE (S)









































Dec 26 2018 9:00AM

[KIM SOON LEE PTE LTD]

Precision Motorworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/18 18:04	Accident Statement From: SC - Reg. No: XD2509G, Claimant: KIM SOON LEE PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/01/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
35	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
36	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
37	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
38	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
39	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
40	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
41	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
42	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
43	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
44	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
45	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
46	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
47	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
48	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
49	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
50	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
51	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
52	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
53	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
54	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
55	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
56	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
57	02/01/19 14:31	General View		Load JPG	<input checked="" type="checkbox"/>
58	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
59	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
60	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
61	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
62	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	02/01/19 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	07/01/19 14:31	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	07/01/19 14:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/18 18:04	TPD GBF1548A GIA REPORT From: SC - Reg. No: XD2509G, Claimant: KIM SOON LEE PTE LTD	 Load PDF	
2	27/12/18 18:09	TPD GBF1548A - PRI	 Load PDF	
3	28/12/18 15:29	Reject email to TP lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18023287/UCD3E2

Date: 07/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S28949814MKC

Claimant Vehicle No : GBF1548A

Insured Vehicle No : XD2509G

Date of Loss: 26/12/2018

Nature of Claim: TP

Claim No: 580261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF1548A

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2626546

Reg. Date: 18/07/2016 (Man. Year: 2016)

Chassis No: JTFAT35Y60K206625

Colour: Silver

Odometer: 128253 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12 (D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/12/2018

Date Inspected: 31/12/2018 Inspected At:

Precision Motorworks Pte Ltd (HQ)
68 KAKI BUKIT AVENUE 6 #01-02
ARK@KB
Singapore 417896

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$11,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 07 Jan 2019)
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF1548A)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >