

ASS. REC. BY:

REF

ES3/MSG18023321/Ged30

Special Instruction:

Surveyor
Menemen

Guo Qidong

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

M8/G

Date/Time:

31/12/18 9.19pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

8JX7211S

Insured:

SJF 6957A

at Workshop m/s

Monster Tune

Tel:

9018 4170

of

25 kaki Bukit Rd 4 #06-37 Synergy

Policy No.:

29080721 TMC

Claim No.:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/12/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

9:20am 31/12/18

Person Contacted:

Derrick

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

8JX7211S-X

SJF 6957A-X

Dismantle: 2/1/2019

Synergy

Xhe

REF: MS19

PRS

ASSIGNMENT

From:

Date: 31/12/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJX 7211S

at Workshop m/s

Monster Tune

of 25 kaki Bukit Rd 4 #06-37 synergy

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

90184170 @ Dmick

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

cup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJX 7211S

Yr Regn:

Jul / 10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Scirocco C.C 1390

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

71288

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

www888138 AV 443 100

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

235/40ZR18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

Rear

R/Bal.

6

mm

L/Bal.

6

mm

D.O.I.

31-12-18

Survey held at

w/s

11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair range 3K - 4K

4 repair days

4/1/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

120

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

10

130

Report Format :

PRS.

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2018 18:29		31 Dec 2018 09:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PREMIER RENT A CAR PTE LTD, Co. Reg. No.: 200612929E								
Main Claimant:	DEREK LAU HAN YOUNG, ID: S7928113A								
Vehicle Reg. No.:	SJX7211S	Date of Loss:	24/12/2018 00:00 - :59 [101 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29080721TMC Coverage: 01/05/2018 - 30/04/2019						
Vehicle Reg. No. (Insured):	SJF6957A	Policy No. (Claimant):							
		Excess:							
Repairer:	Monster Tune (HQ) 25 Kaki Bukit Road 4, #06-37 Synergy@Kaki Bukit, 417800 Kaki Bukit - Tel: 83331487								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/01/2019]								
Driver/Custodian (Insured):	DAKSHINAMOORTHY SUBRAMANIAN (), NRIC: S2691303I								
Adj Asg. Remarks:	Liability down. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants as the SJE. Contact Person: Mr Derrick / 9018 4170								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJX7211S		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	VOLKSWAGEN		
Vehicle Model :	SCIROCCO 1.4L AT TSI 1372Q5		
Chassis No. :	WVWZZZ13ZAV443100		
Propellant :	Petrol		
Engine No. :	CAV190400		
Engine Capacity :	1390 cc		
Maximum Power Output :	118.0 kW (158 bhp)		
Maximum Laden Weight :	1730 kg		
Unladen Weight :	1285 kg		
Year Of Manufacture :	2010		
Original Registration Date :	06 Jul 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$20,802.00		
COE Expiry Date :	05 Jul 2020		
Road Tax Expiry Date :	05 Jul 2019		
PARF Eligibility Expiry Date :	05 Jul 2020		
Inspection Due Date :	05 Jul 2019		
Intended Transfer Date :	03 Jan 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8113A
Vehicle Details	
Vehicle No.:	SJX7211S
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	CAV190400
Chassis No.:	WVWZZZ13ZAV443100
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$24,391.00
Original Registration Date:	06 Jul 2010
First Registration Date:	06 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$24,391.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jul 2020
PARF Rebate Amount:	\$13,415.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jul 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$3,131.00
Total Rebate Amount:	\$16,546.00

The information contained herein is correct as at 03 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/12/2018 15:22
Date Of Accident	24/12/2018 12:50
Exact Location Of Accident	SLE (CTE) BEFORE EXIT 11
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX7211S
Insured/Policyholder	
Name Of Registered Owner	DEREK LAU HAN YOUNG
NRIC No	S7928113A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91016832
Alternative Phone No	OFFICE-91016832

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	SCIROCCO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104712348
Cover Note Number	

Driver

Name of Driver	DEREK LAU HAN YOUNG
NRIC No	S7928113A
Date Of Birth	26/09/1979
Occupation	INDOOR
Date Of Driving Pass	27/01/2003
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91016832
Fax Number	
Contact Number	OFFICE-91016832
EMail Address	NOEMAIL

Address	37 JALAN CHERMAT
Postcode	538387
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

FRONT VEHICLES BRAKE AND STOP. I BRAKE AND MANAGED TO STOP IN TIME. VEHICLE B COULD NOT STOP IN TIME AND HIT INTO MY VEHICLE'S REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF6957A
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

deret6660@gmail.com

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

front vehicles brake and stop, I brake and managed
to stop in time. Vehicle B could not stop in time
and hit into my vehicle's rear portion

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	28 Dec 2018 18:29		31 Dec 2018 09:19 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: PREMIER RENT A CAR PTE LTD , Co. Reg. No.: 200612929E									
Main Claimant: DEREK LAU HAN YOUNG , ID: S7928113A									
Vehicle Reg. No.: SJX7211S		Date of Loss: 24/12/2018 13:00 - :59 [101 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 580382		Policy/Cover Note No.: B29080721TMC (Third Party Only) Coverage: 01/05/2018 - 30/04/2019							
Vehicle Reg. No. (Insured): SJF6957A		Policy No. (Claimant): Excess:							
Repairer: Monster Tune (HQ) 25 Kaki Bukit Road 4, #06-37 Synergy@Kaki Bukit, 417800 Kaki Bukit - Tel: 83331487									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 01/01/2019]									
Driver/Custodian (Insured): DAKSHINAMOORTHY SUBRAMANIAN () , NRIC: S2691303I									
Adj Asg. Remarks: Liability down. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants as the SJE. Contact Person: Mr Derrick / 9018 4170									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJX7211S (580382)
[SJF6957A]
TP
DEREK LAU HAN YOUNG
Dec 24 2018 1:00PM
[PREMIER RENT A CAR PTE LTD]
Monster Tune

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
2	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
3	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
4	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
5	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
6	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
7	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
8	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
9	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
10	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
11	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
12	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
13	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
14	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
15	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
16	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
17	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
18	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
19	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
20	03/01/19 14:50	General View		Load JPG	<input checked="" type="checkbox"/>					
21	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
22	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
23	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
24	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
25	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
26	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
27	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
28	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
29	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
30	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
31	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
32	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
33	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
34	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
35	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
36	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
37	03/01/19 14:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/01/19 14:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	03/01/19 14:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	03/01/19 14:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/12/18 18:34	Email - PRI	 Load PDF	
2	28/12/18 18:36	TP workshop details	 Load PDF	
3	28/12/18 18:41	TP disagree with our SJE list. Proceed to appoint LKK as the SJE	 Load PDF	
4	31/12/18 09:45	SJX7211S GIA Rpt	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18023321/GCD3E2

Date: 07/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29080721TMC

Claimant Vehicle No : SJX7211S

Insured Vehicle No : SJF6957A

Date of Loss: 24/12/2018

Nature of Claim: TP

Claim No: 580382

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJX7211S

Make & Model: VOLKSWAGEN SCIROCCO, 1.4 L (A)

Engine No: CAV190400

Reg. Date: 06/07/2010 (Man. Year: 2010)

Chassis No: WVVZZZ13ZAV443100

Colour: Grey

Odometer: 71298 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40Z R18

Rear Tyre Size: 235/40Z R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/12/2018

Date Inspected: 31/12/2018 Inspected At:

 Monster Tune (HQ)
 25 Kaki Bukit Road 4, #06-37
 Synergy@Kaki Bukit
 Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2019)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX7211S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >