

22/03/2002

ASS. REC. BY:

REF:

3
CS/MSG/18023323/Gcd302

Special Instruction:

Surveyor:
Menimen

G.W. Chang

ASSIGNMENT (Office)

From (Person):

Samy Tay

of

MSG

Date/Time:

31/12/18 @ 9.16am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 6229X

Insured:

SJY 8381Y

at Workshop m/s

AT performance

Tel:

9686 6219

of

Blk 160 Sin Ming Drive # 07-18/19

Policy No:

80452 646 @ MX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/12/2018

CA / REV / REP. / REV 24 HRS

(up)

03012019

H.O.D. Endorsement:

Date/Time:

9.24am @ 31/12/18

Person Contacted:

Alvin

Vehicle IN/OUT

(OUT)

Date/Time	Action/Instruction	Estimate
	(X)	
	SKH 6229X - NR / MSG17017896 / Y	JVA: 16/09/2017
	SJY 8381Y - X:	

PRS

REF: MSLH

3158F

Surrogate

XHL

Meriman

ASSIGNMENT

From: Date: 03012019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKH 6229X

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SKH 6229X

Yr Regn.

13 Oct 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW Z4 2.3 C.C. 2497

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

136009

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA LM32090E 155243

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

265 / 30 ZR19

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

KUMHO

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

03-01-19

Survey held at

w/s

2:45pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

RECEIVED

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

-

Survey Fee:

120

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

10

130

Report Format :

PRS

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018		31 Dec 2018 09:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SANDRA KUMAR S/O BATUMALAI, ID: S7603905D, Tel: +6596221846, Email: CHANRUKZ@GMAIL.COM			
Main Claimant:	HO KWOK WOH, ID: S7033158F			
Vehicle Reg. No.:	SKH6229X	Date of Loss:	25/12/2018 22:00 - :59 [110 Months and 12 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	80452646QMX (Comprehensive) Coverage: 02/01/2018 - 01/01/2019	
Vehicle Reg. No. (Insured):	SJY8381Y	Policy No. (Claimant):		
		Excess:	S\$500.00	
Repairer:	At Performance (160 Sin Ming) (HQ) Blk 160 Sin Ming Drive, #07-18/19, 575722 Sin Ming - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mel Ling - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/01/2019]			
Driver/Custodian (Insured):	SANDRA KUMAR S/O BATUMALAI (42 / Female), NRIC: S7603905D, Tel: +6596221846			
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY UNCLEAR Please appoint LKK AUTO to conduct the survey . Kindly contact MR ALVIN @ 9686 6219 to arrange for survey			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3158F

Vehicle Details

Vehicle No.:	SKH6229X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2019
Vehicle Make:	B.M.W.
Vehicle Model:	Z4 2.3I A
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	75094520N52B25AF
Chassis No.:	WBALM32090E155243
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$41,944.00
Original Registration Date:	13 Oct 2009
First Registration Date:	13 Oct 2009
Transfer Count:	3
Actual ARF Paid:	\$41,944.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Oct 2019
PARF Rebate Amount:	\$20,972.00

Intended COE Rebate Details

COE Expiry Date:	12 Oct 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$17,501.00
COE Rebate Amount:	\$1,296.00
Total Rebate Amount:	\$22,268.00

The information contained herein is correct as at 04 Jan 2019

OK

► BMW Z4 Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
BMW Z4 Roadster 2.5i	\$27,800	-	05-Mar-2009	2,496 cc	-		Availal
Only \$5.5K Per Year With 10 Years COE Renewal, Call To Arrange Your Viewing, Must Sell Due To No Parking Space At Home. Office No. - - R Goh - 91131962							
BMW Z4 Roadster 2.5i	\$29,900	-	01-Sep-2009	2,496 cc	138,000 km		Availal
Owner No Time To Use. So Must! Office No. - - J L - 90198553							
BMW Z4 sDrive23i	\$38,000	\$19,270 /yr	13-Oct-2009	2,497 cc	94,000 km		Availal
Amazing Car To Drive For The Coming Months And Then Renew The COE Or Cash In. Amazing Low Depreciation For A Fantastic Car. Suitabl For All Kind Of People With A Trunk Fitting The Shopping And Short ... Office No. - - Matt - 91196031							
BMW Z4 sDrive23i (New 10-yr COE)	\$75,800	\$7,570 /yr	24-Jun-2009	2,497 cc	89,600 km	Faster Auto Trading	Availal
100% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In. Office No. - 64761970 Yi De - 97480900 Jimmy - 91010213 Thomas - 96645002							
BMW Z4 sDrive23i (New 10-yr COE)	\$75,888	\$7,580 /yr	10-Sep-2009	2,497 cc	102,898 km	Wheels Singapore Pte Ltd	Availal
With The Roof Opened And Your Hair Down, Hear The Meaty Roar Of The Engine In The MCE. You Have Earned The Right To Drive BMW's World Renowned Z4 Roadster. Plush Beige Color Leather Hugs You Like Your... Office No. - 66815662 Jacson - 87881825 Mr Ng - 86857799 Benjamin - 83237600							
BMW Z4 sDrive35i (New 10-yr COE)	\$92,000	\$9,190 /yr	22-Jun-2009	2,979 cc	95,000 km		Availal
Well Maintained Car Under Utilised For Sale To Direct Owners. No Consignment Or Dealers. Family's 3rd Car. Letting Go To Upgrade. Bidded Number Plate Can Be Bought With The Car With Top Up. Office No. - - Nicky - 84904444							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2018 15:52
Date Of Accident	25/12/2018 22:25
Exact Location Of Accident	SELETAR MALL CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH6229X
Insured/Policyholder	
Name Of Registered Owner	HO KWOK WOH
NRIC No	S7033158F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96806338
Alternative Phone No	OTHERS-96806338

Vehicle Particulars

Manufacturer	BMW
Model	Z4 2.3i A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104614329
Cover Note Number	

Driver

Name of Driver	KELVAN HO JIAN WEI
NRIC No	S9529617C
Date Of Birth	21/08/1995
Occupation	INDOOR
Date Of Driving Pass	21/06/2017
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92720688
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 686 #02-186 HOUGANG STREET 61
Postcode	530686
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TOH WEN HUI
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER CAPTURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY8381Y
Vehicle Make/Model/Colour	TOYOTA VIOS E AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

26 DEC 2019

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre
Name: **23 Kaki Bukit Ave 4
Singapore 415933**
Tel: **67416697** Fax: **67492305**
Email: **vackb@singnet.com.sg**

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 25th December, At around 10:20 Pm, I was turning out of Seletar mall carpark when vehicle SSY 8381X entered the carpark and did a wide turn and collided into the right rear side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

20 DEC 2010

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2018		31 Dec 2018 09:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SANDRA KUMAR S/O BATUMALAI , ID: S7603905D, Tel: +6596221846, Email: CHANRUKZ@GMAIL.COM									
Main Claimant: HO KWOK WOH , ID: S7033158F									
Vehicle Reg. No.: SKH6229X		Date of Loss: 25/12/2018 22:00 - :59 [110 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.: 80452646QMX (Comprehensive) Coverage: 02/01/2018 - 01/01/2019							
Vehicle Reg. No. (Insured): SJY8381Y		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: At Performance (160 Sin Ming) (HQ) Blk 160 Sin Ming Drive, #07-18/19, 575722 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 01/01/2019]									
Driver/Custodian (Insured): SANDRA KUMAR S/O BATUMALAI (42 / Female) , NRIC: S7603905D, Tel: +6596221846									
Adj Asg. Remarks: SJE : DISAGREED / LIABILITY UNCLEAR Please appoint LKK AUTO to conduct the survey . Kindly contact MR ALVIN @ 9686 6219 to arrange for survey									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKH6229X**
[SJY8381Y]
TP
HO KWOK WOH
Dec 25 2018 10:00PM
[SANDRA KUMAR S/O BATUMALAI]
At Performance (160 Sin Ming)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	03/01/19 16:41	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/12/18 15:07	TPD SKH6229X GIA REPORT	 Load PDF	
2	28/12/18 15:07	OI SJY8381Y GIA REPORT	 Load PDF	
3	28/12/18 15:07	SKH6229X - PRI	 Load PDF	
4	28/12/18 15:38	TPD SKH6229X - PRI	 Load PDF	
5	28/12/18 16:28	Reject email to TP lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18023323/GCD3E2

Date: 07/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80452646QMX

Claimant Vehicle No : SKH6229X

Insured Vehicle No : SJY8381Y

Date of Loss: 25/12/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH6229X

Make & Model: BMW Z4, 2.5 (A)

Engine No: 75094520N52B25AF

Reg. Date: 13/10/2009 (Man. Year: 2009)

Chassis No: WBALM32090E155243

Colour: Grey

Odometer: 136009 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/30Z R19

Rear Tyre Size: 265/30Z R19

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/12/2018

Date Inspected: 03/01/2019 Inspected At:

At Performance (160 Sin Ming) (HQ)
Blk 160 Sin Ming Drive, #07-18/19
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2019)

Parts: M1-COUPÉ BMW Z4 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKH6229X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >