

ASS. REC. BY:

REF

CS/AGI18023328/11qdz<sup>12</sup>

Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Julie Mengubut

of

AGI

Date/Time:

31/12/18 @ 11:10am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 838GS

Insured:

SJT 2468Y

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

2 kaki Bulat Ave 2 # 01-17/18

Policy No:

Claim No:

C10002446/JM

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/18 ..

CA / REV / REP. / REV 24 HRS <sup>lup</sup>

H.O.D. Endorsement:

Date/Time:

11:21am @ 31/12/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 838GS - NA/AGI180233280/k4 DUA: 28/12/18
	SJT 2468Y - NA/AGI180233280/k4 DUA: 28/12/18
18/1/19 @ 5:33pm	Informed Julie, we are pending estimate from repairer.

Tanji

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s: \_\_\_\_\_  
of: \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_



(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt. Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 4 days Res: Yes or No  
Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 51583865 Yr Regn: 2017 2t  
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Nissan Qashqai G.O. 1197  
Colour: Black A/C Insured / Std / NI / NA  
Sp. Reading: 30363 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: SJNFEA51142030424  
Gen. Cond: ☒ Good / Fair / Poor / Burnt  
Steering: ☒ Inorder / Jammed / Leaked / Burnt or  
Brake: ☒ Inorder / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or 215/60K17.  
Tyre Size: F: \_\_\_\_\_ R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Continuty

Front 6 Rear 6  
R/Bal. mm R/Bal. mm  
L/Bal. mm L/Bal. mm  
D.O.A. D.O.L. 17/1/17  
Survey held at N-SI  
Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5/200, 4 days further with u/s in phone.  
Used to 2757.78, 4120

RECEIVED 06 MAY 2019

Date/Time. File Pass to? ☐ : Preli. Report

1) 06/5/2019 ☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation

\$ + RS + SI

Photos

Draws

TOTAL

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Report Format: TP

Lump Sum / I.R. (\$)

3200

250

## Nivitha (LKK Auto)

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Monday, 31 December 2018 11:10 AM  
**To:** 'assignments'; SUR  
**Subject:** FW: SLS8386S & SJT2468Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS || Our ref: C10002446/JM  
**Attachments:** 8386.pdf

Hi Team

Please accept TPPD survey and survey without prejudice basis.

Please note TP would like Mr Muhamad Taufihk to survey their client's vehicle.

Thank you,  
-Julie

**From:** Chin Hui Xin <huixin@n51.com.sg>  
**Sent:** Monday, 31 December, 2018 10:21 AM  
**To:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Subject:** Re: SLS8386S & SJT2468Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS || Our ref: C10002446/JM

Dear Sir / Madam,

We appoint your surveyor Mr Mohamad Taufihk from Lkk Auto Consultants Pte Ltd.

Please see attached.

Regards,  
Melody Chin  
N-51 Automotive Pte Ltd  
Office : 6842 0051  
Fax : 6741 0510  
**www.n51.com.sg**



On Mon, Dec 31, 2018 at 9:30 AM Julie Mangubat <julie.m@budgetdirect.com.sg> wrote:

Dear Sir

Please find the list of surveyors to choose from.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Kenneth Kong LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Marcus Chua LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Kenji Tan FormTeam Adjusters Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you,

-Julie

**From:** Chin Hui Xin <[huixin@n51.com.sg](mailto:huixin@n51.com.sg)>

**Sent:** Friday, 28 December, 2018 3:50 PM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>

**Subject:** SLS8386S & SJT2468Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Regards,

Melody Chin

TWINCAR Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 18 January 2019 5:33 PM  
**To:** 'Julie Mangubat'; assignments  
**Cc:** SUR  
**Subject:** RE: SLS8386S & SJT2468Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS || Our ref: C10002446/JM

Dear Julie,

Please be informed that we have inspected the vehicle SLS 8386S on 17/01/2019.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)

**Sent:** Monday, 31 December 2018 11:21 AM

**To:** 'Julie Mangubat' <[julie.m@budgetdirect.com.sg](mailto:julie.m@budgetdirect.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: SLS8386S & SJT2468Y - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS || Our ref: C10002446/JM

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** Julie Mangubat [<mailto:julie.m@budgetdirect.com.sg>]

**Sent:** Monday, 31 December 2018 11:10 AM

**To:** 'assignments' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/12/2018 15:41
Date Of Accident	28/12/2018 12:40
Exact Location Of Accident	HOUGANG AVE 1 TWDS INFR YU YING SECONDARY SCHOOL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS8386S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EVERLYN PTE LTD
Co Reg No	201613598G
Email Address	DOMINICGOH@LIVE.COM
Mobile Phone No	(LOCAL) +65-83281023
Alternative Phone No	OFFICE-83281023

### Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORKING HOURS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700070275-01
Cover Note Number	

### Driver

Name of Driver	GOH QING HAO, DOMINIC ( WU QINGHAO, DOMINIC )
NRIC No	S8325561G
Date Of Birth	24/08/1983
Occupation	INDOOR
Date Of Driving Pass	19/06/2004
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83281023
Fax Number	
Contact Number	OTHERS-83281023
Email Address	DOMINICGOH@LIVE.COM

Address	BLK 52 LENGKOK BAHRU #08-289
Postcode	150052
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - DIRECTOR OF CO.
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT2468Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

28/12/2018

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING STRAIGHT, ON THE RIGHT HAND
OF HONGKONG AVE 1.
WHILE SOMEWHERE IN FRONT OF YIN YEH SECONDARY SCHOOL,
WHILE PROCEEDING STRAIGHT AHEAD, SUDDENLY A VEHICLE
ON MY LEFT SWERVED AND SHIFT INTO MY LANE AND
HIT INTO THE LEFT SIDE OF MY VEHICLE.
ALIGHTED FROM MY VEHICLE AND REALIZED IT WAS
A VEHICLE WITH LICENSE PLATE NUMBER (SJT 2468 Y)
THAT COLLIDED TO THE LEFT SIDE OF MY VEHICLE.
THIS WHOLE ACCIDENT FOOTAGE WAS CAPTURED BY
MY IN-CAR CAMERA, WITH FRONT AND REAR VIEW.
VEHICLE A - SLS 8386S
VEHICLE B - SJT 2468 Y

## DECLARATION

I/We declare the foregoing statements are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

# TwinCar AUTOMOTIVE PTE LTD

(Mr. Taufik)

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

EVERLYN PTE LTD

1 COMMONWEALTH LANE #09-12 ONE

COMMONWEALTH

SINGAPORE 149544

Contact : 83281023

## ESTIMATE

Repair Code : CLM14361

Date in : 28/12/2018

Vehicle Num. : SLS8386S

Model : NISSAN QASHQAI 1.2 DIG-T CVT

Chassis/Eng# : SJNFEAJ11U2030424/HRA2491867A

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR PROTECTOR	1	323.60	cut ✓ 323.60
FRONT LH DOOR SIDE MIRROR	1	644.80	cut ✓ 644.80
FRONT LH DOOR SIDE MIRROR COVER	1	105.10	cut ✓ 105.10
REAR LH DOOR PROTECTOR	1	264.80	cut ✓ 264.80
REAR LH FENDER ARCH GARNISH	1	483.00	cut ✓ 483.00
REAR LH SPORT RIM	1	1231.90	cut ✓ 1,231.90 / 1000
Subtotal before discount		2821.30	3,053.20
Percentage discount 10%		2539.17	305.32
Sub-total 1			2,747.88
DOOR CHROME MOULDING - SET	1	600.00	cut ✓ 600.00
FRONT LH DOOR PROTECTOR CLIPS - SET	1	50.00	30.00 ✓ 50.00
REAR LH DOOR ARCH RUBBER SEAL	1	250.00	100 X 250.00
REAR LH DOOR PROTECTOR CLIPS - SET	1	50.00	30.00 ✓ 50.00
REAR LH FENDER ARCH GARNISH CLIPS - SET	1	30.00	20.00 ✓ 30.00
REAR LH WHEEL BEARING	1	329.40	100 X 329.40
Subtotal before discount		580	1,309.40
Percentage discount 0%			0.00
Sub-total 2			1,309.40
Parts-total			4,057.28

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

EVERLYN PTE LTD

1 COMMONWEALTH LANE #09-12 ONE

COMMONWEALTH

SINGAPORE 149544

Contact : 83281023

## ESTIMATE

Repair Code : CLM14361

Date in : 28/12/2018

Vehicle Num. : SLS8386S

Model : NISSAN QASHQAI 1.2 DIG-T CVT

Chassis/Eng# : SJNFEAJ11U2030424/HRA2491867A

## LABOUR

To remove, reinstall rear suspension and undercarriage part. (to FR)

100.00

To road test driving, check and resetting wheel alignments system.

80 100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

500 800.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

300 400.00

Labour Total

1,400.00

Parts & Labour Total

880 5,457.28

3999.12

41383200

4 days

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 2

Tanji 17495747

17/1/19

4 days

Insurance

Resurvey after repair

See Mclento.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO &amp; GENERAL INSURANCE (S) PL

Ref : CS/AGI18023328/T1qd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 08-05-2019



Code : AGI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJT 2468Y	Veh. Inspected	SLS 8386S
Policy No.		Coverage (\$)	0.00
Claim No.	C10002446/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	31/12/2018

**2. Vehicle Particulars & Condition**

Make & Model	NISSAN QASHQAI	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFEAJ11U2030424	Colour	BLACK
Odometer	30363	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	28/12/2018	Inspection Date	17/01/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

**5a. Remarks**A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8386S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT LH DOOR PROTECTOR	CUT	323.60	323.60
1	FRONT LH DOOR SIDE MIRROR	CUT	644.80	644.80
1	FRONT LH DOOR SIDE MIRROR COVER	CUT	105.10	105.10
1	REAR LH DOOR PROTECTOR	CUT	264.80	264.80
1	REAR LH FENDER ARCH GARNISH	CUT	483.00	483.00
1	REAR LH SPORT RIM	CUT	1,231.90	1,000.00
	LESS 10% DISCOUNT		-305.32	-282.13
			2,747.88	2,539.17
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET DOOR CHROME MOULDING (SN)	CUT	600.00	500.00
1	SET FRONT LH DOOR PROTECTOR CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR LH DOOR ARCH RUBBER SEAL (SN)	NOT NECESSARY	250.00	-
1	SET REAR LH DOOR PROTECTOR CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR LH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
1	REAR LH WHEEL BEARING (SN)	NOT NECESSARY	329.40	-
			1,309.40	580.00
<b><u>LABOUR</u></b>				
	TO REMOVE,REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR).	NOT NECESSARY	100.00	-
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		800.00	500.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		400.00	300.00
	-		-	-
	-		-	-
	-		-	-
			1,400.00	880.00
<b>GRAND TOTAL</b>			<b>5,457.28</b>	<b>3,999.17</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/AGI18023328/T1qd3n2



Report Ref No. CS/AGI18023328/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.