

ASS. REG. BY:

REF

083/ICS18023333/Ed3

Special Instruction:

Surveyor

Menner

ASSIGNMENT (Office)

From (Person):

Jenice Goh

of

ICS

Date/Time:

31/12/18 @ 11:34am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME1910L

Insured:

SJM 8663Y

at Workshop m/s:

E.M. Solution

Tel:

6456 0226

of

160 Sin Ming Drive #07-18/19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Imps

02/01/2019

H.O.D. Endorsement:

Date/Time:

11:36am 31/12/18

Person Contacted:

James

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SME1910L-X

SJM8663Y-X

Dismantle: 31/12/18 (GQ)

From: **02/01/2019**  
 Date: **02/01/2019**  
 Estimated Cost:  
 OD **(TP)** / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: **SME 1910L**  
 at Workshop m/s: **Em Solution**  
 of: **160 Sin Ming Dr #03-18**  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: Excess:  
 (Client's Record)  
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: **9** days Res.: Yes or No  
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **SME 1910L** Yr Regn: **21/09/2018**  
 Type: **(M)** Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **Hyundai ELantra** C.C. **1.6 1591**  
 Colour: **Silver** A/C: Insured / Std / NI / NA  
 Sp. Reading: **7861** T/Radio: Insured / Std / NI / NA  
 Eng/No:  
 C/No: **KMH0841CMJU 740285**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **In** order / Jammed / Leaked / Burnt or  
 Brake: **In** order / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **195/65 R15**  
 R: **195/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **NEXEN**

Front		Rear	
R/Bal.	<b>6</b> mm	R/Bal.	<b>6</b> mm
L/Bal.	<b>6</b> mm	L/Bal.	<b>6</b> mm
D.O.A.	<b>28/12/2018</b>	D.O.I.	<b>2/1/2019</b>
Survey held at <b>EM Solution</b>			

Des. of Damages: **(F)** / **(R)** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 70,000
	PV - 49,519
	NV - 29,481
	Repair range - 9K - 10K
	8 repair day
	uplnd photo VIEWS & minor dnce
	<b>3/1/2019</b>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **9**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Report Format : **PRE**

Lump Sum / I.B.I. (\$) )

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

## Nivitha (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Monday, 31 December 2018 11:34 AM  
**To:** Sally Chong; assignments  
**Cc:** EM Solution Pte Ltd; 'Judy Soh'; ECICS Claims  
**Subject:** RE: OUR REF.: E21-MISC.18 (SME 1910 L @ 28/12/2018) ECICS REF NO : SJM 8663 Y

Without Prejudice

Dear Sally

Thank you for your email.

We are not agreeable to your proposed motor surveyors.

We are appointing LKK for the PRS.

Hi LKK

Kindly do the needful.

*" Please be informed that our office will be closed at 12pm on 31 Dec 2018. Thank You. "*

Thank you,  
Janice Goh

---

**From:** Sally Chong [mailto:sallychong@visionlawllc.com]  
**Sent:** Monday, December 31, 2018 11:24 AM  
**To:** ECICS Claims  
**Cc:** EM Solution Pte Ltd; 'Judy Soh'  
**Subject:** RE: OUR REF.: E21-MISC.18 (SME 1910 L @ 28/12/2018) ECICS REF NO : SJM 8663 Y  
**Importance:** High

## URGENT

Dear Janice,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

**CLAIMANT: CHUA KAH PENG**

**ACCIDENT INVOLVING SME 1910 L (3rd), SJM 8663 Y (4TH), SKQ 5498 U (5th), SKM 2112 Z (6th), SMD 3022 S (2nd) & SLB 42 B (1st) ON 28 DEC 2018 ALONG CTE AT ABOUT 17:40 HRS**

We refer to your email of even date below and your list of surveyors.

**TAKE NOTICE** that we object to your surveyor stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

<u>Name of Surveyor</u>	<u>Company Name</u>
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd

Please be informed that the said vehicle can be inspected at:-

Venue : E M SOLUTION PTE LTD  
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,  
Singapore 575722  
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

*Sally Chong*

(Secretary)  
VISION LAW LLC  
133 NEW BRIDGE ROAD,  
#18-01/02, CHINATOWN POINT,  
SINGAPORE 059413  
TEL.: 6534-2811 (ext 115)  
FAX : 6535-6802

---

**From:** ECICS Claims [<mailto:claims@ecics.com.sg>]  
**Sent:** Monday, 31 December, 2018 10:28 AM  
**To:** Sally Chong  
**Cc:** ECICS Claims  
**Subject:** RE: OUR REF.: E21-MISC.18 (SME 1910 L @ 28/12/2018) ECICS REF NO : SJM 8663 Y

**Without prejudice**

Dear Judy

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop.

We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight

3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

*" Please be informed that our office will be closed at 12pm on 31 Dec 2018. Thank You. "*

Thank you.

Best regards,  
Janice Goh  
Claims Division  
DID: +65 6303 0182  
FAX: +65 6338 9267

ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Center  
Singapore 408600

---

**From:** Sally Chong [<mailto:sallychong@visionlawllc.com>]  
**Sent:** Monday, December 31, 2018 10:16 AM  
**To:** ECICS Claims  
**Subject:** FW: OUR REF.: E21-MISC.18 (SME 1910 L @ 28/12/2018) ECICS REF NO : SJM 8663 Y  
**Importance:** High

---

**From:** Judy Soh [<mailto:judysoh@visionlawllc.com>]  
**Sent:** Saturday, 29 December, 2018 12:51 PM  
**To:** [claims@ecics.com.sg](mailto:claims@ecics.com.sg)  
**Cc:** [emaautosolution@singnet.com.sg](mailto:emaautosolution@singnet.com.sg); [sallychong@visionlawllc.com](mailto:sallychong@visionlawllc.com); [PhoebeJay\\_Xie@ecics.com.sg](mailto:PhoebeJay_Xie@ecics.com.sg); [lionel\\_chua@ecics.com.sg](mailto:lionel_chua@ecics.com.sg); [Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)  
**Subject:** OUR REF.: E21-MISC.18 (SME 1910 L @ 28/12/2018) ECICS REF NO : SJM 8663 Y  
**Importance:** High

### VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO  
PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES  
CLAIMANT: CHUA KAH PENG  
ACCIDENT INVOLVING SME 1910 L (3<sup>rd</sup>), SJM 8663 Y (4<sup>TH</sup>), SKQ 5498 U (5<sup>th</sup>), SKM 2112 Z (6<sup>th</sup>), SMD 3022 S  
(2<sup>nd</sup>) & SLB 42 B (1<sup>st</sup>) ON 28 DEC 2018 ALONG CTE AT ABOUT 17:40 HRS

We are instructed by **CHUA KAH PENG** to notify you of a road traffic accident on **28 DEC 2018 ALONG CTE AT ABOUT 17:40 HRS** involving our client's vehicle registration number **SME 1910 L, SKQ 5498 U, SKM 2112 Z, SMD 3022 S & SLB 42 B** and vehicle registration number **SJM 8663 Y** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

***Judy Soh***

VISION LAW LLC  
133 NEW BRIDGE ROAD,  
#18-01/02, CHINATOWN POINT,  
SINGAPORE 059413  
TEL.: 6534-2811 (ext 147)  
FAX : 6535-6802

C.c.: VEHICLE OWNER OF SJM 8663 Y  
**TAN HOE BENG**  
25 Jalan Gelegar  
Singapore 739784

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

---

**VISION LAW LLC**

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/12/2018 13:05
Date Of Accident	28/12/2018 17:40
Exact Location Of Accident	CTE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME1910L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA KAH PENG
NRIC No	S1661862D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93364341
Alternative Phone No	OFFICE-93364341

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	0
Cover Note Number	CN014502

### Driver

Name of Driver	CHUA KAH PENG
NRIC No	S1661862D
Date Of Birth	03/02/1964
Occupation	INDOOR
Date Of Driving Pass	03/07/1985
Driving Experience	33 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93364341
Fax Number	
Contact Number	OFFICE-93364341
Email Address	NOEMAIL



Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKQ5498U  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKM2112Z  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SMD3022S  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SLB42B  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20181228/2161

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

1 of 3

Report No. T/20181228/2161

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 28/12/2018 21:25	Vide Report No.: E/20181228/0124	Station Diary No.: 197
--	-------------------------------------	---------------------------

**Informant's Particulars**

Name of Informant: CHUA KAH PENG			Address: APT BLK 801D KEAT HONG CLOSE #04-49 SINGAPORE 684801	
ID Type / ID No.: NRIC NO / S1661862D			Contact No.: Home/Office: Mobile: 93364341	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 54	Date of Birth: 03/02/1964	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: CONSTRUCTION SITE MANAGER			Driving Licence Information: Class: 2B,2A,3,4,5 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/12/2018 17:40	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY  CTE towards City, before Bukit Timah Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SJM8663Y	Car					3
SKM2112Z	Car				Slightly Damaged	0
SKQ5498U	Car				Slightly Damaged	3
SLB42B	Car				Slightly Damaged	4
SMD3022S	Car				Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20181228/2161

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

3 of 3



Report No. T/20181228/2161

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  Sgt 2 OH DING FENG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/12/2018 21:25
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI Contact No.: 65476904	Classification Of Case:

Authentication Stamp  
NP168

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1862D
Vehicle Details	
Vehicle No.:	SME1910L
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	G4FGJU250219
Chassis No.:	KMHD841CMJU740285
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,572.00
Original Registration Date:	21 Sep 2018
First Registration Date:	21 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$12,572.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2028
PARF Rebate Amount:	\$9,429.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,997.00
COE Rebate Amount:	\$31,090.00
Total Rebate Amount:	\$40,519.00

The information contained herein is correct as at 02 Jan 2019

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad


Advertiser Login

Ways of Selling

New 5 Years CoE Renewal Toyota Altis 1.6A



2.88% P.a. Lowest Interest @ GV  
Cars Finance \$1800  
Downpayment Monthly From  
\$558  
GV Credit Pte Ltd



Browse by Category

Sort by Date Posted

20 results/page

5 vehicles

Hyundai Elantra

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection								
	Hyundai Elantra	Any	Any	2018	Any	Any	Any	Available
	Hyundai Elantra 1.6A GLS	\$65,800	\$6,630 /yr	16-Jan-2018	1,591 cc	-	Sedan	Available
Nice Bidded Number (7887), Up To 90% In-House Loan And Balloon Scheme Available, No Gimmicks! 1 Owner, Keyless Entry/Start, Android Auto/Apple CarPlay, Bluetooth, Reverse Camera, Rear Aircon, White In...								
Posted: 01-Jan-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	Hyundai Elantra 1.6A GLS	\$75,800	\$7,030 /yr	20-Nov-2018	1,591 cc	85 km	Sedan	Available
Low Cash Upfront! High Loan Available! No Admin Fee/no Gimmicks. Warranty By Komoco Till 2023! Contact Us Today!								
GS Automobiles Pte Ltd								
Posted: 24-Dec-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	Hyundai Elantra 1.6A GLS Elite	\$82,800	\$7,640 /yr	20-Nov-2018	1,591 cc	80 km	Sedan	Available
Priced To Sell! Keyless Entry And Push/Start! Top Of The Range Specs! All You Need In A Car Is Here! Very Low Mileage Done, Warranty By Komoco Till 2023, Black Interior! Hurry In To Secure This Once I...								
GS Automobiles Pte Ltd								
Posted: 16-Dec-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	Hyundai Elantra 1.6A GLS (OPC)	\$56,999	\$5,200 /yr	27-Nov-2018	1,591 cc	38 km	Sedan	Available
High Loan, As Low As \$600/Month Drive Away! No Admin/No Gimmicks. Contact Us To Seize This Good Deal!								
GS Automobiles Pte Ltd								
Posted: 02-Dec-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								
	K & P Auto Services Pte Ltd - Repair & Servicing							
K & P Auto Services Pte Ltd is a Service Centre specializing in the service and repair of Japanese & Korean car-makes.								
More info about this shop								
	Hyundai Elantra 1.6A GLS	\$71,999	\$6,730 /yr	17-Nov-2018	1,591 cc	144 km	Sedan	Available
Low Cash Upfront! High Loan Available! No Admin Fee/no Gimmicks. Warranty By Komoco Till 2023! Contact Us Today!								
GS Automobiles Pte Ltd								
Posted: 29-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai								

Save this search criteria, to get email alerts whenever a match is found.

Compare

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 14:53 <a href="#">Edit Reg</a>		31 Dec 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: EMAIL@YAHOO.COM		
Main Claimant:	-		
Vehicle Reg. No.:	<b>SME1910L</b>	Date of Loss:	28/12/2018 17:00 - :59 [3 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	<b>SJM8663Y</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Em Solution Pte Ltd - Sin Ming (HQ)</b> BLK 17 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR A, 575675 Sin Ming - Tel: 6456 0556		
Handling Insurer:	<b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 10/01/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date    Priority    Type    Task Group    Subject    Handler    Assigned By    Completed On    Created On    Done?

No results.





## Claim Documents

**\*SME1910L**  
**[SJM8663Y]**

TP































Dec 28 2018 5:00PM

















































[-]
















































Em Solution Pte Ltd - Sin Ming
















































Upload Documents Upload Photos Compose New Letter































View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 15:06	General View	 Load JPG	✓
2	02/01/19 15:06	General View	 Load JPG	✓
3	02/01/19 15:06	General View	 Load JPG	✓
4	02/01/19 15:06	General View	 Load JPG	✓
5	02/01/19 15:06	General View	 Load JPG	✓
6	02/01/19 15:06	General View	 Load JPG	✓
7	02/01/19 15:06	General View	 Load JPG	✓
8	02/01/19 15:06	General View	 Load JPG	✓
9	02/01/19 15:06	General View	 Load JPG	✓
10	02/01/19 15:06	General View	 Load JPG	✓
11	02/01/19 15:06	General View	 Load JPG	✓
12	02/01/19 15:06	General View	 Load JPG	✓
13	02/01/19 15:06	General View	 Load JPG	✓
14	02/01/19 15:06	General View	 Load JPG	✓
15	02/01/19 15:06	General View	 Load JPG	✓
16	02/01/19 15:06	General View	 Load JPG	✓
17	02/01/19 15:06	General View	 Load JPG	✓
18	02/01/19 15:06	General View	 Load JPG	✓
19	02/01/19 15:06	General View	 Load JPG	✓
20	02/01/19 15:06	General View	 Load JPG	✓
21	02/01/19 15:06	General View	 Load JPG	✓
22	02/01/19 15:06	General View	 Load JPG	✓
23	02/01/19 15:06	General View	 Load JPG	✓
24	02/01/19 15:06	General View	 Load JPG	✓
25	02/01/19 15:06	General View	 Load JPG	✓
26	02/01/19 15:06	General View	 Load JPG	✓
27	02/01/19 15:06	General View	 Load JPG	✓
28	02/01/19 15:06	General View	 Load JPG	✓
29	02/01/19 15:06	General View	 Load JPG	✓
30	02/01/19 15:06	General View	 Load JPG	✓
31	02/01/19 15:06	General View	 Load JPG	✓
32	02/01/19 15:06	General View	 Load JPG	✓
33	02/01/19 15:06	General View	 Load JPG	✓
34	02/01/19 15:06	General View	 Load JPG	✓
35	02/01/19 15:06	General View	 Load JPG	✓

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
56	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
58	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
59	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
60	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
61	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
62	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
63	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
64	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
65	02/01/19 15:06	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
123	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
124	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
125	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
126	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
127	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
128	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
129	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
130	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
131	03/01/19 16:49	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
133	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
134	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
135	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
136	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
137	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
138	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
139	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
140	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
141	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
142	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
143	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
144	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
145	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
146	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
147	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
148	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
149	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
150	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
151	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
152	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
153	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
154	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
155	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
156	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
157	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
158	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
159	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
160	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
161	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
162	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
163	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
164	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
165	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
166	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
167	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
168	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
169	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
170	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
171	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
172	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
173	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
174	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
175	03/01/19 16:49	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
176	03/01/19 16:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
177	03/01/19 16:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
178	03/01/19 16:50	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
179	03/01/19 16:50	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
180	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
181	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
182	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
183	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
184	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
185	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
186	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
187	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
188	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
189	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
190	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
191	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
192	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
193	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
194	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
195	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
196	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
197	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
198	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
199	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
200	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
201	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
202	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
203	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
204	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
205	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
206	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
207	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
208	03/01/19 16:50	Dismantled Parts	 Load JPG	✓
209	03/01/19 16:50	Dismantled Parts	 Load JPG	✓

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18023333/ECD3S2  
Date: 07/01/2019

## REFERENCE

Handling Insurer: ECICS Limited Policy No:  
Claimant Vehicle No: SME1910L Insured Vehicle No: SJM8663Y  
Date of Loss: 28/12/2018 Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SME1910L  
Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU250219  
Reg. Date: 21/09/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU740285  
Colour: Silver Odometer: 7861 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm  
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 31/12/2018  
Date Inspected: 02/01/2019 Inspected At: Em Solution Pte Ltd  
160 SIN MING DRIVE #03-18/19  
SIN MING AUTOCITY  
SINGAPORE 575722  
Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME1910L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >