

Our Ref : T 1218/ SHC3816H /KS(st)

Your Ref :

Date : 15-Feb-19

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

Lonpac Insurance Bhd
300 Beach Road
#17-04 / 07, The Concourse
Singapore 199555

Attn : Motor Claim Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHC3816H YOUR INSURED SKD1066C AND OTHER SJN7206K ON 27.12.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHC3816H which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SKD1066C we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

| | | |
|-------------|-------------------------------------------|-------------|
| 1 | Cost of Repair | \$ 5,617.50 |
| 2 | 5 days Loss of Rental @ \$ 117.28 per day | \$ 586.40 |
| 3 | Survey Report Fees (Surveyed by M/s LKK) | \$ - |
| 4 | LTA Search Fees | \$ 7.49 |
| 5 | GIA / Police Report Fees | \$ - |
| 6 | Towing / Medical / Transporation Fees | \$ - |
| Sub Total : | | \$ 6,211.39 |

HIRER'S CLAIM

| | | |
|---------------|-------------------------------------------|-------------|
| 7 | 5 days Loss of Income @ \$ 80.00 per days | \$ 400.00 |
| Total Claims: | | \$ 6,611.39 |

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.
- b) LTA search slip/s of : SJN5240Z
- c) GIA / Police report/s of : SHC3816H
- d) Letter of authority from owner / hirer / operator
- () PIR () Towing/Medical bill/receipts () Certificate of Insurance
- (X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel : 6214 8736 Fax: 6214 1843 Email: kazali@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SHC3816H , SKD1066C , SJN7206K **ON 27-Dec-18 08:45**
ALONG T JUNCTION OF YISHUN AVE 8 AND YISHUN AVE 1

I / We **PEK CHENG BOON** (Hirer) NRIC No.: **S7136039C**

and/or (Relief) NRIC No.:

Taxi Number **SHC3816H**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **27-Dec-2018**

Name of Hirer **PEK CHENG BOON**

Hirer NRIC **S7136039C**

Signature :



Address **182 RIVERVALE CRESCENT #15-321**
540182

Contact No. **90238085**

TAX INVOICE

8010042

LONPAC INSURANCE BERHAD
THE CONCOURSE

300 BEACH ROAD #17-04/07
SINGAPORE 199555

CONTACT NO: 62507388

VEHICLE NO
SHC3816H

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
07.08.2014

CHASSIS CODE
KMHLB41UMEU056314

NO/DATE
91423048 29.01.2019

JOB NO.
305254793

ODOMETER READING

JOB TYPE

Description : 3P 27.12.2018 -C

Invoice for Lump Sum Repair

| | | |
|-----------------------------|--|-----------------|
| Total Lump Sum Repair Amt | | 5,250.00 |
| Add GST @ 7.000 % | | 367.50 |
| Total Invoice amount | | 5,617.50 |

Issued by : KATHERINE TAN 29.01.2019 10:50:30
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

- 1) WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- 2) CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- 3) INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- 4) PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of **COMFORTDELGRO**

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

| ACCOUNT No. | INVOICE No. | AMOUNT | BANK/CHQ No. |
|-------------|-------------|--------|--------------|
| | | | |
| | | | |
| | | | |

Our Ref: CT18120755

Date: 21 January 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 27/12/2018 @ 08:45 hrs
ALONG T JUNCTION OF YISHUN AVE 8 AND YISHUN AVE 1
INVOLVING SKD1066C, SJN7206K

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC3816H** (the "Taxi"). The Taxi was hired to **PEK CHENG BOON IC NO S7136039C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$117.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

则规录

请在换班前将里数记录在簿上。记录里数时，点后的数字。

以撕掉记录簿内的任何页数。

理局官员随时检查。

好好报告。

灵簿的工友，采取纪律行动。

必须注明在簿子内。工友必须保存一切有关的

[illegible]

Enquire Vehicle Insurer

| Vehicle No. | Incident Date/Time | Search Status | Insurance Company Code | Insurance Company Name |
|-------------|------------------------|---------------|------------------------|------------------------|
| SKD1066C | 27 Dec 2018 / 08:45:00 | Successful | L06 | LONPAC INSURANCE BHD |

[Previous](#)[OK](#)

SUC 3816 H

