ASS. REC. BY:	REF: CS/F(1 190	NV 81000	Special Instruction:	
Surveyor Noz	ASSIGNM	ENT (Office)		
From (Person); (W.S. String	e ler of	FCL	Date/Time: 0	12012019 1005cm
Estimated Cost:		Bill to:		
OD THAWSATP RES / OD TO Inspect Vehicle No:	SLG 1959Z	CS	Insured: SHE	3796AL
at Workshop m/s	World Auto		Tel: 6362 17	76
ofNb.	1 Kranji Loop			
Policy No:	3 1	Claim No:	D19000059M1	FSH
Sum Insured:		Excess:		
Make of Veh: (Client's Record)		T _w	D.O.A. 3	7122018
CA / REV / REP. / REV 2			H.O.D. Endo	rsement:
Date/Time: 02012019 110	Person Contacted:	Daniel	Vehicle N	DUT
Date/Time Action/Instruction	on (/) Estimate	2	*/	
SIG 1959Z				
1896C 8HS	- NS/TNC18014660	/Klvbn2	DIA:	11 082018
Hill9 Email pre	li revised to Fo	Z		·

Envour M2	REF: FA			
Chrydia , 1001	AS	SIGNMENT		
From:	Date: 03013019	Veh No. SLG 19592 Type: M.Car / M.Gycle / Bus / Van /	Yr Regn. 23	
Estimated Cost:		Truck / Trailer or	Long i som i me	
OD (T) / WS / TP RES / OD RES /		Access to the second	1 1.5X cc	1,496
	19592	Colour BLUE		Std / NI / NA
at Workshop m/s World			T/Radio (Insured)	1
of No. 1 Krani	i mob	Sp.Reading 126, 40/		1
Insured		Eng/No: RU 3(2) \	058 .	
Policy No.		Gen. Cond: Good /(Fair / Poor / Bur		
Claims No.	was the	Steering: (Inorder/ Jammed / Leake		
Sum Insured:	Excess:	Brake: (Inorder / Jammed / Leake		
(Client's Record)		Modi: Nil / S/Rim / STD A/Rim		
Make of Veh:			15/60 R16	
			13 /60 12-16	
(Policy Condition) Remark: The veh had commenced	its N/S O/S	BS (DUN) EXNOVA / GY / FS / LIZ	A / MIC / OHTSII / PIR /	SUML
repair at the time of insp		TOYO / YOKO or R (G	2	JOINI 1
TOTAL PROPERTY OF THE PARTY OF) X X X		Rear	
Bal, or Market Value:	onsistent? : Yes or No	Front R/Bal. 5 mm	R/Bal.	mm
ione risolatin ripola	onsistent?: Yes or No	L/Bal. 5 mm	L/Bal.	mm
7		D.O.A. 27/12/18	D.O.I. 2/1	119
Est. Repairs: 5 days	3 Val.: Yes or No	Survey held at Work		
Larri Carri		Des. of Damages : Frt / (Rear /) O/		on or
CA / REV / REP. / 24 HRS	Vehicle: IN / OU			-
Date: Person Cont		The U/C / Chassis frame / Bo	ody Structure affected	due to collision.
Date / Time Action / Instruction	n		ŦC	1019
Naz	No check	parts prices. &		1111
	on my rem	arks.	Amosta.	
21/1/19 FINAL 1287	PART BY PART R	Arks. FPAIR 03436.40/3	DAYD.	
(Red 5	33.40, 60/9	'	1	
			41	
	RECEIVED 2 3	JAN 2019		
Date/Time, File Pass to?	eli. Report	Days Of Repair: 3		
1) : Fit Date/Time. File Return to?	nal Report	Resurvey No. of Trip:	Survey Fee:	160
2) 23/1- typist	Add F	ee: Site Insp (\$)S+RSSI	50
I. Ph.		: Interview (\$) Photos	21
Report Format :	ws .	Tech Invs (\$) Others	
	+36-HO	Weekend (\$,).	
	76	Treasure of	TOTAL	281



Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

31-12-2018

Our Ref No. D19000095MFSH

Accident Date

27-12-2018

Claim Type. Third Party

Insured Vehicle

SHB2969L

Third Party Vehicle. SLG1959Z

Survey Location

NO.1, KRANJI LOOP

Contact Person.

AINEE

Contact No.

63621776/0

Fax No. 63631250

Survey Type

WITHOUT PREJUDICE: NO EST. PROVIDED [QUANTUM TO BE AGREED]

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

WORLD AUTO PTE LTD

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 4 January 2019 10:37 AM

To: Cc: 'CWS Motor Claims' 'Serene Ler'; SUR

Subject:

RE: SURVEY ASSESSMENT - D19000095MFSH/1, SLG 1959Z

Attachments:

SLG 1959Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLG 1959Z

Date of survey: 2/1/2019 Number of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 2 January 2019 11:02 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19000095MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 2 January, 2019 10:05 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg >; Serene Ler < Sereneler@msfirstcapital.com.sg >

Subject: PRI: SURVEY ASSESSMENT - D19000095MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

D19000095MFSH

Our ref:

CS/FCI19000018/Nvb

Date: 4/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 1959Z

We thank for your instruction on

2/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on $\underline{2/1/2019}$ at the premises of M/s $\underline{WORLD\ AUTO\ PTE\ LTD}$ and have the following to report:-

Workshop Estimate Amount	: S\$8,669.80
Revised Estimate Amount	: S\$3,496.40
"Check" Items Amount	: S\$1,493.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage: The vehicle sustained damages at the rear portion nearside front offside

Comments/Present Status:

Damages Consistent

Yours faithfully,

Muhd Nazril

Technical Investigator

la Captal

MWA118166817 / World Auto Pte Ltd - HQ ENTRY DATE & TIME: 28/12/2018 15:36 SUBMITTED BY: Gan Ping

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

•	•							ΓEΝ	0 E N	VТ
	٩.	, C	ı	_	VII.	\sim	м	- 1	41-11	ч.

Date Of Report

28/12/2018 15:36

Date Of Accident

27/12/2018 09:45

Exact Location Of Accident

PIE & CHANGI AIRPORT

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLG1959Z

Insured/Policyholder

Name Of Registered Owner

LION CITY RENTALS PTE LTD

Co Reg No

201504621K

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-62414992

Vehicle Particulars

Manufacturer

HONDA

Model

VEZEL-1.5 HYBRID (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

YES

Policy Number

999995145

Cover Note Number

Driver

Name of Driver

ONG KAY HONG

NRIC No

S7837332F

Date Of Birth

02/12/1978

Occupation

OUTDOOR

Date Of Driving Pass

28/09/2012

Driving Experience

6 YEARS AND 2 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-83326365

Fax Number

Contact Number

EMail Address

NOEMAIL

Address **NOADDRESS**

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured PAID DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

NO

YES

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

If Yes. Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHB2969L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report gorzectly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Formby insurance companies is not an admission of palicy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forw orded by the insurers of the GIA Records Management Centre established by the General insurance Association
 of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 6. Consent under the Personal Data Protection Act (PDPA)
- l understand, acknowledge, agree and consent that :
- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose andfor process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "lineurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (§ processing, handing and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (6) investigating the accident and/or my claims:
- (4) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the malting of correspondence, statements, involves, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/multi packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insuran(s) who have insured vehicle(s) involved in this accident and the insurans' law yeraflaw firms, may fare permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GBA to their third party service providers or agents (including their law yers faw firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's-Signature / Data &

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnal

Vehicle A SLG19597 Ú hod

Sketch Plan #2


Describe Circumstances of the Accident

The very river statistill of Very de P LECTION
SI 4 1959 2 was fragelling along PIE towards
Chang's Airport directions I was sending a demake
passenges to flora Dr. in my vehicle A on PIE
when 2 noticed frat the car in drant of me
make a emergency bruke and un his harard
light, hence I also make a emergency
brake to stop my vehicle After that I
Seel a stong impact buy unto the back of
my car I abyted my car and saw the
damage that have been damaged by Vehlile
B because of this instal
Declaration
We declare the foregoing particulars are true in every respect.
The second
128/2/R
Order's Signature / Date & Driver's Signature (if griver is not the solicyholder) / Date Witnessed by Reporting Centre Personnel

Sketch Plan #3











This coust is not transferable, and is the property of the Land Transport.

Authority (LTA): It must be surrendered to the LTA at request. It tours, please return to LTA, 10 Ser Ming Drive, Singapore S76721.

Type Theoription Tests Date

02 TAXT VL 17/02/2014

03 BUS VL 20/05/2014

04 BMS ATTENDANT 20/05/2014

1 1

Unit Price Amount S\$

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03 Halcyon 2, S'pore 577200

Tel No.: 6451 3933 Fax No.: 6455 7576 E-Mail: worldaut@singnet.com.sg Website: www.worldauto.com.sg

Tax Reg. No.: 200006765-H Buss. Reg. No.: 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

S/N Quantity

Attention : Motor Claim Department
Contact : 6222 2311 Fax No. : 6222 3547

Particular

Estimate: ES000453

Date: 29/12/2018

Vehicle Num. : SLG 1959Z (LCR) Make/Model : HONDA VEZEL HYBRID

Chassis/Eng#:

Accident Date : 27/12/2018

Claim No. : Reference : Policy No. :

2. 3.	1 1	LIST ITEMS: REAR BOOT LID REAR BOOT HYBRID EMBLEM (VEZEL)		DEF CNEC
•	1	REAR BOOT VEZEL EMBLEM (VEZEL) REAR WINDSCREEN GLASS MOULDING		and o KNA
•	1	REAR BOOT LOCK ASSY	300.00	
	4	REAR BOOT LOCK ASST REAR BOOT HAND GRIP COVER	78.00	
:	2	REAR BOOT REFLECTOR LAMP	580.00 1,160.00	
	1	REAR BUMPER	900.00	
	1	REAR END PANEL Phato		?5502
0.	1	REAR END PANEL TOP GARNISH	260.00	
1.	1	REAR BOOT WEATHER STRIP	180.00	
		List TotalS\$: 20.00% Discount S\$:	2,358 5,286.00 1,057.20	
			88 6.40 4,228.80	
		SPECIAL NETT ITEMS :		300 NEU
	1	REAR WINDSCREEN SEALANT	1 00 .00	
	1	REAR BUMPER CLIP REVERSE SENSOR	2 80.0 0	1/200
	1	REAR END PANEL TOP GARNISH CLIPS	40.00	220 1
		Special Nett Total S\$:	300 821.00	1
		LABOUR:		
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	180.00	20
		. REMOVE & REFIT REAR WINDSCREEN GLASS	180.00	100
			120	

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03 Halcyon 2, S'pore 577200

Tel No.: 6451 3933 Fax No.: 6455 7576 E-Mail: worldaut@singnet.com.sg

Website: www.worldauto.com.sg

Tax Reg. No.: 200006765-H Buss. Reg. No.: 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention: Motor Claim Department

Contact: 6222 2311 Fax No.: 6222 3547

Estimate: ES000453

Date: 29/12/2018

Vehicle Num.: SLG 1959Z (LCR)

Make/Model: HONDA VEZEL HYBRID

Chassis/Eng#:

Accident Date: 27/12/2018

Claim No.: Reference: Policy No.:

S/N Quantity

Particular

Unit Price Amount S\$

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS

REVERSE SENSORS AND START/STOP UNIT CAPACITORS

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME

(HV HYBRID SYSTEM SAFETY PROCEDURES)

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST

REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

Labour Total S\$:

180.00

1,000.00 400

400

1,000.00

180.00 30

450.00 200

100

450.00 200

100

1, 250 3,620.00

E. & O.E.

Total S\$:

8.669.80

========

LKK Auto Consultants hence notify

. To display damaged part(s) during resurvey

. Third party survey is on a "Without Prejudice" basis

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

· Parts prices are subject to confirmation

. No illegal modification(s) is allowed

the Repairer of the following: . To resurvey before/after spray painting

for WORLD AUTO PTE LTD

PART \$2358.00 LESS 20% \$1886.40

S/NETT \$ 300.00

LABOUR \$1,250.00

TOTAL \$3,436. 40/3 DAYS

NAZ LKIC .2/1/19 1600

CHECKED ITEMS PHOTOS

BEFORE PAIN PHOTOS

Acknowledged by Repairer Signature:

Date:

Veron Chen (LKKAuto)

From:

Naz (LKKAuto)

Sent:

Monday, 21 January 2019 12:42 PM

To:

tgttan@worldauto.com.sg

Cc: Subject: Veron Chen (LKKAuto); SUR Re: SLG 1959Z Finalization

Attachments:

FINALIZATION.pdf

Dear Ms Tan,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on the part prices. We will proceed to finalize if you are agreeable with the amended COR:

PARTS - \$2358

LESS 20% - \$1886.40

SPECIAL NET ITEMS - \$300

LABOUR - \$1250

TOTAL - \$3436.40 / 3 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tgttan@worldauto.com.sg <tgttan@worldauto.com.sg>

Sent: Friday, 18 January 2019 4:27 PM

To: Naz (LKKAuto)

Subject: RE: SLG 1959Z Finalization

. Naz

No dismantle parts.

Rdgs Sophia

From: Naz (LKKAuto) <Naz@lkkauto.com> Sent: Thursday, 17 January 2019 6:13 PM

To: tgttan@worldauto.com.sg

Cc: Veron Chen (LKKAuto) < veronchen@lkkauto.com>; SUR < sur@lkkauto.com>

Subject: Re: SLG 1959Z Finalization

Dear Ms Sophia,

Before paint photos received. Kindly send me the dismantle photos as there are check items.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | \$(408933)

From: tgttan@worldauto.com.sg <tgttan@worldauto.com.sg>

Sent: Wednesday, 16 January 2019 1:31 PM

To: Naz (LKKAuto)

Subject: FW: SLG1959Z Our ref: TP/2394/18

Hi Naz

Attach b/f paint photos.

Rdgs Sophia

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>

Sent: Wednesday, 16 January 2019 1:08 PM

To: tgttan@worldauto.com.sg

Subject: SLG1959Z

Ainee Thanks and Rgds, World Auto Pte Ltd Kranji: 63621776 Fax: 63631250

₹LD AUTO PTE LTD

an Pemimpin #01-02/03 2yon 2, S'pore 577200

/ No.: 6451 3933 Fax No.: 6455 7576

≟-Mail: worldaut@singnet.com.sg Website: www.worldauto.com.sg

Tax Reg. No.: 200006765-H Buss. Reg. No.: 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention: Motor Claim Department

Contact: 6222 2311 Fax No.: 6222 3547

Estimate: ES000453

Date: 29/12/2018

Vehicle Num. : SLG 1959Z (LCR)

Make/Model: HONDA VEZEL HYBRID

Chassis/Eng#:

Accident Date : 27/12/2018

Claim No. : Reference : Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :	¥ 22	-D
	1	REAR BOOT LID	1,15	1,300.00
	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00
	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00
	1	REAR WINDSCREEN GLASS MOULDING		250.00
	1	REAR BOOT LOCK ASSY		300.00
5.	1	REAR BOOT HAND GRIP COVER		78.00
	2	REAR BOOT REFLECTOR LAMP	580.00	1,160.00
3.	1	REAR BUMPER		900.00
).	1	REAR END PANEL Phate		680.00
0.	1	REAR END PANEL TOP GARNISH		260.00
1.	1	REAR BOOT WEATHER STRIP		180.00
		List TotalS\$:	2,35	5,286.00
		20.00% Discount S\$:		1,057.20
		20.00% Discount S\$:		
			1,886	40 4,228.80
		SPECIAL NETT ITEMS :		
	1	REAR WINDSCREEN SEALANT		100.00
	1	REAR BUMPER CLIP	9	401.00
	1	REVERSE SENSOR		286.00
	1	REAR END PANEL TOP GARNISH CLIPS		40.00
		Special Nett Total S\$:	3	821.00
		LABOUR:		
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00
		. REMOVE & REFIT REAR WINDSCREEN GLASS		180:00
				120

CONTINUE / ...

RLD AUTO PTE LTD

lan Pemimpin #01-02/03 cyon 2, S'pore 577200

J No.: 6451 3933 Fax No.: 6455 7576 č-Mail: worldaut@singnet.com.sg

Website: www.worldauto.com.sg

Tax Reg. No.: 200006765-H Buss. Reg. No.: 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention: Motor Claim Department

Contact: 6222 2311 Fax No.: 6222 3547

Estimate: ES000453

Date: 29/12/2018

Vehicle Num. : SLG 1959Z (LCR)

Make/Model: HONDA VEZEL HYBRID

Chassis/Eng#:

Accident Date: 27/12/2018

Claim No. : Reference: Policy No.:

S/N Quantity

Particular

Unit Price Amount S\$

TO APPLY RUSTPROOFING! TUFFCOATING TREATMENT TO REPLACED PARTS.

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

Labour Total S\$:

180:00 50

1,000.00 400

400 1.000.00

180.00 30

450.00 200 100

450.00 100

100

1, 250 3,620.00

E. & O.E.

Total S\$:

8,669.80 ------

for WORLD AUTO PTE LTD

PARTS \$2358.00

1555 20% \$1886. 40

SINETT 1 300.00

NAZ LKIC -2/1/19 1600

CHECKED ITEMS PHOTOS

BEFORE PAIN PHOTOS

TOTAL \$3,436. 40/3 Days

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inte	rnationale Des Experts En Auton	nobile
MS FIRST CAPITAL I	NSURANCE LTD	Ref : CS/FCI190000	18/Nvbe2
36 ROBINSON ROAD #16-01 CITY HOUSES	SINGAPORE 068877	Date: 24-01-2019 Code: FCI2	
	Policy Particu	lars :- THIRD PARTY CLAI	M
Insured Veh.	SHB 2969L	Veh. Inspected	SLG 1959Z
Policy No.		Coverage (\$)	0.00
Claim No.	D1900095MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	02/01/2019
2.	Vehicle I	Particulars & Condition	
Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31211058	Colour	BLUE
Odometer	126401	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
	Co	nditions of Tyres	Hart Ret Constitution
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	GITI	5 mm
L/H Rear Tyre	215/60 R16	GITI	5 mm
	Desc	ription of Damages	
THE VEHICLE SU	JSTAINED DAMAGES AT TH	E REAR PORTION.	
DAMAGES SEE I	DETAILS.		
	Ge	neral Information	
Accident Date	27/12/2018	Inspection Date	02/01/2019
Survey held at	NO 1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		
ia.		Remarks	
B)THE INSPECTI		EPORT. A"WITHOUT PREJUDICE" BAS NS, WE HAVE NOT AUTHORIS	
5b.		nate Days of Repair	
ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	3 Working Day	s



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 1959Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	DEFORMED	1,300.00	1,100.00
1	REAR BOOT HYBRID EMBLEM (VEZEL)	NECESSARY	89.00	89.00
1	REAR BOOT VEZEL EMBLEM (VEZEL)	NECESSARY	89.00	89.00
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	250.00	-
1	REAR BOOT LOCK ASSY	SERVICEABLE	300.00	-
1	REAR BOOT HAND GRIP COVER	SERVICEABLE	78.00	-
2	REAR BOOT REFLECTOR LAMP @\$580.00	SERVICEABLE	1,160.00	-
1	REAR BUMPER	DENTED	900.00	900.00
1	REAR END PANEL	SERVICEABLE	680.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	260.00	-
1	REAR BOOT WEATHER STRIP	DEFORMED	180.00	180.00
	LESS 20% DISCOUNT		-1,057.20	-471.60
			4,228.80	1,886.40
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR BUMPER CLIP (SN)	NECESSARY	401.00	30.00
1	REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
			821.00	300.00
	LABOUR			
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	50.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	50.00
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,000.00	400.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER / OUTER)		1,000.00	400.00

Report Ref No. CS/FCI19000018/Nvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START / STOP UNIT CAPACITORS.		180.00	30.00
	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	100.00
	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	100.00
	30 - Carlotte (1864 - 1864 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865 - 1865		3,620.00	1,250.00
	GRAND TOTAL		8,669.80	3,436.40

RECOMMENDED COST OF REPAIRS	3,436.40
-----------------------------	----------

Report Ref No. CS/FCI19000018/Nvbe2

1

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.