

ASS. REC. BY:

REF: CS/FCU9000042/Ksbn2

Special Instructions:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of

FCL

Date/Time: 02012019 1:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TR RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GU 1577C

Insured:

SHC 606S

at Workshop in/

Tropical Success

Tel:

of

Blk 5032 Annk bu Park 2 #01-303

Policy No:

Claim No:

D19000097MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29122018

CA / REV / REP. / REV 24 HRS 'DS'

07.01.2019

H.O.D. Endorsement:

Date/Time: 02012019 1:53pm

Person Contacted:

Calvin

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	GU 1577C - CS/TP09029047 / Ar	Out-03122019
	SHC 606S - NS/INC:15021370 / 111qbn2	Out: 09122015
03/01/19	@ 17:29 pm. revised PA to Karen via email.	
14/16	81826.68 email & confirmed	
	C \$1,206.71 e.d - 40% ~	

REF: FCI

ASSIGNMENT

From: Date: 07/01/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: GU1577C
at Workshop m/s: Tropical Success

of Blk 5032 AMK Ind. park 2 #01-303

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

after 10:30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$52k

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 03 days Res: Yes or No

Lum Sum: 1.8.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GU1577C Yr Regn: 02, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyno

C.C. 2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp Reading:

48457

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEA T35Y 90K 207316

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: B5

195/75R15

R:

155 R12 X 8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal:

1 B.5 mm

Rear:

R/Bal:

11 B.9 mm

L/Bal:

1 0.5 mm

L/Bal:

99 Max axle mm

D.O.A:

27/12/18

D.O.I:

7/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/1 File pass to CA

RECEIVED 17 JUN 2019

Date/Time, File Pass to?

17/06/19

Date/Time, File Return to?

3)

Report Format:

Lump Sum (I.B.) (\$ 1,826.65 p/p)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

S + RS of

Notes

Others

TOTAL

130

50

50

18

248



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000097MFSH

Date: 08 January 2019

Our Ref: CS/FCI19000042/Ksb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GU 1577C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/01/2019 at the premises of M/s Tropical Tech Automobile Services and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,033.40</u>
Revised Estimate Amount	: <u>S\$ 2,373.10</u>
"Check" Items Amount	: <u>S\$</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-12-2018	Our Ref No. D19000097MFSH
Accident Date	27-12-2018	Claim Type. Third Party
Insured Vehicle	SHC0606S	Third Party Vehicle. GU1577C
Survey Location	Blk 5032 Ang Mo Kio Ind Pk 2 #01-303	
Contact Person.	CALVIN	
Contact No.	64817773/ 64817773	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TROPICAL SUCCESS AUTO CARE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 17 June 2019 8:02 AM
To: Shirley Hiew (LKK Auto)
Subject: FW: Finalised for GU1577C,

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: William Tan <tanlihao74@gmail.com>
Sent: Saturday, 15 June 2019 6:45 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; William Tan <tanlihao74@gmail.com>
Subject: Re: Finalised for GU1577C,

Dear Sir / Madam,

I accept your cost of repair (Part by Part) @ \$1,826.69 and accept 3 working repair day.

From : William Tan

On Fri, 14 Jun 2019 at 9:08 AM, Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com> wrote:

Attach finalised for GU 1577C. Kenneth

From: William Tan [mailto:tanlihao74@gmail.com]
Sent: Friday, 14 June, 2019 4:53 AM
To: Kenneth Kong (LKKAuto); Veron Chen (LKKAuto); William Tan
Subject: Fwd: GU1577C, defective photo

Dear Sir / Madam,

Can we finalist this vehicle GU1577C (Part by Part).

Your message is ready to be sent with the following file or link attachments:

IMG_7910
IMG_7902
IMG_7903
IMG_7904
IMG_7905
IMG_7906
IMG_7907
IMG_7908
IMG_7909

From : William Tan

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 8 January 2019 5:29 PM
To: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19000097MFSH/1
Attachments: GU 1577C - Preli Advise -.pdf

Dear Karen,

Enclosed preliminary revised of vehicle GU 1577C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 2 January, 2019 1:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000097MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4500X
Vehicle Details	
Vehicle No.:	GU1577C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2674064
Chassis No.:	JTFAT35Y90K207316
Maximum Power Output:	-
Open Market Value:	\$26,436.00
Original Registration Date:	28 Feb 2017
First Registration Date:	28 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$1,322.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,360.00
COE Rebate Amount:	\$35,268.00
Total Rebate Amount:	\$35,268.00

The information contained herein is correct as at 10 Jan 2019

OK

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Vehicle A: GU 1579C

Vehicle B: SHC 6065

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26-12-2018 at about 18.00 hrs, I parked my lorry outside of my neighbour 12 Jalan Mahir (landed house) and left.

On 27-12-2018 at about 0039 hrs, my vehicle GU1579C was hit by a taxi SHC 6065 while entering in to alight passengers. The passenger in the taxi asked the driver to look for me at my residence which is a few unit away from the scene.

I went with the taxi driver to examine my lorry and found that ^{the} front RH head-lamp, front RH door & front bumper were damaged.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy ☒ Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

Email: sm@idac.com.sg Tel no: 6555 6888

*If no proper documents are produced, IDAC shall not file the report. Information will be discarded after one week.

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 27 / 12 / 2018 (dd/mm/yy) Time of Accident: 00 39 (24-HR-FORMAT)

Vehicle No.: Gu 1577C Vehicle Make & Model: Toyota Dyna 150

Exact location of Accident: Parking stationary outside of 12 Jalan Mahir.

Policyholder's Name / IC No.: Ming Tian Fresh Flower Supplier / S0214500X

Driver's Name / IC No.: Estee Tan Swan Thai (2) Estee Chen Xuan Chai / S0162888C (As Above) ☐

Driver's Contact No.: 98286810 Company Contact No (Company Veh Only): 6457 5575

Driver's Address: 6 Jalan Mahir, Singapore 537808

Email address: tsac303@singnet.com.sg Insurance Company: India International Insurance
Esteehen9@yahoos.com

Relationship between Owner & Driver: (Please CIRCLE one only)

☒ Owner ☐ Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident:

☐ Private use / ☒ Work purpose

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

*No. of Passengers (Including Driver): _____

*Passenger Name: N/A

*Passenger Name: N/A

Gender: Male / Female
Gender: Male / Female

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☒ Yes / ☐ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: _____ Vehicle No.: SHC 606S
Driver's Contact No.: 9620 0873 Insurance Company: _____

2. Driver's Name / IC No (If Any): _____ Vehicle No.: _____
Driver's Contact No.: _____ Insurance Company: _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1980 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1994 (MALAYSIA)

This certificate is not transferable to a new owner of the vehicle. If for any reason the insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the legislation relating to compulsory insurance.
The Certificate must be returned if the insurance is suspended during its currency.

Agency Code: **87396SE**
Comprehensive

Excess: \$600/-Sect. 1 & additional \$2500/- Sect. 1 for age <21 years
or > 65 years &/or S'pore D.L. < 2 years
Windscreen: \$5100/-

CERTIFICATE NO.

M495651

1. Index Mark and Registration
Number of Vehicle

GU 1577 C

2. Name of Policy Holder

Ming Tian Fresh Flower Supplier

3. Effective date of the commencement of
insurance for the purposes of the Act

28th February 2018

4. Date of Expiry of Insurance

27th February 2019

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has
been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving
the Motor Vehicle.

6. Limitations as to use*

- (1) Use in connection with the Policyholder's business
- (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
- (3) Use for social, domestic and pleasure purposes

The Policy does not cover

- (1) Use for hire or reward or for racing, pace-making, reliability trial, or speed-testing
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

*Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the
Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy in which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Date of Issue: **hh/05.02.2018**

SUNMEX ENTERPRISE
8 ENGGOR STREET
#24-02
SINGAPORE 079718
TEL: 6220 5977 FAX: 6220 1698

for India International Insurance Pte. Ltd.
(APPROVED INSURERS)

M2, 100% (GOODS CARRYING)
PRIVATE TYPE

IMPORTANT NOTICE

Authorised Signatory

Policyholders are hereby warned that under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person
to use or to cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

Policyholders are further warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance
company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this
obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed
to by the insurance company concerned. If the insurance company agrees to cover the new owner they will endorse the policy accordingly and will issue a
new Certificate of Insurance in the new owner's name.

IN THE EVENT OF AN ACCIDENT NOTIFICATION SHOULD BE GIVEN IMMEDIATELY TO THE COMPANY. FAILURE TO DO SO WILL RESULT IN
UNDERWRITERS DECLINING LIABILITY.

Agent/Broker Name: **Sunmex**

Hire Purchase Company: **NA**

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2162888C



Name

ESTEE TAN SWAN THOI
@ESTEE CHEN XUANCHAI

陈 璇 钗

Race

CHINESE

Date of birth

01-11-1955

Country/Place of birth

MALAYSIA

Sex

F

REPUBLIC OF SINGAPORE DRIVING LICENCE



Identity Card No. S2162888C

ESTEE TAN SWAN THOI

Birth Date: 01 Nov 1955

Issue Date: 15 Jul 2003



0005579778

3339872



NRIC No. S2162888C



Date of Issue

15-08-2014

Address

8 JALAN MAHIR
SINGAPORE 537808

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS/ES

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

18 Aug 1995



Licence No. S2162888C

NP 425A

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / S : **First Capital Insurance Ltd**
36, Robinson Road, #16-01
City House, Singapore 068877

Estimate bill : TT 63 / 18 / TP / WT

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Registration No : GU1577C
Make / model : Toyota Dyna 150

Mileage :

Date : 02 / 01 / 201

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHC606S AND GU1577C ALONG
OUTSIDE 12 JALAN MAHIR ON 27 DECEMBER 2018 AT ABOUT 0040 HRS.**

1pc	Front RH head-lamp	474.25	864.00
1pc	Front bumper		702.00
1pc	Front bumper side bracket (RH)		243.00
1pc	Front door-step board (RH)		257.00
	Sub total :		2,066.00
	Less 10% Discount:	258	206.60
	A total :		1,859.40

Special net items :

Front RH door 'Company Address' label
B total

25.00
\$ 44.00
\$ 44.00

Total amount of Page 1 :

\$ 1,903.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to consultation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services



(Authorised Signature)
William Tan

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **First Capital Insurance Ltd**
36, Robinson Road, #16-01
City House, Singapore 068877

Estimate bill : TT 63 / 18 / TP / WT

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Registration No : GU1577C

Make / model : Toyota Dyna 150

Mileage :

Date : 02 / 01 / 201

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHC606S AND GU1577C ALONG
OUTSIDE 12 JALAN MAHIR ON 27 DECEMBER 2018 AT ABOUT 0040 HRS.**

Remove and transfer front bumper necessary attachment spare part items.

Remove & refit front RH head-lamp, front bumper, front bumper side bracket (RH), front
door-step board (RH)

Heat / weld / beating front RH door, heat / weld / beating / pull / straighten / align front
chassis frame by Chassis Alignment Jack.

To check and refit front head-lamp wiring.

Tuff kote front damaged portion.

Putty / primer application, spray painting front bumper, front RH door.

Balance amount brought from Page 1 :

Grand final amount:

300
\$ 350.00

20
\$ 80.00

\$ 200.00

400
\$ 500.00

\$ 1,903.40

\$ 3,033.40

Tropical Tech Automobile Services



(Authorised Signature)
William Tan



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000042/Ksbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 606S	Veh. Inspected	GU 1577C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000097MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	02/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y90K207316	Colour	SILVER	
Odometer	48457	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	BRIDGESTONE	1 mm	
L/H Front Tyre	195/75 R15	BRIDGESTONE	1 mm	
R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	1/1 mm	
L/H Rear Tyre	155 R12X8 (D)	MAXMILER	9/9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2018	Inspection Date	07/01/2019	
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 1577C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT RH HEAD-LAMP	CUT / CRACKED	864.00	725.00
1	FRONT BUMPER	BUCKLED / DISTORTED	702.00	474.25
1	FRONT BUMPER SIDE BRACKET (RH)	DISTORTED	243.00	243.00
1	FRONT DOOR -STEP BOARD (RH)	SERVICEABLE	257.00	-
	LESS 10% DISCOUNT		-206.60	-
	LESS 25% DISCOUNT		-	-360.56
			1,859.40	1,081.69
SPECIAL NETT ITEMS				
1	FRONT RH DOOR 'COMPANY ADDRESS' LABEL (SN)	NECESSARY	44.00	25.00
			44.00	25.00
LABOUR				
	REMOVE AND TRANSFER FRONT BUMPER NECESSARY ATTACHMENT SPARE PART ITEMS.)		350.00	300.00
	REMOVE & REFIT FRONT RH HEAD-LAMP ,FRONT BUMPER ,FRONT BUMPER SIDE BRACKET (RH),FRONT DOOR-STEP BOARD (RH).)		-	-
	HEAT/WELD/BEARING FRONT RH DOOR ,HEAT /WELD/BEARING/PULL /STRAIGHTEN /ALIGN FRONT CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.)		-	-
	TO CHECK AND REFIT FRONT HEAD-LAMP WIRING.		80.00	20.00
	TUFF KOTE FRONT DAMAGED PORTION.	NOT NECESSARY	200.00	-
	PUTTY/PRIMER APPLICATION ,SPRAY PAINTING FRONT BUMPER ,FRONT RH DOOR.		500.00	400.00
			1,130.00	720.00
GRAND TOTAL			3,033.40	1,826.69
RECOMMENDED COST OF REPAIRS				1,826.69

Report Ref No. CS/FCI19000042/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.