Surveyor Taufiq | REF: ASM(AXA)

ASSIGNMENT

From: | Date: 04/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 5952G

at Workshop m/s Performance

of 303 Alexandra Road

Insured:

Policy No.:

Claims No.:

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 3.30 Kalvin

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: @138K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No. SLW5952G | Yr Regn. 2018, Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 318 | c.c 1499

Colour: Black | A/C: Insured / Std / NI / NA

Sp.Reading: 13423 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA8E3604DN4 82307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17 | R: 2 | 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	4/1/19

Survey held at PWL.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: ___S + RS___SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)