

INS. CASE OWNER:

CC 6/1111900 0057, Aebo

LKK:  
IDAC:

Surveyor: Adrian


DOI: ASSIGNMENT  
21/12/18

Date / Time: 21/12/18

Registered in Merimen: 21/19

Pre-assign / CCU / FTE

SMA 7681M



Insured Vehicle No. : \_\_\_\_\_

Claim No. : \_\_\_\_\_

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II :SS \_\_\_\_\_ D.O.A : 20/12/18

Place of Accident : \_\_\_\_\_

Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : \_\_\_\_\_

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SGC 5555



INSRS: Ho  
WSP: Bing  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/Time	STAGE	DATE / PIC	
<u>SGC 5555</u> <u>SMA 7681M</u>	Non-Reporting ltr (1st):		
	Non-Reporting ltr (2nd):		
	Non-Reporting ltr (Final):		
	Notification ltr (if non-pickup):		
	Call OI:		
	After call ltr to OI:		
	<b>Documentation Check List: Handler Typist</b>		
	Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>	<input type="checkbox"/>	
PIR:	<input type="checkbox"/>	<input type="checkbox"/>	
Mandate/Reject Instruction:	<input type="checkbox"/>	<input type="checkbox"/>	
LOD	<input type="checkbox"/>	<input type="checkbox"/>	
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>	
Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>	
Others:	<input type="checkbox"/>	<input type="checkbox"/>	

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_ Confirm by: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_  
 Repair Cost: \$ ( \_\_\_\_\_ days) Reduction: % Email  Call

**FINAL SETTLEMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call   
 Final Liability: % (Agreed / Assessed) BOLA S/N No. : \_\_\_\_\_ If NO or B 28, Ass. Lia : \_\_\_\_\_

Repair Cost: \$  
 Loss of Rental (LOR): \$ ( \_\_\_\_\_ days)  
 Loss of Use (LOU): \$ ( \$ x \_\_\_\_\_ days)  
 Loss of Income (LOI): \$ ( \$ x \_\_\_\_\_ days)

LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]  
 GIA/LTA Search \$  
 Medical: \$

Disbursement: \$ (e.g. Tow/ Independent )  
 Legal Cost \$  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format:  
 3) Survey fee:

**Total:** \$ **Global Sum \$:**  
**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$ Name 1: \_\_\_\_\_  
 Payee 2: (Strike if N.A.) \$ Name 2: \_\_\_\_\_  
 Payee 3: (Strike if N.A.) \$ Name 3: \_\_\_\_\_

REF:

Surveyor

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGC 5555J Yr Regn: 2007 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 257870 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROS3ZEC107145211

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 185/70R14

R: 185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 31/12/18

Survey held at Paya Ubi.

Des. of Damages: Ft / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP III Ho Beng.
	MV : 22K
	PV : 16.6K
	Nett: 5.4K.

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation: \_\_\_\_\_ \$ + RS. \_\_\_\_\_ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )

: Interview (\$ \_\_\_\_\_ )

: Tech. Invs (\$ \_\_\_\_\_ )

: Weekend (\$ \_\_\_\_\_ )