

INSURANCE

INS. CASE OWNER

CC 6/III1900 0057, Aebog

LOG

IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

21/11/18

Date / Time:

21/11/18

Registered in Merimen:

21/1/19

Pre-assign / CCU / FTE

S/K 7681M



Insured Vehicle No.:

U102

Name of Insured:

Insured Tel No.:

HP:

Excess See II (SS)

D.O.A.:

21/11/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Mohamad Ummy Izzah

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MET18120906

Policy No.:

MLOM0015

Make / Model:

MAZDA 3

Place of Accident:

SPRUITSWOODS WALK

OI GIA REPORT: YES / NO

YES / NO

TP GIA REPORT: YES / NO

YES / NO

Insured Liability: %

Final? Yes/No

SGC 5555



INSRS:
WSP:
Tel:
Liability:
RMKS:

Ho Bong



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
21/1/19 Mkr	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI: After call Itr to OI:	
26-1-19	Seek mandate for liability.	
30-1-19	mandate approve liability	
20-1-19	email copy liability cover	
05-04-19	FILE PASS TO TYPIST TO PREPARE REPORT.	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call Itr to OI	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: LOP

Repair Cost: 85 \$5 900 (Agreed / Assessed) BOLA S/N No.: 05 Email Call

FINAL SETTLEMENT Date/Time: 7/8/19 Confirm with: Chris Email Call

Final Liability: 60 (Agreed / Assessed) BOLA S/N No.: 05 If NO or B 28, Ass. Lia.

Repair Cost: 900.00 (100.00) (50 x 2 days) (5 x 2 days)

Loss of Rental (LOR): 55 (5 x 2 days)

Loss of Use (LOU): 100.00 (50 x 2 days)

Loss of Income (LOI): 55 (5 x 2 days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: 55 (1) Claim status: Normal/Reject/Private Settle

Medical: 55 (2) Report Format:

Disbursement: 55 (e.g. Tow/Independent) (3) Survey fee:

Legal Cost: 55

Total: 55 1000.00 Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: 55 1000.00 Name 1: Ho Bong Trading.

Payee 2: (Strike if N.A.) 55 Name 2:

Payee 3: (Strike if N.A.) 55 Name 3:

REF:

Surrey

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SGC5555J Yr Regn: 2007 April
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Altis C.C. 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 257870 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MROS3ZEC107145211

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil (S/Rim) / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 31/12/18

Survey held at Paya UbiDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction
TP III Ho Beng.

Hs: 4900 (RED) 10,491.20 92%.

MV: 22K
 PV: 16.6K
 Nett: 5.4K.

Date/Time, File Pass to?

 : Prel. Report : Final Report

Date/Time, File Return to?

3)

Report Format :

Lump Sum / L.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$ _____) Interview (\$ _____) Tech Invs (\$ _____) Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

) \$ + RS. \$ _____

) Photos _____

) Others _____

TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III19000057/Aeb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 02-01-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7681M	Veh. Inspected	SGC 5555J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/01/2019

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/12/2018	Inspection Date	31/12/2018
Survey held at	HO BENG TRADING BLK 3020A, UBI ROAD 1 #01-33 SINGAPORE 408714		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

31st DECEMBER 2018

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP111
Ashes.

Accident date: 20th December 2018

Estimated repair cost for vehicle no: SGC5555J TOYOTA ALTIS 1.6 '07

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet lock		\$53.90 +
2	1	Front bonnet inner rubber		\$83.10 +
3	6	Front bonnet inner rubber clips	\$12.90	\$77.40 +
4	2	Front headlamp	\$2,101.10	\$4,202.20 +
5	1	Front grille <i>cracked</i>		\$280.70 ✓
6	2	Front grille side nizzer <i>HP m</i>	\$16.20	\$32.40 +
7	1	Front grille emble logo <i>New</i>		\$89.40 38
8	1	Front bumper <i>torn</i>		\$415.65 ✓
9	2	Front Bumper Side Bracket <i>new</i>	\$53.10	\$106.20 64
10	8	Front bumper clips <i>new</i>	\$12.90	\$103.20 30
11	1	Front bumper number plate <i>cracked</i>		\$50.00 ✓
12	1	Front bumper reinforcement <i>Not new</i>		\$281.70 +
13	2	Front bumper fog lamp cover	\$131.10	\$262.20 +
14	2	front bumper reinforcement bracket <i>new</i>	\$131.10	\$262.20 +
15	1	front support panel <i>Rep</i>		\$852.00 +
16	1	Front air-con condenser		\$950.20 +
17	1	Front radiator <i>new</i>		\$1,020.00 +
18	1	Front radiator fan motor assy		\$518.75 +
Subtotal :-				<u>\$9,641.20</u>

878.35

658.76

Labour charges

To remove & re-fix cushion		\$120.00 x
To remove & re-fix air-condenser, front radiator fan & top up gas		\$250.00 x
To Check Wiring System		\$60.00 30
Tuff kote	480.	\$120.00 x
Panel beating		\$600.00 250
Spray painting		\$600.00 200

Subtotal :- \$1,750.00
 Total:- \$11,391.20

total: 1138.76
 L/S: 900
 02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 8384Z

Vehicle Details

Vehicle No: SGC5555J
 Vehicle to be Exported: Yes
 Intended Deregistration Date: 31 Dec 2018
 Vehicle Make: TOYOTA
 Vehicle Model: COROLLA ALTIS 1.6 AUTO
 Primary Colour: Silver
 Manufacturing Year: 2007
 Engine No.: 3Z24641734
 Chassis No.: MR053ZEC107145211
 Maximum Power Output: 81.0 kW (108 bhp)
 Open Market Value: \$15,245.00
 Original Registration Date: 23 Apr 2007
 First Registration Date: 23 Apr 2007
 Transfer Count: 5
 Actual ARF Paid: \$14,772.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Apr 2022
 COE Category: A - Car (1600cc & below)
 COE Period(Years): 5
 PQP Paid: \$25,115.00
 COE Rebate Amount: \$16,631.00
 Total Rebate Amount: \$16,631.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Dec 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	8384Z
Vehicle No.:	SGC5555J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4641734
Chassis No.:	MR053ZEC107145211
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,245.00
Original Registration Date:	23 Apr 2007
First Registration Date:	23 Apr 2007
Transfer Count:	5
Actual ARF Paid:	\$14,772.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	22 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,115.00
COE Rebate Amount:	\$16,631.00
Total Rebate Amount:	\$16,631.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Dec 2018

OK



Toyota Corolla Altis 1.6A (COE till 03/2021) \$13,000 \$5,910 /yr 14-Mar-2006 1,598 cc 245,990 km Sedan Available

Note That Its Engine Is Smooth N Gearbox Is In Perfect Condition. 2 Front Tyres Were Changed In Less Than 1 Year. Definitely More Cost Worthwhile To Drive For More Than 2 Years Or So. Schedule A Test D...

CONSIGNMENT

Carro

Posted: 19-Dec-2018 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 03/2026) \$42,800 \$5,920 /yr 22-Mar-2006 1,598 cc - Sedan Available

100% Loan Guaranteed Approval! All Our Cars Have Undergone A Workshop Check. Buy With Trust And Assurance! Expect Only Honest Deals! Call Our Friendly Sales Staff For A Non Obligatory Viewing Now!

Posted: 29-Nov-2018 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 05/2021) \$15,300 \$6,430 /yr 19-May-2006 1,598 cc - Sedan Available

Come View This Popular Japanese Reliable Work Horse. All Servicing Done Diligently. Radiator Changed Recently. View To Offer. Serious Seller.

CREDIT FINANCE

Posted: 22-Dec-2018 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 06/2021) \$15,899 \$6,400 /yr 26-Jun-2006 1,598 cc 128,000 km Sedan Available

\$2000 Down Payment. Low Mileage, Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained By Previous Owner. Clean And Neat Interior! B...

Ken Garage Pte Ltd

Posted: 28-Dec-2018 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Sell to direct buyers at the price you want!

Make the choice to sell only if the price meets your expectations. Contact our agents to find out how to list on consignment.

Find out more!



Toyota Corolla Altis 1.6A (COE till 06/2021) \$15,899 \$6,390 /yr 27-Jun-2006 1,598 cc 123,000 km Sedan Available

\$2000 Down Payment. Low Mileage Done, Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained By Previous Owner. Clean And Neat Interi...

Ken Garage Pte Ltd

Posted: 29-Dec-2018 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 06/2021) \$18,800 \$7,530 /yr 30-Jun-2006 1,598 cc - Sedan Available

Posted: 21-Jan-2019 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 10/2021) \$18,800 \$6,640 /yr 31-Oct-2006 1,598 cc - Sedan Available

COE Till 30/10/2021, Good Condition, Loan Up To 80% (ie \$15,000 Loan)

Posted: 27-Dec-2018 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 11/2021) \$19,800 \$6,890 /yr 15-Nov-2006 1,598 cc - Sedan Available

Ideal For Short-Term Usage! 2 Owners Only! Nice & Good Condition! No Repairs Needed! Hurry! Call For Viewing Today Before Its Gone!

Posted: 14-Feb-2019 Tags: 2006 Toyota Corolla, 2006 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2022) \$27,388 \$8,780 /yr 12-Feb-2007 1,598 cc - Sedan Available

New Arrival! Owned By A Careful, Non Smoker Ownr. Service Regularly At 10k Km Without Fail. Original Paint, Beautiful Leather And Accident Free. Most Popular Sedan Among Its Class. She Not Only Provi...

Posted: 24-Dec-2018 Tags: 2007 Toyota Corolla, 2007 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 04/2022) \$28,800 \$8,680 /yr 26-Apr-2007 1,598 cc 143,000 km Sedan Available

Best COE Renewed Condition. View Yourself To See. Well Maintained. Smooth Engine. Just Replaced Front And Rear Brake Pad And Battery On Dec 2017. Car Serviced On Dec 2017. Original Dash Board Radio An...

Prem Roy Motoring

Posted: 30-Nov-2018 Tags: 2007 Toyota Corolla, 2007 Toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

MOBILITY160 42274641

Compare

Print Received Message

This mail is associated with :

***SGC5555J (MCT18120906)**
[SHA7681M]
TP
TAN CHEE KUONG
Dec 20 2018 2:00AM
[COMFORT TRANSPORTATION PTE LTD]
Ho Beng Trading

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 27/05/2019 09:30 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1020.00) - SGC5555J - Claim Handler: Zuhaidah Bte Samsuri

Approved:1020.00.

Asher Sng (LKKAuto)

From: chan pick yuen <chris_chanbebe@hotmail.com>
Sent: Thursday, 4 April 2019 10:34 PM
To: Mei Kwan (LKKAuto)
Cc: Vic (LKKAuto); Joy Irene (LKKAuto)
Subject: Re: SGC5555J DOA 20.12.2018
Attachments: SGC5555J SD.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Sir / Mdm ,

Enclosed is our client's GIA report , LOA , LTA fee & Invoice .
Please advise our OIC & claim .
As request following :

1. RC \$ 900 (AS AGREED)
2. LOU\$200 (\$100 X 2 DAYS)

@ 100% (PARKED)

Total \$1100/-.

Please let us have our offer soon . Thanks

Regards,
Chris Chan Pick Yuen
HO BENG TRADING
HP: 92712214

From: chan pick yuen
Sent: Monday, December 31, 2018 12:47 PM
To: assignments@lkkauto.com
Subject: SGC5555J ESTIMATE

Dear Sir / Mdm ,

Enclosed is estimate & log card .
Claim iii . Surveyed by Mr Adrian . Thanks

Regards,
Chris Chan Pick Yuen

LETTER OF AUTHORISATION

HO BENG TRADING
BLOCK 3020A UBI
ROAD 1 # 01-33
SINGAPORE 408714.

Dear Sir,

Accident on 20/12/18 @ 02:00 hrs

Involving Vehicle Nos SGC 5555J

Along Spottiswoode Park Rd

I/We, the registered owner /driver of vehicle registration no: SGC 5555J
have involved in the above accident.

I/We hereby authorize **M/S HO BENG TRADING** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitors _____ to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.
Thank you.

Yours truly,



Owner's Signature
(Company's stamp if applicable)

Name: Tan Chee Kwong

NRIC No: S7688304Z

Date: _____

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18120906
 Claimant Ref: 9GC555J

We/I, Ho Beng Trading ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 900.00 (repair cost), S\$ 100.00 (loss of use/rental), S\$ NIL (search fee), vehicle no. SGC 5555J that was damaged pursuant to the accident which occurred on 20/12/2018 (date) at SPOTTISWOODE PARK RD (location) involving vehicle no. SHA 7681M (insured vehicle). This is pursuant to the inspection conducted on 31/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN CHEE KUONG ("the third party claimant") of vehicle no. SGC 5555J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGC 5555J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,000.00 to Ho Beng Trading.

Dated this 7 day of 8

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by "the workshop" (with chop)

Tan Chee Kuong

S7688384Z

3020A#01-33

UBI Rd 1 S408714

Malaysia

Manager



WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

2017

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

INVOICE

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04/#05/#06-02
IOB BUILDING
Singapore 049711

Date: 03rd April 19

Accident date: 20th DECEMBER 2018
Final Bill For Vehicle No: SGC5555J TOYOTA ALTIS

Descriptions	AMOUNT
Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD Surveyor : Mr Adrian Ling	\$900.00
Total	\$900.00

S/DLRS: NINE HUNDRED ONLY

> Back to OneMotoring


Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 31 Dec 2018 / 11:49:53

Receipt Date/Time : 31 Dec 2018 / 11:49:53

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181231-000854

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA7681M As at 20 Dec 2018/02:00:00 Insurance Co: INDIA INTL INS PTE LTD				
1	Insurance Enquiry - SHA7681M Enquiry Fee 20181231114829599665	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20181231114852707	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jan 2019 Edit Reg		31 Dec 2018 00:00 Edit Adj Rpt	S\$900.00 Edit Estimates	S\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	TAN CHEE KUONG, ID: 57688384Z								
Vehicle Reg. No.:	SGC555J	Date of Loss:	20/12/2018 02:00 - :59 [139 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18120906	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA7681M	Policy No. (Claimant):	5090492662-01						
		Excess:							
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (27/05/2019): Alert - Adj Mandate Approved (S\$1020.00) - SGC555J - Claim Handler: Zuhaidah Bt... • III_SG (13/05/2019): Alert - Adj Mandate Maintained - SGC555J - Claim Handler: Zuhaidah Bte Samsuri • III_SG (28/01/2019): Alert - Adj Mandate Approved (S\$0.00) - SGC555J - Claim Handler: Zuhaidah Bte S... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGC5555J (MCT18120906)
 [SHA7681M]
 TP
 TAN CHEE KUONG
 Dec 20 2018 2:00AM
 [COMFORT TRANSPORTATION PTE LTD]
 Ho Beng Trading

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
2	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
3	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
4	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
5	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
6	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
7	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
8	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
9	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
10	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
11	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
12	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
13	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
14	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
15	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
16	18/02/19 09:18	General View		Load JPG	<input checked="" type="checkbox"/>						
17	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
18	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
19	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
20	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
21	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
22	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
23	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
24	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
25	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
26	18/02/19 09:18	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
27	17/05/19 09:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
28	17/05/19 09:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
29	17/05/19 09:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
30	17/05/19 09:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
31	17/05/19 09:20	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	02/01/19 16:40	TP GIA REPORT		Load PDF							
2	11/04/19 13:30	LTA SEARCH		Load PDF							
3	11/04/19 13:30	LOD		Load PDF							
4	13/08/19 11:13	WORKSHOP INVOICE		Load PDF							

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
5	13/08/19 11:13	AUTHORISATION TO ACT FORM		Load PDF
6	13/08/19 11:13	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	15/01/19 08:55	Singapore Accident Statement - OID		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19000057/AWB3Q2
Date: 13/08/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No : SGC5555J	Insured Vehicle No :	SHA7681M	
Date of Loss: 20/12/2018	Nature of Claim:	TP	Claim No: MCT18120906

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC5555J	Engine No:	3ZZ4641734
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107145211
Reg. Date:	23/04/2007 (Man. Year: 2007)	Odometer:	257870 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,641.20	658.76	8,982.44	93.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	480.00	1,270.00	72.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,391.20	1,138.76	10,252.44	90.00
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	11,391.20	900.00	10,491.20	92.10
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,000.00		

INSPECTION

Date of Assignment:	31/12/2018		
Date Inspected:	31/12/2018	Inspected At:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1 Singapore 408714
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2019)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC5555J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Not Necessary	53.90 F	*- FL
2	1		*FRONT BONNET INNER RUBBER	Not Necessary	83.10 F	*- FL
3	6		*FRONT BONNET INNER RUBBER CLIPS	Not Necessary	77.40 F	*- FL
4	2		*FRONT HEADLAMP	Not Necessary	4,202.20 F	*- FL
5	1		*FRONT GRILLE	Cracked	280.70 F	*280.70 FL
6	2		*FRONT GRILLE SIDE NIZZER	Not Necessary	32.40 F	*- FL
7	1		*FRONT GRILLE EMBLE LOGO	Necessary	89.40 F	*38.00 FL
8	1		*FRONT BUMPER	Torn	415.65 F	*415.65 FL
9	2		*FRONT BUMPER SIDE BRACKET	Necessary	106.20 F	*64.00 FL
10	8		*FRONT BUMPER CLIPS	Necessary	103.20 F	*30.00 FL
11	1		*FRONT BUMPER NUMBER PLATE	Cracked	50.00 F	*50.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	281.70 F	*- FL
13	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	262.20 F	*- FL
14	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	262.20 F	*- FL
15	1		*FRONT SUPPORT PANEL	Repair	852.00 F	*- FL
16	1		*FRONT AIR-CON CONDENSER	Not Necessary	950.20 F	*- FL
17	1		*FRONT RADIATOR	Not Necessary	1,020.00 F	*- FL
18	1		*FRONT RADIATOR FAN MOTOR ASSY	Not Necessary	518.75 F	*- FL

F=Franchise part L=ListItemDisc

Sub Total (S\$)	9,641.20	878.35
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	219.59
Total Parts (S\$)	9,641.20	658.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX CUSHION	New	120.00	0.00
2	TO REMOVE & RE-FIX AIR-CONDENSER ,FRONT RADIATOR FAN & TOP UP GAS	New	250.00	0.00
3	TO CHECK WIRING SYSTEM	New	60.00	30.00
4	TUFF KOTE	New	120.00	0.00
5	PANEL BEATING	New	600.00	250.00
6	SPRAY PAINTING	New	600.00	200.00
Gross Labour Cost (S\$)			1,750.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >