

\*22/03/2002

ASS. REC. BY:

REF:

CS3 / mslh19000065 / Jdoan

Special Instruction:

Survivor  
Mafimin

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSLH

Date/Time:

02012019 4:32pm

Estimated Cost:

Bill to:

OD / TD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7545H

Insured:

FY 3145T

at Workshop m/s

Seng Hwee Motor

Tel:

6755 5205

of

Blok 1018 Tishun Ind Park A # 01-350

Policy No:

MSD / VINT / 18 - 381128 - CA

Claim No:

MSC / V / 19 - 000008

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29122018

(Client's Record)

08.012019 @ after 12pm

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

02012019 4:43pm

Person Contacted:

Mr. Kueh

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLN 7545H - NA / INC 17022915 / 13
	FY 3145T - X
	After repair: 11/1/2019

DAF: 02122017

Surveyor Hwee Jie

REF: MSIG

PRS

ASSIGNMENT

From: \_\_\_\_\_ Date: 08/01/19

Veh No: SLN7545H Yr Regn: 17 May 2017

Estimated Cost: \_\_\_\_\_

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLN7545H

Make: Toyota Prius C.C. 1797

at Workshop m/s Seng Hwee Motor

Colour: Silver A/C: Insured / Std / NI / NA

of Blk 1018, Yishun Ind. Park A # 01-350

Sp. Reading: 139715 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: ZVWS16033958

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: In Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In Order / Jammed / Leaked / Burnt or

Make of Veh: After 12pm

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/65 R15

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Bal. or Market Value: \_\_\_\_\_

Front Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 29/12/18 D.O.I. 8/1/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No


Survey held at Seng Hwee Motor

CA / REV / REP. / 24 HRS <sup>dup</sup>

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$3,000-\$4,000 3 days
	
	22/1/2019.

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2)

Report Format : PRS

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 120

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) ) S + RS. SI

: Interview (\$ \_\_\_\_\_) ) Photos

: Tech. Invs (\$ \_\_\_\_\_) ) Others

: Weekend (\$ \_\_\_\_\_) )

TOTAL 130

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2018		02 Jan 2019 16:32 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by insurer\]](#)

Insured:	<b>KANG HSIEN CHONG (JIANG XIANZONG)</b> , ID: S7626558E, Tel: +6591691367, Email: botak4849@gmail.com		
Main Claimant:	<b>LIANG MENG TRANSPORT SERVICES</b> , Co. Reg. No.: 53357469B		
Vehicle Reg. No.:	<b>SLN7545H</b>	Date of Loss:	29/12/2018 18:00 - :59 [19 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / MSC/V/19-000008</b>	Policy/Cover Note No.:	MSD/VMT/18-381128-CA (Third Party Only) Coverage: 23/05/2018 - 22/05/2019
Vehicle Reg. No. (Insured):	<b>FY3145T</b>	Policy No. (Claimant):	
Repairer:	<b>Seng Hwee Motor (HQ)</b> Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 03/01/2019]</b>		
Driver/Custodian (Insured):	KANG HSIEN CHONG (JIANG XIANZONG) (42 / Male), NRIC: S7626558E, Tel: +6591691367		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: UNCLEAR. CONTACT: MR KUEH 6755 5205 / 9786 5675		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your Ref : FY3145T

Fax : 6538 3708

Our Ref : GS/18/5962/SW/sy/ms (SLN 7545H)

Tel : 3152 0981

Date : 2 January 2019

Email : [accident@kscgp.com](mailto:accident@kscgp.com)

MSIG Insurance (Singapore) Pte Ltd

By Email Only

**DATE OF ACCIDENT: 29 DECEMBER 2018****NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your letter of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services
4.	Leslie Lim	Premier Appraisal Services
5.	Ng Kong Beng, Patrick	Carlink Consultancy
6.	Andrew How	Prominent Appraiser Services Pte Ltd
7.	Gan Song Sing, Roger	ROG Associates
8.	Dennis Yap	Pal's Appraiser Pte Ltd
9.	Michael Yap	Mc-Coy Appraiser Pte Ltd
10.	Nicky Seah	Absolute Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : Seng Hwee Motor  
 Address : Block 1018 Yishun Industrial Park A, #01-350, Singapore  
 768760  
 Contact : Mr Kueh (h/p: 6755 5205 / 9786 5675)

Yours faithfully,

*MS*

Date of Accident : 29 ~~3~~ - 12 - 2018.  
Accident Time : 6.20 pm  
Accident Place : \_\_\_\_\_

Vehicle Reg. No. <sup>(A)</sup> : SLN7545H

Vehicle Make \ Model : TOYOTA A/PRIUS

Insurance company : NTUC

Policy No : 5090937540-01 No: 53357469-B

Name & IC no. OWNER : LIANG MENG TRANSPORT SERVICES

Name & IC- no. DRIVER : CHIA LIANG MENG 51214581-J

DATE OF BIRTH : 19-12-1955

Relationship bet. owner & Driver : Spouse \ Father \ Mother \ son \ daughter  
Others : \_\_\_\_\_

DRIVER'S Address : BIK 489 ADMIRALTY LINK #04-103 (750489)

Contact No. DRIVER : 91181002

Occupation : INDOOR \ OUTDOOR

Fax no \ Email Address : \_\_\_\_\_

Weather & Road Surface : CLEAR | RAINNING | WET | DRY

Reporting type : Reporting Only \ Claim Other Party \ Claim Own Ins.  
TP Claims

**Other Party Driver's Particulars**

<sup>(B)</sup>  
Vehicle Reg. No. : FY 3145T

Vehicle Make \ Model : \_\_\_\_\_

Name DRIVER : \_\_\_\_\_

IC no. DRIVER : \_\_\_\_\_

DRIVER'S contact & add : \_\_\_\_\_

Vehicle Reg. No. : \_\_\_\_\_


Vehicle Make \ Model : \_\_\_\_\_

Name DRIVER : \_\_\_\_\_

IC no. DRIVER : \_\_\_\_\_

DRIVER'S contact & add : \_\_\_\_\_

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making a left turn slowly with left signal into Geylang Lor. 23 when suddenly m/bike FY3145T came at my left and crashed onto the left portion of my car. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

LIANG MENG TRAN  
SPORT SERVICES  
REGNO. 53357469B

Policyholder's Signature  
Date & Time:

*Li*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: (YS)  
NRIC/FIN No.:

31/12/18

GIARMC SketchPlanForm\_V3  Claim Own Policy  Claim Third Party  Reporting Only  
 Claim ~~at~~ TP at other workshop (by own workshop)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	7469B
<b>Vehicle Details</b>	
Vehicle No.:	SLN7545H
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8E AT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ZR6856693
Chassis No.:	ZVW516033958
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$23,474.00
Original Registration Date:	17 May 2017
First Registration Date:	17 May 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2027
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	16 May 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,556.00
COE Rebate Amount:	\$45,439.00
<b>Total Rebate Amount:</b>	<b>\$49,189.00</b>

The information contained herein is correct as at 09 Jan 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/12/2018 12:38
Date Of Accident	29/12/2018 18:20
Exact Location Of Accident	SIMS AVE TURN LEFT TWDS GEYLANG LOR.23
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN7545H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIANG MENG TRANSPORT SERVICES
Co Reg No	53357469B
Email Address	CHIALIANGMENG1955@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-91181002

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8E AT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PTE HIRE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090937540-01
Cover Note Number	17/05/18 - 16/05/19

### Driver

Name of Driver	CHIA LIANG MENG
NRIC No	S1214581J
Date Of Birth	19/12/1955
Occupation	OUTDOOR
Date Of Driving Pass	08/01/1999
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91181002
Fax Number	
Contact Number	
EEmail Address	CHIALIANGMENG1955@GMAIL.COM

Address	BLK 489 ADMIRALTY LINK #04-103
Postcode	750489
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : AHMAD ZAKIR BIN NOORDIN, NRIC S9541007C, HP-93257290
	GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO ATTACH. \*THIRD PARTY CLAIM BY OWN WORKSHOP\*

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FY3145T
Vehicle Make/Model/Colour	FOOD DELIVERY
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SLN 7545H  
INSURER : NTUC  
DATE & TIME: 29/12/18 @ 6:30 pm

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**LIANG MENG TRAN**  
**SPORT SERVICES**  
**REG NO. 53357469B**

Policyholder's Signature  
Date & Time:

*Lin*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:




Report Centre Personnel's Signature  
Name: *(YS)*  
NRIC/FIN No.:

*31/12/18*

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making a left turn slowly <sup>with left signal</sup> into Geylang Lor. 23 when suddenly m/bike FY3145T came at my left and crashed onto the left portion of my car.

No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**LIANG MENG TRAN**  
SPORT SERVICES  
REGNO. 53357469B

Policyholder's Signature  
Date & Time:

*Li*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



*YS* 31/12/18  
(YS)

Reporting Centre/Personnel's Signature  
Name:  
NRIC/FIN No.:

© ARMC SketchPlanForm\_V3  Claim Own Policy  Claim Third Party  Reporting Only  
 Claim-OD/TP at other workshop (by own workshop)

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2018		02 Jan 2019 16:32 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	KANG HSIEN CHONG (JIANG XIANZONG), ID: S7626558E, Tel: +6591691367, Email: botak4849@gmail.com		
Main Claimant:	LIANG MENG TRANSPORT SERVICES, Co. Reg. No.: 53357469B		
Vehicle Reg. No.:	SLN7545H	Date of Loss:	29/12/2018 18:00 - :59 [19 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000008	Policy/Cover Note No.:	MSD/VMT/18-381128-CA (Third Party Only) Coverage: 23/05/2018 - 22/05/2019
Vehicle Reg. No. (Insured):	FY3145T	Policy No. (Claimant):	
		Excess:	
Repairer:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350, 768760 Yishun - Tel: 67555205		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Imm.Advice due 03/01/2019]		
Driver/Custodian (Insured):	KANG HSIEN CHONG (JIANG XIANZONG) (42 / Male), NRIC: S7626558E, Tel: +6591691367		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: UNCLEA. CONTACT: MR KUEH 6755 5205 / 9786 5675		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>
			<b>Subject</b>
			<b>Handler</b>
			<b>Assigned By</b>
			<b>Completed On</b>
			<b>Created On</b>
			<b>Done?</b>
No results.			

### Claim Documents

**\*SLN7545H (MSC/V/19-000008)**  
**[FY3145T]**  
**TP**  
**LIANG MENG TRANSPORT SERVICES**  
**Dec 29 2018 6:00PM**  
**[KANG HSIEN CHONG (JIANG XIANZONG)]**  
**Seng Hwee Motor**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>	
<b>Assessment Reports</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/01/19 15:23	<b>Accident Statement</b> From:SC - Reg. No: FY3145T, Claimant: KANG HSIEN CHONG (JIANG XIANZONG)	Load HTM	
<b>Photos/Images</b>			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	09/01/19 10:06	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
16	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
17	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
18	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
19	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
20	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
21	23/01/19 11:53	<b>Photo After Spray</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/01/19 15:23	<b>SLN7545H TP E-FILE REPORT</b> From:SC - Reg. No: FY3145T, Claimant: KANG HSIEN CHONG (JIANG XIANZONG)	Load PDF	
2	02/01/19 15:24	<b>PRI - KSCGP JURIS LLP</b>	Load PDF	
3	02/01/19 15:24	<b>SURVEY DISAGREE ON SJE - ASSIGN LKK</b>	Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**



**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19000065/JCBE2

**Date:** 23/01/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: MSD/VMT/18-381128-CA		
Claimant Vehicle No: SLN7545H	Insured Vehicle No: FY3145T		
Date of Loss: 29/12/2018	Nature of Claim: TP	Claim No:	MSCV/19-000008

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7545H	Engine No:	2ZR6856693
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 E (A)	Chassis No:	ZVW516033958
Reg. Date:	17/05/2017 (Man. Year: 2016)	Odometer:	139715 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	02/01/2019	
Date Inspected:	08/01/2019 Inspected At:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760
Estimated Period of Repair:	3.0 days	

**Adjuster:** ONG HWEЕ JIE

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2019)
<b>Parts:</b> 144	TOYOTA PRIUS HYBRID 1.8 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN7545H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >