

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: D19000119MFSH

Our ref: CS/FCI19000101/Dvb Date:11/1/2019

The Motor Claims Department

MS FIRST CAPITAL INSURANCE LTD Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SH 8159G

We thank you for your instruction on $\frac{2}{1/2019}$

Please be informed that we had conducted the inspection of the above mentioned vehicle on

<u>3/1/2019</u> at the premises of M/s <u>CHUNNI MOTOR WORK PTE LTD</u>

and have the following to report:-

Description of Damage:

The vehicle sustained damages at the

n/s front and o/s front portion

rear front offside

Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang

Motor Surveyor / Investigator