

ASS. REC. BY

REF

CS3/III 19000108/Ged3er

Special Instruction

Survivor  
MenmenGub Ding  
Gabriel Wee

ASSIGNMENT (Office)

From (Person)

of

TH

Date/Time

31/1/2019 @ 9:05am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 4803D

Insured:

SHC 2334M

at Workshop n/s

MJE Motor

Tel:

9225 1391

of

Blk 7 - Sin Ming Sec. C #01-96

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

29/12/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time

9:28am @ 3/1/18

Person Contacted:

YY

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SLJ 4803D - X
	SHC 2334M - NS / INC 18021936 / K/sbs 2
	Dismantle: 3/1/2019 @ 4.20pm

PRS  
Xnd

REF: III

24614

# ASSIGNMENT

From Date: 3/01/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. SLJ 4803D

at Workshop n/s

of MJE Motor  
Blk 7 sin ming Sec. C # 01-96

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh.

YY@ 92251391

(Policy Condition)

Remark. The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SLJ4803D Yr Regn. 13-Rec2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C

1496

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

48239

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RH1205519

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

03-01-19

Survey held at

n/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s RA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

RECEIVED 07 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

PRS

Lump Sum / I.B.I. (\$

120

10

130

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Thursday, 3 January 2019 9:05 AM  
**To:** Cheonghoh Law; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Pooi Chin Han Daniel  
**Subject:** RE: PRS for SLJ 4803 D involving vehicle SHC 2334 M on 29 December 2018 along Merdeka Bridge Towards KPE (PIE) our ref: LCH.lg/SJEM-90004.19)  
**Attachments:** SKMBT\_C364e19010214290.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SLJ4803D  
III INSURED VEHICLE NO. : SHC2334M  
DATE OF LOSS : 29.12.18

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Daniel.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Cheonghoh Law [mailto:mail@cheonghoh.sg]  
**Sent:** 02 January, 2019 4:31 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Re: PRS for SLJ 4803 D involving vehicle SHC 2334 M on 29 December 2018 along Merdeka Bridge Towards KPE (PIE) our ref: LCH.lg/SJEM-90004.19)

Dear Sirs,

We refer to the above matter and your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Lee Kok Weng
- (2) Patrick Ng Kong Beng
- (3) Ang Guea Kiang
- (4) How Andrew
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis
- (10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre- repair survey of SLT 4803 D and contact our client's workshop, MJE Motor , Blk 7 Sin Ming Sector C #01-96 Singapore 575642 for the said survey.

Contact Person : Y Y / Jo  
9225 1391 / 6454 2203

Please proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

On 2 Jan 2019, at 3:26 PM, Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**

<image001.jpg>

64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Cheonghoh Law [<mailto:mail@cheonghoh.sg>]  
**Sent:** 02 January, 2019 2:34 PM  
**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>  
**Subject:** Re: PRS for SLJ 4803 D involving vehicle SHC 2334 M on 29 December 2018 along Merdeka Bridge Towards KPE (PIE) our ref: LCH.lg/SJEM-90004.19)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards  
Catherine  
CHEONGHOH LAW CORPORATION  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

Begin forwarded message:

**From:** [cheonghoh@singnet.com.sg](mailto:cheonghoh@singnet.com.sg)  
**Subject:** Message from KMBT\_C364e  
**Date:** 2 January 2019 at 2:29:24 PM SGT  
**To:** [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)  
**Reply-To:** [cheonghoh@singnet.com.sg](mailto:cheonghoh@singnet.com.sg)

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.  
It may contain confidential and/or legally privileged information.  
If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification. Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd. Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2461H

### Vehicle Details

Vehicle No.:	SLJ4803D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B4405519
Chassis No.:	RU11205519
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,444.00
Original Registration Date:	13 Dec 2016
First Registration Date:	13 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$12,022.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2026
PARF Rebate Amount:	\$9,016.00

### Intended COE Rebate Details

COE Expiry Date:	12 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$40,445.00
<b>Total Rebate Amount:</b>	<b>\$49,461.00</b>

The information contained herein is correct as at 04 Jan 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/12/2018 17:18
Date Of Accident	29/12/2018 20:00
Exact Location Of Accident	MERDEKA BRIDGE TOWARDS KPE(PIE)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ4803D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN BOON TECK
NRIC No	S7922461H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96355653
Alternative Phone No	OFFICE-96355653

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ18-008459
Cover Note Number	

### Driver

Name of Driver	TAN BOON TECK
NRIC No	S7922461H
Date Of Birth	30/07/1979
Occupation	INDOOR
Date Of Driving Pass	24/11/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96355653
Fax Number	
Contact Number	OFFICE-96355653
Email Address	NOEMAIL



Address	BLK 9A SENGKANG EAST AVE #11-34
Postcode	544743
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : TAN CHU JIE GENDER: : FEMALE
Passenger 2	NAME: : BRAYDON TAN GENDER: : MALE
Passenger 3	NAME: : BRYANNE TAN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4529999 - FAX NO: 6 5535740
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2334M
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any/like reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

31/12/2013

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Merdeka Bridge towards KPE (PIE) in vehicle A. Vehicle B took the exit to Stadium Road and I proceeded straight on the third lane. Suddenly, vehicle B turned out at the chevron of the above junction. I honk him but he still continue to cut into my lane & collided into the front left of my vehicle. I honk him to stop his car but he drove away without stopping. A video record of the accident is available.


& Repair at other workshop.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)

  
 Reporting Centre Personnel's Signature  
 Name:

31/12 @ 1130 AM



## Sketch Plan #2 Pg. 1

31-12-18;01:21PM;MJ Automobile

;6452 3308

# 1/ 3



**SINGAPORE  
POLICE FORCE**



T/20181231/2055

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

1 of 3

Report No. T/20181231/2055

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/12/2018 12:40		Vide Report No.:		Station Diary No.: 10
<b>Informant's Particulars</b>				
Name of Informant: TAN BOON TECK		Address: 9A SENGKANG EAST AVENUE #11-34 SINGAPORE 544743		
ID Type / ID No.: NRIC NO / S7922461H		Contact No.: Home/Office: Mobile: 96355653		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 39	Date of Birth: 30/07/1979	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: SAF REGULAR		Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 29/12/2018 20:00	Type of Location: Straight Road
Location: Along Road 1 NICOLL HIGHWAY  Along Nicoll Highway (Merdeka Bridge) towards KPE (PIE)				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 70 Km/h		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC2334M	BLUE COMFORT TAXI	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue		2
SLJ4803D	Car	HONDA	VEZEL 1.5X CVT	Red	Slightly Damaged	3

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date

## Sketch Plan #2 Pg. 2

31-12-18;01:21PM;MJ Automobile

;6452 3308

# 2/ 3


**SINGAPORE  
POLICE FORCE**


T/20181231/2055

2 of 3

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

Report No. T/20181231/2055

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLJ4803D	EQ INSURANCE COMPANY LTD.	DMPPHQ18-008459	13/12/2018	12/12/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN BOON TECK	ID No.	S7922461H
Related Vehicle	SLJ4803D (Car)	Contact No.	96355653
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 29/12/2018 at about 2000hrs, I was driving my vehicle SLJ4803D (V1) along Nicoll Highway (Merdeka Bridge) towards KPE (PIE). I was travelling on lane 3. There was a taxi SHC2334M (V2) wanted to exit Stadium road (Filter road). Suddenly he swerves into my lane and side swipe my vehicle without stopping the driver of V2 drove off. I tried honk at V2 but V2 refuse to stop. I wish to state during the accident my wife and 2 kids (9yrs & 5yrs) were with me. All was not injured.

I wish to state I have an in-built camera in my car and shows how the collision happened. I am willing to provide the footages to traffic police. I am not sure if there is any government property damage as I was trying to get V2 to stop.

Sketch Plan #2 Pg. 3

31-12-18;01:21PM;MJ Automobile

;6452 3308

# 3/ 3



**SINGAPORE  
POLICE FORCE**



T/20181231/2055

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

3 of 3

Report No. T/20181231/2055

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 JEFFREY LOIS

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

SI KALESWARL PALANI

Contact No: 65476902

IN 070

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

31/12/2018 12:40


Classification Of Case:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI Non-Reporting

#### CLAIM SUBFOLDER TRACKING






































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2019 17:41 <a href="#">Edit Reg</a>		03 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>TAN BOON TECK</b> , ID: S7922461H								
Vehicle Reg. No.:	<b>SLJ4803D</b>	Date of Loss:	29/12/2018 20:00 - :59 <b>[24 Months and 16 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SHC2334M</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Mje Motor (sin Ming, #01-96) (HQ)</b> Block 7 Sin Ming Industrial Estate Sector C, #01-96, 575642 Sin Ming - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Pooi Chin Han Daniel</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 14/01/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> 		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLJ4803D  
[SHC2334M]  
TP  
TAN BOON TECK  
Dec 29 2018 8:00PM  
[-]  
Mje Motor (sin Ming, #01-96)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
2	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
3	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
4	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
5	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
6	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
7	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
8	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
9	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
10	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
11	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
12	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
13	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
14	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
15	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
16	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
17	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
18	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
19	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
20	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
21	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
22	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
23	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
24	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
25	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
26	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
27	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
28	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
29	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
30	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
31	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
32	03/01/19 16:56	General View						Load JPG	<input checked="" type="checkbox"/>	
33	07/01/19 15:05	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
34	07/01/19 15:05	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
35	07/01/19 15:05	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
36	07/01/19 15:05	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
37	07/01/19 15:05	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/01/19 15:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19000108/GCD3E2

Date: 07/01/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLJ4803D

Insured Vehicle No : SHC2334M

Date of Loss: 29/12/2018

Nature of Claim: TP

Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLJ4803D

Make &amp; Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4405519

Reg. Date: 13/12/2016 (Man. Year: 2016)

Chassis No: RU11205519

Colour: Red

Odometer: 48239 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 03/01/2019

Date Inspected: 03/01/2019 Inspected At:

Mje Motor (sin Ming, #01-96) (HQ)  
Block 7 Sin Ming Industrial Estate Sector  
C, #01-96  
Singapore 575642

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLJ4803D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >