

ASS. REC. BY:

REF

CS3/SM019000116/R1cd3²

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

Menmen

From (Person)

chen shuhuaqnes

of

SMO

Date/Time:

3/1/19 @ 12:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJN 8413Y

Insured:

SLZ 2510C

at Workshop m/s:

AMA Autocare

Tel:

8778 3636

of

36 Joh Guan Rd East # 01-36

Policy No:

D18MTPV01007940

Claim No:

CMTP1900043

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/12/2018

CA / REV / REP. / REV 24 HRS (up)

Date/Time:

12:42pm @ 3/1/19

Person Contacted:

melun

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJN 8413Y - X

SLZ 2510C - X

After repair: 7/1/2019

Repair range 3K-4K 5 days repair

8/1/2019

From: *Joan*

REF:

1615L

COO XPRY: 2012 FEB

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJN 84134

at Workshop m/s

AMA AUTOCLARE

of

36, TON Guan RO Car #01-36

Insured:

Sompu

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

8K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJN 84134

Yr Regn:

2007 / FEB

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA FIT 1.3GA

c.c. - *1339*

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

276312

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

9661076370

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S. Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

BS (DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/12/18

D.O.I.

03/01/19

Survey held at

AMA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

PRS

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2018		03 Jan 2019 12:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	WONG POOI KUAN, ID: S8278253B		
Main Claimant:	CAR CONCEPT LEASING, Co. Reg. No.: 53361615L		
Vehicle Reg. No.:	SJN8413Y	Date of Loss:	27/12/2018 18:00 - :59
Claim Type:	TP / CMTD1900043	Policy/Cover Note No.:	D18MTPV01007940 (Comprehensive)
Vehicle Reg. No. (Insured):	SL22510C	Policy No. (Claimant):	
		Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/01/2019]		
Driver/Custodian (Insured):	KIM TAE JIN (), NRIC: S7983729F, Tel: +6590665942		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/12/2018 16:36
Date Of Accident	27/12/2018 18:15
Exact Location Of Accident	ALONG TPE TWDS SLE EXIT PUNGGOL WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN8413Y
Insured/Policyholder	
Name Of Registered Owner	CAR CONCEPT LEASING
Co Reg No	53361615L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-87493960

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5093017849-01 (TP)
Cover Note Number	

Driver

Name of Driver	SUA FENG AN
NRIC No	S9149352G
Date Of Birth	08/08/1991
Occupation	OUTDOOR
Date Of Driving Pass	16/02/2012
Driving Experience	6 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87493960
Fax Number	
Contact Number	
Email Address	NOEMAIL

No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name	SUA FENG AN
Approximate Age	
Injuries Sustain	3 DAYS MC
Injured person in which vehicle?	SJN8413Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


Accident Sketch Plan Pg. 1

Along TPE Towards SLE EXIT PUNGGOH WAY

SKETCH PLAN



B-8LZ-2510C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report Juvy War NPC
T/2018 1228/2160

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature _____

(if driver is not the policyholder)

Date & Time:

~~UAC SIN MING (VAC)~~
Min Drive

385 Sin Ming Drive
575718

Singapore 575719
Tel: 6455 5358 (ARC)
66621

Fax: 6452 6621

Reporting Centre Personnel's Signature

Names

NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20181228/2160

2 of 3

Police Station Of Origin:
Jurong West N P C
700 Corporation Road SINGAPORE 649818
Tel No 1800-2689999

Report No T/20181228/2160

CONTINUATION OF REPORT

Driver			
Name	SUA FENG AN	ID No.	S9149352G
Related Vehicle	SJN8413Y (Car)	Contact No.	87493960
Hospital/Clinic	ACCESS MEDICAL BEDOK SOUTH	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/12/2018	Date Discharge	27/12/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	KIM TAE JIN	ID No.	S7983729F
Related Vehicle	SLZ2510C (Car)	Contact No.	90665942
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/12/2018 at 1815hrs, I was driving, SJN8413Y along TPE towards SLE exit Punggol Way, my vehicle was stationary at the traffic junction when another vehicle, SLZ2510C hit me in my rear.

I alighted my vehicle and saw that SLZ2510C had hit the rear of my vehicle. We exchanged particulars for insurance claim. Subsequently, I went to the clinic for medical check up at Access Medical on 28/12/2018 in Jurong West and acquired 03 days MC. As I was in shock at the accident scene, I had not felt the pain however I feel unwell on 28/12/2018.

I wish to state that I did not consume intoxicating substances prior to the accident. I also wish to state that I have not met the other driver before.

NPCO Chiang T160429 wish to state that the correct clinic is Access Medical in Jurong West.

JURONG WEST NPC
700 Corporation Rd
Singapore 649818
Tel : 6268 9999 Fax : 6267 2478

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1615L
Vehicle Details	
Vehicle No.:	SJN8413Y
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L13A4078549
Chassis No.:	GE61076370
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$11,194.00
Original Registration Date:	28 Feb 2009
First Registration Date:	28 Feb 2009
Transfer Count:	1
Actual ARF Paid:	\$11,194.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2019
PARF Rebate Amount:	\$5,597.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,460.00
COE Rebate Amount:	\$63.00
Total Rebate Amount:	\$5,660.00

The information contained herein is correct as at 07 Jan 2019

OK

800
5660

2340

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2018		03 Jan 2019 12:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WONG POOI KUAN , ID: S8278253B		
Main Claimant:	CAR CONCEPT LEASING , Co. Reg. No.: 53361615L		
Vehicle Reg. No.:	SJN8413Y	Date of Loss:	27/12/2018 18:00 - :59 [117 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1900043	Policy/Cover Note No.:	D18MTPV01007940 (Comprehensive)
Vehicle Reg. No. (Insured):	SLZ2510C	Policy No. (Claimant):	
		Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/01/2019]		
Driver/Custodian (Insured):	KIM TAE JIN (), NRIC: S7983729F, Tel: +6590665942		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJN8413Y (CMTD1900043)**
[SLZ2510C]
TP
CAR CONCEPT LEASING
Dec 27 2018 6:00PM
[WONG POOI KUAN]
Ama Autocare Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	03/01/19 12:31	Accident Statement From: SC - Reg. No: SLZ2510C, Claimant: WONG POOI KUAN	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/01/19 14:15	General View	1 Load JPG	✓
2	07/01/19 14:15	General View	1 Load JPG	✓
3	07/01/19 14:15	General View	1 Load JPG	✓
4	07/01/19 14:15	General View	1 Load JPG	✓
5	07/01/19 14:15	General View	1 Load JPG	✓
6	07/01/19 14:15	General View	1 Load JPG	✓
7	07/01/19 14:15	General View	1 Load JPG	✓
8	07/01/19 14:15	General View	1 Load JPG	✓
9	07/01/19 14:15	General View	1 Load JPG	✓
10	07/01/19 14:15	General View	1 Load JPG	✓
11	07/01/19 14:15	General View	1 Load JPG	✓
12	07/01/19 14:15	General View	1 Load JPG	✓
13	07/01/19 14:15	General View	1 Load JPG	✓
14	07/01/19 14:15	General View	1 Load JPG	✓
15	07/01/19 14:15	General View	1 Load JPG	✓
16	07/01/19 14:15	General View	1 Load JPG	✓
17	07/01/19 14:15	General View	1 Load JPG	✓
18	07/01/19 14:15	General View	1 Load JPG	✓
19	07/01/19 14:15	General View	1 Load JPG	✓
20	07/01/19 14:15	General View	1 Load JPG	✓
21	07/01/19 14:15	General View	1 Load JPG	✓
22	07/01/19 14:15	General View	1 Load JPG	✓
23	07/01/19 14:15	General View	1 Load JPG	✓
24	07/01/19 14:15	General View	1 Load JPG	✓
25	07/01/19 14:15	General View	1 Load JPG	✓
26	07/01/19 14:15	General View	1 Load JPG	✓
27	07/01/19 14:15	General View	1 Load JPG	✓
28	07/01/19 14:15	General View	1 Load JPG	✓
29	07/01/19 14:15	General View	1 Load JPG	✓
30	07/01/19 14:15	General View	1 Load JPG	✓
31	08/01/19 11:56	General View	1 Load JPG	✓

Assessment Reports				1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
32	08/01/19 11:56	General View		Load JPG	✓
33	08/01/19 11:56	General View		Load JPG	✓
34	08/01/19 11:56	General View		Load JPG	✓
35	08/01/19 11:56	General View		Load JPG	✓
36	08/01/19 11:56	General View		Load JPG	✓
37	08/01/19 11:56	General View		Load JPG	✓
38	08/01/19 11:56	General View		Load JPG	✓
39	08/01/19 11:56	General View		Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	03/01/19 11:33	Pre-Repair Survey		Load PDF	
2	03/01/19 11:33	Pre-Repair Survey - SAS(M)		Load PDF	
3	03/01/19 12:30	Pre-Repair Survey - ASSIGN LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19000116/R1CD3S2
Date: 10/01/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01007940
Claimant Vehicle No: SJN8413Y Insured Vehicle No: SLZ2510C
Date of Loss: 27/12/2018 Nature of Claim: TP Claim No: CMTD1900043

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN8413Y
Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4078549
Reg. Date: 28/02/2009 (Man. Year: 2008) Chassis No: GE61076370
Colour: Grey Odometer: 276312 km
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50R16 Rear Tyre Size: 205/50R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/01/2019
Date Inspected: 03/01/2019 Inspected At: Ama Autocare Pte Ltd (HQ)
36 Toh Guan Road East, #01-36
Singapore 608580
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2019)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN8413Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >