

SYDNEY NAZ

REF: NS/LNC19000117 / NLOS2

FAX/12/18/2118

ASSIGNMENT

From: \_\_\_\_\_ Date: **02012019**

Estimated Cost: \_\_\_\_\_

OD /  P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SHF10021**

at Workshop m/s: **SMRT**

of: **Woodlands**

Insured: **SFJ 961C**

Policy No: **5103822667 300918 - 290919**

Claims No: **MT/1025883-007**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: **SHF 1002 L** Yr Regn: **30 SEPT 2014**

Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: **TOYOTA PRUW** c.c. **1,798**

Colour: **MAROON** A/C:  Insured / Std / NI / NA

Sp. Reading: **523,014** T/Radio:  Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **JTDKN36U9057S2000**

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  Inorder /  Jammed /  Leaked /  Burnt or \_\_\_\_\_

Brake:  Inorder /  Jammed /  Leaked /  Burnt or \_\_\_\_\_

Modi:  Nil /  S/Rim /  STD A/Rim or \_\_\_\_\_

Tyre Size: F: **195/65 R15**

Mirror: R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **P ACKEN**

Front	Rear
R/Bal. <b>6</b> mm	R/Bal. <b>6</b> mm
L/Bal. <b>6</b> mm	L/Bal. <b>6</b> mm

D.O.A. **28/12/18** D.O.I. **2/1/19**

Survey held at **SMRT WOODLANDS**

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  UIC /  Rooftop or **o/s mild**

The  UIC / Chassis frame / Body Structure affected due to collision.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? :  Yes or  No

GIA / PR Seen: \_\_\_\_\_ Consistent? :  Yes or  No

Est. Repairs: **1** days Res.:  Yes or  No

Lum Sum: \_\_\_\_\_ %  3 Val:  Yes or  No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle:  IN /  OUT

Date / Time	Action / Instruction
	- mirror working, cover missing SHF10021 - + SFJ 961C - NA / FCI1401090 / cl INC L/S
25/1/19	FINALIZED Lump sum REPAIR \$175.00 / 1 DAY
25/01/19 @ 3.31pm	confirmed with Poli Swan US \$170, 1 days. (Red to 1249.64, 88%)
	RECEIVED 29 JAN 2019

Date/Time, File Pass to?  : Preli. Report  : Final Report

17/1/19 **turner**

Date/Time, File Return to? \_\_\_\_\_

3)

Report Format: **71**

Lump Sum / I.B.I: (\$) **170**

Days Of Repair: **1**

Resurvey No. of Trip: **1**

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3) \$ + RS \$

Photos

Others

Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech. Invs (\$ )  Weekend (\$ )

TOTAL

**TP Claims against NTUC Income: Follow-Through Survey**

Date : 25/01/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1025883-002	SMIRT TAXIS PTE LTD	SFH 1002L	SFJ 961C	28/12/2018	9:45	\$ 1,419.64

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

My Desktop  
Notice of Loss

Policy Query

Policy No.

Vehicle No. (For Motor)

Date of Accident

Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5103822667		LIN XIAOXIN	S7378341J	GPC	drive CLASSIC	SFJ961C	SFJ961C	30/09/2018	29/09/2019

Continue

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 25 January 2019 3:31 PM  
**To:** 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))'; Naz (LKKAuto)  
**Cc:** SUR; 'Leong Chee kwong'  
**Subject:** RE: SHF 1002L Finalization

Dear Poh Suan,

WITHOUT PREJUDICE

As spoken with you.

Confirm Lump Sum \$170.00 before GST and 1 day.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>  
**Sent:** Friday, 25 January 2019 2:37 PM  
**To:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; 'Leong Chee kwong' <cheekwongwega@gmail.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Subject:** RE: SHF 1002L Finalization

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

---

**From:** Naz (LKKAuto) [<mailto:Naz@lkkauto.com>]  
**Sent:** Friday, 25 January 2019 12:13 PM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
**Cc:** SUR; 'Leong Chee kwong'; Shiau Chan (LKKAuto)  
**Subject:** Re: SHF 1002L Finalization

Dear Ms Yeo,

Finalized Part by Part Repair \$175.00 / 1 Day.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/12/2018 09:00
Date Of Accident	28/12/2018 09:45
Exact Location Of Accident	ANG MO KIO AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF1002L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	WONG AIK LENG
NRIC No	S7107679B
Date Of Birth	24/02/1971
Occupation	OUTDOOR
Date Of Driving Pass	19/02/1999
Driving Experience	19 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	470
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

I WAS STATIONARY ALONG ANG MO KIO AVE 10 AT THE CENTRE LANE DUE TO THE FRONT VEHICLE STOPPING AS THERE WAS RED TRAFFIC LIGHT JUNCTION AHEAD. WHEN THE FRONT VEHICLE MOVED AND BEFORE I COULD MOVE, SUDDENLY THE VEHICLE SFJ961C FROM BEHIND OVERTOOK FROM MY RIGHT AND ITS LEFT SIDE MIRROR HIT ONTO THE RIGHT SIDE MIRROR OF MY TAXI.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SFJ961C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIN XIAOXIN
NRIC/Passport Number	S7378341J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHF1002L
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1443326
Chassis No.:	JTDKN36U905752000
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$23,309.00
<b>Total Rebate Amount:</b>	<b>\$29,375.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jan 2019

OK



## Case Details

Case Reference Number : TAX/12/18/2118  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHF1002L

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-5141-ID  
 Assigned By : Kwai Leng Gan

Insurance Company Name : NTUC Income Insurance Co-operative Ltd  
 Accident Date and Time : 28/12/2018 01:45 AM  
 Vehicle Age(In Months) : 51

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			MIRROR ASSY, RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Giv	✓ / SVL
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	1	80.55	Replace	✓ / Mis
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	1	58.77	Replace	✓ / SVL
<b>Total Spare Part Cost</b>									<b>1,119.64</b>		<b>Surveyor Total</b>	<b>139.32</b>		
<b>Lump Sum Discount (%)</b>									<b>20.00</b>		<b>Lump Sum Dis (%)</b>	<b>20</b>		
<b>Final Spare Part Cost</b>									<b>895.71</b>		<b>Final Sur Total</b>	<b>111.46</b>		

### Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

### Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY VIEW MIRROR	180.00	80	
Total:		180.00	80.00	

### Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		120.00	0.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE AND REFIX WING MIRROR	120.00	0	NN
<b>Total:</b>		<b>120.00</b>	<b>0.00</b>	

### Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	895.71	111.46
Total Labour Cost	0.00	0.00
Total Spray Painting	180.00	80.00
Other	120.00	0.00
Overall Total	1,195.71	191.46
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	1,200.00	200.00
Surveyor Approved Amount		200.00
No of Repair Days*	2	1
Remarks		LUMP SUM REPAIR 1 DAY AFTER REPAIR PHOTOS
Surveyor Name		Naz

Signature

Save Clear

Survey Date

02/01/2019



NAZ LKIC  
 28/1/19 1700  
 LLS  
 1 DAY  
 AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Section A - Accident Details	
Registration Number	SHF1002L
Case Reference Number	TAX/12/18/2118
Registration Date	30/09/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG AIK LENG
Type of Accident	Side Swipe
Accident Date and Time	28/12/2018 9:45 AM
Accident Reported Date and Time	29/12/2018 9:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099452
Special Instruction to ARC, if any	TP
Prepared Date and Time	31/12/2018 10:23 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



SMRT

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$180.00	\$80.00
Total Spare Part Cost	\$1,119.64	\$139.32
Total Other Cost	\$120.00	(\$44.32)
<b>TOTAL COST</b>	<b>\$1,419.64</b>	<b>\$175.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	02/01/2019 6:34 PM	02/01/2019 5:42 PM
Signature		
Remarks		LUMP SUM REPAIR 1 DAY AFTER REPAIR PHOTOS



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
63 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63665592
Estimator Telephone Number 65982623
Accident Reporting Number 65952672

Date Generated : 09/01/2019

User ID : kimkingchin

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1901-0142	Invoice Number	
Quotation Date	08.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
Total Labour		

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$180.00	\$80.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	
Total Other Costs	\$120.00	\$0.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given
		879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	25.00	\$80.55	Replace	Replace
		81730-52090	MIRROR LAMP RH	1.00	\$65.30	10.00	\$58.77	Replace	Replace
Total					\$1,479.80		\$139.32		

SVC MIS SCR

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

139.32 /  
+ 80.00 /  


---

219.32 /  
- 20%  


---

175.45 /  
US \$175 /-

1779.80

NAZUKK N/A 25/1/19

FINALIZED LUMP SUM REPAIR \$175.00 / 1 DAY



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19000117/Nqbs2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 29-01-2019	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SFJ 961C	Veh. Inspected	SHF 1002L
Policy No.	5103822667	Coverage (\$)	0.00
Claim No.	MT/1025883-02	Excess (\$)	0.00
Assign From		Assign Date	02/01/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U905752000	Colour	MAROON
Odometer	523014	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	6 mm
L/H Front Tyre	195/65R15	FALKEN	6 mm
R/H Rear Tyre	195/65R15	FALKEN	6 mm
L/H Rear Tyre	195/65R15	FALKEN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S MIRROR. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	28/12/2018	Inspection Date	02/01/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>1 Working Days</b>	



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 1002L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER, OUTER MIRROR, RH (DISC 25%)	MISSING	107.40	80.55
1	MIRROR LAMP RH (DISC 10%)	SCRATCHED	65.30	58.77
1	MIRROR ASSY, RH	SERVICEABLE	1,307.10	-
			1,479.80	139.32
<b>LABOUR</b>				
	SPRAY PAINT.		180.00	80.00
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
			300.00	80.00
<b>GRAND TOTAL</b>			<b>1,779.80</b>	<b>219.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>170.00</b>

Report Ref No. NS/INC19000117/Nqbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.