

ASS. REC. BY:

REF: CS3/ASM19000119/Bchez

Special Instruction:

Surveyor:

Mr Lim

ASSIGNMENT (Office)

Smart claim

From (Person):

Dominic Yu

of

ASM

Date/Time:

03012019 10:15am

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 7225G

Insured:

SHC 5512X

at Workshop m/s

YSK Auto

Tel:

96402541

of

Blk 1 Kaki Bukit Ave 6 #01-71 (#01-08 Heavy Vehicle)

Policy No:

Claim No:

S9M0188N

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31-12-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

03012019 11:40am

Person Contacted:

Denny

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKB 7225G - X
	SHC 5512X - 004 / AXA 16024867 / Dp3g2
	Diamond: 4/1/2019
	After repair: 10/1/2019

Def: 22122016

PRS

REF: ASM(UXA)

ASSIGNMENT

From: Date: 03012019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 72256

at Workshop m/s

of Btk 1 Kaki Bukit Ave 6 Autobay

Insured: Heavy vehicle #01-08

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Dummy - 96402541

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKB 7225 G Yr Regn: 24/6/2011

Type: ☒ M.Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CERAT FORTE C.C. 1591

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 142342 T/Radio: Insured / Std / NI / NA

Eng/No: GFFCBH361680

C/No: KNAFW511MB5465102

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/45/17

R: 215/45/17

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/12/18 D.O.I. 3/1/19 @ 0323 PM

Survey held at YSK AUTO

Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV 25,000/2

PV 19,740/2

NV 5260/2

Range \$7,000 - \$8,000
4,000/2 - 5,000/2

Date/Time. File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time. File Return to?

Transportation

2)

Add Fee: ☐ : Site Insp (\$)

\$ + RS \$

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$)

100

100




Service Request Details

Claim

S9M018SN

Reference

None 

Loss Date

31 December 2018

Request Date

3 January 2019

Due Date

10 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKB7225G

Make

TPVD KIA

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

YU Dominic Yishan

dominic.yuys@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Ganesh <ganesh@centrollc.com.sg>
Sent: Wednesday, 2 January, 2019 2:53 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: PRI -SKB7225G ; Our Ref: CLLC.PD.99.2018 ; Yr Ref: To Be Advised ; Yr Veh: SHC5512X ; DOA: 31.12.2018
Attachments: 02012019144629.pdf
Categories: Santosh

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.
Kindly refer to attachment.

Best Regards,

Ganesh.V

Centro-Legal Law Corporation
151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

Your Ref : To be advised
Our Ref : CLLC.PD.99.2018

02.01.2019

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811.

BY EMAIL

Attn: **Officer-In-Charge**

Dear Sirs,

NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASE

We act for **ONG BOON TONG**, the owner of motor vehicle **SKB7225G**, who has appointed us to act on his behalf to claim against your insured's vehicle no **SHC5512X** in regards to the road traffic accident on 31.12.2018.

Please be informed that the said motor vehicle can be inspected at:-

YSK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6

#01-71 AutoBay, Singapore 417883 #01-08 Heavy vehicle

Tel: 9007 5148 | Fax: 6556 0801

Email: dannyskyeo@gmail.com

Kindly contact **Danny Yeo** HP: 96402541

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



CENTRO-LEGAL LAW CORPORATION

Cc **Danny**
Fax: 6556 0801

UEN NO.201302032G

CENTRO-LEGAL LAW CORPORATION is incorporated as a company in Singapore

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3340D
Vehicle Details	
Vehicle No.:	SKB7225G
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6 SX 6AT ABS D/AB 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	G4FCBH361680
Chassis No.:	KNAFW511MB5465102
Maximum Power Output:	91.1 kW (122 bhp)
Open Market Value:	\$13,553.00
Original Registration Date:	24 Jun 2011
First Registration Date:	24 Jun 2011
Transfer Count:	0
Actual ARF Paid:	\$13,553.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2021
PARF Rebate Amount:	\$8,131.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$46,989.00
COE Rebate Amount:	\$11,603.00
Total Rebate Amount:	\$19,734.00

The information contained herein is correct as at 04 Jan 2019

OK

Dep 8,260/yr
688/mth

MV 24K - 25,000/2
PV 19,740/2
NV 5,260/2

X GO FROM THIS ...



✓ TO A BELLROY



Both the s

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.88% P.A. Lowest Interest! GV
Cars Financing \$4800
Downpayment Monthly From
\$688
GV Credit Pte Ltd [StarAd](#)

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

Sort by Date Posted ▼

100 results/page ▼

35 vehicles

Kia Cerato

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Kia Cerato		Any	Any	2011	Any	Any	Any	All

**Kia Cerato Forte 1.6A SX SDR****\$29,800****\$8,090 /yr****30-Nov-2011****1,591 cc****118,098 km****Hatchback****Available**

Price Nego. Well Taken Care By Previous Owner. Low Maintenance, Smooth And Fuel Efficient. Call To View Now Before It Is Too Late!

Posted: 03-Jan-2019 Tags: 2011 Kia Cerato, 2011 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato Forte 1.6A SX****\$25,388****\$8,180 /yr****28-Apr-2011****1,591 cc****132,000 km****Sedan****Available**

Very Well Maintained, Low Mileage, Accident Free. Sporty Body Kit. View To Appreciate A1 Condition. Call Now, Don't Miss.

Cycle & Carriage.Fulco Motor Dealer

Posted: 31-Dec-2018 Tags: 2011 Kia Cerato, 2011 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato Forte 1.6A SX (OPC)****\$29,800****\$9,520 /yr****23-Jun-2011****1,591 cc****78,000 km****Sedan****Available**

Scrap Value At \$7336 When You Scrap With Us! 100% Loan Welcomed! Only 1 Owner. Well Maintained With Extreme Sporty Exterior And Servicing Just Done. New Engine Mounting, Brake Pads, Tensioner And Fan ...

HTS Motor

Posted: 31-Dec-2018 Tags: 2011 Kia Cerato, 2011 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato Forte 1.6M SX****\$26,800****\$8,260 /yr****26-Jul-2011****1,591 cc****124,000 km****Sedan****Available**

Full Loan Available. Rare Manuel SX Model. Low Maintenance And Low Fuel Consumption. Please Call Or Visit Us Now For Further Details.

Pure Motors Pte Ltd

Posted: 29-Dec-2018 Tags: 2011 Kia Cerato, 2011 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

**Kia Cerato Forte Koup 1.6A SX****\$27,800****\$8,640 /yr****09-May-2011****1,591 cc****106,000 km****Sports****Available**

Single Owner. Full Agent Service By C & C. Immaculate Condition. Highly Demand Coupe. See To Believe. Ideally For Low Budget Coupe Buyer, Young Drivers Or Young Couple. Wait No More. Trade In Availabl...

Posted: 23-Dec-2018 Tags: 2011 Kia Cerato, 2011 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

**Kia Cerato Forte 1.6A SX****\$24,800****\$7,920 /yr****28-Apr-2011****1,591 cc****95,000 km****Sedan****Available**

\$0 Down Payment Drive Away. Excellent Condition, Call Now For An Appointment, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.

1axis

Posted: 19-Dec-2018 Tags: 2011 Kia Cerato, 2011 kia cerato, Kia Cerato, kia cerato, Kia, Cerato, cerato, Used Kia

Compare [1]

Select used cars to **Compare** or **Add to Alert**

Shortlist [1]



Kia Cerato Forte
1.6M SX
26-Jul-2011

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

Add to Shortlist

Compare Now

Clear All

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 12:01
Date Of Accident	31/12/2018 11:00
Exact Location Of Accident	ALONG CTE TWDS CITY BEF PIE (JURONG EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB7225G
Insured/Policyholder	
Name Of Registered Owner	ONG BOON TONG
NRIC No	S2513340D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96908714
Alternative Phone No	OFFICE-96908714

Vehicle Particulars

Manufacturer	KIA
Model	CARETO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28959331QMX
Cover Note Number	

Driver

Name of Driver	ONG WEI HAN
NRIC No	S8913949Z
Date Of Birth	21/04/1989
Occupation	INDOOR
Date Of Driving Pass	27/05/2009
Driving Experience	9 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96908714
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 756 YISHUN ST 72 #05-270
Postcode	760756
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBANWANG NPC
Police Station Address	ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3792S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC5512X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 97242802
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHD5966P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number 98246908
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ONG WEI HAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKB7225G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Diagram illustrating the positions of vehicles involved in the accident, marked on a grid:

- Vehicle C: SHDS966P
- Vehicle A: QKB7225G
- Vehicle B: SHC5312X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190101/2055

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3




Report No. T/20190101/2055

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 2 BRYAN TAY WEI CHUAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/01/2019 14:10
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	Classification Of Case:
Authentication Stamp NP168 	

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190101/2055

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20190101/2055

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/01/2019 14:10		Vide Report No.: E/20181231/0063		Station Diary No.: 103	
Informant's Particulars					
Name of Informant: ONG WEI HAN			Address: APT BLK 756 YISHUN STREET 72 #05-270 SINGAPORE 760756		
ID Type / ID No.: NRIC NO / S8913949Z			Contact No.: Home/Office: Mobile: 96908714		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 29	Date of Birth: 21/04/1989	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Buyer			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 31/12/2018 11:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY PAN-ISLAND EXPRESSWAY Travelling along CTE towards City before PIE(Jurong Exit)				
Weather: Sunny		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC3792S	Car				No Damage	0
SHC5512X	Car				Seriously Damaged	1
SHD5966P	Car				Slightly Damaged	0
SKB7225G	Car				Seriously Damaged	0

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190101/2055

2 of 3

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

Report No. T/20190101/2055

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ONG WEI HAN	ID No.	S8913949Z
Related Vehicle	SKB7225G (Car)	Contact No.	96908714
Hospital/Clinic	GLENEAGLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	31/12/2018	Date Discharge	01/01/2019
No. of Days granted Medical Leave	06	Degree of Injury	Slight

Brief Details.

On the 31/12/2018 at about 1115hrs, I am driving my vehicle(white KIA) bearing registration no. SKB7225G at along CTE towards City before PIE(Jurong Exit). I was at the first lane together with registration plate no. SHC3792S, SHD5966P, HP:98246908 and SHC5512X, HP:97242802. During that point of time, I saw traffic jam at CTE towards City area. Afterwhich, I saw the vehicle no. SHD5966P e-brake immediately which I stop in time. Subsequently, a vehicle SHC5512X which was driving behind me did not stop in time. As such, the vehicle hit onto my rear bumper which cause my vehicle to move forward and hit onto SHD5966P causing a slight bump. At that point of time, the impact made my forehead hit onto the wind screen and my nose onto the steering wheel which causes nose bleeding. Ambulance was at scene and conveyed me to Gleneagles Hospital. Cisco and EMAS was at scene.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19000119/Bcbe2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date: 16-01-2019		
ATTN: DOMINIC YU		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHC 5512X	Veh. Inspected	SKB 7225G	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M018SN	Excess (\$)	0.00	
Assign From	DOMINIC YU	Assign Date	03/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KNAFW511MB5465102	Colour	WHITE	
Odometer	142342 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
5. General Information				
Accident Date	31/12/2018	Inspect Date / Time	03/01/2019 (03:23 PM)	
Survey held at	Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	

Report Ref No. CS3/ASM19000119/Bcbe2

Inspected By



LIM TEOW GUAN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.