(08/11/13) Wef REF:	MS/V/ CC3/MSG19000121/USbn2
	IGNMENT
	Veh No: SGH & 2659 Yr Regn: 6,06
From: Date: Estimated Cost:	Type; M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD /TP/WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or A
To Inspect Vehicle No: SGH & 26.69	Make: Tous to Ruch as 149 C
	A/C: Insured Std MI (NA
at Workshop m/s	Sp.Reading /9(/)/ T/Radio: Insured / Std / NI / NA
01	Eng/No:
Insured: 5 1 4 9 10 2 ×	C/No: 1200€000 4480
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Anorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	
Make of Veh:	
	Tyre Size: F: 215/65-R/6
(Policy Condition) Remark: The yeh had commenced its N/S O/S	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
	TOYO / YOKO or
Ball of Warrot Value.	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
Est. Repairs: days Res.: Yes or No	D.O.A. 30/12/18
Lum Sum: 20 % 3 Val.: Yes- or No	Survey held at
CA / REV / REP. / 24 HRS 20/6/2021	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction May V value -	
hune No Die LTA	11471 2405 Gods. moresto
	16/1/2019
07/01/19 @ 15.00 p.m. revet pending	cotinete from report to Zene Ten
// Via enail.	
15/1/15 1/2 0 1600 CONF IND	with Alex.
15/01/19 Continued AS \$ 1,650/	- @ 4 days with marcus
(\$5,070.70 Ped 76)	C) KECEIVED D JAH 2019
Date/Time, File Pass to? : Prell. Report	Days Of Repair: 4
1) Types : Final Report	Resurvey No. of Trip: Survey Fee:150
Date/Time, File Return to?	Transportation: 10
2) Add Fe	
B	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 1,650/- 4/5)	: Weekend (\$
	TOTAL 160

.

View Sent Message

This mail is associated with:

*SGH8265A (581060) [SJX9102K]

TP RAYMOND XPERIA CHAN Dec 30 2018 6:00PM [Roswandi bin Ahmad] Fastech Auto Pte Ltd

Resend	View Recipients Print Message Delete Message Forward
From	LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 07/01/2019 15:00 PM.
То	irene_tan@sg.msig-asia.com
cc	sur@lkkauto.com
Subject	SGH8265A (581060) [SJX9102K] TP

Dear Irene,

Please be informed that we have inspected the vehicle SGH 8265A on 03/01/2019.

We are pending estimate from repairer.

Thank you. Best Regards, Shirley Hiew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

Shirley Hiew (LKK Auto)

From:

Low Yi Qian <yiqian_low@sq.msig-asia.com>

Sent:

Monday, 7 January 2019 10:21 AM

To:

Shirley Hiew (LKK Auto); Pang Xiu Shi; Irene Tan

Cc:

KKLau; Accounts (LKKAuto); SUR

Subject:

RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 30/12/2018, SGH 8265A (TP VEHICLE), SJX 9102K (OI VEHICLE) - Claim Ref: 581060

Hi Shirely

Claim reference 581060 for your necessary action.

Thank you and have a great day ahead!

Best Regards Low Yi Qian Administrative Officer Claims Services Department Direct line +65 6594 2525 | Direct fax +65 6225 7402 | yiqian_low@sg.msig-asia.com





MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on @ @MSIG_SG

A member of MS&AD INSURANCE GROUP

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Monday, 7 January, 2019 9:47 AM

To: Pang Xiu Shi <xiushi pang@sg.msig-asia.com>; Irene Tan <irene_tan@sg.msig-asia.com>

Cc: KKLau <kklau@lkkauto.com>; Accounts (LKKAuto) <account@lkkauto.com>; SUR <sur@lkkauto.com>; Low Yi

Qian <yiqian_low@sg.msig-asia.com>

Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 30/12/2018, SGH 8265A

(TP VEHICLE), SJX 9102K (OI VEHICLE)

Dear Xiu Shi/Irene,

Kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Friday, 4 January 2019 1:51 PM

To:

xiushi_pang@sg.msig-asia.com; 'Irene Tan'

Cc:

KKLau; Accounts (LKKAuto); SUR; yiqian_low@sg.msig-asia.com

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

30/12/2018, SGH 8265A (TP VEHICLE), SJX 9102K (OI VEHICLE)

Attachments:

TP GIA REPORT.pdf

Dear Xiu Shi/Irene,

Please be informed that we had inspected the vehicle SGH 8265A at M/s: FASTECH AUTO PTE LTD,1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 03/01/2019.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.


Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



> Back to OneMotoring

wner ID Type:	Singapore NRIC
Owner ID:	2986A
Vehicle Details	
/ehicle No.:	SGH8265A
/ehicle to be Exported:	No
ntended Deregistration Date:	03 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	3SZ1602754
Chassis No.:	J200E0004480
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$22,231.00
Original Registration Date:	23 Jun 2006
First Registration Date:	23 Jun 2006

\$24,455.00

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

Intended PARF Rebate Details

COE Expiry Date: 22 Jun 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$23,227.00

COE Rebate Amount: \$11,471.00

Total Rebate Amount: \$11,471.00

Message

Transfer Count:

Actual ARF Paid:

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jan 2019

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 02/01/2019 13:38

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	nu hereby consent to the archiving of this report at the centre and to copies of the report being made available	
	ACCIDENT STATEMENT	
Date Of Report	02/01/2019 13:25	
Date Of Accident	30/12/2018 18:15	
Exact Location Of Accident	VIVO CITY CARPARK ENTRANCE	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGH8265A	
Insured/Policyholder		
Name Of Registered Owner	RAYMOND XPERIA CHAN	
NRIC No	S7822986A	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-96222986	
Alternative Phone No	OTHERS-96222986	

Vehicle Particulars

Manufacturer	TOYOTA
Model	RUSH 1.5 A
Exact Purpose for which vehicle was being used at	PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

NO

Policy Number

GA228882/1

Cover Note Number

Driver

Name of Driver RAYMOND XPERIA CHAN

NRIC No S7822986A Date Of Birth 07/08/1978 Occupation INDOOR Date Of Driving Pass 06/12/1999

Driving Experience 19 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96222986

Fax Number

Contact Number OTHERS-96222986

EMail Address NOEMAIL Address

279C SENGKANG EAST AVE #08-531 SPORE 543279

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

(+)

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO 2

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident?

...

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

.....

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: AIDRINA

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

was there any video captured by Car Came

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJX9102K

Vehicle Make/Model/Colour

HYUNDAI 145 2.0 AT ABS AIRBAG 2WD 4DR

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: LLin

NRIC/FIN NO: 100401771

Sketch Plan #2

bht on	my nevr	portion.	
seticle dow	Vivo cit	y carpork	entrune Suddenly who
ESCRIBE CIRCUMSTANC		and time	. I was diving my which
		I I I I I I I I I I I I I I I I I I I	6 - SJX 91071
			A - SGH 8265 B - SJX 91021
		19	70

2/5 a 1650/2 **FASTECH AUTO PTE LTD** BLK1 KAKI BUKIT AVE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 VEHICLE NO:SGH 8265A QTY **PARTICULAR** \$121.10 REAR WINDSCREEN MOULDING 1 PCS \$1,655.10 1 PCS REAR BACK DOOR 1455.00 REAR SPARE TYRE OUTER COVER \$1,550.10 1 PCS 478:00 \$645.50 REAR SPARE TYRE INNER COVER 1 PCS \$299.80 REAR SPARE TYRE BRACKET 1 PCS 1 ↑ \$899.10 × REAR BUMPER 1 PCS \$5,170.70 LABOUR CHARGES: \$50.00 20 TO CHECK WIRING U 1 \$120.00 × TO DIMANTLE & REFIX SEAT REAR WINDSCREEN \$50.00 X TO SPRAY RUSF PROOFING \$580.00 300 LABOUR FOR PANEL BEATING & REPLACING PARTS \$750.00 350 TO PUTTY & SPRAY PAINTING \$6,720.70 TO

LICK Auto Consultants Hence notify

- To result by before after spray painting
- To vision wy narrasted parties during resurvey
- the re-served are subject to confirmation
- . Third early survey is on a "Without Projudice" basis
- . No done modification(s) is allowed
- Supplementary liam(a) must be resurvoyed and in suffice to float epotoval from insureace Company

Acknowledged by Repaire

Ontes

1890.20 257 1417.65 2017.65 1670.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG19000121/USBN2

Date:

16/01/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28989959SMA

Claimant

SGH8265A

Insured Vehicle No:

SJX9102K

Vehicle No : Date of Loss:

30/12/2018

Nature of Claim:

TP

Claim No: 581060

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGH8265A

Make & Model:

TOYOTA RUSH, 1.5 (A) 23/06/2006 (Man. Year: 2006) Engine No: Chassis No: Odometer: 3SZ1602754 J200E0004480

195121 km

Reg. Date: Colour:

Black 1495 cc

Engine Capacity: Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES Yes Engine Modification:

No Pre-accident Condition:

215/65R16

Front Tyre Size: Front Left Side: 215/65R16 Michelin 6 mm Michelin 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,170.70	1,417.65	3,753.05	72.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	670.00	880.00	56.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,720.70	2,087.65	4,633.05	68.94
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	6,720.70	1,650.00	5,070.70	75.45
+ GST 7.00/7.00% (S\$)	470.45	115.50	354.95	75.45
Nett Amount (S\$)	7 191 15	1.765.50	5.425.65	75.45

INSPECTION

Date of Assignment:

07/01/2019

Date Inspected:

03/01/2019 Inspected At:

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jan 2019)

Parts: M1-SUV TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGH8265A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recom	mended	Parts
-------	--------	-------

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR WINDSCREEN MOULDING	Not Necessary	121.10 F	*- FL
1			Repair	1,655.10 F	*- FL
1			Cracked	1,550.10 F	*1,455.10 FL
1			Cracked	645.50 F	*435.10 FL
1			Not Necessary	299.80 F	*- FL
1		*REAR BUMPER	Not Necessary	899.10 F	*- FL
nchise	part. L=ListIte	emDisc.	Sub Total (S\$)	5,170.70	1,890.20
		- List Item Discount on L I		0.00	472.55
			Total Parts (S\$)	5,170.70	1,417.65
	1 1 1 1 1 1 1	1 1 1 1 1 1	1 *REAR WINDSCREEN MOULDING 1 *REAR BACK DOOR 1 *REAR SPARE TYRE OUTER COVER 1 *REAR SPARE TYRE INNER COVER 1 *REAR SPARE TYRE BRACKET 1 *REAR BUMPER nchise part. L=ListItemDisc.	1 *REAR WINDSCREEN MOULDING Not Necessary 1 *REAR BACK DOOR Repair 1 *REAR SPARE TYRE OUTER COVER Cracked 1 *REAR SPARE TYRE INNER COVER Cracked 1 *REAR SPARE TYRE BRACKET Not Necessary 1 *REAR BUMPER Not Necessary 1 *REAR BUMPER Sub Total (S\$) - List Item Discount on L Items 0.00/25.00% (S\$)	1 *REAR WINDSCREEN MOULDING Not Necessary 121.10 F 1 *REAR BACK DOOR Repair 1,655.10 F 1 *REAR SPARE TYRE OUTER COVER Cracked 1,550.10 F 1 *REAR SPARE TYRE INNER COVER Cracked 645.50 F 1 *REAR SPARE TYRE BRACKET Not Necessary 299.80 F 1 *REAR BUMPER Not Necessary 899.10 F nchise part. L=ListItemDisc. Sub Total (S\$) 5,170.70 - List Item Discount on L Items 0.00/25.00% (S\$) 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

D		010	haur
Recom	menae	eu La	Doui

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX SEAT REAR WINDSCREEN	New	120.00	
3	TO SPRAY RUSF PROOFING	New	50.00	
4	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	580.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	750.00	350.00
	Gross Labo	ur Cost (S\$)	1,550.00	670.00
_	Report was unsubmitted dur	ing this print out		

< END OF ESTIMATES >