



Case Details

Case Reference Number : BUS/01/19/5001
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB1557P

Company Type : SMRT Buses Ltd
 Estimation ID : EST-5164-ID
 Assigned By : Bus Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 31/12/2018 05:39 PM
 Vehicle Age(In Months) : 49

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	BODY RH	6010161	MIRROR,VIEW:FRONT,RH,FOR MAN	1	1,244.90	1,244.90	10.00	1,120.41	Replace	1	1,120.41	Replace
									Total Spare Part Cost	1,120.41	Surveyor Total	1,120.41	
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20	
									Final Spare Part Cost	896.33	Final Sur Total	896.33	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL FRONT VIEW MIRROR RH	198.00	198.00	
Total:		198.00	198.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Summary

 Estimator Assessment(\$)
 0.00

 Surveyor Assessment(\$)
 0.00

1/3/2019

<https://vacswb.smrt.com.sg/Estimation.aspx>

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	896.33	896.33
Total Labour Cost	198.00	198.00
Total Spray Painting	0.00	0.00
Other	0.00	0.00
Overall Total	1,094.33	1,094.33
Lump Sum Repair Option	☒	☒
Lump Sum Total	1,100.00	1,100.00
Surveyor Approved Amount		1,100.00
No of Repair Days*	1	1
Remarks	-	Surveyor Remarks
Surveyor Name		Taufikh
Signature		
Survey Date	03/01/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**

Taufikh 93495749
WP
Resurvey after repair
old day
sure/whatsapp
wp/63 03/01/19