Surveyor XAR. | REF: ASM (AXA)

ASSIGNMENT

From: Date: 08 01.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S9917CD

at Workshop m/s Premium

of 55 Ubi Rd 1

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) ~~Instam~~ Owner waiting

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $133K.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: S9917CD Yr Regn: 14 Jun 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A4 c.c 1984

Colour white A/C: Insured / Std / NI / NA

Sp.Reading 5131 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZF43JA163696

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm
D.O.A.		D.O.I.	08-01-19

Survey held at W/S 11Am

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) S + RS SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Survey Fee:

Transportation:

TOTAL