Surveyor | REF:

# ASSIGNMENT

CDE NOV 2024

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHA 7181P Yr Regn: 2016 NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai I40 c.c 1685

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 314632 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU690469

C/No: KMHLB41UMHU096496

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 5 mm | R/Bal. | 5 mm |
| L/Bal. | 5 mm | L/Bal. | 5 mm |

D.O.A. 01/01/2019 D.O.I. 03/01/2019

Survey held at Chumni AMK

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rmt y Rmt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | AIG SKS 4731 S |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($ ) ___S + RS.___SI

☐ : Interview ($ ) Photos

☐ : Tech. Invs ($ ) Others

☐ : Weekend ($ )

Survey Fee:

Transportation:

TOTAL