

PRS
Hwee Jie

REF: M5CH

M/M/mn

INSURANCE

Run Date: 15/11/2018

Estimated Cost: 0

OD: AT / WS / TP RES / OD RES / EVA / INV / MV

No. Inspect Vehicle No: SLM 6955U

Workshop name: Perfect Motor

at: No. 3 Defu Lane W

Sum Insured: Excess:

Client's Record:

Make of Veh: Ah Sun - 8799 8628

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No


GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT



Val No: SLM6955U Yr Regn: 6/4/17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Sienta cc: 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp Reading: 95272 T/Radio: Insured / Std / NI / NA

Eng No: 2NR8700409

C/No: NSP170 7065134

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Moth: Nil / SPN / STD A/Rim or

Tyre Size: F: 195/55R15
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Chao Yang

Front		Rear	
R/Bal: 6 mm		R/Bal: 6 mm	
L/Bal: 6 mm		L/Bal: 6 mm	
D.O.A: 13/10/18		D.O.I: 5/11/18	

Survey held at: Perfect Motor @ 1130

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear

The UIC / Chassis frame / Body Structure affected due to collision:

MV 78,000
PV 50,709
NV 27,291

Range: 4,000 - 5,000

[Signature]
7/11/2018

Date/Time: File Pass Preli. Report
 Final Report

Days Of Repair: 6
Resurvey No. of Trip: -

Survey Fee	20
Insurance	
	10
	130

Add Fee: Site Insp: 15
 Interpret: 15
 Team: 15
 Contact: 15

Report Format: PRS
Lump Sum (I.B.):

UNIQUE APPRAISERS SERVICE

BLK 650, HOUGANG AVENUE 8, #07-335,
SINGAPORE 530650

TEL: 97579896 FAX: 68584193

REG. NO. 47083000W

SINGAPORE, 9th November 20 0

M/S NEO R & R PTE LTD

INVOICE NO. UNI/0202/18

ITEM	PARTICULARS	AMOUNT
1.	Automobile inspection report fee for vehicle Registration. No:-SLM 6955 U Inclusive of Photographs & Transport Charges	\$ 400.00 =====

UNIQUE APPRAISERS SERVICE



UNIQUE APPRAISERS SERVICE

BLK 650, HOUGANG AVENUE 8, #07-335,
SINGAPORE 530650.

TEL: 97579896 FAX: 68584193

REG. NO. 47083000W

TO: M/S NEO R & R PTE LTD
61, Ubi Road One, #01-22,
Qxley Bizhub,
Singapore

INSURED : -
POLICY NO : -
CLAIM NO : -
ACC. DATE : -
OUR REF : UNI/MISC/0

VEHICLE PARTICULARS

VEHICLE NO	: SLM 6955 U	COLOUR	: Silver
MAKE/MODEL	: Toyota Senta	AIRCON	: Fitted
CHASIS NO	: NSP170-7065134	SPORTRIM	: Not Fitted
ENGINE NO	: Hidden	SEATBELT	: Fitted
MILEAGE	: 95,270 km	C/RADIO	: Fitted
ENG. CAP.	: 1,496 cc	OTHER	: -

PREACCIDENT CONDITION

BRAKE : Serviceable
STEERING : Serviceable
BODY WORK : Good

FRONT O/S TYRE	BALANCE	80%	SIZE	195/55R15	MAKE	Chao Yang
REAR O/S TYRE	BALANCE	80%	SIZE	195/55R15	MAKE	Chao Yang
FRONT N/S TYRE	BALANCE	80%	SIZE	195/55R15	MAKE	Chao Yang
REAR N/S TYRE	BALANCE	80%	SIZE	195/55R15	MAKE	Chao Yang

ADJUSTMENT AND RECOMMENDED COST OF REPAIR

REPAIRER'S EST.	OUR REVISED
\$ 11,671.30	\$ 7,050.00
LESS EXCESS:-	N.A.
	<u>\$ 7,050.00</u>

REMARKS:

In normal circumstances, repairs to the vehicle would take approximately Six (6) days to complete.(excluding of Sunday & Public Holidays)

The survey was carried out on a "Without Prejudice" basis only.

GENERAL DESCRIPTION OF DAMAGED:

The vehicle sustains damages to the rear portion, description are listed overleaf.

UNIQUE APPRAISERS SERVICE

ADJUSTMENT OF REPAIR COST AND REPLACEMENT OF PARTS:

* Instruction Received

Veh No: SLM 6955 U
 Assign By: Mr. Chris
 Date: 01-11-18

Date of Inspection: 01-11-18
 Date of Re-inspection:
 Date of Report: 09-11-18

Workshop: Neo R & R Pte Ltd

QTY	DESCRIPTION OF PARTS AND LABOUR	DESCRIPTION OF DAMAGE	REPAIR'S EST.	OUR REVISED
1 pc	rear bumper fascia	DD ✓	\$ 801.40	\$ 801.4
1 pc	rear bumper centre pad	DD ✓	721.50	721.5
2 pcs	rear bumper side pad (o/s only)	DIS ✓	524.60	262.3
2 pcs	rear bumper reflector (o/s only)	NN X	220.20	= 110.1
2 pcs	rear bumper side holder	NN X	136.00	= 136.0
2 pcs	rear bumper centre holder	NN X	136.00	136.0
1 pc	tailgate	DD ✓	1,486.80	1,486.8
2 pcs	tailgate lamp (o/s only)	DD ✓	802.40	×401.2
1 pc	tailgate centre garnish	NN X	398.10	398.1
1 pc	tailgate centre emblem	NEC ✓	99.10	99.1
1 pc	tailgate inner lock	NEC ✓	336.15	×336.15
1 pc	tailgate inner lock latch	NN X	49.20	×49.2
1 pc	tailgate weatherstrip	NN X	270.55	270.55
1 set	tailgate trim board clip	DD ✓	40.00	30 40.00
1 pc	rear o/s body panel splash shield	NEC ✓	79.10	×79.10
1 pc	rear end panel	NN X	599.10	×599.10
1 pc	rear end panel trim cover	Repair X NN X	221.10	×221.10
Less 25% discount on parts			\$ 6,921.30	\$ 6,147.70
S/Nett Items				1,536.93
1 pc	tailgate screen solar film	NEC ✓		\$ 4,610.77
1 set	reverse parking sencor	short NEC ✓	\$ 300.00	\$ 150 240.00
1 pc	tailgate screen dam rubber	NEC ✓	300.00	200 ×240.00
1 tube	tailgate screen sealant	NEC ✓	100.00	50 60.00
1 tube	body panel joint sealant	NEC ✓	100.00	50 60.00
		NEC ✓	100.00	40 60.00
Labour charges & misc.			\$ 7,821.30	\$ 5,270.77
To dismantle & refit rear carpeting, side trim cover, rear seat to facilitate repair.			\$ 350.00	\$ 60 280.00
To dismantle and replace damaged parts, to straighten & jack our rear body structure, rear chasis member, to repair & reshape rear o/s body panel & align necessary parts			\$ 1,200.00	\$ 600 1,000.00
To transfer tailgate fittings			\$ 180.00	\$ 60 120.00
To transfer tailgate screen			\$ 300.00	\$ 120 200.00
To repair rear exhaust silencer & align back same.			\$ 200.00	\$ 140.00
To putty & respray paint on affected accident sections.			\$ 1,200.00	\$ 700 1,000.00
Continue page 2.....			\$ 11,251.30	\$ 8,010.77

UNIQUE APPRAISERS SERVICE



Automobile Adjuster K H Quek

UNIQUE APPRAISERS SERVICE

ADJUSTMENT OF REPAIR COST AND REPLACEMENT OF PARTS:

* Instruction Received

Veh No: SLM 6955 U

QTY	DESCRIPTION OF PARTS AND LABOUR	DESCRIPTION OF DAMAGE	REPAIR'S EST.	OUR REVISED
continue from page 1. Balance carried forward		\$ 11,251.30	\$ 8,010.7
	Labour charges & misc			
	To respray rust proof on affected accident areas	✓	\$ 300.00	\$ 200.0 <i>50</i>
	To check, test lighting & wiring systems	✓	\$ 60.00	\$ 40.0 <i>30</i>
	To renew reverse parking sensor & test functions		\$ 60.00	\$ 40.0 <i>✓</i>
	Note:- Contract job as agreed at a lump sum amount of:-		\$ 11,671.30	\$ 8,290.7 \$ 7,050.0
	<p><i>Three de</i></p> <p><i>7/1/19</i></p> <p><i># 5 days</i></p> <p><i>LS -</i></p> <p>Total \$4,877.7</p> <p>Total \$4,200.0</p>			

UNIQUE APPRAISERS SERVICE



Automobile Adjuster K H Quek.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2018 13:43
Date Of Accident	13/10/2018 09:40
Exact Location Of Accident	WEST COAST RDCLEMENTI WEST ST 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM6955U
Insured/Policyholder	
Name Of Registered Owner	NEO R & R PTE LTD
Co Reg No	201026086E
Email Address	90709947@NEORENTALANDRESOURCES.COM
Mobile Phone No	(LOCAL) +65-96391199
Alternative Phone No	OFFICE-96391199

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994579
Cover Note Number	

Driver

Name of Driver	JAKIE CHAN
NRIC No	S1491520F
Date Of Birth	03/09/1961
Occupation	OUTDOOR
Date Of Driving Pass	15/08/1985
Driving Experience	33 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96391199
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 712 WOODLANDS DRIVE 70#03-97
Postcode	730712
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLOUDY
Road Surface	WET

Other information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : 1 PASSENGER
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO REPORT ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD6905M
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SATOH HISAAKI
NRIC/Passport Number	G5306538X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

B - SKD6909M.

On Saturday 9:40am, 13/10/18 when I was stop at a traffic light along West Coast Rd. When the green lights on, I have a rear collision collision when I was moving off.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



[Handwritten signature]

[Handwritten signature] - 13/10/18

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



[Handwritten signature]

[Handwritten signature] 15/10/18

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1491520F



Name
JAKIE CHAN
曾治誠

Race
CHINESE

Date of Birth **03-09-1961** Sex **M**

Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



JAKIE CHAN

Ren. Date: 03 Sep 1961
Exp. Date: 07 Aug 2013


000725438E



3887038



NRIC No. S1491520F



Issued Group: Date of issue
A1 03-09-1961

APT BLK 712 WOODLANDS DRIVE 7D #03-07
SINGAPORE 730712
NRIC No. S1491520F Date: 14/03/2013 No: 7315170

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

CLASS	VEHICLE CLASSIFICATION	ISSUE DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms	15 Aug 1966

NP 425A

License No: S1491520F





NEO R & R PTE LTD
No. 61 Ubi Road One Colley Bizhub #01-22 Singapore 408727
Tel: 6298 6324 / 6298 5324 Fax: 6298 1002
www.neorentalsandresources.com
Reg No: 201026086E

Authorization Letter

NEO R & R PTE LTD appointed Jackie Chan, IC: S1491520F, Vehicle number: SLM6955S to make an accident report on 12-10-2018



Signature, Company's Stamp

Name: Guan Zhu Jie

NRIC No: S9171653D

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2018 09:19
Date Of Accident	13/10/2018 09:40
Exact Location Of Accident	WEST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD6909M
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	Office-64663022
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VPCP/17-002812-00
Cover Note Number	
Driver	
Name of Driver	SATOH HISAAKI
Passport No/FIN	G5306538X
Date Of Birth	01/02/1973
Occupation	INDOOR
Date Of Driving Pass	11/04/1994
Driving Experience	24 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98192270

Fax Number	
Contact Number	
E-Mail Address	SATOH@TOA-V-OVERSEAS.COM.SG
Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLOUDY
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM6955U
Vehicle Make/Model/Colour	TOYOTA SIENTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JAKE CHAN
NRIC/Passport Number	S1491520F
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 15 Oct 2018 18:30



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ESSO

West Coast Rd



Taman Mas Merah

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Among Traffic Jam I delayed to stop and hit to the car in front.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
[If driver is not the policyholder]
Date & Time: 15 Oct 2018 10:20


Reporting Centre Person's Signature
Name:
NRIC/IN No.:

EMPLOYMENT PASS
 Employment of Foreign Manpower Act (Chapter 91A)
 Republic of Singapore

Employer
TOA VALVE OVERSEAS PTE. LTD.

Name
SATOH HISAKI

ID No.
98306388

K0802338







REPUBLIC OF SINGAPORE DRIVING LICENCE

002543180K





VISIT PASS
 Immigration Regulations

Name
SATOH HISAKI

ID No.
98306388

Date of Birth Sex
01-03-1972 M

Nationality
JAPANESE

MULTIPLE JOURNEY VISA (GROUP)

Download the SmartPass App to check status




YOU ARE TO Surrender This Card With All Documents If It Was Expired, Or When A New Card Is Issued To You



Class 3 Motor cars with unladen weight >= 3000kg with >= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight >= 2500kg

01 Sep 2018

License No: 00306388

MP 428A



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



TOYOTA MOTOR CORPORATION JAPAN
MODEL ZGE20R-HPXNP
ENGINE 2ZR-FAE 1798 mL
FRAME No. JTDGG20W805002527
COLOR TRIM PLANT OPTION
1E7 FA12 A54
TRANS./AXLE K311 -02A 956

Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2018		02 Nov 2018 15:26 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N								
Main Claimant:	NEO R & R PTE LTD , Co. Reg. No.: 201026086E								
Vehicle Reg. No.:	SLM6955U	Date of Loss:	13/10/2018 09:00 - :59 [18 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001380	Policy/Cover Note No.:	MSD/VPCP/17-002812-00 (Comprehensive) Coverage: 28/12/2017 - 27/12/2018						
Vehicle Reg. No. (Insured):	SKD6909M	Policy No. (Claimant):							
		Excess:							
Repairer:	Perfect Motor (HQ) No. 51 Defu Lane 9, Defu Industrial Estate, 539277 Defu Lane - Tel: 83549009								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 04/01/2019]								
Driver/Custodian (Insured):	SATOHI HISAAKI (), NRIC: G5306538X, Tel: +6598192270								
Adj Asg. Remarks:	Liability 100%, SJE Disagree - assign LKK, Contact : Ah Soon at 8299 8628								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • MSIG_SG (02/01/2019): Report Send Back Alerts - SLM6955U (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLM6955U (MSC/V/18-001380)**
[SKD6909M]
TP
NEO R & R PTE LTD
Oct 13 2018 9:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Perfect Motor

Upload Documents		Upload Photos	Compose New Letter	View <input type="button" value="View in Browser"/>
Assessment Reports				1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	02/11/18 14:11	Accident Statement <small>From: SC - Reg. No: SKD6909M, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD</small>		Load HTM
Photos/Images				3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
2	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
3	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
4	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
5	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
6	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
7	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
8	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
9	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
10	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
11	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
12	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
13	07/11/18 14:42	General View		Load JPG <input checked="" type="checkbox"/>
14	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
15	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
16	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
17	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
18	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
19	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
20	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
21	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
22	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
23	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
24	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
25	07/01/19 13:59	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	02/11/18 14:11	SLM6955U E-FILE REPORT <small>From: SC - Reg. No: SKD6909M, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD</small>		Load PDF
2	02/11/18 14:19	PRI from Catherine Lim LLC		Load PDF
3	02/11/18 14:19	Survey Disagree - assign LKK		Load PDF
4	28/12/18 18:25	SURVEY REPORT		Load PDF
5	28/12/18 18:25	SURVEY PHOTOS.		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/01/19 10:40	Colour Photo		Load PDF
2	08/01/19 10:40	PRS Invoice		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18019961/JSD3E2-1
Date: 08/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-002812-00
Claimant Vehicle No :	SLM6955U	Insured Vehicle No :	SKD6909M
Date of Loss:	13/10/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-001380

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM6955U	Engine No:	2NR8700409
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	NSP1707065134
Reg. Date:	06/04/2017 (Man. Year: 2016)	Odometer:	95272 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	CHAO YANG 6 mm	Rear Left Side:	CHAO YANG 6 mm
Front Right Side:	CHAO YANG 6 mm	Rear Right Side:	CHAO YANG 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,821.30	3,644.31	4,176.99	53.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,660.00	2,190.00	56.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,671.30	5,304.31	6,366.99	54.55
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	11,671.30	4,200.00	7,471.30	64.01

INSPECTION

Date of Assignment:	02/11/2018	Inspected At:	3 DEFU LANE 12
Date Inspected:	05/11/2018		Repairer : Perfect Motor (HQ)
Estimated Period of Repair:	5.0 days		

Adjuster: ONG HWEE JIE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts:	M1-MPV TOYOTA SIENNA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM6955U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Dented	801.40 F	*801.40 FL
2	1		*REAR BUMPER CENTRE PAD	Dented	721.50 F	*721.50 FL
3	1		*REAR BUMPER SIDE PAD	O/S Distorted	524.60 F	*262.30 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	220.20 F	*- FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	136.00 F	*- FL
6	2		*REAR BUMPER CENTRE HOLDER	Dented	136.00 F	*136.00 FL
7	1		*TAILGATE	Dented	1,486.80 F	*1,486.80 FL
8	2		*TAILGATE LAMP	Not Necessary	802.40 F	*- FL
9	1		*TAILGATE CENTRE GARNISH	Necessary	398.10 F	*398.10 FL
10	1		*TAILGATE CENTRE EMBLEM	Necessary	99.10 F	*99.10 FL
11	1		*TAILGATE INNER LOCK	Not Necessary	336.15 F	*- FL
12	1		*TAILGATE INNER LOCK LATCH	Not Necessary	49.20 F	*- FL
13	1		*TAILGATE WEATHERSTRIP	Dented	270.55 F	*270.55 FL
14	1		*SET TAILGATE TRIM BOARD CLIP	Necessary	40.00 F	*30.00 FL
15	1		*REAR O/S BODY PANEL SPLASH SHIELD	Not Necessary	79.10 F	*- FL
16	1		*REAR END PANEL	Repair	599.10 F	*- FL
17	1		*REAR END PANEL TRIM COVER	Not Necessary	221.10 F	*- FL
18	1		*TAILGATE SCREEN SOLAR FILM	Necessary	300.00 FS	*150.00 FS
19	1		*TAILGATE SCREEN DAM RUBBER	Necessary	100.00 FS	*50.00 FS
20	1		*TUBE TAILGATE SCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
21	1		*TUBE BODY PANEL JOINT SEALANT	Necessary	100.00 FS	*40.00 FS
22	1		*SET REVERSE PARKING SENCOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,821.30	4,695.75
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,051.44
Total Parts (\$\$)	7,821.30	3,644.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REFIT REAR CARPETING, SIDE TRIM COVER, REAR SEAT TO FACILITATE REPAIR	New	350.00	60.00
2	TO DISMANTLE AND REPLACE DAMAGED PARTS, TO STRAIGHTEN & JACK OUR REAR BODY STRUCTURE, REAR CHASIS MEMBER, TO REPAIR & RESHAPE REAR O/S BODY PANEL & ALIGN NECESSARY PARTS	New	1,200.00	600.00
3	TO TRANSFER TAILGATE FITTINGS	New	180.00	60.00
4	TO TRANSFER TAILGATE SCREEN	New	300.00	120.00
5	TO REPAIR REAR EXHAUST SILENCER & ALIGN BACK SAME	New	200.00	0.00
6	TO PUTTY & RESPRAY PAINT ON AFFECTED ACCIDENT SECTIONS	New	1,200.00	700.00
7	TO RESPRAY RUST PROOF ON AFFECTED ACCIDENT AREAS	New	300.00	50.00
8	TO CHECK, TEST LIGHTING & WIRING SYSTEMS	New	60.00	30.00
9	TO RENEW REVERSE PARKING SENCOR & TEST FUNCTIONS	New	60.00	40.00
Gross Labour Cost (S\$)			3,850.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >