

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ) *JM*
CTPL

Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/01/2019
Vehicle Reg. No.:	SHC8526L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	03/12/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4DFDU564952	Chassis No:	KMHLB41UMGU080719
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	716.88
Miscellaneous Items	10.00
Labour	830.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,556.88
+ GST 7.00% (S\$)	108.98
Nett Amount (S\$)	1,665.86

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2019)
Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC8526L/02/01/2019 17:06
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	*553.00FL ✓ CRK
2	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00FL ✓ NEC
3	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00FL ?
4	1		*REAR BUMPER REFLECTOR LAMP RH	20.00	0.00	*30.60FL ✓ OFF
5	1		*REAR BUMPER MAT	0.00	0.00	*50.00F ✓ WBL
Sub Total (\$\$)						883.60
- List Item Discount on L Items (\$\$)						166.72
Total Parts (\$\$)						716.88

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC8526L/02/01/2019 17:06. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400.00 ²⁰⁰
2	SPRAYPAINT	New	300.00 ²⁰⁰
3	WIRING	New	50.00 ^{NW}
4	REMOVE/REFIX REVERSE SENSOR	New	80.00 ²⁰
Gross Labour Cost (S\$)			830.00

ComfortDelGro Engineering Pte Ltd/SHC8526L/02/01/2019 17:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKIC
3/1/19 1545
LIS
2 DAYS
CHECK ITEMS (Photo)
AFTER REPAIR (Photo)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: