





PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC19000207/Gtd3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 22-01-2019		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMA 185R	Veh. Inspected	FBN 6580E	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/19/VP05/021266	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	04/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA AEROX	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3SG4610JJ158438	Colour	RED	
Odometer	979 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/80 R14	IRC	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R14	IRC	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.			
5. General Information				
Accident Date	27/12/2018	Inspect Date / Time	04/01/2019 (12:00 PM)	
Survey held at	S1 MOTORING BLK 3006 UBI ROAD 1 #01-366 SINGAPORE 408700			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19000207/Gtd3e2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.