COMFORTDELGRO ENGINEERING

Our Ref: 305255136

Date: 28.12.2018

Time of Fax : 17 45M

tuma Via Fax:

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Your Insured : SDY 9 008 R

Date of Acc: 27.12.2018

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SH 8134 C

Lovang △59 Loyang Drive Singapore 508969

Fax no. 6546 8156

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811 Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305

Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006 Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176

Larry Ng

Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

for Vice President

Crash Repairs & Claims Recovery













COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8134C

28. Dec. 2018 DATE:

MAKE

: MERCEDES

MODEL : E220 (E6) 27. Dec. 2018 AXA DOA:

NODEL	: E220 (E6)	DOA:	27. Dec. 2018	AXA
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	Radiator Grille SUB TOTAL LESS 20% DISCOUNTED TOTAL Labour Charge 1 Panel Beating		OHIL FILE	\$1,220.00 \$1,220.00 \$244.00 \$976.00
	TOTAL LABOUR ESTIMATE TOTAL			\$200.0 \$1,176.0
	This is an initial estimate based on a visual inspection of t	he above ve	ehicle. The final repair	quantum will
	be prepared after the vehicle is surveyed by a motor Surv			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

foresaid.			
	ACCIDENT STATEMENT		
Date Of Report	28/12/2018 12:06		
Date Of Accident	27/12/2018 02:40		
Exact Location Of Accident	ALONG TANJONG KATONG RD OPPOSITE PARKSTONE RD JUNC		
Country/State of Loss	SINGAPORE		
	ETAILS OF OWN VEHICLE		
Vehicle Registration Number	SH8134C		
Insured/Policyholder			
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD		
Co Reg No	199303821R		
Email Address	FLEETSAFETY@CDGTAXI.COM.SG		
Mobile Phone No			
Alternative Phone No	OFFICE-65508768		
Vehicle Particulars			
Manufacturer	MERCEDES-BENZ		
Model	MERC		
Exact Purpose for which vehicle was being used at time of accident			
Are you claiming under your own insurance policy for repair to your vehicle?	NO		
If No, Please state action to be taken	THIRD PARTY		
Vehicle Category	TAXI		
Insurance Company			
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD		
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT		
Fleet Policy	YES		
Policy Number	MCOM0015		
Cover Note Number			
Driver			
Name of Driver	TEO GEK CHEONG		
NRIC No	S0334514I		
Date Of Birth	17/09/1949		
Occupation	OUTDOOR		
Date Of Driving Pass	31/12/1970		
Driving Experience	47 YEARS AND 11 MONTHS		
Gender	MALE		
Mobile Number	(LOCAL) +65-85222773		
Fax Number			

NOEMAIL

Address

53 #27-112 HAVELOCK ROAD

Postcode

161053

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SDY9008R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

NO DAMAGE

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

CETCH DI AN
SHESSION PROPERTY OF THE PROPE
Tenhone horave
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
Statement as per attached.
7 3
,
·
DECLARATION I/We declare the foregoing particulars are true in every respect. COMFORT TRANSPORTATION PTE LILL Olivia Wendy
Policyholder's Signature Date & Time: (If driver is not the policyholder) Reporting Centre Personnel's Signature Name:

Sketch Plan Pg. 2

REV 3P CARPARK

Describe Circumstances of the Accident.
On 27/12/2018 @ about 02:40hrs, I was driving along Tanjong Katong Rd.
I parked my taxi opposite the Parkstone Rd junction. While I was in my taxi suddenly
vehicle SDY9008R reversing and collided onto the front portion of my taxi.
No passenger on board my taxi. No injury reported at the point of accident.

Declaration

 $\ensuremath{\mathrm{I/We}}$ declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LIL CO. REG. NO. 199303821R X

Policyholder's Signature/Date &

Time

Driver's Signature(If driver is not the policyholder)/Date

& Time

Olivia Wendy

Witnessed by Reporting Centre Personnel

28 DEC 2018

Page 1