



Your Ref: 8435313548SG-003

Date: 30th May 2019

Our Ref: CS1/AIG19000223/Jqd3s2

M/s AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #08-16

Chartis Building

Singapore 079120

Attn: Saliha

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLW 9196X
INSURED VEHICLE: SLK 2128C ACCIDENT DATE: 14/06/2018**

We thank you for your instruction on 04/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLW 9196X from M/s United Appraisal and Management Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLW 9196X and SLK 2128C.
- c) Colour damaged vehicle photographs of SLW 9196X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLW 9196X
Make & Model	: BMW 520i 2.0L
Year of Registration	: 2013
Chassis Number	: WBAXG12000DX53675
Engine Capacity	: 1997 cc
2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.