

27/03/2002

ASS. REC. BY:

REF: CS3

AIG19000242/Gcd302

Special Instruction:

Surveyor:

GUD Oichey

ASSIGNMENT (Office)

From (Person):

Azlan Syazaidin

of

AIG

Date/Time:

4/1/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 7171E

Insured:

8KX6026E

at Workshop m/s

platinumwerkZ

Tel:

88261413

of

53 Ubi Ave 1 # 01-25

Policy No:

099994444

Claim No:

366356664236

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/12/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

3:43pm 4/1/2019

Person Contacted:

Dora

Vehicle IN/OUT

| Date/Time | Action/Instruction (X) Estimate |                     |
|-----------|---------------------------------|---------------------|
|           | SLD 7171E - NA/INC18022621/24   | Dora: 16/12/2018    |
|           | 8KX6026E - NA/INC18022621/24    | Dora: 16/12/2018    |
|           | Spoken to Dora no estimate      | engage independent. |
|           | Dismantle: 7/1/2019             |                     |
|           | After repair: 10/1/2019         |                     |

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Platinum werkz  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 126 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLD7171E Yr Regn: 22 Jul 2016  
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Forte K3 c.c. 1591

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 48296 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNA FZ 411 MH 5635304

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 8R18  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 04-01-19

Survey held at W/S

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/1/19 Pending estimate from Repairer

RECEIVED 31 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Transportation: \_\_\_\_\_

2)

Add Fee: ☐ : Site Insp (\$)

S + RS \$

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format : DAR.

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

180

11

191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |   |               |  |         |               |             |   |
|--------------------------|---|---------------|--|---------|---------------|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status  |
| Main                     | 17 Dec 2018<br><a href="#">Edit Reg</a> |               | 04 Jan 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> |         |               |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents                  | <a href="#">Show All</a> |         |             |              |            |       |
|---|---|------------------------|----------------------------|--------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |   |                        |                            |                          |         |             |              |            |       |
| Insured:  | <b>BLUE STAR CONCIERGE PTE LTD</b> , Co. Reg. No.: 201506692D   |                        |                            |                          |         |             |              |            |       |
| Main Claimant:  | <b>RYAN ANG JIA-HAO</b>   |                        |                            |                          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SLD7171E</b>   | Date of Loss:          | 16/12/2018 18:00 - :59     |                          |         |             |              |            |       |
| Claim Type:   | <b>TP / 3663566642SG</b>  | Policy/Cover Note No.: | 0999994449 (Comprehensive) |                          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SKX6026E</b>   | Policy No. (Claimant): |                            |                          |         |             |              |            |       |
|   |   | Excess:                |                            |                          |         |             |              |            |       |
| Repairer:   | <b>Platinum Werkz Pte Ltd (HQ)</b> 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610                                    |                        |                            |                          |         |             |              |            |       |
| Handling Insurer:   | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com |                        |                            |                          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 15/01/2019]</b>       |                        |                            |                          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |   |                        |                            |                          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (07/01/2019): Request to upload TP GIA Report</li> </ul>  |   |                        |                            |                          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |   |                        |                            |                          |         |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group                 | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |                            |                          |         |             |              |            |       |

- Pre repair inspection request - SLD7171E VS SKX6026E (OI) DOA 16/12/2018

From: Azlan, Syazairdina  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinnul, Chan Yoke Shi, Kaur, Baljit, Fan, Winnie-Li  
Sent: 4/1/2019 3:27:36 PM  
Attachments:  tmp2FA5.tif

---

Hi,

Please refer to the enclosed request from **Kertar & Sandhu LLC**.

Claim no : 3663566642SG003  
Case Owner : JACLYN MANIAM KESAVAL

If you have any queries/concerns, please let us know.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** michelle@kertarlau.com.sg [mailto:michelle@kertarlau.com.sg]  
**Sent:** Friday, January 04, 2019 3:04 PM  
**To:** Azlan, Syazairdina  
**Cc:** kertar@kertarlau.com.sg; harmeet@kertarlau.com.sg; michelle@kertarlau.com.sg  
**Subject:** RE: Pre-Repair Inspection - Accident Involving vehicle SKX 6026E and SLD 7171E on 16 December 2018

Dear Sir

We confirm that we are nominating LKK Auto Consultants named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert."

Please proceed.

Kind regards

Michelle Kaur | Legal Trainee

For and on behalf of Mr. Kertar Singh, Mr. Anil Singh, Mr. James Sebastian, Ms. Jessvir Kaur, Mr. Lee Wei Liang, Mr. Ian Yang & Ms. Praseedha Nair

**Kertar & Sandhu LLC**  
133 New Bridge Road #11-10 Chinatown Point Singapore 059413  
T : +65 (65) 66266 | F : +65 (65) 6557 0113  
Email: [michelle@kertarlau.com.sg](mailto:michelle@kertarlau.com.sg)

This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system.

E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

---

**From:** Azlan, Syazairdina  
**Sent:** Fri, 4 Jan 2019 05:12:04 +0000  
**To:** michelle@kertarlau.com.sg  
**Cc:** kertar@kertarlau.com.sg, harmeet@kertarlau.com.sg  
**Subject:** RE: Pre-Repair Inspection - Accident Involving vehicle SKX 6026E and SLD 7171E on 16 December 2018

Hi,

Please confirm that you are nominating LKK Auto Consultants named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** michelle@kertarlau.com.sg [mailto:michelle@kertarlau.com.sg]  
**Sent:** Friday, January 04, 2019 12:50 PM  
**To:** Azlan, Syazairdina  
**Cc:** kertar@kertarlau.com.sg; harmeet@kertarlau.com.sg  
**Subject:** Pre-Repair Inspection - Accident Involving vehicle SKX 6026E and SLD 7171E on 16 December 2018

Dear Sirs

1. We refer to the above matter and your email dated 3 January 2019.
2. Please note that our client is agreeable to have any LKK Auto Surveyor to inspect the vehicle.
3. The said vehicle can be inspected at:  
Workshop: Platinumwerkz  
Address: 53 Ubi Avenue 1 #01-25 (Paya Ubi Industrial Park) Singapore 408934  
Contact Person: Dora (HP: 88261413)

Kind Regards

Michelle Kaur | Legal Trainee

For and on behalf of Mr. Kertar Singh, Mr. Anil Singh, Mr. James Sebastian, Ms. Jessvir Kaur, Mr. Lee Wei Liang, Mr. Ian Yang & Ms. Praseedha Nair

**Kertar & Sandhu LLC**

133 New Bridge Road #11-10 Chinatown Point Singapore 059415

T: +65 6536 8266 | F: +65 6557 0312

Email: [michelle@kertarlaw.com.sg](mailto:michelle@kertarlaw.com.sg)

This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system.

E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com  
To: kertar@kertarlaw.com.sg; james@kertarlaw.com.sg  
Cc: Andy-SY.Fong@aig.com; Lee-Ying.Chin@aig.com; NoorMariesa.AbuKassim@aig.com; Imran.Ishak@aig.com; ShengYang.Lim@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Yinrul.Hor@aig.com; yokeshi.chan@aig.com; Bal.LW.Fan@aig.com  
Subject: RE: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX6026E AND SLD7171E ON 16/12/2018  
Date: Thu, 3 Jan 2019 06:56:54 +0000  
Dear Sir/Madam,

Reminder for pre-repair survey

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

From: Azlan, Syazairdina  
Sent: Wednesday, January 02, 2019 3:22 PM  
To: kertar@kertarlaw.com.sg; james@kertarlaw.com.sg  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit  
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX6026E AND SLD7171E ON 16/12/2018

Without Prejudice

Your Reference : KS/JS/PDPI011/18 (mck)  
Our Reference : 3663566642SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor      | Company Name                           |
|-----------------------|--|
| AIG In House Surveyor | AIG Asia Pacific Insurance Pte Ltd     |
| Lawrence Ng Chun Kee  | Priority Services                      |
| Jeffrey Ong Leng Kiat | Priority Services                      |
| Jimmy Lee             | Priority Services                      |
| EC Looi               | Automobile Inspection Services Pte Ltd |

|                          |                              |
|--------------------------|------------------------------|
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd   |
| Ng You Han               | Formteam Adjusters Pte Ltd   |
| Soon HanXin (Gary)       | Formteam Adjusters Pte Ltd   |
| Chow Bo Xiong            | Formteam Adjusters Pte Ltd   |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd   |
| Kalvin Ang               | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang           | LKK Auto Consultants Pte Ltd |
| Marcus Chua              | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh          | LKK Auto Consultants Pte Ltd |
| Adrian Ling              | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul           | LKK Auto Consultants Pte Ltd |
| Kenneth Kong             | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II, Singapore FNOL Claims Operations – Auto  
SG Claims Operations | AIG Shared Services

[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Zhou, Aiping  
**Sent:** Wednesday, January 02, 2019 11:25 AM  
**To:** PRDSG.WORKLIST  
**Cc:** Azlan, Syazairdina; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; Chin, Ann; Md Ishak, Mohd Imran; Ho, Choon-Poh; Tan, Lily (AIG); Quek, Joyceline-CH  
**Subject:** #3663566642SG003#002,002#PRI



KERTAR

SANDHU  
Advocates & Solicitors

Your ref: TBA  
Our ref: KS/JS/PDPI0111/18 (mck)

Writer: Mr. James Sebastian  
Email: james@kertarlaw.com.sg

27 December 2018

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**PRE-REPAIR INSPECTION**

**YOUR INSURED VEHICLE REGISTRATION NO. SKX 6026E  
ACCIDENT ON 16<sup>th</sup> DECEMBER 2018 INVOLVING SLD 7171E AND SKX 6026E AT 1840  
HOURS ALONG JUNCTION OF QUEENS ROAD AND PRINCE ROAD**

1. We are instructed by RYAN ANG JIA-HAO to notify you of a road traffic accident on 16<sup>th</sup> December 2018 at approximately 1840 hours along the junction of Queens Road and Prince Road involving our client's vehicle registration no. SLD 7171E and vehicle registration no. SKX 6026E driven by your insured at the material time. A copy of the Singapore Accident Statement filed is enclosed herein.
2. As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **TWO (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the said vehicle without further reference to you.

Yours faithfully

Kertar & Sandhu LLC

Enc

Cc Client

133 New Bridge Road  
#11-10 Chinatown Point  
Singapore 059413

Tel 6536 6266 (General) | 6536 9504 (Civil & Family)  
Fax 6557 0313  
Email: kertar@kertarlaw.com.sg

*No service of court documents by fax or email*

Directors Kertar Singh | Anil Sandhu  
Consultant James Sebastian

**URGENT**

**BY POST & BY FAX**  
**6835 7417**

**REMINDER**

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| Vehicle Owner Particulars     |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Singapore NRIC                       |
| Owner ID:                     | 0058A                                |
| Vehicle Details               |                                      |
| Vehicle No.:                  | SLD7171E                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 07 Jan 2019                          |
| Vehicle Make:                 | KIA                                  |
| Vehicle Model:                | FORTE K3 1.6A                        |
| Primary Colour:               | Black                                |
| Manufacturing Year:           | 2016                                 |
| Engine No.:                   | G4FGGH623476                         |
| Chassis No.:                  | KNAFZ411MH5635304                    |
| Maximum Power Output:         | 95.3 kW (127 bhp)                    |
| Open Market Value:            | \$16,920.00                          |
| Original Registration Date:   | 22 Jul 2016                          |
| First Registration Date:      | 22 Jul 2016                          |
| Transfer Count:               | 1                                    |
| Actual ARF Paid:              | \$16,920.00                          |
| Intended PARF Rebate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 21 Jul 2026                          |
| PARF Rebate Amount:           | \$12,690.00                          |
| Intended COE Rebate Details   |                                      |
| COE Expiry Date:              | 21 Jul 2026                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$52,301.00                          |
| COE Rebate Amount:            | \$39,422.00                          |
| <b>Total Rebate Amount:</b>   | <b>\$52,112.00</b>                   |

The information contained herein is correct as at 07 Jan 2019

OK



MNA118182491 / National Assessment Centre Services - Ubi  
 ENTRY DATE & TIME: 17/12/2018 18:53  
 SUBMITTED BY: Jackson Ho Zhao Tian

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                             |
|----------------------------|-----------------------------|
| Date Of Report             | 17/12/2018 18:53            |
| Date Of Accident           | 16/12/2018 18:40            |
| Exact Location Of Accident | JUNC QUEEN'S RD & PRINCE RD |
| Country/State of Loss      | SINGAPORE                   |

### DETAILS OF OWN VEHICLE

|  |  |
|--|--|
| Vehicle Registration Number  | SLD7171E                               |
| <b>Insured/Policyholder</b>  |  |
| Name Of Registered Owner   | RYAN ANG JIA-HAO                       |
| NRIC No  | S8990058A                              |
| Email Address  | NOEMAIL                                |
| Mobile Phone No  | (LOCAL) +65-88580802                   |
| Alternative Phone No   | OFFICE-88580802                        |
| <b>Vehicle Particulars</b>   |  |
| Manufacturer   | KIA                                    |
| Model  | FORTE K3 1.6A                          |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                            |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                                     |
| If No, Please state action to be taken                                       | THIRD PARTY                            |
| Vehicle Category   | PRIVATE CAR                            |
| <b>Insurance Company</b>   |  |
| Name of Insurance Company  | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage   | COMPREHENSIVE                          |
| Fleet Policy   | NO                                     |
| Policy Number  | 5100648632                             |
| Cover Note Number  |  |
| <b>Driver</b>  |  |
| Name of Driver   | RYAN ANG JIA-HAO                       |
| NRIC No  | S8990058A                              |
| Date Of Birth  | 08/02/1989                             |
| Occupation   | INDOOR                                 |
| Date Of Driving Pass   | 24/11/2011                             |
| Driving Experience   | 7 YEARS AND 0 MONTHS                   |
| Gender   | MALE                                   |
| Mobile Number  | (LOCAL) +65-88580802                   |
| Fax Number   |  |
| Contact Number   | OFFICE-88580802                        |
| Email Address  | NOEMAIL                                |

Address BLK 352 ANG MO KIO STREET 32  
#18-129  
Postcode 560352  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - CROSS JUNCTION  
Weather Conditions RAINING  
Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 5  
Passenger 1  
NAME: : SENG SWEE HENG  
GENDER: : MALE  
Passenger 2  
NAME: : PHUA LAY GUAT  
GENDER: : FEMALE  
Passenger 3  
NAME: : PHUA LAY KHIM  
GENDER: : FEMALE  
Passenger 4  
NAME: : DEBBIE SENG MEI LIN  
GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE  
Police Station Address ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-4629999 - FAX NO: 64628933  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT - T/20181216/2099.

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

|                                     |             |
|-------------------------------------|-------------|
| Vehicle Registration Number         | SKX6026E    |
| Vehicle Make/Model/Colour           | MAZDA       |
| Details Of Properties               |             |
| Vehicle Category                    | PRIVATE CAR |
| Name of Driver                      |             |
| NRIC/Passport Number                |             |
| Contact Number                      |             |
| Address                             |             |
| Postcode                            |             |
| Insurance Company Name              |             |
| Nature Of Damage                    |             |
| No. Of Passenger (Including Driver) |             |

**DETAILS OF INJURED PERSON 1**

|   |                  |
|---|------------------|
| Name  | RYAN ANG JIA-HAO |
| Approximate Age                                     |                  |
| Injuries Sustain                                    | BODY             |
| Injured person in which vehicle?                    | SLD7171E         |
| Were seat belts worn?                               | YES              |
| Was this injured conveyed to hospital by ambulance? | NO               |
| Address   |                  |
| Postcode  |                  |

**DETAILS OF INJURED PERSON 2**

|   |                |
|---|----------------|
| Name  | SENG SWEE HENG |
| Approximate Age                                     |                |
| Injuries Sustain                                    | BODY           |
| Injured person in which vehicle?                    | SLD7171E       |
| Were seat belts worn?                               | YES            |
| Was this injured conveyed to hospital by ambulance? | NO             |
| Address   |                |
| Postcode  |                |

**DETAILS OF INJURED PERSON 3**

|   |               |
|---|---------------|
| Name  | PHUA LAY GUAT |
| Approximate Age                                     |               |
| Injuries Sustain                                    | BODY          |
| Injured person in which vehicle?                    | SLD7171E      |
| Were seat belts worn?                               | YES           |
| Was this injured conveyed to hospital by ambulance? | NO            |
| Address   |               |
| Postcode  |               |

**DETAILS OF INJURED PERSON 4**

|   |               |
|---|---------------|
| Name  | PHUA LAY KHIM |
| Approximate Age                                     |               |
| Injuries Sustain                                    | BODY          |
| Injured person in which vehicle?                    | SLD7171E      |
| Were seat belts worn?                               | YES           |
| Was this injured conveyed to hospital by ambulance? | NO            |
| Address   |               |

Postcode

**DETAILS OF INJURED PERSON 5**

Name DEBBIE SENG MEI LIN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SLD7171E

Were seat belts worn? YES

Was this injured conveyed to hospital by  
ambulance? NO

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any intentional misrepresentation or omission of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any dispute may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to allow of the report being made available to persons.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (including the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents, including their lawyers/law firms, which may be/are outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No.:

# Accident Sketch Plan

SKETCH PLAN Along Junction of Road 1 and Road 2, Queen's Road, Prince Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

FOLLOW POLICE REPORT

## DECLARATION

I/we declare the foregoing particulars are true in every respect.

*[Signature]*  
Insured or a Signatory  
Date & Time:

*[Signature]*  
Driver's signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Officer's signature  
Name:  
N/A/IN No.:

Police Report



**SINGAPORE  
POLICE FORCE**



T/201812162099

Police Station Of Origin  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

Report No: T/201812162099

**REPORT OF A TRAFFIC ACCIDENT**

|  |            |   |                              |
|--|------------|---|------------------------------|
| Date/Time Report Made:<br>16/12/2018 19:23 |            | Video Report No   | Station Diary No:<br>106     |
| <b>Informant's Particulars</b>             |            |   |                              |
| Name of Informant:<br>RYAN ANG JIA-HAO     |            | Address:<br>APT BLK 352 ANG MO KIO STREET 32 #18-129 SINGAPORE 560352 |                              |
| ID Type / ID No:<br>NRIC NO / S8990058A    |            | Contact No.:<br>Home/Office: Mobile: 88580802                         |                              |
| Nationality:<br>SINGAPORE CITIZEN          |            | Email:  |                              |
| Sex:<br>Male                               | Age:<br>29 | Date of Birth:<br>08/02/1989  | Type of Informant:<br>Driver |
| Race:<br>Chinese                           |            | Language:<br>Institution / School Name                                |                              |
| Occupation:<br>IT MANAGER                  |            | Driving Licence Information:<br>Class: Date of Expiry:                |                              |

**General Information of the Accident**

|   |                      |                               |  |                                     |
|---|----------------------|-------------------------------|--|-------------------------------------|
| Type of Accident:   | Non-Injury           | Drnk Drive:<br>No             | Date/Time of Accident:<br>16/12/2018 18:40 | Type of Location:<br>X-Junction     |
| Location:<br>Junction of Road 1 and Road 2<br>QUEEN'S ROAD<br>PRINCE ROAD |                      |                               |  |                                     |
| Weather:<br>Drizzling   | Road Surface:<br>Wet | Road Speed Limit:             |  |                                     |
| Traffic Flow:   | Traffic Control:     | Traffic Volume:<br>No Traffic |  |                                     |
| Type of Collision:<br>Between Moving Vehicles - Head To Side              |                      |                               |  | Anyone conveyed by ambulance:<br>No |

**Details of Vehicle Involved**

| Vehicle No. | Type | Make | Model            | Color | Condition | No of Passenger |
|-------------|------|------|------------------|-------|-----------|-----------------|
| SKX6026E    | Car  |      |                  |       |           | 1               |
| SLD7171E    | Car  | KIA  | FORTE K3<br>1.6A | Black |           | 4               |

**Details of Vehicle Insurance**

| Vehicle No. | Insurance Company                          | Insurance No | Effective  | Expiry Date |
|-------------|--|--------------|------------|-------------|
| SLD7171E    | NTUC Income Insurance Co-Operative Limited | 5100648632   | 19/05/2018 | 21/07/2019  |

Police Report



**SINGAPORE  
POLICE FORCE**



T/201812162099

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No: 1800-4629999

2 of 2  
Report No: T/20181216/2099

CONTINUATION OF REPORT

|                                   |                  |  |                                   |
|-----------------------------------|------------------|--|-----------------------------------|
| <b>Details of Person Involved</b> |                  |  |                                   |
| Any Pedestrian Involved: No       |                  |  |                                   |
| No. of Pedestrians Injured: NIL   |                  | Use of Pedestrian Crossing: NA         |                                   |
| <b>Driver</b>                     |                  |  |                                   |
| Name                              | CHAI YONG MING   | ID No                                  | S9133161F                         |
| Related Vehicle                   | SKX6026E (Car)   | Contact No.                            | 96441211                          |
| Hospital/Clinic                   | NIL              | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL              | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL              | Degree of Injury                       | NIL                               |
| <b>Driver</b>                     |                  |  |                                   |
| Name                              | RYAN ANG JIA-HAO | ID No                                  | S8990058A                         |
| Related Vehicle                   | SLD7171E (Car)   | Contact No.                            | 88580802                          |
| Hospital/Clinic                   | NIL              | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL              | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL              | Degree of Injury                       | NIL                               |

**Brief Details.**

On 16/12/2018 at about 1840hrs, I was driving along Queen's Rd towards Empress Rd. As I was driving past the junction of Queen's Rd and Prince Rd when suddenly a black Mazda (SKX6026E) had collided onto the driver side of my vehicle. I made a check on my 4 passengers before exiting the vehicle. The driver and I exchanged particulars and agreed to settle with our insurance. No one was injured. The driver side of my vehicle (SCD7171E) sustained dents and scratches from the impact. The other vehicle sustained damages on the front bumper.

I wish to state that there was a stop line on Prince Rd and I had the right of way. No government property damaged. I am lodging this report for record purposes.



Police Report



SINGAPORE  
POLICE FORCE



T/20181216/2099

Police Station Of Origin  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268914  
Tel No. 1800-4529999

3 of 3

Report No. T/20181216/2099

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 QARISSA BINTE ZAINI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/12/2018 19:23

Officer In Charge Of Case:

TP / GtA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP168

10/04/2018

Condition (ACQSI)

(01)Item (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched  
 (07)Deformed (08)Shuffled (09)Buckled (10)Broken (11)Necessary (12)Missing  
 (13)Torn (14)Unconfirmed (15)Not Working

# MOTOR CAR (RH)

ACTION/AC/

(1)Replace (✓) (2)Repair (X) (3)Check (?)  
 (4)Not Consistent (NC)

Aug 2015

## Right Portion

| NAC  | INC    | Item                              | CON | AC | Qty |
|------|--------|-----------------------------------|-----|----|-----|
| 1316 | 995327 | Frt RH Door                       | BUC | ✓  |     |
| 1317 | 991654 | Frt RH Door Protector             |     |    |     |
| 1318 | 991601 | Frt RH Door Hinge                 |     |    |     |
| 1319 | 991685 | Frt RH Door Wing Mirror           |     |    |     |
| 1320 | 991583 | Frt RH Door Garnish               |     |    |     |
| 1321 | 991639 | Frt RH Door Glass Outer Moulding  |     |    |     |
| 1322 | 991588 | Frt RH Door Glass Inner Moulding  |     |    |     |
| 1323 | 991584 | Frt RH Door Glass Black Sticker   | NEC | ✓  |     |
| 1324 | 991595 | Frt RH Door Glass Regulator       |     |    |     |
| 1325 | 991596 | Frt RH Door Glass Regulator Motor |     |    |     |
| 1326 | 991662 | Frt RH Door Rubber                | NEC | ✓  |     |
| 1327 | 991636 | Frt RH Door Outer Handle          |     |    |     |
| 1328 | 991607 | Frt RH Door Inner Handle          |     |    |     |
| 1329 | 991625 | Frt RH Door Lock w/Key            |     |    |     |
| 1330 | 991624 | Frt RH Door Lock                  |     |    |     |
| 1331 | 991562 | Frt RH Door Central Lock          |     |    |     |
| 1332 | 991675 | Frt RH Door Switch                |     |    |     |
| 1333 | 991617 | Frt RH Door Inner Trim Board      |     |    |     |
| 1334 | 991568 | Frt RH Door Checker               |     |    |     |
| 1335 | 991575 | Frt RH Door Felt                  |     |    |     |
| 1336 | 991688 | Frt RH Door Wire Harness          |     |    |     |
| 1337 | 991683 | Frt RH Door Window Glass Pillar   |     |    |     |
| 1338 | 991640 | Frt RH Door Outer Pillar          |     |    |     |
| 1339 | 991613 | Frt RH Door Inner Pillar          |     |    |     |
| 1340 | 991646 | Frt RH Door Pillar Inner Garnish  |     |    |     |
| 1341 | 990554 | Centre Pillar RH                  |     |    |     |
| 1342 | 990543 | Centre Inner Pillar RH            |     |    |     |
| 1343 | 990518 | Centre Pillar Upper Garnish RH    |     |    |     |
| 1344 | 990565 | Centre Pillar Lower Garnish RH    |     |    |     |
| 1345 | 991670 | Frt RH Door Step Garnish          |     |    |     |
| 1346 | 994058 | Rocker Panel RH                   |     |    |     |
| 1347 | 994049 | Rocker Panel Inner Panel RH       |     |    |     |
| 1348 | 994047 | Rocker Panel Garnish RH           |     |    |     |
| 1349 | 994055 | Rocker Panel Outer Side Skirt RH  |     |    |     |
| 1004 | 991300 | Frt Bumper                        | CUT | ✓  |     |
| 1006 | 991325 | Frt Bumper Bracket                | NEC | ✓  | 6   |
| 1007 | 991462 | Frt Bumper Side Retainer RH       | DB  | ✓  |     |
| 1008 | 991433 | Frt Bumper Reinforcement          |     |    |     |
| 1010 | 991468 | Frt Bumper Sponge                 |     |    |     |
| 1011 | 991427 | Frt Bumper Protector              |     |    |     |
| 1014 | 991301 | Frt Bumper Moulding               |     |    |     |
| 1015 | 991407 | Frt Bumper Lower Spoiler          |     |    |     |
| 1030 | 991821 | Frt RH Headlamp Assy              | CUT | ✓  |     |
| 1032 | 995089 | Frt RH Side Lamp                  | BUC | ✓  |     |
| 1105 | 995071 | Frt RH Fender                     |     |    |     |
| 1107 | 991744 | Frt RH Fender Lamp                |     |    |     |
| 1108 | 991752 | Frt RH Fender Protector           |     |    |     |
|      |        | Frt RH Wheel Rim                  | CUT | ✓  |     |

Vehicle No: SLD 7171 E

| NAC  | INC    | Item                                | CON | AC | Qty |
|------|--------|-------------------------------------|-----|----|-----|
| 1350 | 993201 | Rear RH Door                        | BUC | ✓  |     |
| 1351 | 993284 | Rear RH Door Protector              |     |    |     |
| 1352 | 995307 | Rear RH Door Hinge                  |     |    |     |
| 1353 | 993228 | Rear RH Door Garnish                |     |    |     |
| 1354 | 993278 | Rear RH Door Glass Outer Moulding   |     |    |     |
| 1355 | 993231 | Rear RH Door Glass Inner Moulding   |     |    |     |
| 1356 | 993229 | Rear RH Door Glass Black Sticker    | NEC | ✓  |     |
| 1357 | 993289 | Rear RH Door Glass Regulator        |     |    |     |
| 1358 | 993240 | Rear RH Door Glass Regulator Motor  |     |    |     |
| 1359 | 993294 | Rear RH Door Rubber                 | NEC | ✓  |     |
| 1360 | 993276 | Rear RH Door Outer Handle           |     |    |     |
| 1361 | 993251 | Rear RH Door Inner Handle           |     |    |     |
| 1362 | 993261 | Rear RH Door Lock                   |     |    |     |
| 1363 | 993256 | Rear RH Door Inner Trim Board       |     |    |     |
| 1364 | 993218 | Rear RH Door Checker                |     |    |     |
| 1365 | 993230 | Rear RH Door Glass Channel          |     |    |     |
| 1366 | 993242 | Rear RH Door Glass Triangle Garnish |     |    |     |
| 1367 | 993285 | Rear RH Door 1/4 Glass              |     |    |     |
| 1368 | 993288 | Rear RH Door 1/4 Glass Rubber       |     |    |     |
| 1369 | 993287 | Rear RH Door 1/4 Glass Pillar       |     |    |     |
| 1370 | 993306 | Rear RH Door Step Garnish           |     |    |     |
| 1371 | 993309 | Rear RH Door Switch                 |     |    |     |
| 1371 | 994070 | Roof Top Panel                      |     |    |     |
| 1372 | 994098 | Roof Top Moulding                   |     |    |     |
| 1373 | 994085 | Roof Top Air-bag                    |     |    |     |
| 1374 | 994084 | Roof Top Air-bag Sensor             |     |    |     |
| 1375 | 994083 | Roof Top Air-bag Control Unit       |     |    |     |
| 1376 | 992958 | Rear Bumper                         |     |    |     |
| 1377 | 992976 | Rear Bumper Bracket                 |     |    |     |
| 1378 | 993068 | Rear Bumper Side Retainer           |     |    |     |
| 1379 | 993045 | Rear Bumper Reinforcement           |     |    |     |
| 1380 | 993077 | Rear Bumper Sponge                  |     |    |     |
| 1381 | 993040 | Rear Bumper Protector               |     |    |     |
| 1382 | 993026 | Rear Bumper Moulding                |     |    |     |
| 1383 | 993023 | Rear Bumper Lower Spoiler           |     |    |     |
| 1384 | 995116 | Rear RH Taillamp                    |     |    |     |
| 1385 | 993456 | Rear RH Fender                      |     |    |     |
| 1386 | 993450 | Rear RH Fender Protector            |     |    |     |
| 1387 | 990247 | Sticker                             |     |    |     |

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

(01)Bent (02)Dented (03)Distorted (04)Cracked (05)Cut (06)Scratched  
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary  
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

### ACTION (AC)

(1) Replace (✓)    (2) Repair (X)    (3) Check (?)  
(4) Not Consistent (NC)

Vehicle No: SLD 7111 E

| NAC  | INC    | Item                            | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| 1372 | 995163 | Frt LH Shock Absorber           |     |    |     |
| 1373 | 991944 | Frt LH Shock Absorber Mounting  |     |    |     |
| 1374 | 990632 | Frt LH Coil Spring              |     |    |     |
| 1375 | 995198 | Frt LH Knuckle Arm              |     |    |     |
| 1376 | 995199 | Frt LH Knuckle Arm Bearing      |     |    |     |
| 1377 | 995178 | Frt LH Lower Arm                |     |    |     |
| 1378 | 995169 | Frt LH Upper Arm                |     |    |     |
| 1379 | 995183 | Frt LH Tie Rod                  |     |    |     |
| 1380 | 995143 | Frt LH Drive Shaft              |     |    |     |
| 1381 | 990661 | Frt LH Control Arm              |     |    |     |
| 1382 | 992062 | Frt LH Trailing Arm             |     |    |     |
| 1383 | 991848 | Frt LH Leaf Spring              |     |    |     |
| 1384 | 991293 | Frt LH Brake Disc Rotor         |     |    |     |
| 1385 | 991281 | Frt LH Brake Caliper            |     |    |     |
| 1386 | 991292 | Frt LH Brake Pipe               |     |    |     |
| 1387 | 991287 | Frt LH Brake Hose               |     |    |     |
| 1388 | 991295 | Frt LH Brake Sensor Wire        |     |    |     |
| 1389 | 991989 | Frt Stay Bar Bracket            |     |    |     |
| 1390 | 994455 | Steering Rack & Pinion          |     |    |     |
| 1391 | 994435 | Steering Cross Member           |     |    |     |
| 1392 | 994519 | Frt Sub Frame                   |     |    |     |
| 1393 | 992003 | Frt Sub Frame Mounting          |     |    |     |
| 1394 | 991217 | Frt Anti Roll Bar               |     |    |     |
| 1395 | 991219 | Frt Anti Roll Bar Linkage       |     |    |     |
| 1396 | 990887 | Engine Block                    |     |    |     |
| 1397 | 990890 | Engine Block Gasket             |     |    |     |
| 1398 | 990972 | Engine Oil Sump                 |     |    |     |
| 1399 | 990960 | Engine Oil                      |     |    |     |
| 1400 | 992224 | Gear Box Assy                   |     |    |     |
| 1401 | 992229 | Gear Box Gasket                 |     |    |     |
| 1402 | 992241 | Gear Box Oil Sump               |     |    |     |
| 1403 | 992257 | Gear Oil                        |     |    |     |
| 1410 | 990534 | Centre Exhaust Pipe Assy        |     |    |     |
| 1411 | 990532 | Centre Exhaust Mounting         |     |    |     |
| 1404 | 991134 | Floor Panel                     |     |    |     |
| 1405 | 993719 | Rear LH Shock Absorber          |     |    |     |
| 1406 | 993723 | Rear LH Shock Absorber Mounting |     |    |     |
| 1407 | 993170 | Rear LH Coil Spring             |     |    |     |
| 1408 | 993550 | Rear LH Knuckle Arm             |     |    |     |
| 1409 | 993551 | Rear LH Knuckle Arm Bearing     |     |    |     |
| 1410 | 993597 | Rear LH Lower Arm               |     |    |     |
| 1411 | 993884 | Rear LH Upper Arm               |     |    |     |
| 1412 | 995161 | Rear LH Drive Shaft             |     |    |     |
| 1413 | 995216 | Rear LH Control Arm             |     |    |     |
| 1414 | 993881 | Rear LH Trailing Arm            |     |    |     |
| 1415 | 993573 | Rear LH Leaf Spring             |     |    |     |
| 1416 | 992941 | Rear LH Brake Disc Rotor        |     |    |     |
| 1417 | 992937 | Rear LH Brake Caliper Assy      |     |    |     |
| 1418 | 990434 | Rear LH Brake Pipe              |     |    |     |
| 1419 | 992946 | Rear LH Brake Hose              |     |    |     |
| 1420 | 993819 | Rear Sub Frame                  |     |    |     |
| 1421 | 993820 | Rear Sub Frame Mounting         |     |    |     |
| 1422 | 992813 | Rear Anti Roll Bar              |     |    |     |
| 1423 | 990168 | Rear Anti Roll Bar Linkage      |     |    |     |
| 1424 | 990202 | Axle Beam                       |     |    |     |
| 1425 | 990170 | Rear Axle Panhard Rod           |     |    |     |
| 1426 | 990810 | Differential Assy               |     |    |     |
| 1427 | 992706 | Propeller Shaft                 |     |    |     |

[illegible]

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

Original copy

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |   |               |   |  |  |             |   |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 17 Dec 2018<br><a href="#">Edit Reg</a> |               | 04 Jan 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference | Claim Details  | Documents  | Show All |         |             |              |            |       |
|---|-----------|--|------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |           |  |            |          |         |             |              |            |       |
| Insured: <b>BLUE STAR CONCIERGE PTE LTD</b> , Co. Reg. No.: 201506692D  |           |  |            |          |         |             |              |            |       |
| Main Claimant: <b>RYAN ANG JIA-HAO</b>  |           |  |            |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>SLD7171E</b>   |           | Date of Loss: 16/12/2018 18:00 - :59<br>[28 Months and 24 Days From LTA Reg Date (Man Yr)] |            |          |         |             |              |            |       |
| Claim Type: <b>TP / 3663566642SG</b>  |           | Policy/Cover Note No.: 0999994449 (Comprehensive)  |            |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SKX6026E</b>   |           | Policy No. (Claimant):   |            |          |         |             |              |            |       |
|   |           | Excess:  |            |          |         |             |              |            |       |
| Repairer: <b>Platinum Werkz Pte Ltd (HQ)</b> 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610  |           |  |            |          |         |             |              |            |       |
| Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ]  |           |  |            |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 15/01/2019]                                    |           |  |            |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |           |  |            |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (07/01/2019): Request to upload TP GIA Report</li> </ul>  |           |  |            |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |           |  |            |          |         |             |              |            |       |
| Due Date  | Priority  | Type   | Task Group | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |           |  |            |          |         |             |              |            |       |

## Claim Documents

**\*SLD7171E (3663566642SG)**  
**[SKX6026E]**

**TP**

























**RYAN ANG JIA-HAO**

**Dec 16 2018 6:00PM**

**[BLUE STAR CONCIERGE PTE LTD]**

**Platinum Werkz Pte Ltd**

| <a href="#">Upload Documents</a> |                 | <a href="#">Upload Photos</a>     | <a href="#">Compose New Letter</a> | <a href="#">Upload Video</a> | <a href="#">Upload Audio</a>        | <b>View</b> | <a href="#">View in Browser</a>     |
|----------------------------------|-----------------|-----------------------------------|------------------------------------|------------------------------|-------------------------------------|-------------|-------------------------------------|
| <b>Photos/Images</b>             |                 |                                   |                                    |                              |                                     | 3 per page  | <input checked="" type="checkbox"/> |
| No                               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |                                    | Thumbnail                    | Print                               |             |                                     |
| 1                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 2                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 3                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 4                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 5                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 6                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 7                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 8                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 9                                | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 10                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 11                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 12                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 13                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 14                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 15                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 16                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 17                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 18                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 19                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 20                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 21                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 22                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 23                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 24                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 25                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 26                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 27                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 28                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 29                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 30                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 31                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 32                               | 08/05/19 12:56  | General View                      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 33                               | 08/05/19 12:56  | Photographs of Damaged Parts      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 34                               | 08/05/19 12:56  | Photographs of Damaged Parts      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 35                               | 08/05/19 12:56  | Photographs of Damaged Parts      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 36                               | 08/05/19 12:56  | Photographs of Damaged Parts      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |
| 37                               | 08/05/19 12:56  | Photographs of Damaged Parts      |                                    | Load JPG                     | <input checked="" type="checkbox"/> |             |                                     |

| Photos/Images |                 |   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
| 38            | 08/05/19 12:56  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 08/05/19 12:56  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 08/05/19 12:56  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 08/05/19 12:56  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 08/05/19 12:56  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 08/05/19 12:56  | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 57            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 58            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG   | <input checked="" type="checkbox"/> |
| 59            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG  | <input checked="" type="checkbox"/> |
| 60            | 08/05/19 12:57  | Photo After Spray                         |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation |                 |   | 1 per page   | <input checked="" type="checkbox"/> |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail  | Print                               |
| 1             | 07/01/19 09:07  | OI GIA REPORT                             |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19000242/GCD3E2

Date: 31/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994449

**Claimant Vehicle No :** SLD7171E

**Insured Vehicle No :** SKX6026E

Date of Loss: 16/12/2018

Nature of Claim:

TP

Claim No: 3663566642SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD7171E**

Make &amp; Model: KIA FORTE K3, 1.6 (A)

Engine No: G4FGGH623476

Reg. Date: 22/07/2016 (Man. Year: 2016)

Chassis No: KNAFZ411MH5635304

Colour: Black

Odometer: 48296 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 04/01/2019

Date Inspected: 04/01/2019 Inspected At:

 Platinum Werkz Pte Ltd (HQ)  
 53 Ubi Ave 1 01-25 Paya Ubi Industrial  
 Park  
 Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No.               | Qty | Part No. | Particulars                  | Condition                | Repairer's  | Amount      |
|-------------------|-----|----------|------------------------------|--------------------------|-------------|-------------|
| 1                 | 1   |          | *FRT RH DOOR                 | Buckled                  | 0.00 F      | *- F        |
| 2                 | 1   |          | *FRT RH DOOR BLACK STICKER   | Necessary                | 0.00 F      | *- F        |
| 3                 | 1   |          | *FRT RH DOOR RUBBER          | Necessary                | 0.00 F      | *- F        |
| 4                 | 1   |          | *FRT BUMPER                  | Cut                      | 0.00 F      | *- F        |
| 5                 | 6   |          | *FRT BUMPER CLIPS            | Necessary                | 0.00 F      | *- F        |
| 6                 | 1   |          | *FRT BUMPER SIDE RETAINER RH | Distorted                | 0.00 F      | *- F        |
| 7                 | 1   |          | *FRT RH HEADLAMP ASSY        | Cut                      | 0.00 F      | *- F        |
| 8                 | 1   |          | *FRT RH FENDER               | Buckled                  | 0.00 F      | *- F        |
| 9                 | 1   |          | *FRT RH WHEEL RIM            | Cut                      | 0.00 F      | *- F        |
| 10                | 1   |          | *REAR RH DOOR                | Buckled                  | 0.00 F      | *- F        |
| 11                | 1   |          | *REAR RH DOOR BLACK STICKER  | Necessary                | 0.00 F      | *- F        |
| 12                | 1   |          | *REAR RH DOOR RUBBER         | Necessary                | 0.00 F      | *- F        |
| F=Franchise part. |     |          |                              | <b>Total Parts (S\$)</b> | <b>0.00</b> | <b>0.00</b> |

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >