

ASS. REC. BY:

REF:

053/MSG19000247/Gcd302

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

Meimer

From (Person):

Monica chung

of

MSG

Date/Time:

4/1/19 @ 4:06pm

Estimated Cost:

Bill to:

 OD / TP / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJK 969D

Insured:

SGP 8428E

at Workshop m/s

E.M. Solution

Tel:

6456 0226

of

160 Sin Ming Drive # 03-18/19

Policy No.:

290675917MP

Claim No.:

580793

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/01/2019

CA / REV / REP. / REV 24 HRS

(up)

7/1/2019

H.O.D. Endorsement:

Date/Time:

4:52pm @ 4/1/19

Person Contacted:

Bernard

Vehicle

 IN OUT

Date/Time	Action/Instruction (X) Estimate
	SJK 969D - NA/INC14002427/d2
	SGP 8428E - C03/11G12023596/71gdi
	DOA: 7/2/14
	DOA: 6/1/2012

PRS
XMR

REF: MSIG

04101 /

(-2023)

ASSIGNMENT

From: _____ Date: 07/01/2019

Veh No: SJK 969D Yr Regn: 02 Oct 2008

Estimated Cost: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To inspect Vehicle No: SJK 969D

Make: Honda Crossroad 1799

at Workshop m/s EM Solution

Colour: white A/C: Insured / Std / NI / NA

of 160 Bin Ming Drive # 03-18/19

Sp. Reading: 154647 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: RT / 100 8500

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: Morning

Modi: Nil / S/Rim / STD / R/Rim or

(Policy Condition)

O	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 215/65 R16

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Linglong

Bal. or Market Value: \$30K

Front Rear

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 6 mm R/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: 5 days Res: Yes or No

D.O.A. _____ D.O.I. 07-01-19

Lum Sum: 20 % 3 Val: Yes or No

Survey held at W/S 3:20pm

CA / REV / REP. / 24 HRS (wp)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$5000 - \$6000

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 5

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: -

Survey Fee:

2) _____

Add Fee: : Site Insp (\$)

Transportation:

Report Format: PRQ

Lump Sum / I.B.I: (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

) S + RS. \$

) Photos

) Others

)

TOTAL

120
10
130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2019		04 Jan 2019 16:06 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM KIM SAI, ID: S1245535F, Tel: +6592302345, Email: NOEMAIL		
Main Claimant:	TANTY WAHYUNI BINTE IDRUS, ID: S7500410I		
Vehicle Reg. No.:	SJK969D	Date of Loss:	03/01/2019 09:00 - :59 [123 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580793	Policy/Cover Note No.:	29067591TMP (Third Party Only) Coverage: 24/01/2018 - 23/01/2019
Vehicle Reg. No. (Insured):	SGP8428E	Policy No. (Claimant):	
		Excess:	
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/01/2019]		
Driver/Custodian (Insured):	LIM KIM SAI (61 / Male), NRIC: S1245535F, Tel: +6592302345		
Adj Asg. Remarks:	liab 80% SJE DISAGREE APPOINT LKK. pls contact Mr. Bernard (Tel.: 6456-0226 / 9101-8302)		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	04101
Vehicle Details	
Vehicle No.:	SJK969D
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CROSSROAD 1.8L A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	R18A3011547
Chassis No.:	RT11008500
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,057.00
Original Registration Date:	02 Oct 2008
First Registration Date:	02 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$20,057.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Oct 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$16,140.00
COE Rebate Amount:	\$15,269.00
Total Rebate Amount:	\$15,269.00
Message	
<p>Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.</p>	

The information contained herein is correct as at 08 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/01/2019 16:41
Date Of Accident	03/01/2019 09:10
Exact Location Of Accident	PASIR RIS DRIVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK969D
Insured/Policyholder	
Name Of Registered Owner	TANTY WAHYUNI BINTE IDRUS
NRIC No	S7500410I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93671975
Alternative Phone No	OFFICE-93671975

Vehicle Particulars

Manufacturer	HONDA
Model	CROSSROAD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA409289
Cover Note Number	

Driver

Name of Driver	MOHAMAD KEFLI BIN ARIS
NRIC No	S7402890Z
Date Of Birth	07/02/1974
Occupation	INDOOR
Date Of Driving Pass	27/07/1998
Driving Experience	20 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90994717
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 719 BEDOK RESERVOIR ROAD #08-4662
Postcode	470719
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TANTY GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGP8428E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM KIM SAI
NRIC/Passport Number	S1245535F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 31 @ 11-3574

(A) SJK 969 D

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3/1/19 at about 9:07 AM, I was driving my vehicle - SJK 969 D along PASIR RIS DRIVE 4. I was travelling on the straight road out of a sudden, a vehicle - SGP 8428 E from the left-side of the road turning into opposite lane and collided onto the front of my vehicle left-side portion. My vehicle sustained damages and I am claiming against SGP 8428 E for my damages.

* Repair at other workshop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Carlyold
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: 3/1 @ 113 [Signature]

Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2019		04 Jan 2019 16:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM KIM SAI , ID: S1245535F, Tel: +6592302345, Email: NOEMAIL								
Main Claimant:	TANTY WAHYUNI BINTE IDRUS , ID: S7500410I								
Vehicle Reg. No.:	SJK969D	Date of Loss:	03/01/2019 09:00 - :59 [123 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 580793	Policy/Cover Note No.:	29067591TMP (Third Party Only) Coverage: 24/01/2018 - 23/01/2019						
Vehicle Reg. No. (Insured):	SGP8428E	Policy No. (Claimant):							
		Excess:							
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 05/01/2019]								
Driver/Custodian (Insured):	LIM KIM SAI (61 / Male), NRIC: S1245535F, Tel: +6592302345								
Adj Asg. Remarks:	liab 80% SJE DISAGREE APPOINT LKK. pls contact Mr. Bernard (Tel.: 6456-0226 / 9101-8302)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJK969D (580793)**
[SGP8428E]
TP
TANTY WAHYUNI BINTE IDRUS
Jan 3 2019 9:00AM
[LIM KIM SAI]
E M Solution Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Assessment Reports		1 per page <input type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/01/19 09:18	Accident Statement <small>From:SC - Reg. No: SGP8428E, Claimant: LIM KIM SAI</small>	Load HTM	<input type="checkbox"/>
Photos/Images		3 per page <input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
2	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
3	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
4	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
5	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
6	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
7	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
8	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
9	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
10	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
11	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
12	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
13	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
14	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
15	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
16	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
17	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
18	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
19	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
20	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
21	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
22	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
23	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
24	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
25	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
26	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
27	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
28	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
29	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
30	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
31	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
32	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>
33	08/01/19 13:42	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	08/01/19 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/01/19 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/01/19 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/01/19 13:42	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/01/19 09:18	Liab- 80% From:SC - Reg. No: SGP8428E, Claimant: LIM KIM SAI	 Load PDF	
2	04/01/19 09:18	SJE DISAGREE APPOINT LKK From:SC - Reg. No: SGP8428E, Claimant: LIM KIM SAI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19000247/GCD3E2

Date: 08/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29067591TMP
 Claimant Vehicle No: SJK969D Insured Vehicle No: SGP8428E
 Date of Loss: 03/01/2019 Nature of Claim: TP Claim No: 580793

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK969D**
 Make & Model: HONDA CROSSROAD, 1.8 (A) Engine No: R18A3011547
 Reg. Date: 02/10/2008 (Man. Year: 2008) Chassis No: RT11008500
 Colour: White Odometer: 154647 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
 Front Left Side: Linglong 6 mm Rear Left Side: Linglong 6 mm
 Front Right Side: Linglong 6 mm Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/01/2019
 Date Inspected: 07/01/2019 Inspected At: E M Solution Pte Ltd (HQ)
 160 Sin Ming Drive,, #03-18, Sin Ming
 Autocity
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jan 2019)

Parts: M1-SUV HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK969D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >