

ASS. REC. BY:

REF:

CS/TMI19000254/Nsd3

Special Instruction:

shl/ky

Surveyor

Menmen

ASSIGNMENT (Office)

From (Person): Dillen Senthilan

of

TMI

Date/Time: 4/1/19 @ 5:03pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SHA 8445Y

Insured:

SJP 4687P

at Workshop m/s

Comfort Delgro

Tel:

6214 8300

of

59 Jayang Drive

Policy No: MV000942

Claim No:

M1900086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

04/21/2019

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

5:07pm @ 4/1/19


Person Contacted:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 8445Y - NA/CT116002718/d2 DOA: 12/2/16
	SJP 4687P - NA/TMI19000224/h4 DOA: 4/1/19

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / P / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA 8445Y Yt Regn: 31 JUL 2018
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HYUNDAI SONATA c.c. 1,991
 Colour: YELLOW A/C: Insured / Std / NI / NA
 Sp. Reading: 314,418 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHE41UMBA 814777
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A / Rim or
 Tyre Size: F: 215 / 60 R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or WESTLAKS (R), HANKOOK (F)

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 4/1/19 D.O.I. 4/1/19
 Survey held at CDRE LOYANG
 Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 - Left 6 months. Need to check margin for repair. TMI L/S

18/1/19 FINALIZED LUMP SUM REPAIR \$2000.00 / 4 DAYS
 21/01/19 Confirmed HS - \$2,000/- @ 4 days with Naz
 (\$3,868.02 Red - 66%)

RECEIVED 22 JAN 2019

[Signature]
 21/1/2019

Date/Time, File Pass to? 22/01/19
 1) Typist
 Date/Time, File Return to?
 2)

Days Of Repair: 4
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: 250
 Transportation: S + RS \$1
 Photos
 Others
 TOTAL 260

Report Format :
 Lump Sum / I.B.I: (\$ 2,000/- HS)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2019 15:33 Sendback Est	04 Jan 2019 15:47 S\$5,868.02	04 Jan 2019 17:03 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HO TENG KIT , Co. Reg. No.: S1195873G		
Main Claimant:	CITYCAB PTE LTD (1/3) , Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHA8445Y	Date of Loss:	04/01/2019 08:00 - :59 [89 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1900086	Policy/Cover Note No.:	MV000942 (Comprehensive) Coverage: 26/03/2018 - 25/03/2019
Vehicle Reg. No. (Insured):	SJP4687P	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$4,100.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2839G

Vehicle Details

Vehicle No.: SHA8445Y

Vehicle to be Exported: Yes

Intended Deregistration Date: 10 Jan 2019

Vehicle Make: HYUNDAI

Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour: Yellow

Manufacturing Year: 2011

Engine No.: D4EAA866996

Chassis No.: KMHET41VMBA814777

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,152.00

Original Registration Date: 30 Jul 2011

First Registration Date: 30 Jul 2011

Transfer Count: 0

Actual ARF Paid: \$14,152.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jul 2019

PARF Rebate Amount: \$8,491.00

Intended COE Rebate Details

COE Expiry Date: 29 Jul 2019

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$37,684.00

COE Rebate Amount: \$2,595.00

Total Rebate Amount: \$11,086.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jan 2019

OK

Report ID : ZFICTP32
DATE : 10.01.2019
TIME : 10:59:33

CityCab Pvt Ltd
Vehicle New for Fleet Safety Division
AS AT 31.12.2018

USER ID : C72NEX03
PAGE : 1

Co. Code : CUB
Licence Pl. No : SH9845Y
Old Asset No : 10008525-0
Veh. Model : Hyundai Sonata
Reg. Date : 30.07.2011
Cap. Date : 30.07.2011
Acq. Date : 04.01.2019
Veh. Age : 090

Asset No	SA No	Bal. Dep. Ats	Per. Mth. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap Value/Estimated
			\$	\$		\$	\$	\$	\$	\$	PAPE Refund
10008525	0	000	222.17	0.00	SH9845Y HSN 30.07.2011 BASIC CUST S21830 W A/BROCN	19,996.00	17,329.00	2,666.00	19,995.00	1.00	0.00
10008525	1	000	31.45	0.00	SH9845Y HSN 30.07.2011 EXPORT DUTY	2,830.37	2,452.99	377.38	2,830.37	0.00	0.00
10008525	2	000	62.90	0.00	SH9845Y HSN 30.07.2011 ARF 100% DWS14152	14,152.00	4,906.20	754.80	5,661.00	8,491.00	0.00
10008525	3	000	418.71	0.00	SH9845Y HSN 30.07.2011 COE 80%	37,684.00	32,659.47	5,024.53	37,684.00	0.00	8,491.00
10008525	4	000	0.00	0.00	SH9845Y HSN 30.07.2011 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10008525	5	000	0.00	0.00	SH9845Y HSN 30.07.2011 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10008525	6	000	0.00	0.00	SH9845Y HSN 30.07.2011 PRINTER DIGITAL THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10008525	7	000	0.00	0.00	SH9845Y HSN 30.07.2011 THERMAL DIGITAL F2	0.00	0.00	0.00	0.00	0.00	0.00
10008525	8	000	1.56	0.00	SH9845Y HSN 30.07.2011 VER REG FEE	140.00	121.34	18.66	140.00	0.00	0.00
			736.79	0.00		74,802.37	57,469.00	8,861.37	66,310.37	8,492.00	0.00
COE			418.71	0.00	Vehicle : Without T/M & COE	37,118.37	24,809.53	3,816.84	28,626.37	8,492.00	0.00
Vehicle			318.08	0.00	Vehicle : Without T/M, With COE	76,802.37	57,469.00	8,861.37	66,310.37	8,492.00	0.00
			736.79	0.00	Taximeter	0.00	0.00	0.00	0.00	0.00	0.00

① Cost of taxi = 74,802.37
ARF 65% = 49,198.80
Depreciation = (Cost of taxi - ARF 65%) ÷ 96
= (74,802.37 - 49,198.80) ÷ 96
= 2683.37

② Book Value = (Depreciation X (Remaining months) + ARF 65%)
= (2683.37 X 67) + 49,198.80
= 1,17,799.02

③ Net Value = Book Value - COE Refund Amount
= 1,17,799.02 - 91,086.00
= 26,713.02

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2839G
Vehicle Details	
Vehicle No.:	SHA8445Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Yellow
Manufacturing Year:	2011
Engine No.:	D4EAA866996
Chassis No.:	KMHET41VMBA814777
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,152.00
Original Registration Date:	30 Jul 2011
First Registration Date:	30 Jul 2011
Transfer Count:	0
Actual ARF Paid:	\$14,152.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2019
PARF Rebate Amount:	\$8,491.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$37,684.00
COE Rebate Amount:	\$2,621.00
Total Rebate Amount:	\$11,112.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Jan 2019

OK

Team: CK ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305256726

STOMER

CITYCAB PTE LTD

7010070

MS

STOMER NO.

383 SIN MING DRIVE

RESS

Singapore SINGAPORE 575717

65551188

(O)

(R)

(P)

COUNT CARD NO.

VAR3

REGN NO.:

SHA8445Y

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

DATE/TIME IN

04.01.2019 09:30

YR OF MANU

31.07.2011

TARGET DATE

CHASSIS CODE

KMHET41VMBA814777

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 04.01.2019

NATURE: 3P 04.01.2019

S/NO

LABOR CODE


DESCRIPTION

FRONT


tokio - Rear damage
LKK/



LEFT SIDE



REAR



RIGHT SIDE

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SHA8445Y

LARRY

Vehicle No.:

SHA8445Y

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/01/2019 10:35
Date Of Accident	04/01/2019 08:30
Exact Location Of Accident	DEFU FLYOVER TWDS CITY AFTER TAMPINES RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA8445Y
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	YEO SUAN HIN
NRIC No	S0165961H
Date Of Birth	20/10/1952
Occupation	OUTDOOR
Date Of Driving Pass	30/11/1977
Driving Experience	41 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97407917
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 448 HOUGANG AVENUE 10 #03-535
Postcode	530448
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP4687P
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HO MUI YAO MELVIN
NRIC/Passport Number	S9528197D
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name YEO SUAN HIN

Approximate Age 67

Injuries Sustain PAIN ON NECK AND BACK

Injured person in which vehicle? SHA8445Y

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loke Wei Yiong

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 4/1/19 at about 08:30 hrs, I was driving at above said location with a female pax. Shortly veh in front braked to stopped and I follow suit. A few second later, Veh B came from behind collided onto the rear portion of my taxi. Later on I found Veh C also involved in this chain collision.

I suffered pain on neck & back, will consult doctor later on.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


CITYCAB PTE LTD
CO. REG. NO. 199502839G





Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

45544C SketchPlanForm_V3





ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CITYCAB PTE LTD

Singapore

Claimant Insurer: MS First Capital Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/01/2019
Vehicle Reg. No.:	SHA8445Y	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	YEO SUAN HIN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	31/07/2011
Vehicle Colour:	YELLOW	Gen Condition:	FAIR
Engine No:	D4EAB988089	Chassis No:	KMHET41VMBA814777
Odometer:	314418 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLS REFER TO ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	3,778.02
Miscellaneous Items	10.00
Labour	2,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,868.02
+ GST 7.00% (S\$)	410.76
Nett Amount (S\$)	6,278.78

This claim is handled by: **NG NYUK PHIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
Parts: 143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA8445Y/04/01/2019 15:47	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID	20.00	0.00	*1,349.50 FL X R
2	1		*BOOT LID RUBBER	20.00	0.00	*110.90 FL XSV C
3	1		*BOOT LID LOCK UPPER	20.00	0.00	*132.10 FL XSV C
4	1		*BOOT LID LOCK LOWER	20.00	0.00	*30.30 FL XSV C
5	1		*BOOT LID SONATA PLATE	20.00	0.00	*43.60 FL NE C
6	1		*BOOT LID HYUNDAI PLATE	20.00	0.00	*24.20 FL NE C
7	1		*BOOT LID H EMBLEM	20.00	0.00	*26.10 FL NE C
8	1		*BOOT LID CRDI PLATE	20.00	0.00	*22.70 FL NE C
9	1		*REAR BUMPER	20.00	0.00	*578.40 FL DB
10	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*483.30 FL DB
11	10		*REAR BUMPER CLIP	20.00	0.00	*22.00 FL NE C
12	1		*REAR BUMPER SPONGE	20.00	0.00	*137.40 FL B
13	1		*REAR BUMPER UNDERCOVER	20.00	0.00	*185.80 FL XSV C
14	1		*TAIL LAMP -RH	20.00	0.00	*344.00 FL XSV C
15	1		*REAR PANEL	20.00	0.00	*391.80 FL XSV C
16	1		*REAR PANEL GARNISH	20.00	0.00	*95.80 FL C
17	1		*BOOT LID CITYCAB & TEL NO. STICKERS	0	0.00	*30.00 FS NE
18	1		*REAR FENDER COMFORT STICKER - RH	0	0.00	*30.00 FS NE
19	1		*REVERSE SENSOR	0	0.00	*135.70 FS XSV C
20	1		*REAR BUMPER RUBBER MAT	0	0.00	*50.00 FS NE
21	1		*ADVERTISEMENT - REAR BUMPER	0	0.00	*50.00 FS NE
22	1		*ADVERTISEMENT - BOOT LID	0	0.00	*100.00 FS NE
23	2		*ADVERTISEMENT - REAR FENDERS - RH/LH	0	0.00	*200.00 FS NE

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,573.60
- List Item Discount on L Items (\$\$)	795.58
Total Parts (\$\$)	3,778.02

ComfortDelGro Engineering Pte Ltd/SHA8445Y/04/01/2019 15:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Larry Ng

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer) ✓	10.00

Sub Total (S\$) 10.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400 850.00
2	SPRAY PAINTING	New	400 1,000.00
3	WIRING CHARGE	New	30 50.00
4	TUFF KOTE	New	40 80.00
5	REMOVE/REFIX REVERSE SENSOR	New	20 100.00
Gross Labour Cost (S\$)			2,080.00

Acknowledged by Repairer
Signature:
Date:

ComfortDelGro Engineering Pte Ltd/SHA8445Y/04/01/2019 15:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK
4/1/19 1600

LIS

4 DAYS

- CHECK ITEMS PHOTO

- AFTER REPAIR PHOTO

- Request book value as COE left 6 months.

- Need to check repair margin.

[Signature]
4/1/19

ComfortDelGro Engineering Pte Ltd (Co. Reg. No: 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CITYCAB PTE LTD

Singapore

Claimant Insurer: MS First Capital Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/01/2019
Vehicle Reg. No.:	SHA8445Y	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	YEO SUAN HIN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	31/07/2011
Vehicle Colour:	YELLOW	Gen Condition:	FAIR
Engine No:	D4EAB988089	Chassis No:	KMHET41VMBA814777
Odometer:	314418 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLS REFER TO ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	3,778.02
Miscellaneous Items	10.00
Labour	2,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,868.02
+ GST 7.00% (S\$)	410.76
Nett Amount (S\$)	6,278.78

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2019)
 Parts: 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHA8445Y/04/01/2019 15:47
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID	20.00	0.00	*1,349.50 FLX R
2	1		*BOOT LID RUBBER	20.00	0.00	*110.90 FLX SVL
3	1		*BOOT LID LOCK UPPER	20.00	0.00	*132.10 FLX SVL
4	1		*BOOT LID LOCK LOWER	20.00	0.00	*30.30 FL ? XSVL
5	1		*BOOT LID SONATA PLATE	20.00	0.00	*43.60 FL /NEC
6	1		*BOOT LID HYUNDAI PLATE	20.00	0.00	*24.20 FL /NEC
7	1		*BOOT LID H EMBLEM	20.00	0.00	*26.10 FL /NEC
8	1		*BOOT LID CRDI PLATE	20.00	0.00	*22.70 FL /NEC
9	1		*REAR BUMPER	20.00	0.00	*578.40 FL /DEF
10	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*483.30 FL ? BT
11	10		*REAR BUMPER CLIP	20.00	0.00	*22.00 FL /NEC
12	1		*REAR BUMPER SPONGE	20.00	0.00	*137.40 FL ? BE
13	1		*REAR BUMPER UNDERCOVER	20.00	0.00	*185.80 FL ? XSVL
14	1		*TAIL LAMP -RH	20.00	0.00	*344.00 FL XSVL
15	1		*REAR PANEL	20.00	0.00	*391.80 FL ? XSVL
16	1		*REAR PANEL GARNISH	20.00	0.00	*95.80 FL /CK
17	1		*BOOT LID CITYCAB & TEL NO. STICKERS	0	0.00	*30.00 FS /NEC
18	1		*REAR FENDER COMFORT STICKER - RH	0	0.00	*30.00 FS /NEC
19	1		*REVERSE SENSOR	0	0.00	*135.70 FS ? XSVL
20	1		*REAR BUMPER RUBBER MAT	0	0.00	*50.00 FS /NEC
21	1		*ADVERTISEMENT - REAR BUMPER	0	0.00	*50.00 FS /NEC
22	1		*ADVERTISEMENT - BOOT LID	0	0.00	*100.00 FS /NEC
23	2		*ADVERTISEMENT - REAR FENDERS - RH/LH	0	0.00	*200.00 FS /NEC

*Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 4,573.60
 - List Item Discount on L Items (\$\$) 795.58

Total Parts (\$\$) 3,778.02

ComfortDelGro Engineering Pte Ltd/SHA8445Y/04/01/2019 15:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Larry Ng

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	400 850.00
2	SPRAY PAINTING	New	400 1,000.00
3	WIRING CHARGE	New	30 50.00
4	TUFF KOTE	New	40 80.00
5	REMOVE/REFIX REVERSE SENSOR	New	20 100.00
Gross Labour Cost (S\$)			2,080.00

ComfortDelGro Engineering Pte Ltd/SHA8445Y/04/01/2019 15:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

N42 LKK
4/1/19 1600

LIS

4 DAYS

- CHECK ITEMS PHOTOS
- AFTER REPAIR PHOTOS
- Request book value as COE left 6 months.
- Need to check repair margin.

PARTS 1433.50
LESS 20% 1146.80
460
SLNETT 890
LABOUR 2496.80
TOTAL 1997.44
LESS LIS 20% 2000.00 / 4 DAYS
LIS TOTAL

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305256726

Date : 11. Jan. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :


Attn : NAZ


Vehicle Reg No. : SHA8445Y

Date of Accident: 4. Jan. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SJP4687P
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$2,000.00
3. Estimated normal period for repairs: 4 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : Larry Ng
Tel : 6214 8316
Fax : 6546 8156

Signature : 
Name : NAZ LKK
Date : 18/1/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:






























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jan 2019 15:33 Sendback Est	04 Jan 2019 15:47 S\$5,868.02	04 Jan 2019 17:03 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: HO TENG KIT , Co. Reg. No.: S1195873G									
Main Claimant: CITYCAB PTE LTD (1/3) , Co. Reg. No.: 199502839G									
Vehicle Reg. No.: SHA8445Y		Date of Loss: 04/01/2019 08:00 - :59 [89 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / M1900086		Policy/Cover Note No.: MV000942 (Comprehensive) Coverage: 26/03/2018 - 25/03/2019							
Vehicle Reg. No. (Insured): SJP4687P		Policy No. (Claimant): D-18088937MFSH							
		Excess: S\$4,100.00							
Repairer: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 15/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




SHA8445Y (M1900086)
[SJP4687P]
TP
CITYCAB PTE LTD (1/3)
Jan 4 2019 8:00AM
[HO TENG KIT]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	04/01/19 10:47	Accident Statement	 Load HTM	
2	04/01/19 15:04	Addendum Sheet	 Load TIF	
3	04/01/19 15:05	Accident Statement Addm. #1	 Load HTM	
4	04/01/19 15:47	Repairer Estimates	 Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	04/01/19 16:54	Accident Statement From: SC - Reg. No: SJP4687P, Claimant: HO TENG KIT	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	04/01/19 10:45	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/01/19 15:13	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
12	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
23	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
24	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
25	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
26	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
27	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
28	07/01/19 15:13	General View	Load JPG	<input checked="" type="checkbox"/>
29	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
33	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
34	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
35	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
36	18/01/19 11:55	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	22/01/19 15:12	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	04/01/19 10:46	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	04/01/19 15:04	Amended Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	04/01/19 10:47	Accident Statement	Load HTM	
2	04/01/19 15:04	Addendum Sheet	Load TIF	
3	04/01/19 15:05	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	04/01/19 10:45	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
8	04/01/19 10:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	04/01/19 10:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	04/01/19 10:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	04/01/19 10:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	04/01/19 10:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	04/01/19 10:45	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	04/01/19 10:46	Sketch Plan		Load TIF	
2	04/01/19 15:04	Amended Accident Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19000254/NSD3E2

Date: 22/01/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MV000942

Claimant Vehicle No : SHA8445Y

Insured Vehicle No : SJP4687P

Date of Loss: 04/01/2019

Nature of Claim: TP

Claim No: M1900086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA8445Y

Make & Model: HYUNDAI SONATA, 2.0 CRDI (A)

Engine No: D4EAA866996

Reg. Date: 30/07/2011 (Man. Year: 2011)

Chassis No: KMHET41VMBA814777

Colour: Yellow

Odometer: 314418 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,778.02	1,606.80	2,171.22	57.47
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,080.00	890.00	1,190.00	57.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,868.02	2,506.80	3,361.22	57.28
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	5,868.02	2,000.00	3,868.02	65.92
+ GST 7.00/7.00% (S\$)	410.76	140.00	270.76	65.92
Nett Amount (S\$)	6,278.78	2,140.00	4,138.78	65.92

INSPECTION

Date of Assignment: 04/01/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 04/01/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2019)
Parts: 143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA8445Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,349.50 FL	*- FL
2	1		*BOOT LID RUBBER	Serviceable	110.90 FL	*- FL
3	1		*BOOT LID LOCK UPPER	Serviceable	132.10 FL	*- FL
4	1		*BOOT LID LOCK LOWER	Serviceable	30.30 FL	*- FL
5	1		*BOOT LID SONATA PLATE	Necessary	43.60 FL	*43.60 FL
6	1		*BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
7	1		*BOOT LID H EMBLEM	Necessary	26.10 FL	*26.10 FL
8	1		*BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
9	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	483.30 FL	*483.30 FL
11	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER SPONGE	Broken	137.40 FL	*137.40 FL
13	1		*REAR BUMPER UNDERCOVER	Serviceable	185.80 FL	*- FL
14	1		*TAIL LAMP -RH	Serviceable	344.00 FL	*- FL
15	1		*REAR PANEL	Serviceable	391.80 FL	*- FL
16	1		*REAR PANEL GARNISH	Cracked	95.80 FL	*95.80 FL
17	1		*BOOT LID CITYCAB & TEL NO. STICKERS	Necessary	30.00 FS	*30.00 FS
18	1		*REAR FENDER COMFORT STICKER - RH	Necessary	30.00 FS	*30.00 FS
19	1		*REVERSE SENSOR	Serviceable	135.70 FS	*- FS
20	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
21	1		*ADVERTISEMENT - REAR BUMPER	Necessary	50.00 FS	*50.00 FS
22	1		*ADVERTISEMENT - BOOT LID	Necessary	100.00 FS	*100.00 FS
23	2		*ADVERTISEMENT - REAR FENDERS - RH/LH	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,573.60	1,893.50
- List Item Discount on L Items 20.00/20.00% (S\$)	795.58	286.70
Total Parts (S\$)	3,778.02	1,606.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	850.00	400.00
2	SPRAY PAINTING	New	1,000.00	400.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	80.00	40.00
5	REMOVE/REFIX REVERSE SENSOR	New	100.00	20.00
Gross Labour Cost (S\$)			2,080.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >