

ASS. REC. BY

REF

CS3/CTI19000255/ECD302

Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person)

Chong Soon Sen

of

CTI

Date/Time:

4/1/19 @ 5:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KQ 212SR

Insured:

GBH 5007H

at Workshop m/s

Synergy Motor

Tel:

9109 4728

of

53 ubi Ave 1 # 01-45

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

31/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

5:11pm @ 4/1/19

Person Contacted:

Gary

Vehicle

IN

OUT

Date/Time	Action/Instruction (X) Estimate
	8KQ 212SR - NA/NIG/7008049/r3
	GBH 5007H - X
	Diamond: #1/2019

DUA: 24/4/17

REF: CTL

ASSIGNMENT

From: Date: 04/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 2125R

at Workshop m/s

of

Synergy Motor
53 Ubi Ave 1 #01-45

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9109 4728 - Gary.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X
X	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKQ 2125R Yr Regn: 15/09/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota AHis

c.c 1-6

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading 103133

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053 REH-104516297

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

225/40ZR18

R:

225/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A.

D.O.I.

4/1/19

Survey held at

Synergy Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 57,000

PV - 47,655

NV - 9,345

Repair range 7K-8K 6 days repair

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

190

Transportation

) S + RS. \$

) Photos

) Others

TOTAL

190

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: PRS.

Lump Sum / I.B.I: (\$)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 4 January 2019 5:02 PM
To: Admin-D (LKKAuto)
Subject: FW: [[[URGENT]]] Your Ref: GBH 5007 H Our Ref: TKS/S743-ACC-MISC.18/cc / OUR REF: TBA
Attachments: PRS (2).pdf
Importance: High

Dear LKK,

Kindly assist with PRS.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chong Boon Sen
Sent: Friday, 4 January, 2019 1:06 PM
To: 'Charlotte Choy' <charlotte.choy@ksteoptr.com>
Subject: RE: [[[URGENT]]] Your Ref: GBH 5007 H Our Ref: TKS/S743-ACC-MISC.18/cc / OUR REF: TBA

Without Prejudice
Save as to costs

Dear Charlotte,

We will appoint LKK accordingly.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Charlotte Choy [<mailto:charlotte.choy@ksteoptr.com>]

Sent: Friday, 4 January, 2019 12:39 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: [[[URGENT]]] Your Ref: GBH 5007 H Our Ref: TKS/S743-ACC-MISC.18/cc / OUR REF: TBA

Dear Sir,

We refer to your email of even date.

Our client **do not** agree to your list. We propose to use one of the motor surveyors named herein to conduct the joint pre-repair survey as a single-joint expert:

Name of Surveyor	Name of Company
Sim Wee Cheng	GT Appraiser Service LLP
Chris Ang	CA Appraiser Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of the above motor surveyor as a single-joint expert.

Regards,

Charlotte Choy

Teo Keng Siang LLC

111 North Bridge Road

#29-07/08, Peninsula Plaza

Singapore 179098

Tel: 6333 4222 Ext (63)

Fax: 6333 5688

On Fri, Jan 4, 2019 at 11:57 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Charlotte Choy [mailto:charlotte.choy@ksteoptr.com]
Sent: Friday, 4 January, 2019 11:52 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Fwd: [[[URGENT]]] Your Ref: GBH 5007 H Our Ref: TKS/S743-ACC-MISC.18/cc

Dear Boon Sen,

As spoken, please help me with this PRS urgently.

Thank you!! :))

Regards,
Charlotte Choy
Teo Keng Siang LLC
111 North Bridge Road
#29-07/08, Peninsula Plaza
Singapore 179098
Tel: 6333 4222 Ext (63)
Fax: 6333 5688

----- Forwarded message -----

From: **Charlotte Choy** <charlotte.choy@ksteoptr.com>
Date: Fri, Jan 4, 2019 at 11:16 AM
Subject: [[[URGENT]]] Your Ref: GBH 5007 H Our Ref: TKS/S743-ACC-MISC.18/cc
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

WITHOUT PREJUDICE

Dear Sir,

We refer to our PRS to you on 2nd Jan 2019.

Please let us have your list of surveyors on an urgent basis failing which we will proceed to conduct repair without any further reference to you.

Thank you.

Regards,
Charlotte Choy
Teo Keng Siang LLC
111 North Bridge Road
#29-07/08, Peninsula Plaza
Singapore 179098
Tel: 6333 4222 Ext (63)
Fax: 6333 5688

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

张景祥大律師樓
(律師兼公証及宣誓官)

TEO KENG SIANG LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098. Tel: 6333 4222 Fax: 6333 5676/5688
ROC: 201510228C GST Reg No.: 201510228C Email: KSTEOCO@singnet.com.sg

(FAX – NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKS/S743-ACC-MISC.18/cc
Your Ref : GBH 5007 H
Date : 2nd January 2019

Secretary in charge: Charlotte

Tel : 6333 4222

Fax : 6333 5676/6333 5688

Email: Charlotte.choy@ksteoptr.com

CHINA TAIPING INSURANCE SINGAPORE PTE LTD

105 Cecil street
#19-00, the Octagon
Singapore 069534

Attention: Motor Claims Department

BY PDX# (8178) & BY FAX (6224 7478)

AALLIANZ PTE LTD

7 Gambas Crescent
#06-12, Ark@Gambas
Singapore 757087

BY POST ONLY

NOTIFICATION OF ACCIDENT

ACCIDENT INVOLVING SKQ 2125 R / GBH 5007 H ON 31/12/18 ALONG GAMBAS AVENUE BEFORE SEMBAWANG ROAD JUNCTION

We act for **ONG HONG HENG** in an accident above.

We are instructed by the abovenamed to notify you of a road traffic accident on **31/12/18** at about **13:50 PM ALONG GAMBAS AVENUE BEFORE SEMBAWANG ROAD JUNCTION** involving our client's motor vehicle **SKQ 2125 R** and motor vehicle **GBH 5007 H** driven by you or your authorized driver at the material time. A copy of the GIA/Traffic Police Report is enclosed. Kindly also let us have your GIA/Traffic Police report for our necessary.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SKQ 2125 R** is now at the following workshop: -

Synergy Motor Pte Ltd
53 Ubi Avenue 1
#01-45 Paya Ubi Industrial Estate
Singapore 408934

Please contact Mr Gary (Hp No. 9109 4728).

Yours faithfully



M/S TEO KENG SIANG LLC
c.c. Workshop by Fax: 6392 1319

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

****Survey was conducted by:-**

Name of Surveyor:

Date of Survey:

Time of Survey:

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8390B

Vehicle Details

Vehicle No.:	SKQ2125R
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1ZRY097572
Chassis No.:	MR053REH104516207
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,650.00
Original Registration Date:	15 Sep 2014
First Registration Date:	15 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$13,650.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2024
PARF Rebate Amount:	\$10,237.00

Intended COE Rebate Details

COE Expiry Date:	14 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,710.00
COE Rebate Amount:	\$37,418.00
Total Rebate Amount:	\$47,655.00

The information contained herein is correct as at 04 Jan 2019

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

**Post an Advertisement**

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes-Benz CLA-Class CLA180 Shooting Brake.



Excellent Condition With Zero Accident. Best Looking In The Market.

Direct Owner StarAd

**PRIME MOTOR & LEASING**

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.



Browse by Category ▼

9 vehicles






Toyota Corolla

Sort by Date Posted ▼

20 results/page

Advanced Search



	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota	Corolla	Any	Any	2014	Any	Any	Any	Available
	Toyota	Corolla Altis 1.6A Elegance	\$58,800	\$8,710 /yr	23-Dec-2014	1,598 cc	70,160 km	Sedan	Available
85% Bank Loan Available With Fast Approval And Low-Interest Rates For A Limited Time, Well Maintained By Single Owner In Pristine Condition, Full Service History. Genuine Low Mileage, Flawless Paintwo...									
Tradeit.Com Pte Ltd									
Posted: 04-Jan-2019 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A Elegance	\$61,800	\$9,340 /yr	13-Nov-2014	1,598 cc	45,000 km	Sedan	Available
A Car Which Need No Introduction! 1 Owner! Low Mileage! Low Fuel Consumption! Flexi Loan! High Approval Rate! Call The Assign Sales Person To Find Out More!									
AL Autocar Pte Ltd									
Posted: 03-Jan-2019 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A Elegance	\$61,900	\$9,260 /yr	04-Dec-2014	1,598 cc	40,100 km	Sedan	Available
Elegant Silver, Elegance Model With Fitted In Navigation System And Reverse Camera, Serviced By Agent, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In Hou...									
Prime Motor & Leasing									
Posted: 03-Jan-2019 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Axio 1.5A X	\$49,800	\$8,260 /yr	26-Sep-2014	1,496 cc	60,000 km	Sedan	Available
Graded B by STRA									
Up To 90% Loan, Flexible Repayment With In House Financing, Our Vehicle Inspected By Professional Team For Highest Quality, Owning A Car Is So Much Easier With Us, View To Believe, Call Us Now!									
Universe Motoring									
Posted: 31-Dec-2018 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Complete Bodykit								
Corolla Altis Full Body 5 pcs kits Include Front Lip, 2 side skirt, rear skirting and Spoiler (FG)									
More info about this product									

Compare

Toyota Corolla	Altis 1.6A	\$55,500	\$9,050 /yr	20-May-2014	1,598 cc	90,000 km	Sedan	Availabl
100% Accident Free, No Repair Needed, Maintained By Agent And Still Under Borneo Warranty, Nice Interior/Exterior Condition, View Or Test Drive To Believe.								



Posted: 27-Dec-2018 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$58,800** **\$9,050 /yr** **02-Oct-2014** **1,598 cc** **84,083 km** **Sedan** **Available**

Single Owner Unit! Selling Just Above Paper And Body Value! Worthy Buy, Well Maintained And Low On Fuel Consumption. Spacious For Passengers And Ample Boot Space! High Loan And Trade In Available! Cal...

Mayfair Motoring

PREMIUM

Posted: 27-Dec-2018 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance **\$57,800** **\$8,900 /yr** **25-Sep-2014** **1,598 cc** **59,000 km** **Sedan** **Available**

High Spec Elegance Model! Still Under Agent Warranty. Driven By A Meticulous Lady Owner. 100% Accident Free. Original Paint. Fully Maintained And Serviced By Borneo Motors With Records. No Expenses Sp...

PREMIUM

Posted: 18-Dec-2018 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$62,800** **\$9,360 /yr** **18-Dec-2014** **1,598 cc** **62,800 km** **Sedan** **Available**

New Road Tax, Vehicle Just Serviced, Brand New Battery, New Paintwork, No Scratches Or Dents, Beautiful Condition, Both Front & Rear Installed With Blackvue Camera, Accident Free, One Owner, Smooth Ru...

DIRECT OWN

Posted: 16-Dec-2018 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance **\$60,800** **\$9,180 /yr** **11-Nov-2014** **1,598 cc** **52,000 km** **Sedan** **Available**

100% Accident-Free, Extremely Well Maintained By Previous Owner, Smooth Running Engine And Gearbox, Spacious Boot And Fuel Efficient Car, All Tyres In Good Condition, Drive With Peace Of Mind, Price N...

DIRECT OWN

Posted: 08-Dec-2018 Tags: 2014 Toyota Corolla, 2014 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates, insurance. Find buy used Toyota Corolla, Toyota Corolla Singapore, used Toyota Corolla Singapore, used Toyota Corolla, used vehicles Singapore or even buy used Toyota Corolla Singapore have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our p sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2019 sgCarMart. All rights reserved.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 13:19
Date Of Accident	31/12/2018 13:50
Exact Location Of Accident	ALONG GAMBAS AVE BEFORE SEMBAWANG ROAD JUNCT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ2125R
Insured/Policyholder	
Name Of Registered Owner	ONG HONG HENG
NRIC No	S1638390B
Email Address	DINESH@STORYTELLER.SG
Mobile Phone No	(LOCAL) +65-85334335
Alternative Phone No	OFFICE-85334335

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 L CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100385712-04
Cover Note Number	

Driver

Name of Driver	DINESH KRISHNAN NAIR
NRIC No	S8928939D
Date Of Birth	12/08/1989
Occupation	INDOOR
Date Of Driving Pass	09/05/2013
Driving Experience	5 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97520012
Fax Number	
Contact Number	
Email Address	DINESH@STORYTELLER.SG

Address	BLK 755 WOODLANDS AVENUE 4 #07-309
Postcode	730755
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE CAR CARE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TAKE FROM DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5007H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GANESAN SANTHOSHKUMAR
NRIC/Passport Number	G2390239M
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

	<p>Vehicle</p> <p>A - SKQ 2125 R</p> <p>B - GBH 5007 H</p> <p>Legend</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> Vehicle </div> <div style="text-align: center;"> Motorcycle </div> </div>
--	---

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, Pooresh Krishnan Nair, 589289390, was driving along the first lane along Gambus Ave towards Woodlands when traffic in front of me had started to brake due to road works on the first lane. As I came to a stop, I was hit from the back by vehicle, GBH 5007 H.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

Vehicle Number: **S8928939D**

Name: **DINESH KRISHNAN NAIR**

Birth Date: **12 Aug 1989**
Valid Date: **09 May 2013**

002178673J



UBLIC OF SINGAPORE
IDENTITY CARD NO. **S8928939D**

Name: **DINESH KRISHNAN NAIR**

Race: **INDIAN**
Date of birth: **12-08-1989**
Country of birth: **SINGAPORE**

Sex: **M**

S8928939D



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE: **09 May 2013**

Class 3 Motor Cars ≤ 3000kg with ≤ 7 passengers, exclusive of the driver; and other motor vehicles ≤ 2500kg

NP 428A

Licence No: **S8928939D**

35

INIC No: **S8928939D**

Date of issue: **10-08-2004**

Address: **APT BLK 755 WOODLAND AVENUE 4
#07-309
SINGAPORE**



Accident Photo



Accident Photo



Accident Photo



TOYOTA MOTOR CORPORATION
MODEL ZRE171R-GEXGKZ
ENGINE 1ZR-FE
FRAME No. MR053REH104516207 1598 mL
COLOR 1D4 FB01 Z35
TRIM PLANT GVM(kg)
BUILT K313 -09A AUG 14
BUILT BY: TOYOTA MOTOR THAILAND CO., LTD. MADE IN THAILAND

Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2019 17:34		07 Jan 2019 17:01 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case









































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ONG HONG HENG , ID: S1638390B								
Vehicle Reg. No.:	SKQ2125R	Date of Loss:	31/12/2018 13:00 - :59 [51 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	GBH5007R	Policy No. (Claimant):	2100385712-04						
		Excess:	S\$0.00						
Repairer:	Synergy Motor Pte Ltd (HQ) 53 UBI AVENUE 1, #01-45 PAYA UBI INDUSTRIAL ESTATE, 408934 Ubi - Tel: 81284368								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 16/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ2125R
[GBH5007R]
TP
ONG HONG HENG
Dec 31 2018 1:00PM
[-]
Synergy Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print					
1	02/01/19 13:23	Accident Statement		1	Load HTM					
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print					
1	02/01/19 13:23	Accident Photo [Linked Accident Report Documents]		1	Load JPG					
2	02/01/19 13:23	Accident Photo [Linked Accident Report Documents]		1	Load JPG					
3	02/01/19 13:23	Accident Photo [Linked Accident Report Documents]		1	Load JPG					
4	02/01/19 13:23	Accident Photo [Linked Accident Report Documents]		1	Load JPG					
5	02/01/19 13:23	Accident Photo [Linked Accident Report Documents]		1	Load JPG					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	08/01/19 13:49	General View		1	Load JPG					
2	08/01/19 13:49	General View		1	Load JPG					
3	08/01/19 13:49	General View		1	Load JPG					
4	08/01/19 13:49	General View		1	Load JPG					
5	08/01/19 13:49	General View		1	Load JPG					
6	08/01/19 13:49	General View		1	Load JPG					
7	08/01/19 13:49	General View		1	Load JPG					
8	08/01/19 13:49	General View		1	Load JPG					
9	08/01/19 13:49	General View		1	Load JPG					
10	08/01/19 13:49	General View		1	Load JPG					
11	08/01/19 13:49	General View		1	Load JPG					
12	08/01/19 13:49	General View		1	Load JPG					
13	08/01/19 13:49	General View		1	Load JPG					
14	08/01/19 13:49	General View		1	Load JPG					
15	08/01/19 13:49	General View		1	Load JPG					
16	08/01/19 13:49	General View		1	Load JPG					
17	08/01/19 13:49	General View		1	Load JPG					
18	08/01/19 13:49	General View		1	Load JPG					
19	08/01/19 13:49	General View		1	Load JPG					
20	08/01/19 13:49	General View		1	Load JPG					
21	08/01/19 13:49	General View		1	Load JPG					
22	08/01/19 13:49	General View		1	Load JPG					
23	08/01/19 13:49	General View		1	Load JPG					
24	08/01/19 13:49	General View		1	Load JPG					
25	08/01/19 13:49	General View		1	Load JPG					
26	08/01/19 13:49	General View		1	Load JPG					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
27	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/01/19 13:49	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
77	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	08/01/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 13:23	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 13:23	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	02/01/19 13:23	DRIVER IC/DL [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/01/19 17:01	PRS CONTACT	 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 13:23	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 13:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 13:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	02/01/19 13:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	02/01/19 13:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	02/01/19 13:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 13:23	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 13:23	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	02/01/19 13:23	DRIVER IC/DL	 Load TIF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19000255/ECD3E2

Date: 23/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SKQ2125R

Insured Vehicle No : GBH5007R

Date of Loss: 31/12/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ2125R

Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A)

Engine No: 1ZRY097572

Reg. Date: 15/09/2014 (Man. Year: 2014)

Chassis No: MR053REH104516207

Colour: Silver

Odometer: 103133 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/01/2019

Date Inspected: 04/01/2019 Inspected At:

Synergy Motor Pte Ltd (HQ)
53 UBI AVENUE 1, #01-45 PAYA UBI
INDUSTRIAL ESTATE
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ2125R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >