

Case Details

Case Reference Number : TAX/12/18/2132
Type of Repair : Accident Repair
Vehicle Registration Number : SHB1856K

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-5178-ID
Assigned By : Claiming Case Owner Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 30/12/2018 11:00 AM
Vehicle Age(In Months) : 53

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95 <i>de</i>	Replace ▾
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08 <i>wh</i>	Replace ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00 <i>re</i>	Replace ▾
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0 ?	Check ▾
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0 ?	Check ▾
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0 ?	Check ▾
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0 X	Not Givt ▾
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00 <i>rw</i>	Replace ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0 ?	Check ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0 ?	Check ▾
Total Spare Part Cost									2,003.84		Surveyor Total	881.86	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									1,603.07		Final Sur Total	705.49	

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give
Total Spare Part Cost									2,003.84		Surveyor Total	881.86	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									1,603.07		Final Sur Total	705.49	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	126.00	0	request tow receipt
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
4	TO REPLACE SUNDRY PARTS	100.00	20	
Total:		486.00	80.00	

S.No. Job Scope

SMRT
Recommendation(\$)

Surveyor Adjustment(\$)

Remarks

5 TO WASH AND VACUUM

60.00

0

Total:

486.00

80.00

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,603.07	705.49
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	486.00	80.00
Overall Total	2,985.07	1,185.49
Lump Sum Repair Option	☒	☒
Lump Sum Total	3,000.00	1,200.00
Surveyor Approved Amount		1,200.00
No of Repair Days*	3	2
Remarks	-	Resurvey after repair
Surveyor Name		Taufikh
Signature		
Survey Date	03/01/2019	

Save

Clear

Taufikh 97445749
-wp-
3/1/19 @ 440pm
Surrel Muntoh

02 days Resurvey after repair

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: