

INS. CASE OWNER:

CC 4 / ASM 1900 0284 / 7.0034

LKK:

IDAC:

91350

Surveyor:

MTH

DOI:

ASSIGNMENT

16/1/19

Date / Time:

4/1/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJS 1035 A

Claim No.:

SJM 0190B

Name of Insured:

ANNEE III RICHARD FRANCIS

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

2017/8

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLX 228S



INSRS:

WSP:

Tel:

Liability:

RMKS:

CW



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

9/1/19

Anne

SLX 228S. X ; SJS 1035A. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

SJM 0190B

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: 02/01/19

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost: PIP

SS\$ 2,050.00

(3 days)

Reduction:

67 %

Email

Call

FINAL SETTLEMENT

Date/Time: 14.06.19

Confirm with: Anne

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

SS\$ 2,204.20

01.711 PARKED TP.

Loss of Rental (LOR): 01/01/19

SS\$ 1,022.30

(6 days)

x 9160

Loss of Use (LOU):

SS\$ -

(\$ x days)

Loss of Income (LOI):

SS\$ -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

LOR + LOI

[Tick only one]

GIA/LTA Search

SS\$ -

Medical:

SS\$ -

Disbursement:

SS\$ -

(e.g. Tow/ Independent)

Legal Cost

SS\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9380

Total:

SS\$ 3,226.40

Global Sum SS:

FINAL PAYMENT

Date/Time: 14-06-19

Confirm with: Anne

Email

Call

Payee 1:

SS\$ 3,226.40

Name 1:

OUIE + CHIEFAGE INDIANAS PIR ID

Payee 2: (Strike if N.A.)

SS\$ -

Name 2:

Payee 3: (Strike if N.A.)

SS\$ -

Name 3:



Mercedes-Benz

LKK Survey

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400357W
GST Reg No. MR-E500111-X

ESTIMATE FOR SLX228S

Ling Kwee Lee

60 Elias Road
#14-01
Singapore 519938

Mobile: 96600400

Vehicle & Document Information

WIP No 29624
Reg No/Reg Date SLX228S / 12/02/2018
Date In/Mileage / 0
Chassis No WDD2130422A339550
Engine No 27492031237670
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
Colour/Trim 029 988 Diamond Sil/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	03/01/2019/ 18:51	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNUN								
POLICY NO/ACC DATE : 1800012558 // 22/12/2018								
DRIVE IN/EXCESS : 03/01/2019 // TP VEH NO SJS1035A AXA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								960, 1200.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.								
A BPIRES								600, 750.00
RESPRAY FRONT BUMPER								
A BPILAB							0.10	✓ 380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.								✓ 120.00
A BPILAB								✓ 120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT, NETT								
M	RIGHT HEADLAMP UNIT		1.00	3352.04	00.00			✓ 3352.04
M	RIGHT FRONT INNER DISTANCE SENSOR		1.00	177.22	00.00			✓ 177.22
M	RIGHT FRONT OUTER DISTANCE SENSOR		1.00	177.22	00.00			✓ 177.22

Tanjin 97495749
- WP
16/1/19 @ 1535
Ready after repair
03 days
sure! Thanks. wu

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chunhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary items must be resurveyed and
is subject to final approval from Insurance Company

Approved by Repairer

Date:

Nett 6,156.48
7% GST on 6156.48 430.95
Total Payable 6,587.43

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



MANDATE IA (S9M0190B / SLX 228S)

Type

🔗 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$2,204.20 (w/GST) Loss of Rental: \$1,027.20 (6days x \$160) (w/GST) Total: \$3,231.40 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (07/05/2019)

Reply



Re:MANDATE IA (S9M0190B / SLX 228S)

Type

🔔 Question

Message

PLS PROCEED AS FOLLOWS: Repair Cost : \$2,204.20 (w/GST) Loss of Rental: \$642 (5days)(w/GST) Total:
\$2,846.20

Reply



RE: Re:MANDATE IA (S9M0190B / SLX 228S)

Type

🔍 Question

Message

Hi Sir, Third party disagreed with our offer on the LOR. Kindly refer to third party email dated 15/05/2019.
Kindly advise or approval on the LOR @ \$1,027.20. Thank you (14/06/2019)

Reply



Re:RE: Re:MANDATE IA (S9M0190B / SLX 228S)

Type

🔍 Question

Message

PLS PROCEED


Reply

Service Request Details

Claim

S9M0190B

Reference

None 

Loss Date

22 December 2018

Request Date

4 January 2019

Due Date

11 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

04012019 @ 1:37 pm

Yike veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLX2285

Make

TPVD MERCEDES BENZ

Service Address

...

Primary Contact/Insured

AMES III RICHARD FRANCIS
4 HACIENDA GROVE, #03-02, 457910, Singapore

ADMIN@JINSHI.COM.SG

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>
Sent: Thursday, 3 January, 2019 7:08 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Accident involving motor vehicle nos. SLX 228 S & SJS 1035 // Propose for Direct Settlement
Attachments: img-103185339-0001.pdf
Categories: Shekhar

To: AXA
Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. SLX 228 S & SJS 1035 A along Orchard road Takashimaya Shopping Centre level 6, Accident date: 22/12/2018

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SLX 228 S), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SJS 1035 A) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at chanhoe.yik@cyclecarriage.com.sg

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Our ref: SLX2289
 Your ref: SSS1035A

Date: - 2 MAY 2019

To: AXA INSURANCE P/Luxx

Singapore _____

Attn: Motor Claims Department

Re: Accident Involving Motor Vehicle Nos. SLX2289 & SSS1035A
 At/Along Ngee Ann City 1001 B On 20/12/18 @ 1230
carpark

I am the owner of vehicle no. SLX2289 that was involved in an accident with your insured vehicle no. SSS1035A of the above accident.

As the accident was caused by your insured negligent/inconsiderate driving, thus I am claiming from you for the following: -

1. Cost of Repairs / Excess	\$ <u>2204.20</u>
2. Loss of Use / Rental (<u>6</u> days @ \$ <u>171.20</u> per day)	\$ <u>1027.20</u>
3. LTA/GIA Search Fee	\$ <u> </u>
4. GIA Report Fee	\$ <u> </u>
5. Others	\$ <u> </u>
Total:	\$ <u>3231.40</u>

I hereby give you fourteen (14) days to comply with the above, failing which, I shall instruct my solicitor to commence legal action against you. If you have any queries, please contact the representative of **CYCLE & CARRIAGE INDUSTRIES PTE LTD** at Telephone No: **67714353 (Mr Yik Chan Hoe) / 67714304 (Ms Amanda Ang)**.

I hereby give full authority to CYCLE & CARRIAGE INDUSTRIES PTE LTD and their representative to negotiate/comprise settlement of the above claim on my behalf.

Your co-operation and immediate attention to the above is greatly appreciated. I hereby look forward to hearing from you soon.

Yours faithfully

Name & Signature 

Address: C/o. 188 Pandan Loop Singapore 128378

Cc: Mr Yik Chan Hoe/ Ms Amanda Ang

E-mail: chanhoe.yik@cyclecarriage.com.sg / amanda.ang@cyclecarriage.com.sg

Fax No. 67795383

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 7 May 2019 6:07 PM
To: rickames@gmail.com
Subject: ACCIDENT INVOLVING SJS 1035A AND SLX 228S ALONG CARPARK TAKASHIMAYA ON 22/12/2018

07 MAY 2019

AMES III RICHARD FRANCIS

Dear Sir/ Mdm

OUR REF : CC4/ASM19000284/T1ea3

YOUR REF : SJS 1035A

ACCIDENT INVOLVING SJS 1035A AND SLX 228S ALONG CARPARK TAKASHIMAYA ON 22/12/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s CYCLE & CARRIAGE INDUSTRIES PTE LTD acting on behalf of the owner of SLX 228S against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had hit Third Party parked vehicle SLX 228S. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher

Case Handler

DID: 6841 6051

FAX: 6741 4108

Email: ashersng@lkkauto.com

c.c. *AXA Insurance Pte Ltd (AXA)*

(Motor Claims Dept)

LETTER OF AUTHORIZATION

To: AXA INSURANCE PTE LTD

Singapore _____

Attn.: Motor Claims Department

Dear Sir / Mdm,


MOTOR ACCIDENT INVOLVING 8LX2285 (OWNER'S
VEHICLE NO.) AND 3591035A (3RD PARTY'S VEHICLE NO.)
ON 22/12/18 (DATE) AT 1230 (TIME)
AT/ALONG Ngee Ann City Level 6 Carpark (ROAD)

I am the registered owner of 8LX2285 (Vehicle No.).

I hereby authorise CYCLE & CARRIAGE INDUSTRIES PTE LIMITED and its agents or any person(s) authorised by Cycle & Carriage Industries Pte Limited to do all or any of the following:-

- Submit, resolve and make any claims which I may have against the 3rd party insurers; and/or
- Execute and sign discharge voucher, indemnity forms and all necessary documents in connection with and arising from the above claim.

All payment towards settlement of my claim should be made in favour of CYCLE & CARRIAGE INDUSTRIES PTE LIMITED.



Registered Owner's Signature
(Company stamp & authorized signature if it is a company-registered vehicle)

Name : Ung Kwee Lee
NRIC No. : S1568854 H
Date : 16/12/2019



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJS 1035A	(Insd veh)	Model: MERCEDES BENZ E200
	SLX 228S	(TP veh)	
Date of Accident/ Time:	22/12/2018 / 12:30		

Repair Estimate	: \$	6,584.43	
Final Repair Cost	: \$	2,204.20	
Loss of Use	: \$	-	days at \$ per day
Rental (if any)	: \$	1,027.20	6 days at \$160.00 per day
LTA / GIA Search Fee	: \$	-	
Others:	: \$	-	
Final Settlement Sum	: \$	3,231.40	
Payee Name: CYCLE & CARRIAGE INDUSTRIES PTE LTD			
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:		Agreed Liability: _____ (%)
B)	For GIA Registered Workshop:		BOLA Applicable: Yes/No BOLA Scenario No: 23
	BOLA Liability: 100 (%)		Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:


- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.


Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative: 
 Name of Representative: **Kerlyn Ong Kai Li**
 Date: 18-6-19 DID: 6771 4420 HP: 9186 5113
 Email: kerlyn.ong@cyclecarriage.com.sg
 Cycle & Carriage Industries Pte Ltd
 Customer Service Centre - Pandan Loop

Signature of Witness / Workshop stamp: 
 Name of Witness: **AMANDA ANG**
 Date: 18-6-19 OFFICER - ADMIN
 BODY CARE & REPAIR CENTER
 DID: 6771 4304
 FAX: 6779 5383
 EMAIL: amanda.ang@cyclecarriage.com.sg

Signature of AXA's surveyor/representative: 
 Name of AXA's surveyor / Representative:
 Date: 18/6/2019



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
LING KWEE LEE	Cust No/Name WCV34130/LING KWEE LEE
C/O AXA INSURANCE PTE LTD	Reg No/Reg Date SLX2285 / 12/02/2018
MOTOR CLAIM DEPARTMENT	Date In/Mileage 16/01/2019/ 32487
B SHENTON WAY #24-01	Chassis No WDD2130422A339550
SINGAPORE 068811	Engine No 27492031237670
Contact No 63387288	Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE
	Colour/Trim 029 988 Diamond Sil/ 042 201 Black



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CSI00001	Cash	02/04/2019/ 18:15	YK	395 / Yik Chan Hoe	29624	28152432

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
M BPNSUN			F.O.C.
POLICY NO/ACC DATE : 1800012558 // 22/12/2018			
DRIVE IN/EXCESS : 03/01/2019 // TP VEH NO SJS1035A AXA			
DATE IN/DATE SURVEY: 16/01/2019 @ 1535 // TAUFIKH LKK			
BY/AUTHORIZED ON : DIRECT SETTLEMENT // ASHER LKK			
A BPILAB			960.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.			
A BPIRES			600.00
RESPRAY FRONT BUMPER			
A BPILAB		0.10	380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			
A BPILAB			120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT			

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Parts	0.00	Nett	2,060.00
Labour	2,060.00	7% GST on	2060.00
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	2,204.20
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	0.00	Total Due	2,204.20
Total(w/o GST)	2,060.00		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

CHAN'S & SONS ENTERPRISE

363 Sembawang Road
Singapore 758379
Tel: 67532536 Fax: 67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

TAX INVOICE

LING KWEE LEE

INVOICE : AR1901-0289
DATE : 23/01/2019
TERMS : C.O.D
STAFF ID : ELAINE
AGREEMENT NO. : HA201901-0156

ATTN : ACCOUNTS PAYABLE

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

Vehicle Reg No : SMD8133Y
Make / Model : SUBARU XV 2.0 AUTO
Rental Dates : Rental Billing From 16/01/2019 To 22/01/2019
Period : 6 days
Rental Rate : S\$ 171.20 Per Day (Including GST)
Reference No : SLX228S

960.00

AMOUNT : S\$
ONE THOUSAND TWENTY-SEVEN DOLLARS AND
CENT TWENTY ONLY

NON-TAXABLE VALUE : 0.00
TAXABLE VALUE : 960.00
GST 7% : 67.20

TOTAL S\$: 1,027.20

Please make your cheques payable to : **CHAN'S & SONS ENTERPRISE**



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	



THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJS 1035A (Insd veh)	Model:	MERCEDES BENZ E200
	SLX 228S (TP veh)		
Date of Accident:	22/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,587.43
Final Repair Cost	:	\$	2,204.20
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,027.20 6 days
LTA / GIA Search Fee	:	\$	

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	3,231.40

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 23
 BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	CYCLE & CARRIAGE INDUSTRIES PTE LIMITED	:	\$ 3,231.40

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

01/07/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19000284/T1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date : 01-07-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 1035A	Veh. Inspected	SLX 228S	
Policy No.	GA160433/1	Coverage (\$)	0.00	
Claim No.	S9M0190B	Excess (\$)	0.00	
Assign From		Assign Date	04/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2130422A339550	Colour	SILVER	
Odometer	27427	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	PIRELLI	6 mm	
L/H Front Tyre	245/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2018	Inspection Date	16/01/2019	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 228S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RIGHT HEADLAMP UNIT (SN) (CONSISTENT)	NOT NECESSARY	3,352.04	-
1	RIGHT FRONT INNER DISTANCE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	177.22	-
1	RIGHT FRONT OUTER DISTANCE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	177.22	-
			3,706.48	-
LABOUR				
	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.		1,200.00	960.00
	RESPRAY FRONT BUMPER.		750.00	600.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS,RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.		120.00	120.00
			2,450.00	2,060.00
GRAND TOTAL			6,156.48	2,060.00
RECOMMENDED COST OF REPAIRS				2,060.00

Report Ref.No. CC4/ASM19000284/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9403103B
Reference	CC4/ASM1900284/T1ea3q2
Loss Date	22 December 2018
Report Date	4 Jan 2019 9:30:00 AM
Request Date	4 January 2019
Due Date	

Next Step

Wait for Approve Invoice

Add Photos

Actions

Vehicle Information	
Incident Vehicle Registration #	SLX2285
Make	TPVD MERCEDES BENZ
Model	E200
Service Address	
...	

Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Primary Contact/Insured	
AMES IB RICHARD FRANCIS	
4 HACIENDA GROVE, #03-02, 457910, Singapore	
ADMIN@JINSHI.COM.SG	

Claim Handler	
CHAN Kian Chuan	
656804269	
kianchuan.chan@axa.com.sg	

Additional Instructions

Messages | Invoices | History | Documents | Assessment | Metrics | Notes

Document Type
Document Subtype

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Accident Statement Reports & Statement

LKXInvoice1 (3).pdf

Invoice

Surveyor/ Assessor
expense

5 July 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
WORKSHOP INVOICE.pdf	Invoice	Regular	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
LETTER TO OL.pdf	Letters and Correspondence	Policy Holders / Issued	LKK AUTO CONSULTANTS PTE LTD (TP)	5 July 2019
EMAIL FROM WSP DTD 150519.pdf	Letters and Correspondence	Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2019
Immediate Advice with Mandate.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2019
LTA PAIRF COE Rebate Details.pdf	Reports & Statement	Market Value Report	LKK AUTO CONSULTANTS PTE LTD (TP)	7 May 2019
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	22 January 2019
EMAIL TPFT PHU.mig	Letters and Correspondence	Workshop	VISHNU BATHAM Shalhar	4 January 2019